

**R. W. Gillespie & Associates, Inc.**

86 Industrial Park Road, Suite 4, Saco, ME 04072  
200 International Drive, Suite 170, Portsmouth, NH 03801  
ME 207-286-8008; Fax: 207-286-2882  
NH 603-427-0244; Fax: 603-430-2041

LETTER OF TRANSMITTAL

Doughty & Associates, Inc.

362 U.S. Route One

Falmouth, Maine 04105

Date:	October 18, 2004	Project No.:	438-05
Attention:	Mr. Phillip Doughty (pdarch@maine.rr.com)		
Re:	New Jetways & Addition to Baggage Claim Laboratory Testing Portland, Maine		

We are sending you attached laboratory test results.

Laboratory No. (s)	Test (s) Performed
10/18/04	Ultrasonic Inspection Report

Remarks:

Copy To: Roy Williams (rsw@ci.portland.me.us)

Signed: Suzan A. Bullock

If enclosures are not as noted, kindly notify us at once.

**Quality Assurance Labs Inc.**

NON-DESTRUCTIVE TESTING AND INSPECTION SERVICES  
80 PLEASANT AVENUE • SOUTH PORTLAND, MAINE 04106 • TEL: (207) 799-8911 • FAX: (207) 799-7251

October 18, 2004

R. W. GILLESPIE & ASSOCIATES, INC.  
86 Industrial Park Road, Suite 4  
Saco, ME 04072

RE: Portland Jctport Terminal Expansion  
Portland, ME  
QAL 04-621  
Project# 438-05

ATTN: ROBERT GILLESPIE

This letter will serve as my report for ultrasonic inspection. On 10/18/04 inspection was performed on the following,


Moment connection 35W.1 was repaired, re-inspected and found acceptable.

Moment connection top only 47W.1 was repaired, re-inspected and found acceptable.

(6) Column cap splices W.1-X-38-47 were inspected and found acceptable..

If you have any questions please call me at 799-8911.

Sincerely,



DAVID L. PRATT JR.  
LEVEL II CWI# 97100861

MTG