

## **EMSL Analytical, Inc.**

161 John Roberts Road South Portland, ME 04106 Phone/Fax: (207) 517-6921 / (207) 517-6922 http://www.EMSL.com / portlandlab@emsl.com

FMSI Order ID: Customer ID: Customer PO:

621700463 ABAT52 17-063

Project ID:

Attn: Kris Rickett

**Abatement Professionals Corporation** 

590 County Road

Suite #2

04092 Westbrook, ME

17-063 / ECO MAINE

Phone: Fax: Collected: (207) 773-1276 (207) 772-1203 3/29/2017

Received:

3/29/2017

Analyzed:

3/30/2017

Summary Test Report for Asbestos Analysis of Bulk Material via EPA 600/R-93/116

Client Sample ID:

**B1-Floor Tile** 

Lab Sample ID:

621700463-0001

621700463-0001A

621700463-0002

621700463-0002A

Sample Description:

Client Sample ID:

Client Sample ID:

Client Sample ID:

Proj:

SCALEHOUSE, FLOOR TILE.

Analyzed Non-Asbestos **TEST** Date Color Fibrous Non-Fibrous **Asbestos** Comment

PLM Grav. Reduction 3/30/2017 Tan/Various 0.0% 100% None Detected

**B1-Mastic** Sample Description: SCALEHOUSE, FLOOR TILE.

Analyzed Non-Asbestos TEST Date Fibrous Non-Fibrous Asbestos Comment Color 3/30/2017 PLM Grav. Reduction Brown 0.0% 100% None Detected

**B2-Floor Tile** Sample Description: SCALEHOUSE, FLOOR TILE.

Analyzed Non-Asbestos **TEST** Date Color Fibrous Non-Fibrous Asbestos Comment PLM Grav. Reduction 3/30/2017 100% Tan/Various 0.0% None Detected

Client Sample ID: **B2-Mastic** Sample Description: SCALEHOUSE, FLOOR TILE.

Analyzed Non-Asbestos TEST Fibrous Non-Fibrous Comment Date Color Asbestos PLM Grav. Reduction 3/30/2017 None Detected Brown 0.0% 100% 621700463-0003

**B3-Floor Tile** Sample Description: SCALEHOUSE, FLOOR TILE.

Non-Ashestos Analyzed **TEST** Date Color Fibrous Non-Fibrous Asbestos Comment PLM Grav. Reduction 3/30/2017 Tan/Various 0.0% 100% None Detected Client Sample ID: Lab Sample ID: 621700463-0003A

Sample Description: SCALEHOUSE, FLOOR TILE.

Analyzed Non-Asbestos **TEST** Date Color Fibrous Non-Fibrous **Asbestos** Comment Insufficient Material PLM Grav. Reduction 3/30/2017 Lab Sample ID: 621700463-0004 Client Sample ID:

Sample Description: SCALEHOUSE, JOINT COMPOUND.

Analyzed Non-Asbestos TEST Non-Fibrous Comment Date Color Fibrous Asbestos PLM 3/30/2017 White 0% 100% None Detected



## **EMSL** Analytical, Inc.

161 John Roberts Road South Portland, ME 04106 Phone/Fax: (207) 517-6921 / (207) 517-6922 http://www.EMSL.com / portlandlab@emsl.com

EMSL Order ID: Customer ID: Customer PO:

621700463 ABAT52 17-063

Project ID:

## Summary Test Report for Asbestos Analysis of Bulk Material via EPA 600/R-93/116

Lab Sample ID: 621700463-0005 Client Sample ID:

Sample Description: SCALEHOUSE, JOINT COMPOUND.

		Analyzed		Non	-Asbestos				
TEST		Date	Color	Fibrous	Non-Fibrous	Asbestos	Comment		
PLM		3/30/2017	White	0%	100%	None Detected			
Client Sample ID:	В6						Lab Sample ID:	621700463-0006	

Sample Description: SCALEHOUSE, JOINT COMPOUND.

	Analyzed		Non-Asbestos			
TEST	Date	Color	Fibrous N	Non-Fibrous	Asbestos	Comment
PLM	3/30/2017	White	0%	100%	None Detected	

PLM: Maine Analyst Certification # BA-0174, BA-0178

PLM EPA NOB: Maine Analyst Certification # BA-0174, BA-0178

Analyst(s):

Stephen Severn PLM (2)

PLM Grav. Reduction (4)

Zackary Carbee PLM (1)

PLM Grav. Reduction (1)

Reviewed and approved by:

Christina Walker, Laboratory Manager or Other Approved Signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. This test report must not be used to claim product endorsement by NVLAP or any agency of the U.S. Government. EMSL bears no responsibility for sample collection activities or analytical method limitations. The laboratory is not responsible for the accuracy of results when requested to physically separate and analyze layered samples. PLM alone is not consistently reliable in detecting asbestos in floor coverings and similar NOBs

Samples analyzed by EMSL Analytical, Inc. South Portland, ME

Initial report from: 03/30/201714:00:10