Reviewed for Code Compliance
Inspections Division
Approved with Conditions
Date: 12/05/17

ICON ENVIRONMENTAL CONSULTANTS
FINAL CLEANING CHECK LIST

DATE: 10/27/2017 **TIME:** 1515 **LOCATION:** 141-148

PROJECT NAME: Phase 2, Former Travel Lodge 1200 Brighton Ave Portland, Maine

CONTRACTOR: AEC Project #1879

PROJECT MONITOR: C. Wilson AM-0019

FINDINGS	YES	NA*	NO*
1. Visible ACBM removed, equipment, supplies, waste.	X		
2. Required poly barriers or tape	X		
3. Surfaces wet wiped, substrate touched to confirm.	X		
4. Design and Notification on site.	X		
5. Negative pressure system operating at/above .02/H_2O	X		
6. Wall, (ceiling), floor, pipe, duct, boiler, gasket, fitting, (transite) visual pass? (-) = Material Abated	X		
7. Does containment match design?	X		
8. Area dry for air test?	X		
9. Has Monitor signed on containment log?		X	

REMARKS *(All NO/NA responses require further explanation)

Abatement quantities per work plan

Completion of post tear down visual Yes/(No) Pass/Fail
Quantity of Asbestos Abated: see above

Visual inspection: Passed X Failed _____

Air Results: Passed X Failed Date: 10/27/2107 No. of Samples 5

PROJECT SUPERINTENDENT: Chris Miller

ICON ENVIRONMENTAL CONSULTANTS