### Portland, Maine



### Yes. Life's good here.

Planning & Urban Development Department

Director of Planning and Urban Development Jeff Levine

> Inspection Services, Director Tammy M. Munson

August 13, 2014

POMROY BETTY A WID KW VET PO BOX 432 WESTBROOK, ME 04098

CBL: 274 B016001

Located at: 91 HOLM AVE

Certified Mail 7012 0470 0002 1928 5563

Dear Ms. Pomroy,

#### SECOND NOTICE OF VIOLATION

An evaluation of the above-referenced property on 08/13/2014 revealed that the structure remains non-compliant with the Housing Code of the City of Portland.

Attached is a list of the violations.

This is a SECOND notice of violation pursuant to Section 6-118 of the Code. All referenced Violations shall be corrected. A re-inspection will occur on 09/12/2014, at which time compliance will be required.

Failure to comply will result in this office referring the matter to the City of Portland Corporation Counsel for legal action and possible civil penalties, as provided for in Section 1-15 of the Code and in Title 30-A M.R.S.A ss 4452.

Please feel free to contact me is you wish to discuss this matter further or have any questions.

Sincerely

Code Enforcement Officer

(207) 874-8789

# CITY OF PORTLAND DEPARTMENT OF PLANNING & URBAN DEVELOPMENT

389 Congress Street Portland, Maine 04101

### Inspection Violations

Owner/Manager		Inspector	Inspection Date
POMROY BETTY A WID KW VET		Chuck Fagone	5/16/2014
Location	CBL	Status	Inspection Type
91 HOLM AVE	274 B016001	Re-Inspect 14 Days	Complaint-Inspection

Code Int/Ext Floor Unit No. Area Compliance Date

1) 6-109.5.

Exterior

Through Out

Violation:

UNOCCUPIED RESIDENTIAL STRUCTURES

Notes:

The owner of any unoccupied structure containing dwelling units or rooming units or any or any combination thereof shall comply with the following minimum standards. See the following sub sections A, c and d.

2) 6-109.5. (a)

Exterior

Garage

Violation:

FOUNDATIONS, CELLARS, EXTERIOR WALLS, ROOFS.

Notes:

Every foundation, basement, cellar, exterior wall and roof shall be substantially weather tight, watertight and vermin-proof; shall be structurally sound and in good repair; and shall be safe for the intended use as well as capable of supporting whatever load normal use may cause to be placed thereon.

3) 6-109.5. (c)

Exterior

Basement

Violation:

EXTERIOR WINDOWS, DOORS AND SKYLIGHTS.

Notes:

Every window or door, including basement or cellar doors and hatchway, and skylight shall be substantially weather tight, water tight and vermin proof, and shall be kept secured to prevent

the ingress of people and animals.

4) 6-109.5. (d)

Exterior

Porch

Violation:

STAIRWAYS, STAIRS & PORCHES.

Notes:

Stairways, stairs, porches. Every outside stairway, stairwell, stairs and porch and any appurtenances

thereto shall be structurally sound, in good repair and safe to use.

Comments:

Per inspection, violations exist of unsecured building and outbuilding, stairs missing to front porch, debris and trash on site.

Strengthening a Remarkable City,
Building a Community for Life
PORTLAND
MAINE

Inspection Services Division 389 Congress Street, RM 315 Portland, Maine 94191 3509

## CERTIFIED MAIL

STEUD ZEUP 0



7012 0470 0002 1928 5563



1000



U.S. POSTAGE PAID PORTLAND, ME 04101 AUG 14.14 AMOUNT

\$6.49 00030643-11

RETURN RECEIPT REQUESTED

8 2495

NOTIFY SENDER OF NEW ADDRESS POMROY

PÕ BÕX 365 FREEPORT ME Ø4032-0365

\*1459-85412-18-19

NIXIE 015 DE 1009 0009/09/14

RETURN TO SENDER UNCLAIMED UNABLE TO FORWARD

233<sup>04098</sup>44980645<del>2</del>

: 04098043232 \*3084-04330-14-40

