

COMMENTS .

05/12/00 - windows in left bedroom 21x27 = not 5.7 square ft = a few
mul plates needed around plumbing fixtures
6/30/00 Final inspection - egress OK. Smokes OK. Nice Job. Close permit for

Inspection Record

Type	Date
Foundation: _____	_____
Framing: _____	_____
Plumbing: _____	_____
Final: _____	_____
Other: _____	_____