Portland, Maine



Yes. Life's good here.

Planning & Orban Development Department

Director of Planning and Urban Development Jeff Levine

> Inspection Services, Director Tammy M. Munson

March 17, 2015

RICCI STEVEN M 915 BRIGHTON AVE PORTLAND, ME 04102

CBL: 284 A004001

Located at: 915 BRIGHTON AVE

Certified Mail 7010 1870 0002 8136 6820

Dear Mr. Ricci,

SECOND NOTICE OF VIOLATION

An evaluation of the above-referenced property on 03/17/2015 revealed that the structure remains non-compliant with the Housing Code of the City of Portland.

Attached is a list of the violations.

This is a **SECOND** notice of violation pursuant to Section 6-118 of the Code. All referenced Violations shall be corrected. A re-inspection will occur on 04/16/2015, at which time compliance will be required.

Failure to comply will result in this office referring the matter to the City of Portland Corporation Counsel for legal action and possible civil penalties, as provided for in Section 1-15 of the Code and in Title 30-A M.R.S.A ss 4452.

Please feel free to contact me is you wish to discuss this matter further or have any questions.

Sincerely,

Chuck Fagone

Code Enforcement Officer

(207) 874-8789

CITY OF PORTLAND DEPARTMENT OF PLANNING & URBAN DEVELOPMENT

389 Congress Street Portland, Maine 04101

Inspection Violations

Owner/Manager RICCI STEVEN M		Inspector Chuck Fagone	Inspection Date 2/12/2015
915 BRIGHTON AVE	284 A004001	Failed	Building-Housing Inspection

Code Int/Ext Floor Unit No. Area **Compliance Date**

1) 6-116. (e)

Interior

Through Out

Violation:

FIRE PROTECTION

Notes:

Every dwelling, dwelling unit, rooming house and rooming unit shall comply with the applicable provisions of the most current edition of the National Fire Protection Association Life Safety Code, and

with all other applicable state statutes and regulations.
Each bedroom will need to have a hard wired battery back-up photo electric smoke detector installed. In the common area of each floor, a combination hard wired, battery back-up smoke/carbon monoxide detector. All detectors will need to be photo electric.

2) 22.3.3(a)

Interior

Basement

Violation:

PREMISES TO BE KEPT FREE FROM RODENT HARBORAGE

Notes:

The owner of a two (2) or more family residential building and the owner or occupant of a single family residential building shall maintain the building and the lot on which the building is located free from any accumulation of any putrid substance, garbage, rubbish, old lumber, debris or rubble, except in

watertight covered containers.

Debris and trash in the basement needs to be removed

3) 6-71. (A-e)

Interior

Basement

Violation:

ENFORCEMENT FOR DEFECTIVE INSTALLATIONS

Notes:

When any electrical work or wiring is found to have been installed in a manner not in accordance with the provisions of this article, the electrical inspector is hereby authorized and empowered to place a stop order, remove fuses, cut wires, or otherwise render the system inoperative until such work or wiring has been corrected, re-inspected and approved.

The electrical panel located in the basement is missing its cover. A cover will need to be installed.

Portland, Maine



Yes. Life's good here


Planning & Urban Development Inspection Division

389 Congress Street, Room 315 Portland, Maine 04101-3509













1000



04102

U.S. POSTAGE PAID PORTLAND,ME 04101 MAR 18, 15 AMOUNT

00100424-12

O410281007

U.S. Postal Service ™ CERTIFIED MAIL RECEIPT (Domestic Mail Only; No Insurance Coverage Provided) For delivery information visit our website at www.usps.com 띠 ш Ш m NO Postage -D \$0.49 0104 Certified Fee 2000 \$3.30 Postmark Return Receipt Fee (Endorsement Required) \$2.70 Restricted Delivery Fee (Endorsement Required) 1870 \$0.00 INST Total Postage & Fees ^l03/18/2015 7070 Street, Apt. No.; or PO Box No. PS Form 3800, August 2006