

---

---

**City of Portland, Maine**

**Inspections Division**

**Inspection Results**

**All Results**

<b>Date</b>	<b>CBL</b>	<b>Business</b>	<b>Appl ID</b>	<b>Appl Type</b>	<b>FT</b>	<b>Sch. Type</b>	<b>Status</b>
10/17/2013	286 A019001	Glenn Dyer Glen @ 312-8542 Ann @ 831-5201for close in. /gg CONFIRMED	201302238	Building	Yes	Close-in Plumbing/Framing w/	Failed
60 GROVESIDE RD						Work covered without inspection. Expose for inspection. Provide engineering for header Block under jack/king studs	
10/17/2013	286 A019001	Glenn Dyer Glen @ 312-8542 Ann @ 831-5201for close in. /gg	201302238	Building	Yes	Electrical Close-in w/Fire & Dra	FOLLOW U
60 GROVESIDE RD						TR outlets, add a couple outlets where needed check wiring of lights	
10/21/2013	286 A019001	Glenn Dyer Glenn, 312-8542, re-inspect close in. Bs.	201302238	Building	Yes	Close-in Plumbing/Framing w/	Passed
60 GROVESIDE RD							
11/15/2013	286 A019001	Glenn Dyer Ann - 831-5201 or GC - 312-8542 Glen	201302238	Building	Yes	Final Inspection	Failed
60 GROVESIDE RD						Correct electrical violations in garage need condensate neutralizer no fixtures, flooring or cabs in kitchen	
11/15/2013	286 A019001	Glenn Dyer Ann - 831-5201 or GC - 312-8542 Glen	201302238	Building	Yes	Final - Electric	
60 GROVESIDE RD							