

## FIELD REPORT

**SRG Engineering, Inc.**  
**P. O. Box 925**  
**Gray, ME 04039-0925**  
**Tel:(207)-657-7323 Fax:(207)-657-7342**

Project No.: **05-132**    Date: **March 6, 2006**  
Project Name:            **Phoenix Welding**  
Project Location:        **Portland, Maine**  
Weather Conditions:    **Mostly Sunny, upper 30's**  
Contact Person(s):      **Steven Grant-SRG Eng.**

### Discussion/Observations:

#### Observations are as follows:

1. Steel frames and most of the roof purlins are in place.
2. Slab-on-grade is not in place.
3. 9 photos taken for the record, see attached.

I contacted Ron Mercier after my visit (about 2:30pm) to let him know that he needs to contact Dave CoWallis at SWC to schedule next site visit for them to check steel framing. I then spoke with Dave at SWC to tell him Ron should be calling soon.

### Diagrams:

Copies To: SWC

Signed: \_\_\_\_\_