

FIELD REPORT

SRG Engineering, Inc.
P. O. Box 925
Gray, ME 04039-0925
Tel:(207)-657-7323 Fax:(207)-657-7342

Project No.: **05-132** Date: **March 21, 2006**
Project Name: **Phoenix Welding**
Project Location: **Portland, Maine**
Weather Conditions: **Mostly Sunny, upper 40's**
Contact Person(s): **Steven Grant-SRG Eng.**
 John (Field Super)-PATCO

Discussion/Observations:

Observations are as follows:

1. **Steel framing and wall/roof bracing is in place.**
2. **Exterior walls are framed at all sides, with exterior siding in place at front and right side.**
3. **Roof insulation and metal deck is in place.**
4. **John brought to my attention the exterior wood curtain walls have a light-gauge metal slip track to allow for steel framing deflection.**
5. **We reviewed wall x-bracing requirements with John on the PE stamped building plans provided by VP and verified all wall bracing is in place.**
6. **9 photographs taken for the record.**

Diagrams:

Copies To: SWC/file

Signed: _____