

Final Report of Special Inspections

Agent's Final Report

Project: *B & L Business Park – Building C 60'x120'*
585 riverside Street, Portland, ME.

Agent: *S.W. Cole Engineering, Inc*

Special Inspector: *Harvey E. Sawyer III*

To the best of my information, knowledge and belief, the Special Inspections or testing required for this project, and designated for this Agent in the *Statement of Special Inspections* submitted for permit, have been performed and all discovered discrepancies have been reported and resolved other than the following:

Comments:


(Attach continuation sheets if required to complete the description of corrections.)

Interim reports submitted prior to this final report form a basis for and are to be considered an integral part of this final report.

Respectfully submitted,
Agent of the Special Inspector
S.W. Cole Engineering, Inc.
286 Portland Road Gray, Maine


Roger Domingo

(Type or print name)


Signature

July 14, 2006

Date



Final Report of Special Inspections

Project: *B & L Business Park – Building C 60'x 120''*

Location: *585 Riverside Street Portland, Maine*

Owner: *B & L Partners*

Owner's Address: *Same*

Architect of Record: *Harvey E. Sawyer III*

Structural Engineer of Record:

To the best of my information, knowledge and belief, the Special Inspections required for this project, and itemized in the *Statement of Special Inspections* submitted for permit, have been performed and all discovered discrepancies have been reported and resolved other than the following:

Comments:

(Attach continuation sheets if required to complete the description of corrections.)

Interim reports submitted prior to this final report form a basis for and are to be considered an integral part of this final report.

Respectfully submitted,
Special Inspector

(Type or print name)

Signature

Date

Licensed Professional Seal