
CITY OF PORTLAND
DEPARTMENT OF PLANNING & URBAN DEVELOPMENT

389 Congress Street
Portland, Maine 04101

Inspection Violations

Owner/Manager PIRONE JOSPEH D & ETALS JTS		Inspector Chris Hanson	Inspection Date 10/29/2008
Locatation 543 RIVERSIDE ST	CBL 312 B010001	Status Re-Inspect 30 Days	Inspection Type Building Permit-Inspection

Code	Int/Ext	Floor	Unit No.	Area	Compliance Date
1) 100.7	Exterior			BackYard	
Violation: Malfunctioning System					
Notes:					
Comments: Failed septic system					