

Permitting and Inspections Department Michael A. Russell, MS, Director

November 6, 2017

NANGARHAR LLC PO BOX 17661 PORTLAND, ME 04112

CBL: 324 B003001

Located at: 1954 FOREST AVE

Certified Mail 7014 1820 0001 4049 7055

Dear NANGARHAR LLC,

An evaluation of the above-referenced property on 11/06/2017 shows that the structure fails to comply with Chapter 6.Article V. of the Code of Ordinances of the City of Portland, The Housing Code. Attached is a list of the violations.

This is a notice of violation pursuant to Section 6-118 of the Code. All referenced violations shall be corrected within 30 days of the date of this notice. A re-inspection of the premises will occur on 12/08/2017 at which time compliance will be required. Failure to comply will result in this office referring the matter to the City of Portland Corporation Counsel for legal action and possible civil penalties, as provided for in Section 1-15 of the Code.

This constitutes an appealable decision pursuant to Section 6-127 of the Code.

Please feel free to contact me if you wish to discuss the matter or have any questions.

Please be advised that the Portland City Council has amended the Building regulations to include a \$150.00 re-inspection fee. This violation will automatically cause a re-inspection at no charge. If there are any subsequent inspections, however, the \$150.00 fee will be assessed for each inspection.

Sincerely,

/s/

Jason Duval

Code Enforcement Officer

CITY OF PORTLAND HOUSING SAFETY OFFICE

389 Congress Street Portland, Maine 04101

Inspection Violations

Owner/Manager NANGARHAR LLC		Inspector Jason Duval	Inspection Date 11/6/2017
Location	CBL	Status	Inspection Type
1954 FOREST AVE	324 B003001	Failed	Housing Safety Inspection
Code	Int/Ext Floor	Unit No. Area	Compliance Date

1) 206

Violation:

SMOKE ALARMS / BEDROOMS; Smoke Alarms - One and Two-Family Dwellings: Single-station or multiple-station (interconnected) photoelectric smoke alarms must be powered by the building electrical system or powered by a 10-year non-replaceable battery and shall be positioned correctly on walls or ceilings: in all sleeping rooms.

NFPA 101 (2009) 24.3.4.1(1), 9.6.2.10, amended by City Code of Ordinances Section 10-3(i)

Notes:

Smoke alarm required in one bedroom.

Comments: Smoke alarm needed in one bedroom. To schedule inspection please contact Licensing & Registration

at 207-756-8131 or housingsafety@portlandmaine.gov within 30 days.