#### CITY OF PORTLAND, MAINE

Department of Building Inspection



### Certificate of Occupancy

LOCATION

90 Milton St.

CBL: 336-K-013

Issued to Joseph Frustaci

Date of Issue

July 24, 2000

This is to certify that the building, premises, or part thereof, at the above location, built — altered — changed as to use under Building Permit No. 000217, has had final inspection, has been found to conform substantially to requirements of Zoning Ordinance and Building Code of the City, and is hereby approved for occupancy or use, limited or otherwise, as indicated below.

PORTION OF BUILDING OR PREMISES

APPROVED OCCUPANCY

Entire

**Limiting Conditions:** 

Single Family Dwelling
Use Group R-3
Type 5B
BOCA "96 1999

This certificate supersedes certificate issued

Approved:

7- 2 U - 111

(Date)

Inspector

Inspector of Buildings

Elect. 1KW 7-272K

Notice: This certificate identifies lawful use of building or premises, and ought to be transferred from owner to owner when property changes hands. Copy will be furnished to owner or lessee for one dollar.

#### **COMMENTS**

Con't	
6-22-00 Roceived As Built plans. Fidditional Framing head room 6'7", wising not consistent, Top step may not need joist hangers in basement at both ends of stair opening. Guardrail height at main stairs can be 36". Garage stairs	issues: Basement stairs - Hatform too high,
head room 6'7", wosing not consistent, Top step may not	+ be consistent when finish flour applied,
need joist hangers in basement at both ends of stair opening.	Note: This permit is under BOCA'96 so
Guardrail height at main stairs can be 36" Garage stairs	: Rise Ht. not consistent at bottom step.
nosing not consistent, width not 36", no handrail. Baseme	ut carrying Beam 2x10 notched out at
bearing wall z"depth by 7'/4 along Length. Require a hely o	olumn supporting each end butted to foundation
wall and I fally placed on a footing reducing the spain at	The left side of the stairs. DB to 6'3"
7-25-00 Punch List inspection: Side deck steps Nosing	overhang irregular of too 2 Steps, main
Interior stairs Nosing exceeds code 1/2", Guardrail not at 3	36" cellar stairs needs 80" headroom
at bottomstep. Plumbing, kitchen/2nd Floor that lav leak, Ext. &	or relief on boiler. OB Solution for required
addition of fally by stairs will be a 2' bearing wall per Mike. N.	XZ
addition of fally by stairs will be a 2' bearing wall per Mike. N. 7/31/2K ALL TEMS LISTED IN PUNCHEIST OF 7-25-	DO CHECK OUT ACCEPTABLE. SKW
CBC: 336-K-013	
CBC: 336-K-013 Dermit: 00217	
· ·	•
	Inspection Record Type Date
Foundation	:
Framing: _	

Other: \_\_\_\_\_

#### **COMMENTS**

5-10-00 Setbacks - No Forms, No Lines, No contractor B	
5-11-00 Sethack inspection to strung lines from pins. All setbacks within requir	red
measurements. Bulkhead to Rear is 23' which is allowable for zoning!	B
5-11-06 Call From Steve Bushy regarding DRC denial of permit. Notified the Fru.	staci
of denial and Stop work order. Referent conditions of approval and contact	t
Deluca Hoffman for permit issuance. 33	
5-12-00 Per Steve Bushy The conditions of DRC Appoint have been met	a
Nemo is forthcoming regarding plans for connecting diamage.	
5-18-00 Backfill INSP-OK for foundation drain-still needs DRC drainage inspection-Jo	e will
Call steve B. Pre-constr meeting. ZY width problematic for Rise/run. Sethack allows for I'ounha	ua in
Front to meet code requirement. Requested chawing to indicate plan change. Reviewed Railing heights, so	the ears
and inspection schedule. Basement stairs will Turn to weet code XB	11.4.
6/20/2000 Changes made in location of doors, the bathroom to We	med -
Exproso Changes made in location of doors, the bathroom, ite. We new plans to reflect these changes. Questions on carry	m
beam also need resolution. also eques in	melions
must be adjusted to give correct domensums. answ.	-
6/22/00 check for garage wall Chimney as 1" clearing = Chimney must have 2" clearance & a	Ql
Combustibles - This is not considered an exterior wall Is	
Inspection Record	
Туре	Date
Foundation:	
Framing:	
Plumbing:	
Final: Other:	
Ouici.	



TEL 207 775 1121 FAX 207 879 0896

SITE PLANNING

CONSTRUCTION ADMINISTRATION

#### **MEMORANDUM**



TO:

Code Enforcement -

Kandi Talbot, Planner

FROM:

Chris Earle, DRC Assistant

Reviewed by Steve Bushey, P.E., Acting Development Review Coordinator

DATE:

July 27, 2000

RE:

Certificate of Occupancy - 90 Milton Street

On July 26, 2000, the site was reviewed for compliance with the conditions of approval. 1.

It is my opinion that a Permanent certificate of occupancy could be issued, assuming Code Enforcement has no outstanding issues.

Office: 207.878.1751 Fax: 207.878.1788 e-mail: tibs@javanet.com

80 Leighton Road • Falmouth, Maine 04105

7/24/2000 00141

JASE Construction
Mr. Joe Frustaci
PO Box 2351
South Portland, Maine 04116

RE: Mazeottie Property, Milton Street, Portland, Maine

Dear Joe,

Pursuant to your request we have conducted a structural analysis for the first floor framing in the above referenced house. The house is newly constructed and is now complete. We understand that two concerns have been raised by the City of Portland Inspection dept. as part of their final inspection.

- 1. Spacing of lolli columns in the basement are currently set at a maximum distance of (8'-0½") on center. These columns are supporting a center-framing girder comprised of three built-up two by tens. The city is concerned because the spacing is greater than (6'-3")
- 2. This same (3) 2x10 girder has been notched nine inches in form the end a depth of two inches, leaving an effective beam depth of 7-1/2" @ 9" in from the end support.

  Apparently the concern is for shear and moment capacity at this notch.

We conducted a structural analysis of the girder and column locations and have determined that the maximum allowable spacing of column supports should be (6'-9") for full compliance with the BOCO and NDS codes, given the lumber used. We used an allowable bending stress of 1120psi. We believe that the quality of the lumber used for these framing girders is very good. If machine stress rated (tested) the allowable bending stress would likely be in the order of 1600 psi or greater. Based on our visual inspection of this framing lumber we believe that it has sufficient visual appearance to justify a higher allowable stress. Use of this higher bending stress in analysis increases the allowable clear span to (8'-4").

However, because the lumber was not machine stress rated our conservative recommendation is to provide screw type columns at a distance such that the maximum allowable free span of these girders does not exceed (6'-9"). If the homeowner wishes to eliminate the screw columns we recommend a sample of the lumber be tested for allowable stress. Our analysis of the notch at the end of the beam shows that the moment and shear values at this notch are at acceptable levels and therefore nothing further needs to be done.

BODEAL

Should the homeowner or the City inspector have any questions please call.

ames A. Thibideau PE

President

Sincerely,



FILL IN AND SIGN WITH INK

## **APPLICATION FOR PERMIT** HEATING OR POWER EQUIPMENT

Ц		
4	PF OF PULL	AND
	00661	4

To the INSPECTOR OF BUILDINGS, PORTLAND, ME.

The undersigned hereby applies for a permit to insaccordance with the Laws of Maine, the Building Code of	stall the following heating, cooking or power equipment in					
Location 90 Milron 57 Partial I						
Installer's name and address Flint's phinBill 358 Prosector 57 56	FUET ME Telephone 74/- DEVED					
Location of appliance:  Basement	Type of Chimney:  Masonry Lined  Factory built					
Type of Fuel:  Gas Solid	☐ Metal Factory Built U.L. Listing #					
Appliance Name: Sold Sold Sold Sold Sold Sold Sold Sold	- Direct Vent  Type UL#					
Will appliance be installed in accordance with the manufacture's installation instructions? Yes  No	Type of Fuel Tank Oil Gas					
	Size of Tank 275 Callon					
The Type of License of Installer:    Master Plumber #   Solid Fuel #   Oil #	Number of Tanks  Distance from Tank to Center of Flame  feet.					
Approved  Fire:  Ele.:  Bldg.:	Approved with Conditions  See attached letter or requirement					
Signature of Installer	PERMIT ISSUED WITH REQUIREMENTS					

(Total)

HHE-211 Rev. 6;94

DATE:	REMARKS:
6-9	brond Rode only 5' Afait & Couldet see
	hat Cafle.
6-3	Ock's Lakeral & Sewer Cuti
10-20	O.K'D to Close - In
7-19	O.K'D to Close - In Final Jusp Keeds First October Outlet (N/A) AFTIN CONVENSATION W/MIKE C. SKW
	CONVERSATION W/MIKE C. SKW
-	

# **ELECTRICAL PERMIT**City of Portland, Me.

I installations

Date

Date

To the Chief Electrical Inspector, Portland Maine:
The undersigned hereby applies for a permit to make electrical installations
in accordance with the laws of Maine, the City of Portland Electrical Ordinance,
National Electrical Code and the following specifications:

Permit # 456 CBL# 336 - K - 013

SITE LOCATION: 90 Miltonst.

head head ber of)	<b>35</b>	fluorescent Underground Underground	18 V	Smoke Detectors Strips TTL AMPS	<800		.20	3.01
head head head ber of)	15	Underground Underground	V		<800			
head head head ber of)	/5	Underground Underground	V		<800			3.0
head head ber of)		Underground	V	TTL AMPS	<800		15.00	
head head ber of)		Underground		TTL AIVIPS	<800	<i>  _  </i>	15.00	
head ber of)						1		
ber of)		9.4	1		>800		25.00	
ber of)	-	Underground	<u> </u>	TTL AMPS	<u> </u>	<b></b>	25.00	
,		Onderground		ITE AIVIPS	ļ			
,		· · · · · · · · · · · · · · · · · · ·					25.00	
DELOH	1.					-	1.00	2.0
ric units							2.00	<del>-</del>
s units	,	Interior		Exterior			1.00	
							5.00	5,00
	/			L				2.0
	-			·	ļ.,			
	<del></del>	<u> </u>	-		1	<u> </u>		6.00
		Ори		vvasi iirig iviad iirie		$\longrightarrow$		2,0
							4	
				Poolo				
2		FMS					i i	<del></del>
		LIVIO		memiosiai				
						-		
							. 1	
	$\dashv$						1	
							I .	
	-+						20.00	
ce		Remote		Main			4.00	
1		Tiomote		IVIAIII				
1	-+							
	-+			TOTAL AMOUNT	- I		10.00	
IUM FEE/CO	MME	RCIAL~35.00-				25.00	~	112.
e ready		101AL 00.00		ill call		<del>49.00</del>	33,00	150
	es Hot s Dactors s (denote) Ond/win Ond/cent c dis/res dis/com y Duty(CRKT) dis/Carnv ditions depairs	es / Hot / S / Dactors / S (denote) / Ond/win / Ond/cent / S / S (S) / Ond/cent / S / Ond/cent / On	res / Cook Tops Water heaters S Disposals Dactors Spa Sis (denote) Dond/win Dond/cent C EMS Sis/res Disposals Spa	res / Cook Tops Water heaters S / Disposals Dactors / Spa S (denote) Ond/win Ond/cent C EMS S (s/cent) S (denote) Ond/cent C EMS S (denote) Ond/cent	res / Cook Tops Wall Ovens Hot Water heaters Fans S Disposals Dishwasher Dactors Spa Washing Machine To (denote) Dond/win Dond/cent Pools Thermostat Therm	res / Cook Tops Wall Ovens Hot Water heaters Fans Society Spa Washing Machine / Society Spa	res / Cook Tops Wall Ovens Hot Water heaters Fans S / Disposals / Dishwasher Vactors Spa Washing Machine / Spa Washing Machine / Spa Washing Machine / Spa	Cook Tops   Wall Ovens   2.00