



Permitting and Inspections Department
Michael A. Russell, MS, Director

January 23, 2018

HERNANDEZ HECTOR A &
150 PLYMOUTH ST
PORTLAND, ME 04103

CBL: 341 B011001
Located at: 50 BROADWAY

Certified Mail 7017 2680 0000 5498 1181

Dear Hernandez Hector A & ,

An evaluation of the above-referenced property on **01/19/2018** shows that the structure fails to comply with Chapter 6.Article V. of the Code of Ordinances of the City of Portland, The Housing Code. Attached is a list of the violations.

This is a notice of violation pursuant to Section 6-118 of the Code. All referenced violations shall be corrected within **30** days of the date of this notice. A re-inspection of the premises will occur on **02/22/2018** at which time compliance will be required. Failure to comply will result in this office referring the matter to the City of Portland Corporation Counsel for legal action and possible civil penalties, as provided for in Section 1-15 of the Code.

This constitutes an appealable decision pursuant to Section 6-127 of the Code.

Please feel free to contact me if you wish to discuss the matter or have any questions.

Please be advised that the Portland City Council has amended the Building regulations to include a \$150.00 re-inspection fee. This violation will automatically cause a re-inspection at no charge. If there are any subsequent inspections, however, the \$150.00 fee will be assessed for each inspection.

Sincerely,

/s/

A handwritten signature in black ink, appearing to read "Jason Duval", written over a horizontal line.

Jason Duval
Code Enforcement Officer

**CITY OF PORTLAND
HOUSING SAFETY OFFICE**

389 Congress Street
Portland, Maine 04101

Inspection Violations

Owner/Manager Hernandez Hector A &		Inspector	Inspection Date 1/19/2018
Location 50 BROADWAY	CBL 341 B011001	Status Violations Exist	Inspection Type Inspection

Code	Int/Ext	Floor	Unit No.	Area	Compliance Date
------	---------	-------	----------	------	-----------------

1) 207

Violation: CARBON MONOXIDE ALARMS / LEVEL; Carbon Monoxide Alarms - One and Two-Family Dwellings: Single-station or multiple-station (interconnected) Carbon Monoxide alarms must be powered by the (A) building electrical system, or (B) 10-year non-replaceable battery and shall be positioned correctly on walls or ceilings: (1) on each level of the dwelling unit, and (2) including the basement.

NFPA 720 (2009) 9.5.1, 9.5.3, amended by State Law Title 25, Chapter 317 § 2468

Notes: CO alarms required in basement and first floor.

2) 205

Violation: SMOKE ALARMS / LEVEL; Smoke Alarms - One and Two-Family Dwellings: Single-station or multiple-station (interconnected) photoelectric smoke alarms must be powered by the building electrical system or powered by a 10-year non-replaceable battery and shall be positioned correctly on walls or ceilings: (1) within 21 feet of any door to a sleeping room and (2) in living areas separated by doors on each level of the dwelling unit and (3) including the basement.

NFPA 101 (2009) 24.3.4.1(2)(3), 9.6.2.10, amended by City Code of Ordinances Section 10-3(i)

Notes: Smoke alarm on first floor requires new batteries.

3) 210

Violation: ESCAPE WINDOWS; Escape Windows - One and Two-Family Dwellings: Escape windows shall be a free and clear outside window or door operable from the inside without the use of tools, keys, or special effort. Windows shall be within 20 feet of the finished ground level or accessible by rescue apparatus (if approved), or opening onto an exterior balcony and when below ground level shall be provided with an accessible, free and clear, window well.

NFPA 101 (2009) 24.2.2.3.3

Notes: Bedroom in basement does not have egress compliant window. Bedroom in basement will need to be removed.

4) 6-108.(a)

Violation: FOUNDATIONS CELLARS, EXTERIOR WALLS, ROOFS; Every foundation, basement, cellar, exterior wall, and roof shall be substantially weathertight, watertight, and vermin proof; shall be structurally sound and in good repair; and shall be safe for the intended use as well as capable of supporting whatever load normal use may cause to be placed thereon. Every exterior wall or portion thereof shall be painted or stained. Insulation shall be installed and maintained so as not to present a health or safety hazard to occupants. Water from roofs shall be so drained and conveyed therefrom as not to cause repeatedly wet floors, walls, or ceilings, or hazard to adjacent buildings or the occupants thereof.

Notes: Remove large hanging antenna on roof.

Comments: CO alarms needed on 1st floor and basement. Antenna needs to be removed that is hanging from roof. Smoke alarm on first floor needs new battery. Bedroom in basement needs to be removed due to window does not meet egress.