CITY OF PORTLAND DEPARTMENT OF PLANNING & URBAN DEVELOPMENT

389 Congress Street Portland, Maine 04101

Inspection Violations

Owner/Manager WOODWARD LORALYN M				Inspector Don McPherson			Inspection Date 2/22/2011		
Locatation CBL			CBL	Status			Inspection Type		
124 ALLEN AVE			342 B016001	Re-Insp	Re-Inspect 10 Days			Complaint-Inspection	
	Code	Int/Ext			Floor	Unit No.	Area	Compliance Date	
1)	6-111.(c)	6-111.(c) Interior		2nd			Kitchen		
	Violation: Water supply.								
Notes: Provide cold water to Kitchen sink. A licensed plumber is required to per							to perform t	he repairs.	

Comments: