

---

---

**CITY OF PORTLAND**  
**DEPARTMENT OF PLANNING & URBAN DEVELOPMENT**

389 Congress Street  
Portland, Maine 04101

---

**Inspection Violations**

<b>Owner/Manager</b> Woodward Loralyn M		<b>Inspector</b> Don McPherson	<b>Inspection Date</b> 2/11/2011
<b>Location</b> 124 ALLEN AVE	<b>CBL</b> 342 B016001	<b>Status</b> Re-Inspect 10 Days	<b>Inspection Type</b> Complaint-Inspection

<b>Code</b>	<b>Int/Ext</b>	<b>Floor</b>	<b>Unit No.</b>	<b>Area</b>	<b>Compliance Date</b>
1) 6-111.(c)	Interior	2nd		Kitchen	
<b>Violation:</b> Water supply.					
<b>Notes:</b> Provide hot and cold water to Kitchen sink. A licensed plumber is required to perform the repairs.					

**Comments:**