

## Inspection Violations

	Code	Int/Ext	Floor	Unit No.	Area	Compliance Date
1)	6-108.2	Interior	1	10	Living Room	
	<b>Violation:</b>	Interior floors, walls, ceilings and doors				
	<b>Notes:</b>	Water stains on Living Room ceiling indicating leak from Bathroom area above. Ceiling must be in good repair.				
2)	6-111.1	Interior	2	10	Bathroom	
	<b>Violation:</b>	Plumbing standards/Basic facilities.				
	<b>Notes:</b>	Tub drains at inadequate rate.				
3)	6-108.2	Interior	2	10	Bedroom	
	<b>Violation:</b>	Interior floors, walls, ceilings and doors				
	<b>Notes:</b>	water stains on bedroom ceiling indictes leak from outside.				
4)	6-108.1	Exterior	1	10	Living Room	
	<b>Violation:</b>	Foundations cellars, exterior walls, roofs				
	<b>Notes:</b>	Water seeping into Living room from outside wall. Indicated by wet carpet by foot of stairway. This leakage situation must be resolved.				
	<b>Comments:</b>	Unit 10 was inspected on 3/21/2007 for same violations. However a violation letter was not sent to owner.				