

MEMORANDUM

6 February 2015

Inspections Division
389 Congress Street
Portland, Maine 04101

RE: 54 Hennessy Drive, Portland, Maine

Dear Sir/Madam,

It is requested that you look at 54 Hennessy Drive, Portland, Maine.

Based on the City's zoning structure, it is believed that the storage area in the front of the house does not and is not up to code. All houses on Hennessy Drive are set back 25 feet from the property line and it is believe that only a 50 square foot platform could be attached to the house and encroach on the set back. Well if you inspect this house you will notice that there is a set of steps and a storage unit has been build onto the front of the house that covers the kitchen windows. It has a roof attached to it, which is anchored to the house, so this structure is not of a temporary nature. It is an eye sore and should be removed as I believe that a building permit was not given for this structure to be build.

Sincerely,

Concerned Neighbor