

## PORTLAND MAINE

Strengthening a Remarkable City, Building a Community for Life . www.portlandmaine.gov

Lee Urban - Director of Planning and Development Jeanie Bourke - Inspection Division Services Director

April 9, 2007

SARGENT MALCOLM A & 4 ORAMEL AVE PORTLAND, ME 04103

CBL: 349 D006001 Located at 4 ORAMEL AVE COPY

Certified Mail: 70033110000260641084

Dear SARGENT MALCOLM A &,

An evaluation of the above-referenced property on the twenty seventh day of March, 2007 shows that the structure fails to comply with Chapter 6.Article V. of the Code of Ordinances of the City of Portland, The Housing Code. Attached is a list of the violations.

This is a notice of violation pursuant to Section 6-118 of the Code. All referenced violations shall be corrected within thirty (30) days of the date of this notice. A re-inspection of the premises will occur on the ninth day of May, 2007 at which time compliance will be required. Failure to comply will result in this office referring the matter to the City of Portland Corporation Counsel for legal action and possible civil penalties, as provided for in Section 1-15 of the Code.

This constitutes an appealable decision pursuant to Section 6-127 of the Code.

Please feel free to contact me if you wish to discuss the matter or have any questions.

Please be advised that the Portland City Council has amended the Building regulations to include a \$75.00 reinspection fee. This violation will automatically cause a re-inspection at no charge. If there are any subsequent inspections, however, the \$75.00 fee will be assessed for each inspection.

Sincerely.

Jon Rioux @ (207) 874-8702

**B**uilding Inspector

## CITY OF PORTLAND

## DEPARTMENT OF PLANNING & URBAN DEVELOPMENT

389 Congress Street Portland, Maine 04 01

## Inspection Violations

Owner/Manager SARGENT MALCOLM A &		Inspector Jon Rioux	Inspection Date 3/27/2007
Locatation	CBL	Status	Inspection Type
4 ORAMEL AVE	349 D006001	Re-Inspect 30 Days	Complaint-Inspection

4 (	4 ORAMEL AVE		349 D006001 Re-Inspect 30 Days		Complaint-Inspection				
	Code	Int/Ext		Floor	Unit No.	Area	Compliance Date		
1)	22-3.3(a)	Exterior			Various locations				
	Violation:	Premises to be kept free from rodent harborage							
Economic Miles	Notes:	Maintain your property lot free of garbage, rubbish, old lumbar, debris or rubble, except for watertight covered containers.							
2)	6-114.3	Interior			Basement				
	Violation:	Maintenance of equipment.							
	Notes:	Maintain the furnace so that it is properly vented and maintained in safe operating condition							
3)	12-79	Exterior Various locations							
	Violation:	Junk Vehicles							
	Notes:	Remove old discarded, worn out or junked motor vehicles, or parts thereof, on your property.							
4)	6-108.1	Exterior							
	Violation:	Foundations cellars, exterior walls, roofs							
	Notes:	Maintain the exterior wall, and roof so they are substantially weather-tight, watertight, and vermin proof, and in good repair. Insulation shall be installed and maintained so as not to present a health or safety hazard to occupants.							
5)	100.7	Exterior BackYard							
	Violation:	Malfunctioning System							
	Notes:	When a malfunctioning system is discovered, the system shall be corrected or its use discontinued. The Plumbing Inspector will meet with the Landlord to re-inspect the septic system for code compliance.							
6)	6-109.2	Interior	Interior Bedroom						
04444004444	Violation:	Maintenance of shared areas.							
	Notes:	Every occupant of a dwelling unit shall maintain in a clean and sanitary manner that part of the dwelling, and dwelling premises which he or she occupies and controls. This shall include removing the broken glass, rubbish, and other non-food wastes, in the rear bedroom.							
7)	6-113.5	Interior							
	Violation:	Maintenance of lighting fixtures							
	Notes:	All electrical fixtures installed shall be maintained in good and safe working conditions and shall be installed in accordance with the electrical code of the city. This shall include replacing the electrical box cover in the basement.							

Comments: