

Record of Completion

Presented To

Bathfitters

351 Riverside Industrial Parkway
Portland ME 04101
USA

This site has been inspected and tested in compliance with applicable standards.

Completed

Monday, June 10, 2019

Test Session: 06/10/19

ACCEPTED BY

Bathfitters
351 Riverside Industrial Parkway
Portland ME 04101
USA

TESTED BY

Norris Inc.
Norris Inc
2257 Broadway
South Portland ME 4106
USA

Inspection Location and Organizations

Building Information

PROPERTY	Bathfitters	CONTACT
ADDRESS	351 Riverside Industrial Parkway	PHONE
CITY/STATE/ZIP	Portland, ME 04101	MOBILE
COUNTRY	USA	EMAIL

Installer Information

NAME	Norris Inc
ADDRESS	2257 Broadway South Portland ME 4106
PHONE	(207) 883-3473
EMAIL	NICentralOperations@norrisc.com

Service Company Information

NAME	Norris Inc
ADDRESS	2257 Broadway South Portland ME 4106
PHONE	(207) 883-3473
EMAIL	NICentralOperations@norrisc.com

Testing Company Information

NAME	Norris Inc
ADDRESS	2257 Broadway South Portland ME 4106
PHONE	(207) 883-3473
EMAIL	NICentralOperations@norrisc.com
CONTRACT DATE	

Secondary Power

TYPE	Battery - Sealed Lead-Acid	DESCRIPTION	AES Main Entry
NOMINAL VOLTAGE		LOAD VOLTAGE	
AMP HOURS		STANDBY HOURS	
ALARM MINUTES		CHARGER VOLTAGE	
BATTERY LOCATION			

Description of Service

This is an existing system.

Permit #

NFPA72 Edition:

Number of devices participating in Alarm Verification: 0

Initiating Device Summary

EQUIPMENT TYPE	TOTAL
Initiating Device	25
Alarm Notification Appliance	14
Supervising Station Transmitting Equipment	1
Power Supplies	1
Fire Control Panel	2
Combination System	1

Notification Device Summary

Norris Inc

EQUIPMENT TYPE	TOTAL
Initiating Device	25
Alarm Notification Appliance	14
Supervising Station Transmitting Equipment	1
Power Supplies	1
Fire Control Panel	2
Combination System	1

Device Summary

EQUIPMENT TYPE	TOTAL
Initiating Device	25
Alarm Notification Appliance	14
Supervising Station Transmitting Equipment	1
Power Supplies	1
Fire Control Panel	2
Combination System	1

Certification Information

Certification

The equipment specified herein was inspected and tested according to the NFPA 72 standard for fire alarm and signaling systems, with the inspection completed on Monday, June 10, 2019

INSTALLED BY

6/11/2019

Norris Inc.

Installer

TESTED BY



6/11/2019

Norris Inc.

Technician

ACCEPTED BY

6/11/2019

Building Representative

ACCEPTED BY

6/11/2019

AHJ

Testing Details

Fire Control Panel

Passed

EQUIPMENT TYPE	ADDRESS	DESCRIPTION	METHOD	DATE/TIME
Fire Panel Batteries		Main Entry NFW 100X	Manual	6/10/2019 3:46 PM
Acceptable Battery Voltage	Passed	Manufacturer	Sigmatas Tek	
Acceptable Battery Amp Hours	Passed	Visual Inspection		
Acceptable Charger Voltage	Passed	Functional Inspection		
Fire Alarm Panel		Main Entry NFW 100X	Manual	6/10/2019 3:46 PM
		Visual Inspection		
		Functional Inspection		
		Alarm Signal	0 sec	
		Trouble Signal	0 sec	
		Supervisory Signal	0 sec	
		Ground Fault	False	
		Disconnect Switches	False	
		Alarm Verification Timer (s)	30 seconds	

Power Supplies

Passed

EQUIPMENT TYPE	ADDRESS	DESCRIPTION	METHOD	DATE/TIME
Battery - Sealed Lead-acid		AES Main Entry	Manual	6/10/2019 3:46 PM
		Visual Inspection		
		Functional Inspection		

Initiating Device

Passed

EQUIPMENT TYPE	ADDRESS	DESCRIPTION	METHOD	DATE/TIME
Manual Pull Station	L1M1	Main Entry	Manual	6/10/2019 3:35 PM
		Visual Inspection		
		Functional Inspection		
		Alarm Verification Participation	False	
Manual Pull Station	L1M2	Rear Exit	Manual	6/10/2019 3:35 PM
		Visual Inspection		
		Functional Inspection		
		Alarm Verification Participation	False	
Manual Pull Station	L1M3	Warehouse Exit	Manual	6/10/2019 3:35 PM
		Visual Inspection		
		Functional Inspection		
		Alarm Verification Participation	False	
Smoke Detector - General	L1D12	Showroom	Manual	6/10/2019 3:35 PM
		Visual Inspection		
		Functional Inspection		
Smoke Detector - General	L1D5	Conference Hall	Manual	6/10/2019 3:35 PM
		Visual Inspection		

EQUIPMENT TYPE	ADDRESS	DESCRIPTION	METHOD	DATE/TIME
		Functional Inspection		
		Drift Compensation	0	
		Alarm Verification Participation	False	
Smoke Detector - General	L1D6	Conference Room	Manual	6/10/2019 3:35 PM
		Visual Inspection		
		Functional Inspection		
		Drift Compensation	0	
		Alarm Verification Participation	False	
Smoke Detector - General	L1D7	Reception	Manual	6/10/2019 3:35 PM
		Visual Inspection		
		Functional Inspection		
		Drift Compensation	0	
		Alarm Verification Participation	False	
Smoke Detector - General	L1D13	Electrical Room	Manual	6/10/2019 3:35 PM
		Visual Inspection		
		Functional Inspection		
		Drift Compensation	0	
		Alarm Verification Participation	False	
Heat Detector - Single or Multi Station	L1D2	Secretary office	Manual	6/10/2019 3:35 PM
		Visual Inspection		
		Functional Inspection		
		Drift Compensation	0	
		Manufacture Date	12/31/2011 8:00 PM	
		Alarm Verification Participation	False	
Heat Detector - Single or Multi Station	L1D1	Manager's office	Manual	6/10/2019 3:36 PM
		Visual Inspection		
		Functional Inspection		
		Drift Compensation	0	
		Manufacture Date	12/31/2011 8:00 PM	
		Alarm Verification Participation	False	
Heat Detector - Single or Multi Station	L1D3	Showroom Restroom	Manual	6/10/2019 3:36 PM
		Visual Inspection		
		Functional Inspection		
		Drift Compensation	0	
		Manufacture Date	12/31/2011 8:00 PM	
		Alarm Verification Participation	False	
Heat Detector - Single or Multi Station	L1D4	Conference Restroom	Manual	6/10/2019 3:36 PM
		Visual Inspection		
		Functional Inspection		
		Drift Compensation	0	
		Manufacture Date	12/31/2011 8:00 PM	
		Alarm Verification Participation	False	
Heat Detector - Single or Multi Station	L1D8	Rear Office	Manual	6/10/2019 3:36 PM
		Visual Inspection		
		Functional Inspection		
Heat Detector - Single or Multi Station	L1D22	Rear Exit	Manual	6/10/2019 3:36 PM
		Visual Inspection		
		Functional Inspection		
		Drift Compensation	0	
		Manufacture Date	12/31/2011 8:00 PM	
		Alarm Verification Participation	False	
Heat Detector - Single or Multi Station	L1D21	Warehouse Northwest	Manual	6/10/2019 3:36 PM

EQUIPMENT TYPE	ADDRESS	DESCRIPTION	METHOD	DATE/TIME
		Visual Inspection		
		Functional Inspection		
		Drift Compensation	0	
		Manufacture Date	12/31/2011 8:00 PM	
		Alarm Verification Participation	False	
Heat Detector - Single or Multi Station	L1D18	Warehouse Northeast	Manual	6/10/2019 3:36 PM
		Visual Inspection		
		Functional Inspection		
		Drift Compensation	0	
		Manufacture Date	12/31/2011 8:00 PM	
		Alarm Verification Participation	False	
Heat Detector - Single or Multi Station	L1D17	Warehouse Northeast	Manual	6/10/2019 3:36 PM
		Visual Inspection		
		Functional Inspection		
		Drift Compensation	0	
		Manufacture Date	12/31/2011 8:00 PM	
		Alarm Verification Participation	False	
Heat Detector - Single or Multi Station	L1D16	Warehouse Receiving	Manual	6/10/2019 3:36 PM
		Visual Inspection		
		Functional Inspection		
		Drift Compensation	0	
		Manufacture Date	12/31/2011 8:00 PM	
		Alarm Verification Participation	False	
Heat Detector - Single or Multi Station	L1D15	Warehouse Receiving	Manual	6/10/2019 3:36 PM
		Visual Inspection		
		Functional Inspection		
		Drift Compensation	0	
		Manufacture Date	12/31/2011 8:00 PM	
		Alarm Verification Participation	False	
Heat Detector - Single or Multi Station	L1D11	Warehouse Bathroom	Manual	6/10/2019 3:36 PM
		Visual Inspection		
		Functional Inspection		
		Drift Compensation	0	
		Manufacture Date	12/31/2011 8:00 PM	
		Alarm Verification Participation	False	
Heat Detector - Single or Multi Station	L1D19	Warehouse Northeast	Manual	6/10/2019 3:36 PM
		Visual Inspection		
		Functional Inspection		
		Drift Compensation	0	
		Manufacture Date	12/31/2011 8:00 PM	
		Alarm Verification Participation	False	
Smoke Detector - General	L1D10	File Storage	Manual	6/10/2019 3:39 PM
		Visual Inspection		
		Functional Inspection		
		Drift Compensation	0	
		Alarm Verification Participation	False	
Heat Detector - Single or Multi Station	L1D9	Break Room	Manual	6/10/2019 3:40 PM
		Visual Inspection		
		Functional Inspection		
Heat Detector - Single or Multi Station	L1D20	Warehouse Northeast	Manual	6/10/2019 3:40 PM
		Visual Inspection		
		Functional Inspection		

EQUIPMENT TYPE	ADDRESS	DESCRIPTION	METHOD	DATE/TIME
		Drift Compensation	0	
		Manufacture Date	12/31/2011 8:00 PM	
		Alarm Verification Participation	False	
Smoke Detector - General	L1D14	Warehouse Closet	Manual	6/11/2019 11:32 AM
	Comment:	no access		
		Visual Inspection		
		Functional Inspection		
		Drift Compensation	0	
		Alarm Verification Participation	False	

Alarm Notification Appliance

Passed

EQUIPMENT TYPE	ADDRESS	DESCRIPTION	METHOD	DATE/TIME
Visible		BATHROOM SHOW ROOM AREA	Manual	6/10/2019 4:05 PM
		Manufacturer	System Sensor	
		Visual Inspection		
		Functional Inspection		
		Candela Rating	0	
Audible And Visible		Main Entry	Manual	6/10/2019 4:05 PM
		Manufacturer	System Sensor	
		Visual Inspection		
		Functional Inspection		
		Candela Rating	0	
		Ambient Sound Pressure	0	
		Active Sound Pressure	0	
Audible And Visible		Back of Showroom	Manual	6/10/2019 4:05 PM
		Manufacturer	System Sensor	
		Visual Inspection		
		Functional Inspection		
		Candela Rating	0	
		Ambient Sound Pressure	0	
		Active Sound Pressure	0	
Visible		Breakroom	Manual	6/10/2019 4:05 PM
		Manufacturer	System Sensor	
		Visual Inspection		
		Functional Inspection		
		Candela Rating	0	
Visible		Kitchen	Manual	6/10/2019 4:05 PM
		Manufacturer	System Sensor	
		Visual Inspection		
		Functional Inspection		
		Candela Rating	0	
Visible		Shower Room	Manual	6/10/2019 4:05 PM
		Manufacturer	System Sensor	
		Visual Inspection		
		Functional Inspection		
		Candela Rating	0	
Audible And Visible		Outside Shower Room	Manual	6/10/2019 4:05 PM
		Manufacturer	System Sensor	
		Visual Inspection		

EQUIPMENT TYPE	ADDRESS	DESCRIPTION	METHOD	DATE/TIME
		Functional Inspection		
		Candela Rating	0	
		Ambient Sound Pressure	0	
		Active Sound Pressure	0	
Visible		Conference Room	Manual	6/10/2019 4:05 PM
		Visual Inspection		
		Functional Inspection		
		Candela Rating	0	
Audible And Visible		Warehouse	Manual	6/10/2019 4:05 PM
		Visual Inspection		
		Functional Inspection		
		Candela Rating	0	
		Ambient Sound Pressure	0	
		Active Sound Pressure	0	
Audible And Visible		Warehouse	Manual	6/10/2019 4:05 PM
		Visual Inspection		
		Functional Inspection		
		Candela Rating	0	
		Ambient Sound Pressure	0	
		Active Sound Pressure	0	
Audible And Visible		Warehouse	Manual	6/10/2019 4:05 PM
		Visual Inspection		
		Functional Inspection		
		Candela Rating	0	
		Ambient Sound Pressure	0	
		Active Sound Pressure	0	
Audible And Visible		Warehouse	Manual	6/10/2019 4:05 PM
		Visual Inspection		
		Functional Inspection		
		Candela Rating	0	
		Ambient Sound Pressure	0	
		Active Sound Pressure	0	
Visible		Warehouse Bathroom	Manual	6/10/2019 4:05 PM
		Visual Inspection		
		Functional Inspection		
		Candela Rating	0	
Audible And Visible		Warehouse	Manual	6/10/2019 4:05 PM
		Visual Inspection		
		Functional Inspection		
		Candela Rating	0	
		Ambient Sound Pressure	0	
		Active Sound Pressure	0	

Supervising Station Transmitting Equipment

Passed

EQUIPMENT TYPE	ADDRESS	DESCRIPTION	METHOD	DATE/TIME
Radio Alarm Transmitter		AES Main Entry	Manual	6/10/2019 3:46 PM
		Visual Inspection		
		Functional Inspection		
		Alarm Signal	0 sec	

EQUIPMENT TYPE	ADDRESS	DESCRIPTION	METHOD	DATE/TIME
		Alarm Restore	0 sec	
		Trouble Signal	0 sec	
		Trouble Restore	0 sec	
		Supervisory Signal	0 sec	
		Supervisory Restore	0 sec	

Combination System

Passed

EQUIPMENT TYPE	ADDRESS	DESCRIPTION	METHOD	DATE/TIME
CO Detector	L1M4	Reception CO	Manual	6/10/2019 3:37 PM
		Visual Inspection		
		Functional Inspection		

Device/Equipment Details

Fire Control Panel

ADDRESS	DESCRIPTION	Manufacturer	Model	SERIAL	INSTALL DATE
Fire Alarm Panel					
	Main Entry NFW 100X				6/10/2019
Fire Panel Batteries					
	Main Entry NFW 100X	Sigmatas Tek			6/10/2019

Power Supplies

ADDRESS	DESCRIPTION	Manufacturer	Model	SERIAL	INSTALL DATE
Battery - Sealed Lead-acid					
	AES Main Entry				6/10/2019

Initiating Device

ADDRESS	DESCRIPTION	Manufacturer	Model	SERIAL	INSTALL DATE
Heat Detector - Single or Multi Station					
L1D18	Warehouse Northeast				6/10/2019
L1D2	Secretary office				6/10/2019
L1D16	Warehouse Receiving				6/10/2019
L1D3	Showroom Restroom				6/10/2019
L1D20	Warehouse Northeast				6/10/2019
L1D21	Warehouse Northwest				6/10/2019
L1D11	Warehouse Bathroom				6/10/2019
L1D4	Conference Restroom				6/10/2019
L1D19	Warehouse Northeast				6/10/2019
L1D22	Rear Exit				6/10/2019
L1D1	Manager's office				6/10/2019
L1D8	Rear Office				6/10/2019
L1D15	Warehouse Receiving				6/10/2019
L1D17	Warehouse Northeast				6/10/2019
L1D9	Break Room				6/10/2019
Manual Pull Station					
L1M1	Main Entry				6/10/2019
L1M3	Warehouse Exit				6/10/2019
L1M2	Rear Exit				6/10/2019
Smoke Detector - General					
L1D14	Warehouse Closet				6/10/2019
L1D6	Conference Room				6/10/2019
L1D12	Showroom				6/10/2019
L1D10	File Storage				6/10/2019
L1D13	Electrical Room				6/10/2019
L1D5	Conference Hall				6/10/2019
L1D7	Reception				6/10/2019

Alarm Notification Appliance

ADDRESS	DESCRIPTION	Manufacturer	Model	SERIAL	INSTALL DATE
Audible And Visible					

Norris Inc

ADDRESS	DESCRIPTION	Manufacturer	Model	SERIAL	INSTALL DATE
	Back of Showroom	System Sensor			6/10/2019
	Warehouse				6/10/2019
	Outside Shower Room	System Sensor			6/10/2019
	Warehouse				6/10/2019
	Warehouse				6/10/2019
	Main Entry	System Sensor			6/10/2019
	Warehouse				6/10/2019
	Warehouse				6/10/2019

Visible

	Conference Room				6/10/2019
	Breakroom	System Sensor			6/10/2019
	Shower Room	System Sensor			6/10/2019
	BATHROOM SHOW ROOM AREA	System Sensor			6/10/2019
	Kitchen	System Sensor			6/10/2019
	Warehouse Bathroom				6/10/2019

Supervising Station Transmitting Equipment

ADDRESS	DESCRIPTION	Manufacturer	Model	SERIAL	INSTALL DATE
Radio Alarm Transmitter					
	AES Main Entry				6/10/2019

Combination System

ADDRESS	DESCRIPTION	Manufacturer	Model	SERIAL	INSTALL DATE
CO Detector					
L1M4	Reception CO				6/10/2019

Supplementary Information

Monitoring Information

TYPE	Radio Alarm Transmitter	DESCRIPTION	AES Main Entry
ORGANIZATION NAME		ACCOUNT NUMBER	
ORGANIZATION ADDR.		PHONE LINE 1	
ORGANIZATION PHONE		PHONE LINE 2	
ORGANIZATION EMAIL		ENTITY TO RETRANSMIT ALARMS TO	