47 Pamela Rd

Reviewed for Code Compliance
Inspections Division
Approved with Conditions
Date: 07/21/17

The gas fired furnace and hot water source is in the basement of the building, mounted on the rear wall.

Phil Requia

(207) 607-2586