

COMMENTS

Dec 4, 2009 Received permit today, asked to inspect tower - All work completed - From review of plans all work in place as per plans - Gate around equipment locked - outside visual insp. only, JF

Permit #000233

CBL 415-B-6

Inspection Record

Type	Date
Foundation: _____	_____
Framing: _____	_____
Plumbing: _____	_____
Final: _____	_____
Other: _____	_____