CITY OF PORTLAND FIRE PREVENTION BUREAU

380 Congress Street, Portland, Maine 04101 fireprevention@portlandmaine.gov (207) 874-8400

NOTICE OF VIOLATION AND ORDER TO CORRECT

August 18, 2017

Responsible Party 1:				
J & H PROPERTIES LLC				
340 PRESUMPSCOT ST				
PORTLAND, ME 04103				
Location	CBL	Inspection Date		
Location 340 PRESUMPSCOT ST	CBL 422 B058001	Inspection Date 8/3/2017		
		=		

The City of Portland Fire Department inspected this property, and found the fire and life safety code violations listed below, which you are hereby ordered to correct. You must propose a date of completion to remedy each violation, a final date of completion, and a date of re-inspection.

You must send this form to the Fire Prevention Bureau no later than 9/15/2017.

Your failure to submit a plan of action by the date provided, or to correct any violation within the applicable time frame, may result in legal action against you, the imposition of civil penalties, and the pursuit of other legal remedies.

Violation	Proposed Date of Completion
NFPA 101-7.9.3 EMERGENCY LIGHTS REQUIRE MAINTENANCE; 7.9.3 Periodic Testing of Emergency Equipment 7.9.3.1 Required emergency lighting systems shall be tested in accordance with one of the three options offered by 7.9.3.1.1, 7.9.3.1.2, or 7.9.3.1.3. 7.9.3.1.1 Testing of required emergency lighting systems shall be permitted to be conducted as follows: (1) Functional testing shall be conducted monthly with a minimum of 3 weeks and a maximum of 5 weeks between tests, for not less than 30 seconds, except as otherwise permitted by 7.9.3.1.1(2). (2) The test interval shall be permitted to be extended beyond 30 days with the approval of the authority having jurisdiction. (3) Functional testing shall be conducted annually for a minimum 1-1/2 hours if the emergency lighting system is battery powered. (4) The emergency lighting equipment shall be fully operational for the duration of the test required by 7.9.3.1.1(1) and (3). (5) Written records of visual inspections and tests shall be kept by the owner for inspection by the authority having jurisdiction. Front lobby and rear door near loading dock emergency lights failed. LIGHTS REPAIRED AND FUNCTIONAL	//
NFPA 1 EXCESSIVE/DISORDERLY STORAGE; Reference NFPA 1 for excessive fuel-load. Boxes closer than 36" around furnace on second floor over look area. PHOTOS PROVIDED OF THE CLEARED AREA AND BOTH TAPE AND SIGNAGE IN PLACE RECEIVED ON 8/16/2017.	//

Violation		Proposed Date of Completion
issued by the AHJ and shall bear the designated representative. In addit activities for which the permit is issess to be conducted (3) Name and a	INSPECTION STICKER REQUIRED; Permits shall be ne name and signature of the AHJ or that of the AHJ's ion, the permit shall indicate the following: (1) Operation or ued (2) Address or location where the operation or activity ddress of the permittee (4) Permit number and date of e permit (6) Inspection requirements and other permit	//
Inspection tag required. None on t	he panel	
FINAL DATE OF COMPLETED VIOLATION(S)		//
FIRE PREVENTION BUREAU RE	-INSPECTION OF COMPLETED VIOLATION(S)	//
	reject or modify any proposed plan of action, and may related to complete the proposed plan. Please contact N	-
•	listed within the timeframes provided. If I require addi he Fire Prevention Bureau <u>prior to the deadline</u> to requ iscretion to grant or deny.	1 2
· ·	y responsibility to schedule a reinspection of my proper ly failure to schedule a reinspection shall be deemed an ed.	•
	ement, I understand that I am liable for penalties pursue \$ 1-15 and 10-25, and 30-A M.R.S. \$ 4452 and may be s	• •
Date	Responsible Party	
Date	Responsible Party	
SEEN AND AGREED		
Date	Fire Prevention Bureau	