

## Permitting and Inspections Department Michael A. Russell, MS, Director

November 15, 2017

HILL ADAM C & PO BOX 4242 PORTLAND, ME 04101

CBL: 427 F007001

Located at: 46 ARCADIA ST

Certified Mail 7014 1820 0001 4049 7260

Dear HILL ADAM C &,

An evaluation of the above-referenced property on 11/15/2017 shows that the structure fails to comply with Chapter 6.Article V. of the Code of Ordinances of the City of Portland, The Housing Code. Attached is a list of the violations.

This is a notice of violation pursuant to Section 6-118 of the Code. All referenced violations shall be corrected within 14 days of the date of this notice. To schedule a re-inspection please contact Housing Safety at 207-756-8131 or email housingsafety@portlandmaine.gov within 14 days. Failure to comply will result in this office referring the matter to the City of Portland Corporation Counsel for legal action and possible civil penalties, as provided for in Section 1-15 of the Code.

This constitutes an appealable decision pursuant to Section 6-127 of the Code.

Please feel free to contact me if you wish to discuss the matter or have any questions.

Please be advised that the Portland City Council has amended the Building regulations to include a \$150.00 re-inspection fee. This violation will automatically cause a re-inspection at no charge. If there are any subsequent inspections, however, the \$150.00 fee will be assessed for each inspection. Sincerely,

/s/

Jason Duval

Code Enforcement Officer

## CITY OF PORTLAND HOUSING SAFETY OFFICE

389 Congress Street Portland, Maine 04101

## **Inspection Violations**

Owner/Manager HILL ADAM C &		Inspector Jason Duval	Inspection Date 11/15/2017
46 ARCADIA ST	427 F007001	Failed	Housing Safety Inspection
Code	Int/Ext Floor	Unit No. Area	Compliance Date

1) 207

Violation:

CARBON MONOXIDE ALARMS / LEVEL; Carbon Monoxide Alarms - One and Two-Family Dwellings: Single-station or multiple-station (interconnected) Carbon Monoxide alarms must be powered by the (A) building electrical system, or (B) 10-year non-replaceable battery and shall be positioned correctly on walls or ceilings: (1) on each level of the dwelling unit, and (2) including the basement.

NFPA 720 (2009) 9.5.1, 9.5.3, amended by State Law Title 25, Chapter 317 § 2468

Notes:

CO Alarm required in basement.

2) 210

Violation:

ESCAPE WINDOWS; Escape Windows - One and Two-Family Dwellings: Escape windows shall be a free and clear outside window or door operable from the inside without the use of tools, keys, or special effort. Windows shall be within 20 feet of the finished ground level or accessible by rescue apparatus (if approved), or opening onto an exterior balcony and when below ground level shall be provided with an accessible, free and clear, window well.

NFPA 101 (2009) 24.2.2.3.3

Notes:

Remove boxes and other debris from in front of the window in bedroom upstairs.

Comments:

CO/Smoke needed in basement. Upstairs bedroom needs to be accessible. To schedule a reinspection please contact Housing Safety at 207-756-8131 or email housingsafety@portlandmaine.gov within 14 days.