CITY OF PORTLAND DEPARTMENT OF PLANNING & URBAN DEVELOPMENT

389 Congress Street Portland, Maine 04101

Inspection Violations

| Owner/Manager | | Inspector | Inspection Date | |
|--------------------|-------------|---------------|----------------------|--|
| LAMOUR HAENDEL & | | Jonathan Reed | 1/31/06 | |
| Locatation | CBL | Status | Inspection Type | |
| 635 WASHINGTON AVE | 428 L017001 | | Complaint-Inspection | |

| | Code | Int/Ext | Floor | Unit No. | Area | Compliance Date | |
|----|------------|---|------------|-----------------|---------------|--------------------|--|
| 1) | 6-108.4 | Exterior | | | Rear Entry | 03/02/2006 | |
| | Violation: | Stairways, stairwells, stairs, porches. | | | | | |
| | Notes: | Rear porch-broken safety rail | | | | | |
| 2) | 6-108.4 | Exterior | | | | | |
| | Violation: | Stairways, stairwells, stairs, porches. | | | | | |
| | Notes: | Rear porch-missing balusters | | | | | |
| 3) | 6-108.3 | Interior | | | Basement | | |
| | Violation: | Exterior windows, doors and skylights | | | | | |
| | Notes: | Cellar window-broken glass(THIS IS URGENT AND MUST BE REPAIRED IMMEDIATELY) | | | | | |
| 4) | 6-108.3 | Exterior | 2 | | | | |
| | Violation: | Exterior windows, doors and skylights | | | | | |
| | Notes: | Right window-broken screen | | | | | |
| 5) | 6-109.4 | Exterior | | | BackYard | | |
| · | Violation: | Disposal of rubbish, garbage and waste. | | | | | |
| | Notes: | Entire yard-remove mattress, tires, rugs, metal, plastic, trash and misc. rubble. | | | | | |
| 6) | 6-114.3 | Interior | | | Basement | | |
| | Violation: | Maintenance of equipment. | | | | | |
| | Notes: | boiler is missing extension pipe | | | | | |
| 7) | 6-109.4 | Interior | | | Basement | | |
| | Violation: | Disposal of rubbish, garbage and waste. | | | | | |
| | Notes: | Remove clothes pile | | | | | |
| 8) | 6-109.4 | Interior | | | Kitchen | | |
| , | Violation: | Disposal of rubbish, garbage and waste. | | | | | |
| | Notes: | repair ceiling damage in kitchen | | | | | |
| 9) | 6-109.4 | Interior | | | Attic | | |
| | Violation: | Disposal of rubbish, garbage and waste. | | | | | |
| | Notes: | Attic is full of bedding, extension cords, ol cleaned up immediately. | d space he | ater, trash, et | c This area n | nust be completely | |

Comments: