

Code Int/Ext
 Status/Date Notes: Unit No. Floor Area Compliant/Compliance Date

ScheduleID:	27192	ViolationID:	41846	428 L017001				
12-79	Exterior			BackYard	<input checked="" type="checkbox"/>	04/08/2005	Violation Date	
Open	Green 1970's Chevy Camaro. No plates on vehicle. Blue VW sedan with no plates.						04/08/2005	Violation Date
6-108.4	Exterior			Rear Entry	<input type="checkbox"/>	03/02/2006	Violation Date	
Open	Rear porch-broken safety rail						01/31/2006	Violation Date
6-108.4	Exterior				<input type="checkbox"/>		Violation Date	
Open	Rear porch-missing balusters						01/31/2006	Violation Date
6-108.3	Interior			Basement	<input type="checkbox"/>		Violation Date	
Open	Cellar window-broken glass (THIS IS URGENT AND MUST BE REPAIRED IMMEDIATELY)						01/31/2006	Violation Date
6-108.3	Exterior		2		<input type="checkbox"/>		Violation Date	
Open	Right window-broken screen						01/31/2006	Violation Date
6-109.4	Exterior			BackYard	<input type="checkbox"/>		Violation Date	
Open	Entire yard-remove mattress, tires, rugs, metal, plastic, trash and misc. rubble.						01/31/2006	Violation Date
6-114.3	Interior			Basement	<input type="checkbox"/>		Violation Date	
Open	boiler is missing extension pipe						01/31/2006	Violation Date
6-109.4	Interior			Basement	<input type="checkbox"/>		Violation Date	
Open	Remove clothes pile						01/31/2006	Violation Date
6-109.4	Interior			Kitchen	<input type="checkbox"/>		Violation Date	
Open	repair ceiling damage in kitchen						01/31/2006	Violation Date
6-109.4	Interior			Attic	<input type="checkbox"/>		Violation Date	
Open	Attic is full of bedding, extension cords, old space heater, trash, etc. . This area must be completely cleaned up immediately.						01/31/2006	Violation Date

635 WASHINGTON Ave