

17 Pembroke Street

428-B-7

September 28, 1977 /

Ms. Patricia Labbe
19 Pembroke Street
Portland, Maine 04103

Dear Ms. Labbe:

Re: 19 Pembroke Street - 428-B-7
NCP-East Deering
Neighborhood Conservation Program

The Housing Inspections Division of the Department of Neighborhood Conservation has recently completed an exterior inspection of your property in conjunction with the above referred program.

Congratulations are extended to you for the general condition of your property which was found to meet the standards established by the City's Housing Code.

Good maintenance is the best way to protect the value of your property and neighborhood.

Please feel free to call on us if we can be of assistance to you.

Sincerely yours,

Josep' E. Gray, Jr. Director
Neighborhood Conservation

By _____
Lyle D. Noyes
Chief of Housing Inspections

Inspector

Marland Wing
M. Wing

Housing Inspection Division

1) Insp. Name MARLAND WING

OK 1st EXT. ONLY

[illegible]