CITY OF PORTLAND FIRE PREVENTION BUREAU

380 Congress Street, Portland, Maine 04101 fireprevention@portlandmaine.gov (207) 874-8400

NOTICE OF VIOLATION AND ORDER TO CORRECT

September 20, 2017

Responsible Party 1:				
ROCKPROP LLC				
PO BOX 184				
EAST BOOTHBAY, ME 04544				
· ·				
Location	CBL	Inspection Date		
Location 14 VERANDA ST	CBL 429 C006001	Inspection Date 9/7/2017		
		=		

The City of Portland Fire Department inspected this property, and found the fire and life safety code violations listed below, which you are hereby ordered to correct. You must propose a date of completion to remedy each violation, a final date of completion, and a date of re-inspection.

You must send this form to the Fire Prevention Bureau no later than 10/15/2017.

Your failure to submit a plan of action by the date provided, or to correct any violation within the applicable time frame, may result in legal action against you, the imposition of civil penalties, and the pursuit of other legal remedies.

Violation	Proposed Date of Completion
NFPA 101-7.9 EMERGENCY LIGHTING	
All emergency lights do not work.	
NFPA 101- 7.10.9.1 AND 7.10.9.2 EXIT SIGNS NEED MAINTENANCE; Exit signs shall be visually inspected for operation of the illumination sources at intervals not to exceed 30 days or shall be periodically monitored in accordance with 7.9.3.1.3 (7.10.9.1). Exit signs connected to, or provided with, a battery-operated emergency illumination source, where required 7.10.4, shall be tested and maintained in accordance with 7.9.3 (7.10.9.2). Exit signs do not illuminate when tested.	
NFPA 10- 7.1.1 FIRE EXTINGUISHERS NEED ANNUAL SERVICE; The owner or designated agent or occupant of a property in which fire extinguishers are located shall be responsible for inspection, maintenance, and recharging. Extinguisher under bar needs to be inspected.	
NFPA 10- 7.2.2 FIRE EXTINGUISHER NOT ACCESSIBLE; Periodic inspection or electronic monitoring of fire extinguishers shall include a check of at least the following items: (1) Location in designated place (2) No obstruction to access or visibility (3) Pressure gauge reading or indicator in the operable range or position (4) Fullness determined by weighing hefting for self-expelling-type extinguishers, cartridge-operated extinguishers, and pump tanks (5) Condition of tires, wheels, carriage, hose, and nozzle for wheeled extinguishers (6) Indicator for nonrechargeable extinguishers using push-to-test pressure indicators Fire extinguisher on front wall of kitchen obstructed.	

Violation		Proposed Date of Completion
protection for personnel for with 590.6 (A) and (B). This supply temporary power to maintenance, repair, or den	EXT. CORD USED FOR PERMENANT WIRING; Ground-fault all TEMPORARY wiring installations shall be provided to comply section shall apply only to temporary wiring installations used to equipment used by personnel during construction, remodeling, nolition of buildings, structures, equipment or similar activities. on cords for permanent wiring in basement.	
FINAL DATE OF COMPLE	TED VIOLATION(S)	//
FIRE PREVENTION BURE	EAU RE-INSPECTION OF COMPLETED VIOLATION(S)	//
	right to reject or modify any proposed plan of action, and may chnical capacity to complete the proposed plan. Please contac	-
I agree to remedy the viol understand that I must co	lations listed within the timeframes provided. If I require add intact the Fire Prevention Bureau <u>prior to the deadline</u> to requ eau's discretion to grant or deny.	- ·
•	it is my responsibility to schedule a reinspection of my prope so. My failure to schedule a reinspection shall be deemed ar remedied.	•
2 2	is agreement, I understand that I am liable for penalties pursunces §§ 1-15 and 10-25, and 30-A M.R.S. § 4452 and may be	• •
Date	Responsible Party	
Date	Responsible Party	
SEEN AND AGREED		
Date	Fire Prevention Bureau	