## CITY OF PORTLAND FIRE PREVENTION BUREAU

380 Congress Street, Portland, Maine 04101 fireprevention@portlandmaine.gov (207) 874-8400

## NOTICE OF VIOLATION AND ORDER TO CORRECT

June 6, 2017

Responsible Party 1:				
EAST DEERING PROPERTIES LLC				
PO BOX 184				
EAST BOOTHBAY, ME 04544				
Location	CBL	<b>Inspection Date</b>		
Location 18 VERANDA ST	<b>CBL</b> 429 C007001	Inspection Date 5/18/2017		

The City of Portland Fire Department inspected this property, and found the fire and life safety code violations listed below, which you are hereby ordered to correct. You must propose a date of completion to remedy each violation, a final date of completion, and a date of re-inspection.

## You must send this form to the Fire Prevention Bureau no later than 6/30/2017.

Your failure to submit a plan of action by the date provided, or to correct any violation within the applicable time frame, may result in legal action against you, the imposition of civil penalties, and the pursuit of other legal remedies.

Violation	Proposed Date of Completion
NFPA 70- ARTICLE 422 DEFECTIVE ELECTRICAL APPLIANCE; This article covers electrical appliances used in any occupancy. The requirements of Article 430 shall apply to the installation of motor-operated appliances, and the requirements of Article 440 shall apply to the installation of appliances containing a hermetic refrigerant motor-compressor(s), except as specifically amended in this article.  Freezer cord in center of shop needs repair, outer sheath pulled from plug.	
NFPA 70- ARTICLE 422.16 DEFECTIVE APPLIANCE CORD; Flexible cord shall be permitted (1) for the connection of appliances to facilitate their frequent interchange or to prevent the transmission of noise or vibration or (2) to facilitate the removal or disconenction of appliances that are fastened in place, where the fastening means and mechanical connections are specifically designed to permit ready removal for maintenance or repair and the appliance is intended or identified for flexible cord connection.  Plug on freezer in the rear of shop has bent prongs and possibly a broken ground prong.	
NFPA 70- ARTICLE 590.6 EXT. CORD USED FOR PERMENANT WIRING; Ground-fault protection for personnel for all TEMPORARY wiring installations shall be provided to comply with 590.6 (A) and (B). This section shall apply only to temporary wiring installations used to supply temporary power to equipment used by personnel during construction, remodeling, maintenance, repair, or demolition of buildings, structures, equipment or similar activities. Power strip used as permanent wiring in front corner to right of serving window.	
NFPA 101- 9.1.2 IMPROPER WIRING, NOT TO CODE; Electrical wiring and equipment shall be in accordance with NFPA 70, unless such installations are approved existing installations, which shall be permitted to be continued in service.  Floor outlets do not appear to be GFCI Protected.	

Violation		Proposed Date of Completion
FINAL DATE OF COMPLETED	VIOLATION(S)	//
FIRE PREVENTION BUREAU	RE-INSPECTION OF COMPLETED VIOLATION(S)	//
•	to reject or modify any proposed plan of action, and may cal capacity to complete the proposed plan. Please contaction	-
•	ns listed within the timeframes provided. If I require add t the Fire Prevention Bureau <u>prior to the deadline</u> to req s discretion to grant or deny.	1 5
	my responsibility to schedule a reinspection of my prope My failure to schedule a reinspection shall be deemed a died.	
	reement, I understand that I am liable for penalties pursi §§ 1-15 and 10-25, and 30-A M.R.S. § 4452 and may be	
Date	Responsible Party	
Date	Responsible Party	
SEEN AND AGREED		
Date	Fire Prevention Bureau	