		Motorwion.	
	clost	Spare bedroom  (business area) total  115.5  56.4	1
Hallway			
Reviewed for Code Compliance Permitting and Inspections Department April 5/24/20 18 ons		Master Bedroom	
		266+	
		VDOWNStairs L Back door	
	Stairs >	Kitchen	1
		20 F+	
Front Door		Living Room  Total SB. Foodage 960 Sq. Ft	
Trunt Door		2084	

12/17/06 100

## THIS IS NOT A BOUNDARY SURVEY

This copyrighted document expires 03-15-09. Reproduction and/or dissemination after this date is unauthorized. COUNTY \_\_Cumberland PAGE \_\_\_204\_\_\_ PAGE \_\_\_\_ PLAN BOOK \_\_\_\_ LOT \_ p/o 1\_ ADDRESS: 7-9 Kensington Street, Portland, Maine Job Number: 309-25-R Inspection Date: 12-15-08 Scale: \_\_\_1" == 30' Gerald K. & Susan J. Campbell Client File #: 80550 Seller: New Stream R E Funding 20, LLC 2 story wood duplex w\concrete foundation shared drive Manage Committee Kensington Street Permitting and Inspections Apr**05/24/201/8**ons APPARENT EASEMENTS AND RIGHTS OF WAY ARE SHOWN. OTHER ENCUMBRANCES, RECORDED OR NOT, MAY EXIST. THIS SKETCH WILL NOT REVEAL ABUTTING I HEREBY CERTIFY TO: Bay Area Title Services; Gerald K. & Susan J. Campbell, and its title insurer.

Monuments found did not conflict with the deed description. DEED CONFLICTS, IF ANY. The dwelling setbacks do not violate town zoning requirements. As delineated on the Federal Emergency Management Agency Community Livingston - Hughes Panel 230051-0007B: Professional Land Surveyors & Foresters

THIS SKETCH IS FOR MORTGAGE PURPOSES ONLY

88 Guinea Road

Kennebunkport - Maine 04046

207-967-4831 fax

207-967-9761 phone

The structure does not fall within the special flood hazard zone.

The land does not fall within the special flood hazard zone.

A wetlands study has not been performed.