

Legalization Inspection Form

Date: 3/23/17

Address: 252 Veranda Street

Legal Use: Two unit

Proposed Use: Three unit

Basement

- Fire Door: Utility room needs a fire door
- Detection: Proper detection is in place
- Sprinkler Head: Sprinkler head needed in the utility room

Notes: Handrails on stairs need to return into the wall and should not have open ends

Unit 1

- Fire Door: Fire door needed (rated, self closing)
- Detection: Proper detection is in place

Notes: _____

Unit 2

- Fire Door: Fire door is needed (rated, self closing)
- Detection: _____

Notes: _____

Unit ____

- Fire Door: _____
- Detection: _____

Notes: _____

Unit ____

- Fire Door: _____
- Detection: _____

Notes: _____

Unit ____

- Fire Door: _____
- Detection: _____

Notes: _____

Unit ____

- Fire Door: _____
- Detection: _____

Notes: _____

Overall

Pass _____ Fail _____ Follow up Required