



CWS ARCHITECTS
ARCHITECTURE | INTERIOR DESIGN
434 CUMBERLAND AVENUE
PORTLAND, MAINE 04101
T: 207.774.4441
F: 207.774.4016
WWW.CWSARCH.COM

DESIGNER
OWNER
PROJECT
DRAWING

NORTHFIELD GREEN HOUSING PARTNERS LP.

NORTHFIELD GREEN

UNIT MATRIX

DRAWING NUMBER
G1.02

SCALE:
DATE: 11/22/2017

ISSUED NOVEMBER 22, 2017

1 = replace x = leave existing or reuse existing

Bldg #	Unit #	Unit Type	Kitchen Range Alt #8	Kitchen Existing Disposal	Replace Refrigerator Alt #8	Bath Replace tub/tile	Bath Shower Fixture	Bath Replace Toilet	Bath Grab bars exist/new	Living Ceiling Fan	Living Remove AC sleeve	Living Replace ACT Clg	Living Comm Strobes	Bedroom Ceiling Fan	Bedroom Remove AC sleeve	Doors 1 entry	Doors 2 storage	Doors 3 linen	Doors 7 closet	Doors 4 bath	Doors 5 bedroom	Doors 6 BR closet	Ceiling and Wall Repairs.
149	60	A1.U3		No	1		P-3	P-1	x				x										
149	61	A1.U1		Yes	1		P-3	P-1	x	no lights													
149	62	A1.U2		No	1		P-3	P-1	x								1						
149	63	A1.U5	1	No	1	P-3A	P-3A	P-1A	1	no lights				no lights									
149	64	A1.U2		No	1		P-3	P-1	x													1	
149	65	A1.U5	1	No	1	P-3A	P-3A	P-1A	1												1		
149	66	A1.U1		Yes	1		P-3	P-1	x	with lights							hrdwre	hrdwre		hrdwre			
149	67	A1.U1	1	Yes			P-3	P-1	x						1								
149	68	A1.U1		No	1		P-3	P-1	x	no lights													
149	69	A1.U1		Yes			P-3	P-1	x	no lights													
149	70	A1.U3	1	No			P-3	P-1	x								1	1				1	
149	71	A1.U2		No			P-3	P-1	x														
149	72	A1.U1		Yes	1		P-3	P-1	x														
149	73	A1.U2		Yes	1		P-3	P-1	x								1			1			Ceiling repairs required at interior wall
149	74	A1.U5		No		P-3A	P-3A	P-1A	1	with lights							1	1		1		1	
149	75	A1.U3		Yes	1		P-3	P-1	x								1					1	ceiling repairs needed at interior wall
149	76	A1.U6		Remove		P-3A	P-3A	P-1A	1								1						Repair ceiling, which is sagging
149	77	A1.U1		Yes	1		P-3	P-1	x														
149	78	A1.U1	1	No	1		P-3	P-1	x		1					1							
149	79	A1.U1		No			P-3	P-1	x											1			
149	80	A1.U1		No	1		P-3	P-1	x	with lights						1	1	1					
149	81	A1.U1	1	No	1		P-3	P-1	x											1			
149	82	A1.U1	1	Yes			P-3	P-1	x	no lights													
149	83	A1.U1		Yes	1		P-3	P-1	x	no lights					1			1				1	Repair cracked wall above storage room door
149	84	A1.U2		Yes	1		P-3	P-1	x	with lights											1		
149	85	A1.U1		Yes			P-3	P-1	x	with lights					1		1					1	
149	86	A1.U2	1	No	1		P-3	P-1	x											1	1		
149	87	A1.U2	1	No			P-3	P-1	x	no lights													
149	88	A1.U2		Yes	1		P-3	P-1	x	no lights			x				1						1
149	89	A1.U1		Yes	1		P-3	P-1	x	no lights													
149	90	A1.U2		No	1		P-3	P-1	x	no lights							1						1
149	91	A1.U2	1	No	1		P-3	P-1	x									1		1			
149	92	A1.U7		No	1		P-3	P-1	x	no lights			x		1		1						
149	93	A1.U2	1	Yes	1		P-3	P-1	x	no lights													1
149	94	A1.U1	1	No	1		P-3	P-1	x	with lights													
149	95	A1.U1	1	No	1		P-3	P-1	x	with lights					1								1
149	96	A1.U1		Yes			P-3	P-1	x	no lights					1								
149	97	A1.U1		Yes	1		P-3	P-1	x	no lights			x										
149	98	A1.U1		Yes	1		P-3	P-1	x						1		1	1					
149	99	A1.U1		Yes	1		P-3	P-1	x	with lights							1	1					
149	100	A1.U7	1	No	1		P-3	P-1	x	no lights			1		1		1					1	
149	101	A1.U1		No	1		P-3	P-1	x	no lights					1								
149	102	A1.U1		Yes	1		P-3	P-1	x	no lights													
149	103	A1.U1		No	1		P-3	P-1	x				x		1								
149	104	A1.U1		Yes	1		P-3	P-1	x	no lights												1	
149	105	A1.U2		No	1		P-3	P-1	x	no lights												1	
149	106	A1.U1		No			P-3	P-1	x	with lights					1								
149	107	A1.U2		No	1		P-3	P-1	x														
149	108	A1.U1		Yes	1		P-3	P-1	x	no lights													
149	109	A1.U1		No	1		P-3	P-1	x											1			
149	110	A1.U1		No	1		P-3	P-1	x	no lights													
149	111	A1.U1		No			P-3	P-1	x						1								1
149	112	A1.U1		Yes	1		P-3	P-1	x	no lights					1								
149	113	A1.U2		No	1		P-3	P-1	x						1								
149	114	A1.U2	1	No	1		P-3	P-1	x	with lights					1		1						
149	115	A1.U2		Yes	1		P-3	P-1	x	no lights					1								
149	116	A1.U2		Yes	1		P-3	P-1	x	no lights					1								
149	117	A1.U1		No	1		P-3	P-1	x	no lights					1								
149	118	A1.U1		Yes	1		P-3	P-1	x	no lights												1	
149	119	A1.U1		Yes			P-3	P-1	x														
149	120	A1.U2		No	1		P-3	P-1	x														
149	121	A1.U1		Yes	1		P-3	P-1	x	It fixt only					1								
149	122	A1.U2		Yes	1		P-3	P-1	x	no lights													ceiling repairs above bathroom door
149	123	A1.U1		No	1		P-3	P-1	x						1								Wall and ceiling repairs at bedroom door and bathroom ceiling
149	124	A1.U2		Yes	1		P-3	P-1	x	no lights													
149	125	A1.U1	1	No	1		P-3	P-1	x	no lights													
149	126	A1.U2		Yes	1		P-3	P-1	x						1		1	1					
149	127	A1.U2		No			P-3	P-1	x														Ceiling repairs that are cracked from movement.
149	128	A1.U1	1	Yes	1		P-3	P-1	x	no lights				no lights	1								
149	129	A1.U2	1	No	1		P-3	P-1	x	no lights			x		1								

Notes: All unit kitchen cabinets are to be replaced. Refer to unit plans and elevations for more information.
Refer to unit plans, reflected ceiling plans, and electrical plans for typical light fixtures scheduled to be replaced.
Disposal information is provided for planning purposes. Coordinate installation while resetting kitchen sinks.
Remove disposals and associated control switch (provide blank plate) as scheduled above.

Grab bars. Maintain existing grab bar locations (x) as is or update grab bars according to accessible unit plans (1).
Ceiling Fans provided for information. Maintain existing ceiling fan equipment and locations.
Communication strobes. Maintain existing strobes (x). Update/install strobe devices features for units with Communications Features (1). Refer to unit plans and electrical unit plans.
Ceiling and Wall Repairs. Repair cracks and holes in ceilings and walls where identified (typically off corners of door heads). Paint entire wall area adjacent to repaired section.

1

2

3

4

5