	:	
		ŧ
		•

## HOUSING INSPECTION REPORT

Location: 72 VERANDA ST Housing Conditions Date: AUGUST 27, 1998 Expiration Date: OCTOBER 02, 1998

<ol> <li>INT - BASEMENT - HOT WATER HEATER</li></ol>	<ol> <li>INT - 2ND FLOOR APT 2 - FRONT &amp; REAR HALLS</li></ol>
Relief valve on hot water tank drain tube missing	Storing and stacking items in hallways
114.30	116.30

3. INT - BASEMENT -Replace temporary laly column with permanent lally 108.10

4. INT - BASEMENT -Install trap on washing machine waste line column 111.40

 INT - BASEMENT - 2ND FLOOR Panel needs blank; for missing breaker 5. INT - BASEMENT OPEN JUNCTON BOX INSTALL COVER PLATE

113.50

7. INT - BASEMENT - 103
Broken floor joist center of basement replace or sister new joist

 EXT-LEFT PORCH REAR Rotted decking and hand railings repair or replace 108.40

9. EXT - FRONT AND FRONT -Broken siding and damaged corner trim repair 108.10

 INT - THROUGHOUT
 No hardwired smoke alarms in the building an electrical permit must be obtained by a licensed electrician, then alarms must be installed to current new construction standards

389 Congress St Portland, Maine 04101 (207) 874-8700 FAX 874-8716 TTY 874-8936