

6/19/03 Setbacks/tubes - setback ok - tubes
2 end tubes ok - hit rack @ 42" in center tubes
will clear as much as possible around sides of rack &
Be sure surface of deck is clean before pour


7/18/03 open risers on stairs must be closed in
return on handrails - no stud @ this time'

DETENTION BASIN PERIMETER

PROPOSED BUILDING
* LOT NUMBER
IRON PIN TO BE SET
5/8" REBAR W/ PLASTIC CAP
CITY OF PORTLAND - STONE POST
RIGHT-OF-WAY MONUMENT

"I HEREBY STATE THAT THIS SURVEY WAS PERFORMED UNDER MY DIRECTION AND TO THE BEST OF MY KNOWLEDGE AND ABILITY CONFORMS TO THE MAINE REGISTRATION FOR LAND SURVEYORS GATE CONDITION III"

PRESIDENT
SAWYER ENGINEERING & SURVEYING



ALTERATIONS TO ORIGINAL APPROVED RECORDS HAVE BEEN APPROVED BY THE CITY OF PORTLAND DEPARTMENT OF PLANNING AND URBAN DEVELOPMENT IN COMPLIANCE WITH SECTION 14-496(3) OF SUBDIVISION ORDINANCE SEE NOTE 12

DIRECTOR OF PLANNING AND URBAN DEVELOPMENT
DATE 2/27/98
RECORDED BK 198 CHART 274

CITY OF PORTLAND
APPROVED SITE PLAN

SUBJECT TO DEPARTMENTAL
8-27-98 CONDITIONS

REVISOR
DATE OF APPROVAL 8-28
REVISOR
P.R.U.D. LOT PLAN
COPLEY WOODS
PORTLAND, MAINE

