

165 Congress Street

13-1-13

Anthony Rumo

MUND NO



35 Form 3811, Jan. 1979

SENDER. Complete items 1, 2, and 3.
Add your address in the "RETURN TO" space on reverse.

1. The following service is requested (check one):

- Show to whom and date delivered..... 6
- Show to whom, date and address of delivery..... 6
- RESTRICTED DELIVERY..... 6
Show to whom and date delivered..... 6
- RESTRICTED DELIVERY..... 6
Show to whom, date, and address of delivery..... 6

(CONSULT POSTMASTER FOR FEES)

2. ARTICLE ADDRESSED TO:

Mr. Anthony Rumo
418 Woodfords Street
Portland, Maine 04103

3. ARTICLE DESCRIPTION:

REGISTERED NO.	CERTIFIED NO.	INSURED NO.
	0925624	

(Always obtain signature of addressee or agent)

I have received the article described above.

SIGNATURE Addressee Authorized agent

4. DATE OF DELIVERY

5. ADDRESS (Complete only if requested)

6. UNABLE TO DELIVER BECAUSE:

POSTMARK
1981
NIP

CLERK'S INITIALS
JL

Re: 165-167 Congress St. - Carroll

RETURN RECEIPT, REGISTERED, INSURED AND CERTIFIED MAIL

CERTIFICATE OF INSPECTION

DATE August 3, 1979

City of Portland
Housing Inspections Division
Department of Neighborhood Conservation
Tel: 775-5451 Ext. 358 - 448

Mr. Anthony Rumo
418 Woodford Street
Portland, Maine 04102

Re: Premises Located at ~~165~~ 167 Congress Street, Portland, Maine ME 13-L-13

Dear Mr. Rumo:

An inspection of the above referred premises was recently completed by Housing Inspector Carroll.

Although the structure does not meet the minimum standards as described in the Housing Code, it has been determined that no major code deficiencies exist at this time.

Items included on the enclosed list should be corrected as part of your normal maintenance procedures in order to avoid extensive repairs in the future and to prolong the useful life of the building.

Thank you for your cooperation and your efforts to help us maintain decent, safe, and sanitary housing for all Portland residents.

Please do not hesitate to call this office if you have any questions regarding this notice.

Sincerely yours,
Joseph E. Gray, Jr., Director
Neighborhood Conservation

Inspector K. Carroll

K. Carroll

By Lyle D. Noyes

Lyle D. Noyes,
Chief of Housing Inspections

dtd

165 - 167 Congress Street, Portland, Maine MN 13 - L - 13

8/3/79

FIRST FLOOR NEAR BATHROOM

1. Cross connection at bathtub.

T/

CITY OF PORTLAND MAINE
DEPARTMENT OF NEIGHBORHOOD CONSERVATION
HOUSING INSPECTIONS DIVISION

NOTICE OF HEARING

sent to 7/20/79

April 23, 1979

OK
COI
BY (P)
DATE 7/24/79

To: Mr. Anthony Lumo
418 Woodford Street
Portland, Maine 04102

Re: Premises located at 165-167 Congress Street, Portland, Maine MN 13-L-13

Dear Mr. Lumo:

Because of your failure to comply with previous NOTICES, you are hereby invited to appear in Room 315, City Hall, 389 Congress Street, Portland, Maine at 9:00 a.m. on May 3, 1979, to show cause why legal action should not be taken against you for violations of the Municipal Codes relating to housing conditions at the above referred premises, as described more fully in the attached copy of the original NOTICE received by you on or about Dec. 20, 1976.

FAILURE TO APPEAR MAY RESULT IN SEQUESTRATION

Please notify this office at once if you have corrected all violations before the above noted hearing date. Telephone 775-5451 Extension 448 - 358.

Joseph E. Gray, Jr., Director
Neighborhood Conservation

By Lyle D. Noyes
Lyle D. Noyes,
Chief of Housing Inspections

Requested by Kenneth W. Carroll
Inspector Kenneth W. Carroll

Enclosure

VW

TK
April 23, 1979 165-167 Congress Street, Portland, Maine MN 13-L-13

Remaining Housing Code Violations to be corrected:

- 72472 }
~~3. SUPERIOR CHIMNEY clean chimney by removing and properly disposing of all soot. 3e~~
~~2. GUTTER TRIM remove loose and peeling paint and make the trim weathertight and watertight by painting or some other suitable means. 3a~~

- 72474 }
FIRST FLOOR FRONT
~~3. KITCHEN CEILING remove loose and peeling paint. 3b~~
~~4. LIVING ROOM WALL determine the reason and remedy the condition causing leakage. 3a~~

- FIRST FLOOR REAR
~~3. BATHROOM TUB - correct the condition at the fixture that causes a cross connection at the bathtub. 6d~~

- 72474 }
SECOND FLOOR
~~6. KITCHEN & LIVING ROOM WINDOWS secure loose glass by reglazing windows. 3c~~
THIRD FLOOR
~~7. KITCHEN & LIVING ROOM WINDOWS replace broken glass. 3c~~
~~3. LIVING ROOM WINDOWS secure loose glass by reglazing points and/or reglazing. 3c~~

NOTICE OF HOUSING CONDITIONS

CITY OF PORTLAND
 DEPARTMENT OF HEALTH & SOCIAL SERVICES
 HOUSING DIVISION
 Telephone 775-5451 - Extension 448
 Mr. Anthony Rumo
 418 Woodford Street
 Portland, Maine 04102

DU 4
 Ch.-Bl.-Lot 13-L-13
 Location 165-167 Congress Street
 Project Joy Worth
 Issued: 12-20-76
 Expired: 2-20-77

Dear Mr. Rumo:

An examination was made of the premises at 165-167 Congress Street, Portland, Maine by Housing Inspector Gendreau. Violations of Municipal Codes relating to housing conditions were found as described in detail below.

In accordance with provisions of the above mentioned Codes, you are requested to correct these defects on or before February 20, 1977. You may contact this office to arrange a satisfactory repair schedule if you are unable to make such repairs within the specified time. We will assume the repairs to be in progress if we do not hear from you within ten days from this date and, on re-inspection within the time set forth above, will anticipate that the premises have been brought into compliance with Code Standards. Please contact this office if you have any questions regarding this Notice.

Your cooperation will help this Department in its goal to maintain all Portland residents in decent, safe and sanitary housing.

Sincerely yours,

David C. Bittenbender, Director
 Health & Social Services

Inspector D. Gendreau
 D. Gendreau

By [Signature]
 Chief of Housing Inspections

EXISTING VIOLATIONS CHAPTER 307 - "MINIMUM STANDARDS FOR HOUSING" - SECTION(S)

1. INTERIOR CHIMNEY - clean chimney by removing and properly disposing of all soot. 3-a
2. First Floor - rear
 BATHROOM - bathtub - Correct the condition at the fixture that causes a cross connection at the tub in the bathroom. 6-d
3. Second Floor
 KITCHEN - LIVING ROOM - windows - secure loose glass by reglazing windows. 3-c
 BATHROOM - HALL - ceiling - remove peeling paint. 3-b
4. Third Floor
 KITCHEN - LIVING ROOM - windows - replace broken glass. 3-c
 LIVING ROOM - windows - secure loose glass by reglazing. 3-c

First Floor - front

At the time of the survey, we were unable to gain access to this apartment. We suggest that if there were any conditions which need correcting in this apartment that you make the repairs while doing the work on the rest of the structure.

WHEN MAKING YOUR REPAIRS, FIRST PRIORITY IS TO BE GIVEN TO ITEMS WITH ASTERISKS, AS THEY CONSTITUTE EXTREME HAZARDS TO THE HEALTH OR SAFETY OF THE OCCUPANTS OF THIS STRUCTURE.

NOTE: ADDITIONAL VIO. NIS ON REAR SIDE

REINSPECTION RECOMMENDATIONS

LOCATION 165-167 Congress
 PROJECT _____
 OWNER ANTHONY RUMO

INSPECTOR GENE REA

NOTICE OF HOUSING CONDITIONS		HEARING NOTICE		FINAL NOTICE	
Issued	Expired	Issued	Expired	Issued	Expired
<u>12/20/76</u>	<u>2/20/78</u>				

A reinspection was made of the above premises and I recommend the following action:

DATE	RECOMMENDATION
<u>7-24-77</u>	<p>MAJOR</p> <p>ALL VIOLATIONS HAVE BEEN CORRECTED ✓ Send "CERTIFICATE OF COMPLIANCE" ✓ Inspection ✓ "POSTING RELEASE" ✓</p>
	SATISFACTORY Rehabilitation in Progress
	Time Extended To: _____
	Time Extended To: _____
	Time Extended To: _____
<u>7-24-77</u>	<p>UNSATISFACTORY Progress <u>May 3 at 9:00</u> Send "HEARING NOTICE" ✓</p>
	"NOTICE TO VACATE" POST Entire _____ POST Dwelling Units _____
	UNSATISFACTORY Progr "LEGAL ACTION" To Be Taken _____

Stamp: **OK**
COI
 BY [Signature]
 DATE 7-24-77
 "FINAL NOTICE"

INSPECTOR'S REMARKS.

4-20-77 2 Re/OT - very little progress - also 130 additional violations noted - HN
5-3-77 2 Heavy load - owner expressed to be very cooperative - 30 day work order
7-21-77 2 Re/OT - All violations corrected except as noted on NOKC.
Send COI with following comment:
FIRST FLOOR REAR DU. BATHTUB -- CROSS CONN. AT FIXTURE

INSTRUCTIONS TO INSPECTOR:

Additional Violations 4-19-79

2 - RM LOPED PAINT OIA TRIM - 3A

1ST FL FR


~~4~~ - 3 RM LOPED PAINT KI Ceil - 3B

~~2~~ - 4 DE LE

KI WALL - 3A

165 CONGRESS STREET

Housing



[The main body of the document contains several lines of text that are extremely faint and illegible due to the quality of the scan. The text appears to be organized into a structured format, possibly a list or a series of entries, but the specific content cannot be discerned.]

DEFECTOR IN STALL
1/27/84 Om
CITY OF PORTLAND



DEPARTMENT OF PLANNING & URBAN DEVELOPMENT
INSPECTION SERVICES DIVISION

January 18, 1984

Mr. Anthony Rumo
418 Woodfords Street
Portland, Maine 04103

Re: 165-167 Congress St. 13-L-13 NDP

Dear Mr. Rumo:

During a recent inspection of the property owned by you at 165-167 Congress Street, it was noted that smoke detectors were missing in the following areas:

"PER THE MAINE STATE STATUTES, "SEC. 1.25 MRSA 2464", WITHIN TEN (10) DAYS OF THE DATE OF THIS NOTICE, A SMOKE ALARM MUST BE INSTALLED IN EACH AREA OF THIS STRUCTURE, AS LISTED BELOW:

First Floor Front Dwelling Unit.

Re-inspection will be made in ten (10) days for compliance. Lack of compliance may result in legal action.

Sincerely yours,
Joseph E. Gray, Jr., Director of
Planning & Urban Development


By Lyle D. Woyes
Lyle D. Woyes
Inspection Services Division

Code Enforcement Officer - Michael Nugent (10)

jmr

165 CONGRESS STREET

Housing





CITY OF PORTLAND

JOSEPH E. GRAY, JR.
DIRECTOR OF PLANNING
AND URBAN DEVELOPMENT

January 30, 1984

#DU: 4

Anthony Rumo
418 Woodfords Station
Portland, Maine 04103

Re: 165-167 Congress St. 13-L-13 ^{MN} ~~NDP~~


The Housing Inspections Division of the Department of Planning and Urban Development has recently completed an overall inspection of the above referred property.


Congratulations are extended to you for the general condition of your property which was found to meet the standards established by the City's Housing Code.

Good maintenance is the best way to protect the value of your property and neighborhood.

Please feel free to call on us if we can be of assistance to you.

Sincerely yours,
Joseph E. Gray, Jr., Director
Planning & Urban Development


Code Enforcement Officer
Michael Nugent (10)

By 
Lyle D. Noyes
Inspections Services Division

jmr

City of Portland

Excellent Building *J.P. 1st*

Check via sheet
STRUCTURE INSPECTION SCHEDULE
ARTICLE 5 HOUSING CODE

Housing Inspection Division

1) Insp. Name MIKE AUGER

2) Insp. Date 1/5/87 3) Insp. Type RS 4) Pres. Code NBP 5) Ass't's: Chstt 13 6) Bl 2 7) Lst 13 8) Census: Int 1011 9) Blk. 1011 10) Insp. 1011 11) Form No. 1011

12) House No. 165.167 13) Sec. H. No. 165.167 14) Surf. 165.167 15) Direct 165.167 16) Street Name CONGRESS ST 17) St. Design. ST 18) Owner or Agent: ANTHONY RUMIO 19) Status ABO 20) Bldg's Ra. 1

21) Address: 418 WOODWARDS ST. Zip Code 04103

22) City and State: PORTLAND, ME. ME 04103

23) D. Units 4 24) Occ. D. U.'s 4 25) Rm. Units 6 26) Occ. R. U.'s 6 27) No. Occupants 3 28) Com' U. 0 29) Bldg. Type DE 30) Stairs 5 31) Const. Mat BR 32) O. B's 0

33) C.H. YES 34) Pho. No 35) Zoned For RES 36) Actual Land Use RES 37) D.D. PO 38) Lbs Ad. Bth. Fac. PO 39) Disp. PO 40) Closing Date

EXTERIOR - Structure		Cd. Viol.	INTERIOR - Structure		Cd. Viol.
Foundation	EX/FO	108-2	Lighting		113
Walls	EX/WA	108-2	Elec. Wiring	EW	108-2
Roof	RO	108-4	Floors	FL	108-2
Porch	PO	108-4	Walls	IN/WA	108-2
Stairs	EX/SR	108-4	Ceilings	CE	108-3
Steps	SP	108-4	Windows	IN/WI	108-3
Doors	DO	108-3	Airshafts	AS	108-1
Windows	EX/WI	108-3	Roof Juffers	ROR	109-5
Eaves	EA	108-1	Sanitation	SAN	108-4
Trim	TR	108-1	Stairways	IN/SRW	108-4
Chimney	EX/CH	108-5	Stair Treads	SRT	111-4
Gutters	GU	108-1	Wastelines	WSL	111-2
Roof Drains	RD	108-1	Supply Lines	SUL	114-1
Bulkhead	BU	108-4	Stacks	ST	114-1
Outbuildings	GR - SH		Flues	FU	114-1
Yard	YA		Vents	VE	114-1
Garbage	GA	109-4	Chimney	IN/CH	114-2
Rubbish	RU	109-4	Heating Equip. Furnace - FU	Space heater - SKH	109-4
Containers	CO	109-4	Dsm. Sanitation Litter - LI	Debris - DE	108-1
Drainage	DR	108-1	Dampness	DMP	113
Infestation	IN-CR-FL	109-5	Lighting	RS/LI	113
Rats	RA	109-5	Elec. Panel	EL/PA	108-2
Other		109-5	Stairs	RS/SR	108-2
Fire Escape	FE	116-2	Foundation	IN/FO	108-2
Dual Egress	DE	116-2	Floor Joists		108-2
Driveways	DW		Carrying Timbers		108-2
Walks	WA		Stairs		110-6
Fences	FN		Bmnt, Dwelling Unit RDU		

Remarks on reverse side

No. SMOKE DETECTOR

ARTICLE 5 HOUSING CODE
Health Department
DWELLING UNIT SCHEDULE

Housing Inspection Division

City of Portland

INSP DATE: 01/10/15
INSP: 20
FORM NO.: 05
NO VIOLATIONS

FLR.#: 1 LOCATION: FR. DU 3 #RMS.: 1 #PEO.: 4 1/2 SLR.RM.: 1

TENANTS NAME: LEYDEN, MONICA
Child Un. 10: 0
Child 1-6: 1
+ Lead Survey - Results: []
Rent Code: []
Furn: []
Hot Water: YES
Dual Egrs.: YES
Ck'ng.: GAS
Heat: OFF
Lav.: PL
Bath: PB
Flush: PL

- KITCHEN**
- () Plaster - L, C, M, - Ceiling/Walls 108-2
 - () Windows - loose, broken glass, glaze 108-3
 - () Sash/Frames - broken, missing, worn 108-3
 - () Floor - loose, worn, Dam., buckled 108-2
 - () Doors - Knob/lk - missing - Panels/Frames dam. 108-3
 - () Counter/Stor. Space Yes ___ No ___ 111-1
 - () Sink - chipped, cracked, leaks 114-1
 - () Range - improper stack, flue, vent - 114-1
 - () Refrigerator Space Yes ___ No ___ 111-3
 - () Plumbing (a) 6(a) Water Supply, Hot ___ Cold ___ 113
 - () Electrical (a) 109
 - () Sanitation (a) 109

- BATHROOM**
- () Plaster - L, C, M - Ceiling/Walls 108-2
 - () Window - loose, broken glass glaze 108-3
 - () Sash/Frames - broken, missing, worn 108-3
 - () Floor - loose, worn, Dam., buckled 108-2
 - () Door - knob/lk - missing - Panels/Frames dam. 108-3
 - () Toilet - Tnk - brkn, loose, leaks, Seat, l'se crkd. 111-1
 - () Lavatory - chipped, crkd, leaks, trap leaks 111-1
 - () Bath tub/Shower - leaks cross connection 111-1
 - () Ventilation Yes ___ No ___ 112
 - () Plumbing (b) 6(a) Water Supply Hot ___ Cold ___ 111-3
 - () Electrical (b) 113
 - () Sanitation (b) 109

- LIVING ROOM**
- () Plaster - L, C, M, - Ceiling/Walls 108-2
 - () Windows - loose, broken, glaze 108-3
 - () Sash/Frames - broken, missing, worn 108-3
 - () Floor - loose, worn, Damaged 108-2
 - () Door - knob/lk - missing - Panels/Frames dam. 108-3
 - () Electrical (c) 113
 - () Sanitation (c) 109

- DINING ROOM**
- () Plaster - L, C, M - Ceiling/Walls 108-2
 - () Windows - loose, broken, glaze 108-3
 - () Sash/Frames - broken, missing, worn 108-3
 - () Floor - loose, worn, damaged 108-2
 - () Doors - Knobs/lk - missing, Panels/Frames dam. 108-3
 - () Electrical (d) 113
 - () Sanitation (d) 109

Bedrooms and/or other rooms

Code	Description	Code

- () Plaster - L, C, M - Ceiling/Walls 108-2
- () Windows - Loose, broken, glaze 108-3
- () Sash/Frames - broken, missing, worn 108-3
- () Floors - loose, worn, damaged 108-2
- () Door - knobs/lk - missing - Panels/Frames dam. 108-3
- () Electrical (e) 113
- () Sanitation (e) 109
- () Clothes Closet Yes ___ No ___

Plumbing: [] Electrical: [] Sanitation - Vermin O R: []

REMARKS:

ARTICLE 5 HOUSING CODE
Health Department
DWELLING UNIT SCHEDULE

Housing Inspection Division

City of Portland

INSP DATE

11/01/81

N. VIOLATIONS

INSP

101

FORM NO.

103

TEHANTS NAME

WADSWORTH, AGNES

FLR.# LOCATION RMG.TP. #RMS. #PEO. #ALL'D SLPRH.

2 0A DU 4 1 6 2

Child Un. 10	Child 1 - 6	+ Lead Survey - Results	Rent	Rent Code	Furn	Hot Water	Dual Egrs.	Ck'ng.	Heat	Lav.	B.th	Flush
						YES	YES	DLK	OFF	PL	DB	DF

KITCHEN

DESCRIPTION	CODE
() Plaster - L, C, M, - Ceiling/Walls	108-2
() Windows - loose, broken glass, glaze	108-3
() Sash/Frames - broken, missing, worn	108-3
() Floor - loose, worn, dam., buckled	108-2
() Doors - Knob/1k - missing - Panels/Frames dam.	108-3
() Lounter/Stor. Space Yes No	-
() Sink - chipped, cracked, leaks	111-1
() Range - improper stack, flue, vent.	114-1
() Refrigerator Space Yes No	-
() Plumbing (a) 6(a) Water Supply Hot Cold	111-3
() Electrical (a)	113
() Sanitation (a)	109

BATHROOM

DESCRIPTION	CODE
() Plaster - L, C, M - Ceiling/Walls	108-2
() Window - loose, broken glass, glaze	108-3
() Sash/Frames - broken, missing, worn	108-3
() Floor - loose, worn, dam., buckled	108-2
() Door - knob/1k - missing - Panels/Frames dam.	108-3
() Toilet - Tnk - brkn, loose, leaks, Seat, l'se crkd.	111-1
() Lavatory - chipped, crkd, leaks, trap leaks	111-1
() Bathtub/Shower - leaks cross connection	111-1
() Ventilation Yes No	112
() Plumbing (b) 6(a) Water Supply Hot Cold	111-3
() Electrical (b)	113
() Sanitation (b)	109

LIVING ROOM

DESCRIPTION	CODE
() Plaster - L, C, M, - Ceiling/Walls	108-2
() Windows - loose, broken, glaze	108-3
() Sash/Frames - broken, missing, worn	108-3
() Floor - loose, worn, damaged	108-2
() Door - knob/1k - missing - Panels/Frames dam.	108-3
() Electrical (c)	113
() Sanitation (c)	109

DINING ROOM

DESCRIPTION	CODE
() Plaster - L, C, M - Ceiling/Walls	108-2
() Windows - loose, broken, glaze	108-3
() Sash/Frames - broken, missing, worn	108-3
() Floor - loose, worn, damaged	108-2
() Doors - Knobs/1k - missing, Panels/Frames dam.	108-3
() Electrical (d)	113
() Sanitation (d)	109

Bedrooms and/or other rooms

DESCRIPTION	CODE
() Plaster - L, C, M - Ceiling/Walls	108-2
() Windows - loose, broken, glaze	108-3
() Sash/Frames - broken, missing, worn	108-3
() Floors - loose, worn, damaged	108-2
() Door - knobs/1k - missing - Panels/Frames dam.	108-3
() Electrical (e)	113
() Sanitation (e)	109
() Clothes Closet Yes No	

Code

DESCRIPTION	CODE
() Plaste - L, C, M - Ceiling/Walls	108-2
() Windows - loose, broken, glaze	108-3
() Sash/Frames - broken, missing, worn	108-3
() Floors - loose, worn, damaged	108-2
() Door - knobs/1k - missing - Panels/Frames dam.	108-3
() Electrical (e)	113
() Sanitation (e)	109
() Clothes Closet Yes No	

Plumbing _____ Electrical _____ Sanitation - Vermin O R _____

REMARKS:

ARTICLE 5 HOUSING CODE
Health Department
DWELLING UNIT SCHEDULE

Housing Inspection Division

City of Portland

INSP DATE: 01/05/84 INSP: 10 FORM NO.: 524
Old Violations
 TENANTS NAME: _____ FLR.#: 30A LOCATION: S/O RMG. TP.: 40 #RMS.: 6 #PEO.: 2
 Y.A. A.A.H.

Child Un. ID	Child 1-6	+ Lead Survey - Results	Rent	Rent Code	Furn	Hot Water	Dual Egrs.	Ck'ng.	Heat	Lav.	Bath	Flush
						YES	YES	NE	OFF	PL	PB	PF
KITCHEN						BATHROOM						
<input type="checkbox"/> Plaster - L, C, M, - Ceiling/Walls <input type="checkbox"/> Windows - loose, broken glass, glaze <input type="checkbox"/> Sash/Frames - broken, missing, worn <input type="checkbox"/> Floor - loose, worn, dam., buckled <input type="checkbox"/> Doors - Knob/lk - missing - Panels/Frames dam. <input type="checkbox"/> Counter/Stor. Space Yes ___ No ___ <input type="checkbox"/> Sink - chipped, cracked, leaks <input type="checkbox"/> Range - improper stack, flue, vent <input type="checkbox"/> Refrigerator Space Yes ___ No ___ <input type="checkbox"/> Plumbing (a) 6(a) Water Supply Hot ___ Cold ___ <input type="checkbox"/> Electrical (a) <input type="checkbox"/> Sanitation (a)						<input type="checkbox"/> Plaster - L, C, M - Ceiling/Walls <input type="checkbox"/> Window - loose, broken glass, glaze <input type="checkbox"/> Sash/Frames - broken, missing, worn <input type="checkbox"/> Floor - loose, worn, dam., buckled <input type="checkbox"/> Door - knob/lk - missing - Panels/Frames dam. <input type="checkbox"/> Toilet - Tnk - brkn, loose, leaks, Seat, l'se crkd. <input type="checkbox"/> Lavatory - chipped, crkd, leaks, trap leaks <input type="checkbox"/> Bathtub/Shower - leaks cross connection <input type="checkbox"/> Ventilation Yes ___ No ___ <input type="checkbox"/> Plumbing (b) 6(a) Water Supply Hot ___ Cold ___ <input type="checkbox"/> Electrical (b) <input type="checkbox"/> Sanitation (b)						
LIVING ROOM						DINING ROOM						
<input type="checkbox"/> Plaster - L, C, M, - Ceiling/Walls <input type="checkbox"/> Windows - loose, broken, glaze <input type="checkbox"/> Sash/Frames - broken, missing, worn <input type="checkbox"/> Floor - loose, worn, damaged <input type="checkbox"/> Door - knob/lk - missing - Panels/Frames dam. <input type="checkbox"/> Electrical (c) <input type="checkbox"/> Sanitation (c)						<input type="checkbox"/> Plaster - L, C, M - Ceiling/Walls <input type="checkbox"/> Windows - loose, broken, glaze <input type="checkbox"/> Sash/Frames - broken, missing, worn <input type="checkbox"/> Floor - loose, worn, damaged <input type="checkbox"/> Doors - Knobs/lk - missing, Panels/Frames dam. <input type="checkbox"/> Electrical (d) <input type="checkbox"/> Sanitation (d)						
Bedrooms and/or other rooms												
						<input type="checkbox"/> Plaster - L, C, M - Ceiling/Walls <input type="checkbox"/> Windows - Loose, broken, glaze <input type="checkbox"/> Sash/Frames - broken, missing, worn <input type="checkbox"/> Floors - loose, worn, damaged <input type="checkbox"/> Door - knobs/lk - missing - Panels/Frames dam. <input type="checkbox"/> Electrical (e) <input type="checkbox"/> Sanitation (e) <input type="checkbox"/> Closets Closet Yes ___ No ___						
Plumbing						Electrical						
REMARKS:						Sanitation - Vermin O R						

City of Portland

NOT HOME
ARTICLE 5 HOUSING CODE
Health Department
DWELLING UNIT SCHEDULE

Housing Inspection Division

INSP DATE
10/21/84

INSP FORM NO.
101

TENANTS NAME
DUBOISE, SAM

Child Un. id 1-6
FLR.# 1
LOCATION RE-DW
RMG. TP. 3
#RMS. 1
#PEO. 1
YALL'D 1/2
SLRM. 1

Hot Water YES
Dual Egr. YES
Cl'ng. LG
Heat OFF
Lav. DC
Bath PA
Flush DE

KITCHEN
() Plaster - L, C, M, - Ceiling/Walls
() Windows - loose, broken glass, glaze
() Sash/Frames - broken, missing, worn
() Floor - loose, worn, dam., buckled
() Doors - Knob/Ik - missing - Panels/Frames dam.
() Counter/Stor. Space Yes No
() Sink - chipped, cracked, leaks
() Range - improper stack, flue, vent
() Refrigerator Space Yes No
() Plumbing (a) 6(a) Water Supply Hot Cold
() Electrical (e)
() Sanitation (a)

BATHROOM
() Plaster - L, C, M - Ceiling/Walls
() Window - loose, broken glass, glaze
() Sash/Frames - broken, missing, worn
() Floor - loose, worn, dam., buckled
() Door - knob/ik - missing - Panels/Frames dam.
() Toilet - Tnk - brkn, loose, leaks, Seat, l'se crkd.
() Lavatory - chipped, crkd, leaks, trap leaks
() Bath/Shower - leaks cross connection
() Ventilation Yes No
() Plumbing (b) 6(a) Water Supply Hot Cold
() Electrical (b)
() Sanitation (b)

LIVING ROOM
() Plaster - L, C, M, - Ceiling/Walls
() Windows - loose, broken, glaze
() Sash/Frames - broken, missing, worn.
() Floor - loose, worn, damaged
() Door - knob/ik - missing - Panels/Frames dam.
() Electrical (c)
() Sanitation (c)

DINING ROOM
() Plaster - L, C, M - Ceiling/Walls
() Windows - loose, broken, glaze
() Sash/Frames - broken, missing, worn
() Floor - loose, worn, damaged
() Doors - Knobs/Ik - missing, Panels/Frames dam.
() Electrical (d)
() Sanitation (d)

Bedrooms and/or other rooms

() Plaster - L, C, M - Ceiling/Walls
() Windows - Loose, broken, glaze
() Sash/Frames - broken, missing, worn
() Floors - loose, worn, damaged
() Door - knobs/ik - missing - Panels/Frames dam.
() Electrical (e)
() Sanitation (e)
() Clothes Closet Yes No

REMARKS:
Plumbing
Electrical
Sanitation - Vermin O R

Inspection Services
Samuel P. Hoffses
Chief



Planning and Urban Development
Joseph E. Gray Jr.
Director

CITY OF PORTLAND
Notice of Housing Conditions
FIVE YEAR INSPECTION

October 26, 1991

DJ: 3
CHART, BLOCK, LOT: 13-L-13
LOCATION: 156 Congress St.

District: M. Leary
Issued: 10/28/91
Expires: 12/28/91

Anthony & Beatrice Rumo
48 Woodfords St.
Portland, Maine 04103

Dear Mr. and Mrs. Rumo:

You are hereby notified, as owner or agent, that an inspection was made of the premises at 156 Congress St. by Code Enforcement Officer Merle Leary. Violations of Article V of the Municipal Ordinance (Housing Code) were found as described in detail on the attached "Housing Inspections Report".


In accordance with the provisions of the above mentioned Code, you are hereby ordered to correct those defects on or before December 28th, 1991. If you are unable to make such repairs within the specified time, you may contact this office to arrange a satisfactory repair schedule. If we do not hear from you within 10 days from this date, we will assume the repairs to be in progress and, on re-inspection within the time set forth above, will anticipate that the premises have been brought into compliance with the Housing Code Standards.


Please Note: You should consult this department to insure that any corrective action you should undertake complies with the building, plumbing, electrical, zoning and other Article of the City Code.

Please contact this office if you have any questions regarding this order.

Your cooperation will aid this department in its goal to maintain decent, safe, and sanitary housing for all of Portland's residence.

Sincerely,


Merle Leary
Code Enforcement Officer


P. Samuel Hoffses
Chief of Inspection Services

HOUSING INSPECTION REPORT

Location: 165 Congress St. Owner: Anthony & Beatrice Kumo
CEO: M. Leary
Housing Conditions Date: 10/28/91
Expiration Date: 12/28/91

Items listed below are in violation of Article V of the Municipal Codes,
"Housing Codes", and must be corrected before the expiration date:

- | | | |
|-----------------------------|---------------------|-------|
| 1. Interior - Cellar Stairs | Missing Safety Rail | 108-4 |
| 2. Interior - Cellar Flue | Excessive Soot | 114-2 |

SMOKE DETECTOR & ORDINANCE

Inspection Services
Samuel P. Hoffses
Chief



Planning and Urban Development
Joseph E. Gray Jr.
Director

CITY OF PORTLAND

Date 10/24/91

Name Beatrice R
Address 418 Woodfr St.
Address Portland, ME 04103

Re: building Address 165 Congress St.
CB# 4: 13-L-013
DU: 4

Dear Ms. Rumo:


During a recent inspection of the property owned by you at 165 Congress St. it was noted that smoke detectors were missing/inoperable in some locations.


25 MRSA 2464 required that approved smoke detectors be installed in each apartment in the immediate vicinity of the bedrooms. When actuated, the detector shall provide an alarm suitable to warn the occupants within the individual unit. Failure to comply with this statute may result in a fine of up to \$500 for each violation.

Re-inspection of your property will be made in 24 hours. Lack of compliance will result in referral of the matter for legal action.

Loss control is a responsibility of your management. Our observations are intended to assist you. Recommendations are a result of conditions observed at the time of our visits. They do not necessarily include every possible loss potential: code violation, or exception to good practice.

Sincerely,


Merle Leary
Code Enforcement Officer


S. Samuel Hoffses
Chief of Inspection Services

SMOKE DETECTOR & ORDINANCE

Inspection Services
Samuel P. Hofftes
Chief



Planning and Urban Development
Joseph E. Gray Jr.
Director

CITY OF PORTLAND

Date 10/24/91

Name Beatrice Rumo
Address 418 Woodfords St.
Address Portland, ME 04103

Re: Building Address 165 Congress St.
CBL #: 13-L-013
DU: 4

Dear Ms. Rumo:


During a recent inspection of the property owned by you at 165 Congress St. it was noted that smoke detectors were missing/inoperable in some locations.


25 MRS 2464 required that approved smoke detectors be installed in each apartment in the immediate vicinity of the bedrooms. When actuated, the detector shall provide an alarm suitable to warn the occupants within the individual unit. Failure to comply with this statute may result in a fine of up to \$500 for each violation.

Re-inspection of your property will be made in 24 hours. Lack of compliance will result in referral of the matter for legal action.

Loss control is a responsibility of your management. Our observations are intended to assist you. Recommendations are a result of conditions observed at the time of our visit. They do not necessarily include every possible loss potential code violation, or exception to good practice.

Sincerely,


Merle Leary
Code Enforcement Officer


P. Samuel Hofftes
Chief of Inspection Services

Inspection Services
Samuel P. Hoffses
Chief



Planning and Urban Development
Joseph E. Gray Jr.
Director

CITY OF PORTLAND

January 15, 1992

Anthony & Beatrice Ruro
48 Woodford St
Portland, ME 04103

Re: 165 Congress St
GBL #: 013-L-013
DU: 3

Dear Mr. & Mrs. Ruro,

A re-inspection of the premises noted above was made on January 6th, 1992 by Code Enforcement Officer Merle Leary.

This is to certify that you have complied with our request to correct the violation(s) of the Municipal Code relating to housing conditions noted on our letter dated October 28, 1991.

Thank you for your cooperation and your efforts to help us maintain decent, safe and sanitary housing for all Portland residents.

In order to aid in the preservation of Portland's existing housing inventory, it shall be the policy of this department to inspect each residential building at least once every five years.

Sincerely,

Merle Leary
Code Enforcement Officer

P. Samuel Hoffses
Chief of Inspection Services

Inspection Services
P. Samuel Hoffses
Chief



Planning and Urban Development
Joseph E. Gray Jr.
Director

CITY OF PORTLAND

August 02, 1995

FENTON DAVID
RR2 BOX 3991
OAKLAND ME 04963

Re: 165 Congress St
CBL: 013- - L-013-001-01
DU: 3

Dear Mr. Fenton:

The Housing Inspections Division of the Department of Planning and Urban Development has recently completed an overall inspection of the above referred property.


Congratulations are extended to you for the general condition of your property which was found to meet the standards established by the City's Housing Code. We did, however, note the following items that could cause future problems:


- | | | |
|----|---|--------|
| 1. | INT - 1ST FL; APT #1 -
REAR EXIT IS OBSTRUCTED | 116.20 |
| 2. | INT - 3RD FL; APT #3 - FRONT
STAIRWAY IS MISSING A RAILING | 108.40 |
| 3. | INT - 3RD FL; APT #3 - FRONT
STORE ROOM IS BEING USED FOR SLEEPING PURPOSES | 108.30 |
| 4. | INT - OVERALL -
HARD-WIRED BATTERY-BACK/UP SMOKE DETECTORS ARE REQUIRED IN EACH UNIT | 113.50 |

Good maintenance is the best way to protect the value of your property and neighborhood.

Please feel free to call on us if we can be of assistance to you.

Sincerely,


Merle Leary
Code Enforcement Officer


Tammy Munson
Code Enfc. Offr./ Field Supv.