

CERTIFICATE 0 F COMPLIANCE

✓ September 18, 1979

✓

CITY OF PORTLAND

Department of Neighborhood Conservation Housing Inspections Division Telephone: 775-5451 - Extension 448 - 358

Ralph S. & Gloria Nappi 75 Atlantic Street Portland, Maine 04101

Premises located at \_75 Atlantic Street, Portland, Maine NCP-EE 16-B-16

Dear Mr. & Mrs. Nappi: A re-inspection of the premises noted above was made on  $_{\underline{\phantom{a}}}$  9/17/79 by Housing Inspector Addato This is to certify that you have complied with our request to correct the violation of the Municipal Codes relating to housing conditions as described in our "Notice of Housing Conditions" dated 8/11/77Thank you for your cooperation and your efforts to help us maintain decent, safe and sanitary housing for all Portland residents.

In order to aid in the preservation of Portland's existing housing inventory, it shall be the policy of this department to inspect each residential building at least once every five years. Although a property is subject to re-inspection at any time during the said five year period, t.e. next regular inspection of this property is scheduled for <u>September 1984</u>.

Sincerely yours, Joseph E. Gray, Jr., Director Neighborhood Conservation

Chief of Housing Inspections

dld

Inspector

NOTICE OF HOUSING CONDITIONS City of Portland Department of Neighborhood Conservation Ch.-B1.-Lot: 16-B-16 Housing Inspections Division Location 75 Atlantic Street Tel. 775-5451 - Ext. 448 - 358 Project: NCP-East End Ralph S. & Gloria Nappi Issue: August 11, 1977 November 11, 1977 Expired 75 Atlantic Street Portland, Maine 04101 Dear Mr. & Mrs. Nappi: Maine, by Housing Inspector Carrell . Violatio to housing conditions were found as described in detail below. In accordance with provisions of the above mentioned Codes, you are requested to correct these defects on or before November 11, 1977. You may contact this office to arrange a satisfactory repair schedule if you are unable to make such repairs within the spethese defects on or before cified time. We will assume the repairs to be in progress if we do not bear from you within ten days from this date and, on reinspection within the time set forth above, will anticipate that the premises have been brought into compliance with Code Standards. Please contact this office if you have any questions regarding this Notice. Your ecoperation will help this Department in its goal to maintain all Portland residents in decent, safe and sanitary housing. Very truly yours, Joseph E. Gray, Jr. Director Neighborhood Conservation k. Carroll Chief of Housing Inspections EXISTING VIOLATIONS OF CHAPTER 307 - "MINIMUM STANDARDS FOR HOUSING" -Section(c) TRONT EXTERIOR TRIM- remove loose and peeling paint. \*/72 - RIGHT MIDDLE EXTERIOR ROOF - repair or -- place loose and broken -skylight. \*/73. -- THIRD FLOOR REAR FORCH ROOF - replace roof. <del>3</del>a 1/74c REAR GELLAR STAIRS & HALLS -repair-broken-plaster-77 5: LEFT REAR-OBLIAR WINDOW replace-broken-glass/frame-&-oachr /// 76- TEFF FRONT GELLAR CELLING- repair-or-replace-broken-and-missing-plaster. 1777- FIRST FLOOR FRONT HALL DOOR - Tepair loose door 8-+ FIRST FLOOR-FRONT-HALL DOOR -- replace oracked-panel: 9.0 FIRST FLOOR FRONT WALL DOOR - repair lease knobs - repair or replace locse, sagging, end-cracked-plaster--SECOND-FLOOR-FRONT HALL STARKS a repair loos a handrail 9 / 12. FIRST & SECOND PLOOR NEAR - HALL WALL & WEILING - repair or replace missing, cracked, 3dand loose plaster.

9/9 13/FIRST FLOOR REAR - HALL STAIRS - replace broken & worn tr

continued

	continued 75 Atlantic Street, Portland, Maine NCP-EE 16-B-16	
7/17	ATTIC CEILING - repair broken plaster. As an energy conservation measure, you may wish to install insulation.	3b
	FIRST FLOOR	
9/17	15. VKITCHEN WINDOW - repair Loose sesh. 16. VKITCHEN WINDOW - repair Loose sesh. 17. PATHROOM GETTING - repair eracked plaster.	-3c-
9/1	17 PATIRON GETLING reputrerschol-plaster	3t- 3h
9/1	18:- NATHROOM GETAING - remove loose and pueltus paints	~ <del>3</del> 8
9/1	7 19: LEFT FROM: & LEFT REAR DEN CRILING repeir segging placter.  721: LEFT FROM: DEN FLOOR repair tracked de king.  721: RIGHT MIDDLE BEDROOM CRILING repair sagging placter.  WINDCH replace broken glass.	~3b
9//	721 RICHT MINDLE REDECOM CRITING - WOOD RECEIVED	-3b-
all	722 bell II WINGLIA FAALAGA broken el age	-3b-
η,		بنالت.
./ .	SECOND FLOOR FRONT	
1//7	23. LIFT F ONT to RIGHT FRANT BEDROOM WHICH secure loose glass-by replacing points	-
	. HULLOF TRUING.	^
9/11	24- LEFT FROM & PIGHT FROM _ REDROOM CZILIN ~ repair cracked and rugging plustor	-3t-
	257 INT MIDDLE BEBROOM WINDOW - replace broken glass.	er S de la
y!	TOTAL MAINTENANCE AND	200
	SECOND FLOOR FEAR	
7/17	27 - KITCHEN WINDOW replace broken 51essy	
,,,,		
m	29. CHATROOM TUB - repair leak in Faucet.	63
7/1	29. CHATAROOM TUB repair leak in faucet. 30. JATIMON TUB repair leak in faucet. at the bathtub.	
2/17	ST KRICET FRONT REDECOM WINDOW - ser 12 loca glass by replacing points and/or reglesing	-6d
′	- A Committee of the Co	
	*** WHEN MAKING YOUR REPAIRS, FIRST PRIORITY IS TO BE GIVEN TO ITEMS WITH ASTERISKS, AS T	TKEY
	CONSTITUTE EXTREME HAZARDS TO THE HEALTH OR SAFETY OF THE OCCUPANTS OF THIS STRICTURE.	

We suggest you contact the City of Portlard Building Inspection Department, 389 Congress St., Tel7755451 to determine if any of the items listed above require a building or alteration permit.