

			1 N S	SPECTIO	N RECOR	D	C 8 L	T company
		OCATION 53-55	$\pi II$	/ Cf our	D /ACCUT		16 B 22	P. Carlotte
	L	OCATION 57-55	+ (1 La) + (T/P)	To UNITED TO THE	Charles A	1.1/21		
					5 Wilson	1. Her Stiert	<del>,</del>	<u>.</u>
				Fa	r+/2111/	12142		e) de la composition della com
NSP	DŢ,	CONDITIONS FOUND			ACTION TAKEN	(INCLUDE PER	SONS CONTACTED)	
77.7		F/2 59 HOUS	100	10/2/10110	CT/CO	Posted	Third floor	704
	7		<u> </u>	, , , , , , , , , , , , , , , , , , ,	sent N	oc		
						,		
			<u> </u>					
						······································		
								the same
					<u> </u>			
						<u></u>		
	ļ	ļ						
					<u> </u>			
	<del> </del>			***************************************				
	<del> </del>							
							. <del></del>	
	1			,,, <u>,,,</u> ,,	<u> </u>	······································		
	ـــــــــــــــــــــــــــــــــــــ			······································				
				· · · · · · · · · · · · · · · · · · ·				
	<del> </del>				<u> </u>	***************************************		
	1	1			<b>.</b>			

			INSPEC	TION RECORD	C B L
L00	CATIO	N.53-55 Atlantic			1 - 1 - 1
		111111		OWNER/AGENT Richald Mille	16 8 22
				- Richa d Mille - 75 Nilson St	1-
				- 75 Ny/son 5/1	10
INSP	DŢ	CONDITIONS FOUND		Portland Ma	14
INSP	9/9/	2 Fe Housing	Violation	ACTION TAKEN (INCLUDE	PERSONS CONTACTED)
			170720101	s Co/NOC	
		,			
					The same of the sa
	<del></del>				
$\rightarrow$					
			· · · · · · · · · · · · · · · · · · ·		
-					
		The state of the s			
			***************************************		
					The same and the s
_					
_					

.

## P 398 934 853

NO INSURANCE COVERAGE PROVIDED— NOT FOR INTERNATIONAL MAIL

(See Reverse)		
Sent to	<del></del>	7
Et Als Jt	iller,	
	04101	. ☐ F
Postage	\$	"
Certified Fee		53-55
Special Delivery Fee		J
Rostricted Delivery Fee		tia
Return Receipt Showing to whom and Date Delivered		Atlantic
Return Receipt Showing to whom,		
The second secon		St
TOTAL Postage and Fees	\$	1:
Postmark or Date		,
·		B.MacIsaac
	Sent to Richard & Jonas M Street and No. Et Als Jt. F.O., State and Robert Proceed Portland, Maine  Certified Fee  Special Delivery Fee  Return Receipt Showing to whom and Dute Delivery Date, and Address of Delivery  TOTAL Postage and Fees	Sent to Richard & Jonas Miller, Street and No. Et Als Jts. F.O., Sister and Z. Froget Portland, Maine 04101 Postage \$  Certified Fee  Special Delivery Fee  Restricted Delivery Fee  Return Receip: Showing to whom and Dute Delivery Date, and Address of Delivery  TOTAL Postage and Fees \$

 SENDER: Complete items 1, 2, 3, and 4.
 Aid your address in the "RETURN TO" cpace on reverse. (CONSULT POSTMASTER FOR PEES) The following service is requested (check one). Show to whom and date delivered ...... B. MacIsaac Show to whom, date, and address of delivery... RESTRICTED DELIVERY (The restricted delivery fee is charged in addition to the return receipt fee.) TOTAL 3. ARTICLE ADDRESSED TO: 1 Richard & Jonas Miller, Et Als Jts 53-55 Atlantic St. 75 Wilson Street Portland, Maine 04101 ARTICLE NUMBER REGISTERED MISSRED
CENTIFIED COD
EXPRESS MAIL 934 853 (Always obtain signature of addressee or agent) I have received the article described above. Authorized agent ☐ Addressee INSURED Re: 6. ADDRESSEE'S ADDRESS (Only if my AND CERTIFIED 7. UNABLE TO DELIVER DECAUSE:

REQUEST FOR SER	VICE	•	POF	RTLAND HEALTH	DEPARTMENT
DATE RECEIVED	6-14	1-83 BY	Sam	DISTRICT	BU9/_
REQUEST	NAME				<del></del>
BY	ADDRESS	54 (	Mantic		
OWNER	NAME	Dave	of Koplow	- agent	
	ADDRESS		-1-1	tlante C	53-55
CONDITIONS	ADDRESS	(187. C	Ulson FCE	1 lemi C	33-03
Porch falling of					
COMMENTS (1)	Milled-	Te pair L'etter	to stan	T 6-15,	agent
SPECIAL INSTRUCTIO	NS WOZ	R Cemp	rleted OK	6-31-8	S3
DIVISION	SANITA!	ION	HOUSING	MURSING	370
	ROUTINI	E .	SPECIAL		BY
PRIORITY	URGENT		REPORT TO		DATE





# CITY OF PORTLAND

JOSEPH E GRAY, JR. DIRECTOR OF PLANNING ND URBAN DEVELOPMENT

**OK** June 20, 1983

Richard & Jonas Miller, Et Als Jts. 75 Wilson Street Fortland, Maine 04101

Copy to Mr. David Koplow, agent 55 Atlantic Street Portland, Maine

C 80%

Re: 53-55 Atlantic St. 16-B-22 EE

Dear Sirs:

We recently received a complaint and an inspection was made by Inspector Burton Maslsaac of the property owned by you at 53-55 Atlantic Street, Portland, Maine. As a result of the inspection, you are hereby ordered to correct the following substandard housing conditions:

1. Tilted support members - LEFT REAR PORCHES. 3-d

The above mentioned conditions are in violation of Chapter 307 of the Municipal Code of the City of Portland, Maine, and must be corrected on or before <u>June 27, 1983</u>.

Failure to comply with this order may result in a complaint being filed for prosecution in District Court.

Sincerely yours, Joseph E. Gray, Jr., Director of Planning & Urban Development

Inspection Services Division

Code Enforcement Officer - B. MacIsaac

jnur

389 CONGRESS STREET • PORTLAND, MAINE 04101 • TELEPHONE (207) 775-5451

December 14, 1977

Richard and/or Jouas Miller 75 Wilson Street Portland, Maine 04101

Dear Sirs:

Re: 53-55 Atlantic Street - 16-B-22 Second Floor left  $\mathcal{E}\mathcal{E}$ 

As owner or agent of the property located at 53-55 Atlantic Street, Portland, Maine, you are hereby notified that as the result of a recent inspection, the Second Floor Left Apartment is hereby declared unfit for human occupancy.

The above mentioned apartment is to be kept vacent so long as the following conditions continue to existthereon:

(b) The property is lacking plumbing, ventilating, lighting and heating facilities or equipment adequate to protect the health, safety and general welfare of the occupants or the public.

Therefore, you will not occupy, permit anyone to occupy, or rent the above mentioned without the written consent of the Health Officer or his agent, certifying that the conditions have been corrected.

Failure to comply with this order may result in a complaint being filed for prosecution in District Court.

Sincerely yours,

Joseph E. Gray, Jr. Director Naighborhood Conservation

Ву

Lyle D. Noyes Chief of Housing Inspections

Inspector

Carroll

/gg

:ldn/76

#### NOTICE OF HOUSING CONDITIONS

CITY OF PORTLAND DEPARTMENT OF HEALTH & SOCIAL SERVICES HOUSING DIVISION Telephone 775-5451 - Extension 448

Mr. Richard Miller 75 Wilson Street Portland, Maine 04101

Dear Mr. Miller:

An examination was made of the premises at 53-55 Atlantic Street , Portland. by Housing Inspector Leary . Violations of Municipal Codes relating to . Portland, Maine by Housing Inspector Leary . Violations of Mun housing conditions were found as described in detail below.

In accordance with provisions of the above mentioned Codes, you are requested to correct these defects on or before Nov. 15, 1976 . You may contact this office to arrange a satisfactory repair schedule if you are unable to make such repairs within the specified time. We will assume the repairs to be in progress if we do not hear from you within ten days from this date and, on re-inspection within the time set forth above, will anticipate that the premises have been brought into compliance with Code Standards. Please contact this office if you have any questions regarding this Notice.

Your cooperation will help this Department in its goal to maintain all Portland residents in decent, safe and sanitary housing.

Sincerely yours,

/ Ch.-Bl.-Lot

Location:

Project:

Issued:

Expired:

16-3-22

General

Sept. 13, 1976

Nov. 15, 1976

53-55 Atlantic Street

David C. Bittenbender, Director

Health & Social Services

Inspector

Chief of Housing inspections

- Repair hanging, loose light fixture. 8e

EXISTING VIOLATIONS OF CHAPTER 307 - "MINIMUM STANDARDS FOR HOUSING" -SECTION(S)

RIGHT FRONT EXTERIOR WALL - Bricks & Ortan LEFT REAR PORCH FLOOR - Boards RIGHT REAR PORCH FLOOR - Boards Replace missing bricks & mortar. 3a Repair or replace broken boards. 3c RIGHT REAR PORCH FLOOR LEFT FRONT "ALL MOR - Latch As Repair or replace broken latch assembly. Repair or replace broken, missing LEFT FRONT EXH ALCH PRICHT FRONT EXTERIOR WALL -Downspout Downspouts downspouts. Repair or replace broken plaster. 3b **\*5.** 2nd FLOOR FRONT HALL WALLS -Plaster 2nd FLOOR REAR HALL WALLS Plaster 3rd FLOOR FRONT HALL Determine the reason and remedy the Ceiling leaking conditions.
Repair or replace broken plaster.3b \*7. 2nd FLOOR FRONT HALL - Stairway LEFT FROMT CELLAR · Ceiling Replace missing Junction box cover. 8e - Celling LEFT REAR CELLAR RIGHT FRONT CELLAR Secura electrical wiring. - Celling 8e LEFY FRONT CELLAR - Celling 8e \*10. LEFT FRONT CELLAR - Calling

CONTINUED....

FR-18 St.
SENDER: Complete items 1, 2, and 3, Add-your address in the "RETURN TO" space-on reverse.
The following service is requested (check one).
Show to whom, date, & address of delivery 354
RESTRICTED DELIVERY.  Show to whom and date delivered
RESTRICTED DELIVERY. Show to whom, date, and address of delivery 85f
2. ARTICLE ADDRESSED TO:
S WINDER WARRENCE IO.
Design of the second se
S. ARTICLE DESCRIPTION: REGISTERED NO. CERTIFIED NO. INSURED NO.
(Always obtain signature of addresses or agent)
staye receiver the article described above.  StanATURE L Addresse . Authorized agent
muler
DATE OF DELIVE TO
S. ADDRESS' (Comple a only if requested)
W ONT
G. UNABLE TO DELIVER BECAUSE: CLERK'S
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1

53-55 Atlantic Street, continued.... FIRST FLOOR, LEFT install heating heating facilities capabel of providing minimum temperature of 68 degrees. LIVING ROOM Windows - Replace missing stops and sash. 3с BEDROUM 3с BATHROOM Floor - Remedy the segging conditions of floor. 3Ь 14. EATHROOM Lavatory - install a lavatory with not and cold running water. SECCHD FLOOR, LEFT 15. KITCHEN Floor - Repair the buckled boards of kitchen floor. 16. LIVING ROOM 36 Secure glass by replacing points and/or reglazing. Window \*17. RIGHT FRONT BEDROOM- Ceiling- Repair inoperative light fixture. 3€ 18. EVATHROOM 8e Windo vs Replace missing stops and parting beads. 3с PANTRY Windows \*19. BATHROOM Øs Repair leaking hot water faucet. Sink 6đ 20. PANTRY - Window Replace missing counter-balance cords. \*21. PANTRY wall - Repair or replace broken plaster. FIRST FLOOR, RIGHT 22. HALL DOOR - Latch Replace missing latch assembly. \*23. LIVING ROOM - Window Replace missing glass. BEDROOM Window Repair or replace broken frame. 3с LIVING ROOM Window 11 \*25. BEDROOM Зc Window Raplace broken glass. SECOND FLOOR, RIGHT Celling LIVING ROOM Replace the missing tiles. 3b Ceiling 35 LIVING ROOM - Window Replace missing frame and glass. RIGHT REAR BEDRM - Window -Replace missing stops. 3с DINING ROOM - Window -3с - Celling -LIVING ROOM Replace missing junction box cover. Зe RIGHT REAR BEDRM- WIndow Secure glass by replacing points and regiszing. THIRD FLOOR OVERALL \*31. MIDDLE HALL Celling -Repair or replace buckled, cracked plaster. \*32. MIDDLE HALL - Celling Remedy the leaking conditions. LEFT REAR BEDRM- Celling 3b RIGHT REAR BEDRM-Celling 3b \* 11 35 LIVING ROOM - Celling 11 DINING ROOM Calling 11 11 3Ь BATHROOM Window Repair inoperative sesh. LIVING ROOM WIndow Replace missing counter belance cords allowing window sash DEN Window to remain elevated when opened. LIVING ROOM - Window Repair or replace broken parting bead. 3с - Window LIVING ROOM Replace missing stops. LEFT FRONT BEDRM - Window -3€ Secure glass by replacing points and reglazing. HIDDLE HALL - Fixture -3¢ Repair loose light fixture. LEFF FRONT BEDRM- Celling -LIVING ROOM - Wall -8e Repair loose light fixture. 8e depair loose outlet. RIGHT REAR BEDRM - WINdow -3e Replace missing, broken glass.

14

CONTINUED ....

LEFT FRONT BEDRM - Window -

53-55 Atlantic St., continued....

```
(THIRD FL., OVERALL)
```

```
41. LEFT REAR BEDROOM- Celling - Remove Illegal extension cord connected to light
 *42. LEFT FRONT SEDRM - Vall -
 443 PANTRY
                                     Repair or replace broken plaster.
                       - Ceiling - Repair or replace broken plaster.
  44. LEFT FRONT BEDRM - Door
 #45. KITCHER
                                     Repair or replace broken door.
                       " Window
 1446, FRONT HALL
                                     Replace broken glass.
                       - Celling ...
 447. FRONT HALL
                                     Repair c. replace cracked plaster.
                      - Celling
  48.
                                     Enclose alectrical wiring.
      LIVING ROOM
                      " Celling "
                                     Replace missing tiles.
      BATHROOM
                      - Celling
 49.
     DINING ROOM
                         Window
                                                                                     3b
                                    Repair or ruplace broken stop.
SECOND FLOOR, REAR
                                                                                    36
*50. KITCHEN
      LIVING ROOM
                        Window
                                    Replace broken glass.
*51. FRONT HALL
                         Window
                        Stalrway -
                                   Repair or rapiace broken plaster.
*52. BATHROOM
                       Walls
                                   Repair or replace broken plaster.
53. KITCHEN
                      - Window
*54. LIVING ROOM
                                   Replace missing moulding.
                     - Celling ..
55. LIVING ROOM
                                   Remedy the leaking conditions.
                        Window
                                   Replace missing counter balance cords allowing window
    REAR BEDROOM
                                   sash to remain elevated when opened.
                        Celling -
57. DEN
                                   Replace missing tiles.
                       Window - Repair or replace broken stop.
38. UEN
                                                                                   3c
                       Windows - Secure glass by replacing points and registing.
59. FRUNT HALL
```

Repair or replace broken board. WHEN MAKING REPAIRS FIRST PRIORITY SHOULD BE GIVEN TO THOSE ITEMS WITH ASTERISKS AS THEY CONSTITUTE EXTREME HAZARDS TO THE HEALTH OR SAFETY OF THE OCCUPANTS OF THIS STRUCTURE.

LDN: FI

CERTIFICATE

0 F

COMPLIANCE

December 10, 1971

CITY OF PORTLAND Health Department - Housing Division Tel. 774-8221 Ext. 226

Mr. Richard Miller 53 Atlantic Street Portland, Maine 04101

Re: Premises located at 53 Atlantic Street, Portland, Maine

Dear Mr. Miller:

December 7, 1971 A re-inspection of the premises noted above was made on \_\_ by Housing Inspector \_\_\_ McIsaac \_\_, of the Health Department.

This is to certify that you have complied with our request to correct the violations of the Municipal Codes relating to housing conditions described in our "Notice of Housing Conditions" dated November 4, 1971

Thank you for your cooperation and your efforts to help us maintain decent, safe and sanitary housing for all Portland residents.

Very truly yours,

Arthur A. Hughson, CPH, MPH

Health Director

Chief of Housing Inspections

Inspector Hanald M. Inoac

Inspection Services Samuel P. Hoffses Chief



Planning and Urban Development Joseph E. Gray Jr. Director

#### CITY OF PORTLAND

October 15, 1991

Richard Weare POB 781 Portland, ME 04101 5 YEAR INSPECTION

Re: 55 Atlantic/15 Wilson Sts CBL #: 16-B-22 DU: 6

Dear Mr. Weare

You are hereby notified, as owner or agent, that an inspection was made of the premises at 55 Atlantic St/75 Wilson Sts by Code Enforcement Officer Merle Leary. Violations of Article V of the Municipal Ordinance (Housing Code) were found as described in detail on the attached "Housing Inspections Report".

In accordance with the provisions of the above mentioned Code, you are hereby ordered to correct those defects on or before December 15th, 1991. If you are unable to make such repairs within the specified time, you may contact this office to arrange a satisfactory repair schedule. If we do not hear from you within 10 days from this date, we well assume the repairs to be in progress and, on re-inspection within the time set forth above, will anticipate that the premises have been brought into compliance with the Housing Code Standards.

Please Note: You should consult this department to insure that any corrective action you should undertake complies with the building, plumbing, electrical, zoning and other Article of the City Code.

Please contact this office if you have any questions regarding this order.

Your cooperation will aid this department in it's goal to maintain decent, safe, and sanitary housing for all of Portland's residence.

Sincerely

"orle Leary Gede Enforcement Officer P. Samuel Horrses Chief of Inspection Services

389 Congress Street · Portland, Mainc 04101 · (207) 874-8704

### HOUSING INSPECTION REPORT

Location:
Owner:
CEO
Housing Conditions Date:
Expiration Date:

ltems listed below are in violation of Article V of the Municipal Codes, "Housing Codes", and must be corrected before the expiration date:

1. Interior - Front hall stairway - Missing Railings 108-4

2. Interior 3rd fl/Apt #5 - Front bed window - Missing counterbalance cords 108-2

3.\* Interior - Furnace room - Loose and hanging Romex 113-5

4.\* Interior - Furnace room - Missing lalley columns 108-2

Inspection Services
P. Samuel Hoffses
Chief



Planning and Urban Development Joseph E. Gray Jr. Director

#### CITY OF PORTLAND

MAY 01, 1997

WEARE RICHARD E PO BOX 741 PORTLAND ME 04104

> Re: 55 ATLANTIC ST CBL: 016- - B-022-001-01

DU: 8

Dear Mr. Weare:

The Housing Inspections Division of the Department of Planning and Urban Development has recently completed an overall inspection of the above-referred property.

Congratulations are extended to you for the general condition of your property which was found to meet the standards established by the City's Housing Code. We did, however, note the following items that could cause future problems:

1. EXT - LEFT - PORCH -STAIRS HAVE A BROKEN TREAD 108.40

2. INT - 2ND I'LR - REAR APT - HALL STAIRS ARE MISSING A HANDRAIL

108.40

Good maintenance is the best way to protect the value of your property and neighborhood.

Please feel free to call on us if we can be of assistance to you.

Sincerely,

Marland Wing

Code Enforcement Officer

Farland Why

Tammy Munson

Code Enfc.Offc./ Field Supv.