

11 Adams Street

17E

MONI-SO

STANLEY
MADE IN U.S.A.
140033R

X

November 21, 1977 ✓

Antonio C. &/or Mary T. Pulsoni
11 Adams Street
Portland, Maine 04101

Dear Mr. and Mrs. Pulsoni: Re: 11 Adams Street, Portland, Maine NCP-East End
17-E-36

The Housing Inspections Division of the Department of Neighborhood Conservation has recently completed an exterior inspection of your property in conjunction with the above referred program.

Congratulations are extended to you for the general conditions of your property which was found to meet the standards established by the City's Housing Code. We did, however, note the following items that could cause future problems.

1. LEFT REAR EXTERIOR WALLS & TRIM- loose and peeling paint.
2. LEFT REAR EXTERIOR WALLS - broken clapboards.
3. LEFT REAR & FRONT MIDDLE EXTERIOR CHIMNEYS- loose and missing mortar.


Good maintenance is the best way to protect the value of your property and neighborhood.

Please feel free to call on us if we can be of assistance to you.

Sincerely yours,
Joseph E. Gray, Jr., Director
Neighborhood Conservation

By _____
Lyle D. Noyes,
Chief of Housing Inspections

Inspector


W. Carroll