

9 ADAMS STREET 17E

MADISON

November 21, 1977

James W. &/or Mary A. Horr  
P.O. Box 4583  
Portland, Maine 04112

Dear Mr. And Mrs. Horr: Re: 9 Adams Street, Portland, Maine NCP-East End  
17-E-35

The Housing Inspections Division of the Department of Neighborhood Conservation has recently completed an exterior inspection of your property in conjunction with the above referred program.

Congratulations are extended to you for the general conditions of your property which was found to meet the standards established by the City's Housing Code. We did, however, note the following items that could cause future problems.

1. OVERALL EXTERIOR TRIM- loose and peeling paint.
2. RIGHT FRONT EXTERIOR CHIMNEY- loose and missing mortar.
3. REAR MIDDLE EXTERIOR STAIRS - broken handrail.

Good maintenance is the best way to protect the value of your property and neighborhood.

Please feel free to call on us if we can be of assistance to you.

Sincerely yours,  
Joseph F. Gray, Jr., Director  
Neighborhood Conservation

By \_\_\_\_\_  
Lyle D. Noyes,  
Chief of Housing Inspections

Inspector *Kim Carroll*  
A. Carroll

VW