

BUILDINGS#11-14, MCNIFORT ST.

SHAW MFG.
S 9203-3R



APPLICATION FOR AMENDMENT TO PERMIT

Amendment No. #1

September 8 1966

CITY OF PORTLAND

To the INSPECTOR OF BUILDINGS, PORTLAND, MAINE

The undersigned hereby applies for amendment to Permit No. 66/611 pertaining to the building or structure comprised in the original application in accordance with the Laws of the State of Maine, the Building Code and Zoning Ordinance of the City of Portland, plans and specifications, if any, submitted herewith, and the following specifications:

Location Bldgs. #11-14 Mountfort St. Within Fire Limits? Dist. No.

Owner's name and address Munjoy Associates, 97a Exchange St. Telephone

Lessee's name and address

Contractor's name and address Palmer Tarinelli Construction Co. 114 Island Brook Ave. Bridgeport Conn. Telephone

Architect

Proposed use of building Apartment house Plans filed No. of sheets

Last use Apt. house No. families

Increased cost of work Additional fee 50

Description of Proposed Work

To delete this building.

Details of New Work Contractors-114 Island Brook Ave. Bridgeport Conn.

Is any plumbing involved in this work? Is any electrical work involved in this work?

Height average grade to top of plate Height average grade to highest point of roof

Size, front depth No. stories solid or filled land? earth or rock?

Material of foundation Thickness, top bottom cellar

Material of underpinning Height Thickness

Kind of roof Rise per foot Roof covering

No. of chimneys Material of chimneys of lining

Framing lumber—Kind Dressed or full size?

Corner posts Sills Girt or ledger board? Size

Girders Size Columns under girders Size Max. on centers

Studs (outside walls and carrying partitions) 2x4-16" O. C. Bridging in every floor and flat roof span over 8 ft.

Joists and rafters: 1st floor 2nd 3rd roof

On centers: 1st floor 2nd 3rd roof

Maximum span: 1st floor 2nd 3rd roof

Approved: *J. E. M.* Munjoy Associates

Palmer Tarinelli Construction Co.

Signature of Owner by: *J. E. M.*

Approved:

Inspector of Buildings *J. E. M.*

INSPECTION COPY
CS. 105



R6 RESIDENCE ZONE

APPLICATION FOR PERMIT

Class of Building or Type of Structure Third StoriesPortland, Maine, July 12, 1944

PERMIT ISSUED

JUL 22 1944

CITY OF PORTLAND

To the INSPECTOR OF BUILDINGS, PORTLAND, MAINE

The undersigned hereby applies for a permit to erect alter repair demolish install the following building structure equipment in accordance with the Laws of the State of Maine, the Building Code and Zoning Ordinance of the City of Portland, plans and specifications, if any, submitted herewith and the following specifications:

Location 127 de Courcey Street Within Fire Limits? Yes Dist. No. 1
Owner's name and address Hunjor Associates, 97a Exchange St. Telephone 772-3161
Lessee's name and address _____ Telephone _____
Contractor's name and address Palmer Mariniotti Const. Co., 111 Island Ave. Average grade 10 ft. Telephone 7077
Architect _____ Specifications yes Plans yes No. of sheets 1
Proposed use of building Apartment house No. families 4
Last use _____ No. families 4
Material Wood No. stories 3 Heat Gas Style of roof Gabled Roofing Shingles
Other buildings on same lot _____
Estimated cost \$ 35,000 Fee \$ 20.00

General Description of New Work

To construct 2-story frame apartment house as per plans

Amendment #2 Delete this building

It is understood that this permit does not include installation of heating apparatus which is to be taken out separately by and in the name of the heating contractor. PERMIT TO BE ISSUED TO Hunjor Associates

Details of New Work

Is any plumbing involved in this work? Yes Is any electrical work involved in this work? Yes
Is connection to be made to public sewer? Yes If not, what is proposed for sewage? Septic tank
Has septic tank notice been sent? Yes Form notice sent? Yes
Height average grade to top of plate 10 ft. Height average grade to highest point of roof 10 ft.
Size, front 25 ft. depth 35 ft. No. stories 3 solid or filled land? Yes earth or rock? Yes
Material of foundation Concrete Thickness, top 8 in. bottom 12 in. cellar 10 in.
Kind of roof Gabled Rise per foot 1/12 Roof covering Shingles
No. of chimneys 1 Material of chimneys Brick of lining Brick Kind of heat Gas fuel Gas
Framing Lumber-Kind Common Dressed or full size? Common Corner posts Common Sills Common
Size Girder 4x6 Columns under girders 4x6 Size 16 in. Max. on centers 16 in.
Studs (outside walls and carrying partitions) 2x4-16" O. C. Bridging in every floor and flat roof span over 8 feet.
Joists and rafters: 1st floor 16 in., 2nd 16 in., 3rd 16 in., roof 16 in.
On centers: 1st floor 16 in., 2nd 16 in., 3rd 16 in., roof 16 in.
Maximum span: 1st floor 16 in., 2nd 16 in., 3rd 16 in., roof 16 in.
If one story building with masonry walls, thickness of walls? 8 in. height? 10 ft.

If a Garage

No. cars now accommodated on same lot 0, to be accommodated 0 number commercial cars to be accommodated 0
Will automobile repairing be done other than minor repairs to cars habitually stored in the proposed building? No

APPROVED:

J. E. Ni.

Miscellaneous

Will work require disturbing of any tree on a public street? No
Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? Yes

Hunjor Associates

H. J. Ni.

NOTES

9/14/66 - X-12 100'iles
Paved - 110 mph.
(These have regular
footings)

11/19/62 - License issued to
close in 11/1962

Approved

Permit No. 66/67
Location ~~Permit # 11-14 Metamorphic~~ ~~11-14 Metamorphic~~
Owner ~~24~~ ~~Crane Co. Inc.~~ ~~11-14~~
Date of fr ~~11/12/62~~
Notif. ch. in
Inspn ch. in
Final Notf ~~11/14/67~~
Final Inspn ~~11/14/67~~
Cert. of ~~Agency issued~~
Staking Out Notice
Form Check Notice