

217 CUMBERLAND AVENUE



SHAW-WALKER
First cut # 920R - Second cut # 9202R - Third cut # 9203R - Fifth cut # 9205R



R6 RESIDENCE ZONE
 CITY OF PORTLAND, MAINE
 DEPARTMENT OF BUILDING INSPECTION
 COMPLAINT

Location
 217-221 Cumberland Ave.

INSPECTION COPY

COMPLAINT NO. 60/51 Date Received June 17, 1960

Location 217-221 Cumberland Ave. Use of Building _____
 Owner's name and address Morris Berden, 162 Cumberland Ave. Telephone _____
 Tenant's name and address _____ Telephone _____
 Complainant's name and address Mr. Lucian Marino, 43 Wilmot Street Telephone _____ H

Description: Land in rear of building being used for junk yard - old cars.
Wreckers go in through right of way and wreck cars on this lot.

NOTES: 6-22-60. Three passenger cars without plates.
1 - GMC van, 1 - Ford (Commercial Lic. 28252-Me)
could be used for taking away.
One passenger car with plates in rear trunk
section but plates are stacked in back.
217-221 Cumberland Ave.
 6/22/60 - yard has about 2 small pieces of
 junk. One load is being parked here. One
 passenger car without plates. The owner of
 the car says he plans to take it away.
 Allan

2416



217 Cumberland Ave

Nov 12 / 25

POSTAGE
PAID
NOV 12 1925

PLEASE PRINT OR TYPE CLEARLY

