


221. COMBERLAND AVENUE



SLAVE WALKER

Full cut # 920R - Half cut # 9202R - Third cut # 9203R - Fifth cut # 9205R



RECEIVED
 NOV 14 1980
 DEPT. OF BLDG. INS.
 CITY OF PORTLAND



APPLICATION FOR PERMIT

PERMIT ISSUED

B.O.C.A. USE GROUP

B.O.C.A. TYPE OF CONSTRUCTION

972

17 1980

ZONING LOCATION 4-6 PORTLAND, MAINE, Nov. 14, 1980 of PORTLAND

To the DIRECTOR OF BUILDING & INSPECTION SERVICES, PORTLAND, MAINE

The undersigned hereby applies for a permit to erect, alter, repair, demolish, move or install the following building, structure, equipment or change use in accordance with the Laws of the State of Maine, the Portland B.O.C.A. Building Code and Zoning Ordinance of the City of Portland with plans and specifications, if any, submitted herewith and the following specifications:

LOCATION 221 Cumberland Avenue Fire District #1 [], #2 []
1. Owner's name and address David White Memorial S.D. 221 Gray Rd. Telephone
2. Lessee's name and address David White Memorial S.D. 221 Gray Rd. Telephone
3. Contractor's name and address Telephone
4. Architect Specifications Plans No. of sheets
Proposed use of building retail of natural foods No. families
Last use used merchandise store No. families
Material No. stories Heat Style of roof Roofing
Other buildings on same lot
Estimated contractual cost \$ ch of use Fee \$ 15.00

FIELD INSPECTOR—Mr. GENERAL DESCRIPTION

This application is for: @ 775-5451
Dwelling Ext. 234

Garage Change use from retail of used merchandise to retail of natural foods
Masonry Bldg. Stamp of Special Conditions
Metal Bldg.
Alterations
Demolitions
Change of Use
Other

David Jenny
Send to 144 Gray Rd.
Cumberland, Me. 04021

NOTE TO APPLICANT: Separate permits are required by the installers and subcontractors of heating, plumbing, electrical and mechanicals.

PERMIT IS TO BE ISSUED TO 1 [] 2 [] 3 [] 4 []
Other:

DETAILS OF NEW WORK

Is any plumbing involved in this work? Is any electrical work involved in this work?
Is connection to be made to public sewer? If not, what is proposed for sewage?
Has septic tank notice been sent? Form notice sent?
Height average grade to top of plate Height average grade to highest point of roof
Size, front depth No. stories solid or filled land? earth or rock?
Material of foundation Thickness, top bottom cellar
Kind of roof Rise per foot Roof covering
No. of chimneys Material of chimneys of lining Kind of heat fuel
Framing Lumber—Kind Dressed or full size? Corner posts Sills
Size Girder Columns under girders Size Max. on centers
Studs (outside walls and carrying partitions) 2x4-16" O. C. Bridging in every floor and flat roof span over 8 feet.
Joists and rafters: 1st floor 2nd 3rd roof
On centers: 1st floor 2nd 3rd roof
Maximum span: 1st floor 2nd 3rd roof
If one story building with masonry walls, thickness of walls? height?

IF A GARAGE

No. cars now accommodated on same lot, to be accommodated number commercial cars to be accommodated
Will automobile repairing be done other than minor repairs to cars habitually stored in the proposed building?

APPROVALS BY: DATE MISCELLANEOUS
BUILDING INSPECTION—PLAN EXAMINER Will work require disturbing of any tree on a public street?
ZONING: Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed?
BUILDING CODE:
Fire Dept.:
Health Dept.:
Others:

Signature of Applicant David Jenny Phone # 829-5471
Type Name of above David Jenny 1 [] 2 [] 3 [] 4 []

FIELD INSPECTOR'S COPY

Other and Address

NOTES

10/26/81 135000 - 135000 - 135000
Signed A. W. ...

Permit No 801 972
Location 271 Cumberland Ave
Owner Signature [Signature]
Date of term 11-14-80
Approved 11-12-80

[Large handwritten 'X' mark]

[Empty lined area for notes]

City of Portland, Maine
Fire Department

Seymour Nathanson

21 Roundabout Lane
Portland, Me

Re: Fire at 223-225 Cumberland Ave

Dear Mr. Nathanson,

On 9-4-80 a fire occurred in the building listed above, of which you are reported to be the owner.

If permanent repair work is required for this building, you must obtain a permit from the Building & Inspection Dept. in City Hall before starting such work.

Very Truly Yours,

Chief
Portland Fire Department

cc: Building & Inspection Dept.
Health Dept. (Heating Div.)
City Assessor's (Mr. Lucci)

Fire in cellar starting at fuse box. Burned part of first floor flooring and heavily damaged wiring.



APPLICATION FOR PERMIT

Permit No. 2171

Class of Building or Type of Structure

Portland, Maine, October 7, 1912

To the INSPECTOR OF BUILDINGS, PORTLAND, ME.

The undersigned hereby applies for a permit to erect alter install the following building structure equipment in accordance with the Laws of the State of Maine, the Building Code of the City of Portland, plans and specifications, if any, submitted herewith and the following specifications:

Location 221 Cumberland Avenue Within Fire Limits? yes Dist. No. 1
Owner's or lessee's name and address Morris Hadden, 217 Cumberland Avenue Telephone
Contractor's name and address J. Ken Gordon, 221 Cumberland Ave. Telephone 2-2156
Architect Plans filed No. of sheets
Proposed use of building Rooming House No. families
Other buildings on same lot
Estimated cost \$ 15. Fee \$ 25

Description of Present Building to be Altered

Material brick No. stories 4 Heat Style of roof Roofing
Last use Rooming House No. families

General Description of New Work

To cut in new window in basement to provide light and air for stairway (rear wall)

It is understood that this permit does not include installation of heating apparatus which is to be taken out separately by and in the name of the heating contractor.

Details of New Work

Is any plumbing work involved in this work?
Is any electrical work involved in this work? Height average grade to top of plate
Size, front depth No. stories Height average grade to highest point of roof
To be erected on solid or filled land? earth or rock?
Material of foundation Thickness, top bottom cellar
Material of underpinning Height Thickness
Kind of roof Rise per foot Roof covering
No. of chimneys Material of chimneys of lining
Kind of heat Type of fuel Is gas fitting involved?
Framing lumber Kind Dressed or full size?
Corner posts Sills Girt or ledger board? Size
Material columns under girders Size
Studs (outside walls and carrying partitions) 2x4-16" O. C. Girders 6x8 or larger Bridging in every floor and flat roof span over 8 feet. Sills and corner posts all one piece in cross section.
Joists and rafters: 1st floor, 2nd, 3rd, roof
On centers: 1st floor, 2nd, 3rd, roof
Maximum span: 1st floor, 2nd, 3rd, roof

If one story building with masonry walls, thickness of walls? height?

If a Garage

No. cars now accommodated on same lot to be accommodated
Total number commercial cars to be accommodated
Will automobile repairing be done other than minor repairs to cars habitually stored in the proposed building?

Miscellaneous

Will above work require removal or disturbing of any shade tree on a public street? no
Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? yes
Signature of owner Morris Hadden

Signature of owner J. Ken Gordon

INSPECTION COPY

Permit No. 42/1171
Location 221 Cumberland Ave
Owner Morris Padden
Date of permit 10/7/42
Notif. closing-in _____
Ins. n. closing-in _____
Final insp. _____
Final Inspn. 11/10/42
Cert. of Occupancy issued _____

NOTES

10/10/42

