

98 INDIA ST.

CLAWSON
2203 IN



APPLICATION FOR PERMIT

PERMIT ISSUED

B.O.C.A. USE GROUP

1973 OCT 8 1974

B.O.C.A. TYPE OF CONSTRUCTION

ZONING LOCATION PORTLAND, MAINE, Oct. 8, 1974

CITY of PORTLAND

To the DIRECTOR OF BUILDING & INSPECTION SERVICES, PORTLAND, MAINE

The undersigned hereby applies for a permit to erect, alter, repair, demolish, move or install the following building, structure, equipment or change use in accordance with the Laws of the State of Maine, the Portland B.O.C.A. Building Code and Zoning Ordinance of the City of Portland with plans and specifications, if any, submitted herewith and the following specifications:

LOCATION 98-100 India St. Fire District #1 [] #2 []
1. Owner's name and address Peter Roger, same Telephone
2. Lessee's name and address Telephone
3. Contractor's name and address Albert Dupris, 82 Cumberland Ave Telephone 7726838
4. Architect Specifications Plans No. of sheets
Proposed use of building No. families
Last use apartments No. families
Material brick No. stories 3 Heat Style of roof Roofing
Other buildings on same lot
Estimated contractual cost \$ 5,500.00 Fees \$ 24.00

FIELD INSPECTOR Mr. Cartwright GENERAL DESCRIPTION

This application is for: @ 775-5451 to repair after fire, structural damage,
Dwelling Ext. 234 replace roof, 2x8 rafters 16" OC, 17' span,
Garage to provide cellar girts on every other rafter.
Masonry Bldg. Stamp of Special Conditions
Metal Bldg.
Alterations
Demolitions
Change of Use
Other

NOTE TO APPLICANT: Separate permits are required by the installers and subcontractors of heating, plumbing, electrical and mechanicals.

PERMIT IS TO BE ISSUED TO 1 [] 2 [] 3 [x] 4 []
Other:

DETAILS OF NEW WORK

Is any plumbing involved in this work? no Is any electrical work involved in this work? no
Is connection to be made to public sewer? If not, what is proposed for sewerage?
Has septic tank notice been sent? Form notice sent?
Height average grade to top of plate Height average grade to highest point of roof
Size, front depth No. stories solid or filled land? earth or rock?
Material of foundation Thickness, top bottom cellar
Kind of roof Rise per foot Roof covering
No. of chimneys Material of chimneys of lining Kind of heat fuel
Framing Lumber—Kind Dressed or full size? Corner posts Sills
Size Girder Columns under girders Size Max. on centers
Studs (outside walls and carrying partitions) 2x4-16" O. C. Bridging in every floor and flat roof span over 8 feet.
Joists and rafters: 1st floor, 2nd, 3rd, roof
On centers: 1st floor, 2nd, 3rd, roof
Maximum span: 1st floor, 2nd, 3rd, roof
If one story building with masonry walls, thickness of walls? height?

IF A GARAGE

No. cars now accommodated on same lot ... to be accommodated ... number commercial cars to be accommodated ...
Will automobile repairing be done other than minor repairs to cars habitually stored in the proposed building?

APPROVALS BY: DATE
BUILDING INSPECTION—PLAN EXAMINER
ZONING:
BUILDING CODE: O.K. C.R. 10/8/74
Fire Dept.:
Health Dept.:
Others:

MISCELLANEOUS
Will work require disturbing of any tree on a public street?
Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? YCS

Signature of Applicant Albert Dupris Phone # 7726838
Type Name of above Albert Dupris 1 [] 2 [] 3 [x] 4 []
Other and Address

FIELD INSPECTOR'S COPY

030221 T...

NOTES

11-16-74 Went over enclosure of stairway with John Sweazy

10-31-74 Sheetrock going up walls

12-16-74 Front doors on

1-22-75 still finishing

Permit No. 241873
 Location 8500 W. Lincoln St
 Owner Peter King
 Date of permit 10/8/74
 Approved

~~00.00~~
 0.01

Duplex next door should have stairway enclosure

Melvin

CITY OF PORTLAND, MAINE
Application for Permit to Install Wires

Permit No. **1046**

Issued
 Portland, Maine **Dec 24**, 19**33**

To the City Electrician, Portland, Maine:

The undersigned hereby applies for a permit to install wires for the purpose of conducting electric current, in accordance with the laws of Maine, the Electrical Ordinance of the City of Portland, and the following specifications:

(This form must be completely filled out — Minimum Fee, \$1.00)

Owner's Name and Address: **John Rogers** Tel. _____
 Contractor's Name and Address: **Young's Electric** Tel. **2735035**
 Location: **88 India St** Use of Building _____
 Number of Families _____ Apartments _____ Stores _____ Number of Stories _____
 Description of Wiring: **New Work** Additions _____ Alterations _____
 Pipe _____ Cable _____ Metal Molding _____ BX Cable _____ F' _____ No. of feet) _____
 No. Light Outlets **27** Plugs **30** Light Circuits **8** (Circuits **8**)
 FIXTURES: No. _____ Fluor. or Strip Lighting (No. feet) _____
 SERVICE: Pipe Cable Underground _____ No. of Wires **3** Size **4/0**
 METERS: Relocated _____ Added **3** Total No. Meters **4**
 MOTORS: Number _____ Phase _____ H. P. _____ Amps _____ Volts _____ Starter _____
 HEATING UNITS: Domestic (Oil) _____ No. Motors _____ Phase _____ H.P. _____
 Commercial (Oil) _____ No. Motors _____ Phase _____ H.P. _____
 Electric Heat (No. of Rooms) _____
 APPLIANCES: No. Ranges **4** Watts **6500** Brand Feeds (Size and No.) **3/6**
 Elec. Heaters _____ Watts _____
 Miscellaneous _____ Watts _____ Extra Cabinets or Panels _____
 Transformers _____ Air Conditioners (No. Units) _____ Signs (No Units) _____
 Will commence _____ 19 _____ Ready to cover in _____ 19 _____ Inspection _____ 19 _____
 Amount of Fee \$ **13.00**
will call in Signed: **Robert Young**

DO NOT WRITE BELOW THIS LINE

SERVICE		METER		GROUND	
VISITS: 1	2	3	4	5	6
	7	8	9	10	11
					12

REMARKS:

INSPECTED BY **Robert Young**
 (OVER)



R6 RESIDENCE ZONA

APPLICATION FOR PERMIT

Class of Building or Type of Structure Second Class
Portland, Maine, March 12, 1971

PERMIT 137153
304
CITY OF PORTLAND

To the INSPECTOR OF BUILDINGS, PORTLAND, MAINE

The undersigned hereby applies for a permit to erect alter repair demolish install the following building structure equipment in accordance with the Laws of the State of Maine, the Building Code and Zoning Ordinance of the City of Portland, plans and specifications, if any, submitted herewith and the following specifications:

Location #96-98-100 India St. Within Fire Limits? _____ Dist. No. _____
 Owner's name and address Peter J Rogers, 1700 Westbrook St. Telephone _____
 Lessee's name and address _____ Telephone _____
 Contractor's name and address Robert M Jackman, 58 Cross St. Telephone 772-4102
 Architect _____ Specifications _____ Plans 708 No of sheets 1
 Proposed use of building Apartment Building No. families 7
 Last use _____ " " _____ No. families 7
 Material brick No. stories 3 Heat _____ Style of roof _____ Roofing _____
 Other buildings on same lot _____
 Estimated cost \$ 1200.00 Fee \$ 6.00

General Description of New Work

To erect metal fire escape on rear of building from third floor to ground(drop ladder) (see plan)

3/15/71
3/16/71

It is understood that this permit does not include installation of heating apparatus which is to be taken out separately by and in the name of the heating contractor. **PERMIT TO BE ISSUED TO contractor**

Details of New Work

Is any plumbing involved in this work? _____ Is any electrical work involved in this work? _____
 Is connection to be made to public sewer? _____ If not, what is proposed for sewage? _____
 Has septic tank notice been sent? _____ Form notice sent? _____
 Height average grade to top of plate _____ Height average grade to highest point of roof _____
 Size, front _____ depth _____ No. stories _____ solid or filled land? _____ earth or rock? _____
 Material of foundation _____ Thickness, top _____ bottom _____ cellar _____
 Kind of roof _____ Rise per foot _____ Roof covering _____
 No. of chimneys _____ Material of chimneys _____ of lining _____ Kind of heat _____ fuel _____
 Framing Lumber—Kind _____, Dressed or full size? _____ Corner posts _____ Sills _____
 Size Girder _____ Columns under girders _____ Size _____ Max. on centers _____
 Studs (outside wall and carrying partitions) 2x4-16" O. C. Bridging in every floor and flat roof span over 8 feet.
 Joists and rafters: 1st floor _____, 2nd _____, 3rd _____, roof _____
 On centers: 1st floor _____, 2nd _____, 3rd _____, roof _____
 Maximum span: 1st floor _____, 2nd _____, 3rd _____, roof _____
 If one story building with masonry walls, thickness of walls? _____ height? _____

If a Garage

No. cars now accommodated on same lot _____, to be accommodated _____ number commercial cars to be accommodated _____
Will automobile repairing be done other than minor repairs to cars habitually stored in the proposed building? _____

APPROVED:

[Signature] 3-16-71
[Signature] 3/30/71

Miscellaneous

Will work require disturbing of any tree on a public street? no
Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? yes

Peter J Rogers
Robert M Jackman

CS 301

INSPECTION COPY

Signature of owner by: Peter J Rogers

[Signature]


711

NOTES

4/26/71 - work started.
 7/27/71 - Mat
 finished platform
 + some stairs below.
 8/17/71

10/13/71
 appeared to be
 completed according
 to plan.

Permit No. 71/304
 Location 96-98-100 S. Blvd.
 Owner Peter J. Rogers
 Date of permit 4/11/71
 Notif. closing-in
 Inspn. closing-in
 Final Notif.
 Final Inspn.
 Cert. of Occupancy issued
 Issued by JAMES D. JONES
 Issued on 5/11/71
 Form Check Notice





APPLICATION FOR PERMIT

Class of Building or Type of Structure 2nd Class
Portland, Maine, Mar. 9, 1960

To the INSPECTOR OF BUILDINGS, PORTLAND, MAINE

The undersigned hereby applies for a permit to erect alter repair demolish install the following building structure equipment in accordance with the Laws of the State of Maine, the Building Code and Zoning Ordinance of the City of Portland, plans and specifications, if any, submitted herewith and the following specifications:

Location 98 India Street
Owner's name and address Lawrence A. C. Orcutt, 98 India Street
Lessee's name and address
Contractor's name and address owner
Architect
Proposed use of building dwelling - 2 family
Last use 2 family dwelling house
Material brick No. stories Heat Style of roof pitch Roofing Asphalt-Class C
Estimated cost \$ 250. Fee \$ 2.00

General Description of New Work

To construct wooden fire escape on rear of building from third-floor to ground as per plan.

1/4/62 - decided not to press this matter further JPS

Sent to Fire Dept. 3/7/60
Rec'd from Fire Dept. 3/24/60

It is understood that this permit does not include installation of heating apparatus which is to be taken out separately by and in the name of the heating contractor. PERMIT TO BE ISSUED TO OWNER

Details of New Work

Is any plumbing involved in this work? Is any electrical work involved in this work?
Has septic tank notice been sent? Form - notice sent?
Height average grade to top of plate Height average grade to highest point of roof
Material of foundation Thickness, top bottom cellar
Kind of roof Rise per foot Roof covering
No. of chimneys Material of chimneys of lining Kind of heat fuel
Framing Lumber - Kind Dressed or full size? Corner posts Sills
Size Girder Columns under girders Size Max. on centers
Studs (outside walls and carrying partitions) 2x4-16" O. C. Bridging in every floor and flat roof span over 8 feet.
Joists and rafters: 1st floor 2nd 3rd roof
On centers: 1st floor 2nd 3rd roof
Maximum span: 1st floor 2nd 3rd roof
If one story building with masonry walls, thickness of walls? height?

If a Garage

No. cars now accommodated on same lot to be accommodated number commercial cars to be accommodated.
Will automobile repairing be done other than minor repairs to cars habitually stored in the proposed building?

APPROVED:

APPROVED [Signature]
CHIEF OF FIRE DEPT.

Miscellaneous

Will work require disturbing of any tree on a public street?
Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? yes
Lawrence A. C. Orcutt

CS 391

INSPECTION COPY

Signature of owner

By:

[Signature] Lawrence A. C. Orcutt

NOTES

Handwritten notes in the left column, including the word "NOTES" at the top. The notes are mostly illegible due to blurring and bleed-through from the reverse side of the page.

Permit No. 601
Location: 98 S. ...
Owner: ...
Date of permit: 3/1/60
Notif. closing-in: ...
Inspn. closing-in: ...
Final Notif.: ...
Final Inspn.: ...
Cert. of Occupancy issued: ...
Sinking Out Notice: ...
Form Check Notice: ...

Right column of the permit form, containing various checkboxes and fields for inspection status, including sections for "Sinking Out Notice" and "Form Check Notice".

CITY OF PORTLAND, MAINE
MEMORANDUM

TO: Mr. Albert J. Sears, Inspector of Buildings DATE March 22, 1960
FROM: Robert H. Flaherty, Chief Inspector, Fire Prevention Bureau
SUBJECT: Construction of a wood fire escape at 98 India Street.

The building permit for construction of a wooden fire escape from the third floor to the ground on the rear of the building at 98 India Street is approved provided that the window on the third floor will be changed to a door.

This double hung window is approximately 4 feet above the floor making it almost impossible for one to reach the fire escape.

R.H.F.



A-I

CITY OF PORTLAND, MAINE
DEPARTMENT OF BUILDING INSPECTION

COMPLAINT

Location:
98 India Street

INSPECTION COPY

COMPLAINT NO. 59/45

Date Received July 29, 1959

Location 98 India Street Use of Building _____
Owner's name and address Mr. Charles Orcutt, 98 India Street Telephone _____
Tenant's name and address _____ Telephone _____
Complainant's name and address _____ Telephone _____

Description: A rear outside stairway from second floor part way to the ground has been built without first securing a permit and contrary to the Building Code as follows:

NOTES: Stairway is too steep, rise being 9 inches and run or tread about 8 1/2 (plank treads cut between two stringers in such a way that the back edge of each tread would be an inch from a plumb line dropped from the front edge of the tread above, thus making it possible for a person with small heels to have the heel of their shoes project down through the space behind the tread causing an accident); upper landing is supported by two 4x4 posts (one of them out of plumb) both supported on a shoe bearing upon the sagging roof of a one story shed which Mr. Orcutt said was built without a permit; the lower end of the inner stringer has about an inch bearing on loose bricks at a first story window sill, this stringer and the top landing were ^{fastened to} pass to the brick wall only by spiking through stringer into the joints of the brick work; the other side of bottom of stairs supported by 4x4 resting on concrete walk; bottom of stairs about 8 feet above the ground and a portable ladder leaning against the building about 18 inches on the foot of the steps.

7/30/59 - Letter to owner - C.J.F.
8.25.59. Stair supports outside full end part
- no change blade cut while stairway
Second floor shows not appear to be
P.C.C. solid. - could not get into it
for inspection - 7 of fireplace
10/16/59 No change in condition of
stairway - mm
2/15/60 - Putty & order sent to Architect Goodspeed at request
of Mr. Orcutt. - C.J.F.
2/2/60 - mm. For shed part of lined - said he would
and if it owner would pay his fee before
he went & either into the got (over)

2/26/60 - Mr. Goodspeed in with
plan which he is to give to Mr. Orcutt
after making some minor changes - a.g.

3/9/60 - Permit applied for - wa

1/4/62 - Permit never issued because of inability
to get Mr. Orcutt to provide proper construction - a.g.

3/26/64 - Mr. Orcutt died about a year ago - a.g.

2/26/60 - Mr Goodspeed in with
plan which he is to give to Mr. Grant
after making some minor changes. - JG!

3/9/60 - Permit applied for - WJ

1/4/62 - Permit never issued because of inability
to get Mr. Grant to provide - per construction - JG!

3/26/64 - Mr Grant died about a year ago - JG!

Reg. Mail
Ret. Rec.

Complaint - 98 India St.

July 30, 1959

FU-McD-8/24/59

Mr. Charles Orcutt
98 India Street

cc to Raymond S. Ozka, Esq.
465 Congress Street

Dear Mr. Orcutt:

This letter is notice of violations of the Building Code of Portland, As authorized and directed by Sec. 109 of the Building Code (copy enclosed) you are hereby required to have made before August 24, 1959 such changes, repairs, or alterations as deemed necessary and as indicated below to make good the violations. The violations are as follows:

1. A wood outside stairway running from a platform at about second floor level in the rear of the building to a level of about 4 feet above the ground has been constructed without first securing a building permit from this department as required by Sec. 103 of the Building Code.
2. The stairway has been constructed as to framing and supports contrary to Building Code requirements in that:

The upper platform is supported at outside corners by two 4×4 posts (one of these definitely out of plumb), these posts are supported on a wooden shoe which gets support upon the roof of a one-story shed. The roof of the shed was never constructed of adequate strength and is now sagging definitely. The bottom of the outside stair stringer is supported on another 4×4 post which is supported merely upon a concrete walk instead of the required masonry pier extending no less than 4 feet below the surface of the ground and not less than 6 inches above the ground, the post to be securely anchored to the pier.

The stringer against the brick wall of the building is supported at the bottom by a slight bearing upon the brickwork near the sill of a first story window, mortar being out of the joints and the bricks appearing loose. The balance of the stringer and the upper platform against the building are only supported by spiking through the woodwork into the joints of the brickwork.

The stairway is too steep, what would normally be called the tread being 8 inches instead of the minimum of 9 required. This is a "plank" stairway, being constructed of two plank stringers (33 inches wide from outside to outside), with rise and run of tread formed by cutting planks between the stringers. These planks are arranged that there is an open space of about 1 inch between the rear edge of one plank and a plumb line from the front edge of the plank above. This, the hazard is offered to a person wearing shoes with small heels having the heels go down in the rear of one of the treads threatening serious accident and that at time of emergency.

The Building Code allows "drop" ladder to reach the ground at the bottom of such an escape, but always with suitable precautions so that persons using the escape will have a reasonable chance of reaching the ground in safety. In this case there is nothing to prevent a person walking off the bottom end of the stairway in the darkness. A portable ladder has been provided, leaning against the building, but it is about 18 inches from the bottom of the stairway and the entire situation is

in violation of the Building Code.

Mr. Charles Orcutt

Page 2

July 30, 1959

3. You have told us that you built the shed attached to the rear of the building a few years ago without a building permit. The roof and walls of the shed are not only framed inadequately contrary to Building Code requirements therefor, but the shed is in Fire District No. 1 where a wooden building of that size is not allowable.

With due regard for the safety of the persons occupying the second floor apartment, you are to have made a plan of this stairway, the supports and fastenings by some competent party and to show compliance with the requirements of the Building Code therefor, and to have a print of the plan with all of the information on it printed from the original filed with application for a building permit to construct the new stairway; and as soon as this can be checked and the permit issued, you are to proceed to have the stairway constructed according to the plan and application before the above date.

At the proper time when it is fitting for the supports of the present platform to be removed, you are to demolish the wooden shed built without a permit and remove the debris from the premises.

Very truly yours,

Albert J. Sears
Inspector of Buildings

Encs: copy of Sec. 109 of the Building Code

Capt. 98 India--Owner Charles Orcutt whom lives there.

10/16/59.

RGS:

Following your order of 7/30/59, there have been some negotiations, including at least two telephone calls to Raymond Oakes to whom I was referred by Mr. Orcutt as the attorney who has charge of his affairs. Mr. Oakes had a copy of your order. Each time Mr. Oakes has said he would go up there, look the situation over, confer with the owner--then let me know. At my suggestion that I contact Mr. Orcutt direct, Mr. Oakes preferred to do it himself, but the latter has not reported at all. Inspection this morning shows that no improvement and no correction has taken place. While the stairway is built of new lumber, its supports are such that it is dangerous.

Mr. Orcutt is defiant, and while he tries to give the impression that he does not know how to proceed with relation to the Code, it is evident that he does know and is successfully beclouding the issue--for instance he has rented the second floor apartment. Thus, if he is required to remove the stairway, the emergency means of egress will be removed.

It is recommended that the Legal Department be asked to quickly (this has gone on all summer and fall) seek two warrants--one for building the stairway without a permit, the other for building the stairway contrary to requirements for strength and safety. In view of the natural reluctance of the Legal Dept. to give a criminal record to an ordinary property owner, Mr. Donovan will probably prefer a conference with Mr. Orcutt and Raymond Oakes. No doubt he should summon them to such a conference with you present. They will no doubt "stall"; but it is hoped that performance will occur completely by a definite reasonable date, based on decent plans, or the warrants will be sought without further notice.

7th - do engage plan maker

11th - do file permit with application for permit

mcd

Feb. 4, 1960

Mr. Douglas K. Goodspeed
443 Congress Street

cc to: Mr. Charles Orcutt
98 India Street

Dear Mr. Goodspeed:

Enclosed herewith we are sending you at the request of Mr. Orcutt a copy of the letter sent to him by this department concerning violations of the Building Code involving a wooden stairway constructed on the rear of his building at 98 India Street. We understand that he has commissioned you to prepare plans which can be filed with an application for a belated permit, these plans to indicate what corrections are to be made in order to meet Code requirements.

Very truly yours,

Albert J. Sears
Inspector of Buildings

AJS:m



FILL IN AND SIGN WITH INK

APPLICATION FOR PERMIT FOR HEATING, COOKING OR POWER EQUIPMENT

Portland, Maine, July 22, 1959

PERMIT ISSUED

00988 JUL 30 1959

CITY of PORTLAND

To the INSPECTOR OF BUILDINGS, PORTLAND, ME.

The undersigned hereby applies for a permit to install the following heating, cooking or power equipment in accordance with the Laws of Maine, the Building Code of the City of Portland, and the following specifications:

Location ... 98 India Street ... Use of Building ... Dwelling ... No. Stories ... New Building Existing ... Name and address of owner of appliance ... Charles D. Dickett, 98 India St. ... Installer's name and address ... Harris Oil Co., 212 Commercial St. ... Telephone 2-8304

General Description of Work

To install steam heating system and oil burning equipment in place of stove heat

IF HEATER, OR POWER BOILER

Location of appliance ... basement ... Any burnable material in floor surface or beneath? ... Kind of fuel? ... oil ... Minimum distance to burnable material, from top of appliance or casing top of furnace ... 4' ... From top of smoke pipe ... 5' ... From front of appliance ... 4' ... From sides or back of appliance ... 3' ... Size of chimney flue ... 8x10 ... Other connections to same flue ... none ... If gas fired, how vented? ... Rated maximum demand per hour ... Will sufficient fresh air be supplied to the appliance to insure proper and safe combustion? ... yes

Sent to Fire Dept. 7/23/59 Rec'd from Fire Dept. 7/28/59

IF OIL BURNER

Name and type of burner ... General Electric ... Labeled by underwriters' laboratories? ... yes ... Will operator be always in attendance? ... Does oil supply line feed from top or bottom of tank? ... bottom ... Type of floor beneath burner ... concrete ... Size of vent pipe ... 1 1/4" ... Location of oil storage ... basement shed outside of building on dirt floor ... Number and capacity of tanks ... 1-275 gal. ... Make ... McDonnell-Miller ... No. ... 69GE ... Will all tanks be more than five feet from any flame? ... How many tanks enclosed? ... Total capacity of any existing storage tanks for furnace burners ... none

IF COOKING APPLIANCE

Location of appliance ... Any burnable material in floor surface or beneath? ... If so, how protected? ... Height of Legs, if any ... Skirting at bottom of appliance? ... Distance to combustible material from top of appliance? ... From front of appliance ... From sides and back ... From top of smokepipe ... Size of chimney flue ... Other connections to same flue ... Is hood to be provided? ... If so, how vented? ... Forced or gravity? ... If gas fired, how vented? ... Rated maximum demand per hour ...

MISCELLANEOUS EQUIPMENT OR SPECIAL INFORMATION

[Empty lines for miscellaneous information]

Amount of fee enclosed? .. 2.00 ... (\$2.00 for one heater, etc., 50 cents additional for each additional heater, etc., in same building at same time.)

APPROVED: [Signature] 7.22.59 [Signature] Carl E. Johnson CHIEF OF FIRE DEPT.

Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? ... yes ... Harris Oil Co.

INSPECTION COPY

Signature of Installer [Signature]

NOTES

1	Full Size	
2	West Face	
3	East Face	
4	Bottom of Tank	
5	Bottom Integrity & Repair	
6	Bottom of Tank	
7	Shell Out	
8	High Limit Control	
9	Pressure Switch	
10	Pressure Regulator's Protection	
11	Pressure in Supply Line	
12	Capacity of Tank	
13	Tank Integrity & Repairs	
14	Tank Inspection	
15	Oil Pressure	
16	Interlocking Control	
17	Low Pressure Switch	

Permit No. 8-31-59
 Location 98 S. ...
 Owner ...
 Date of permit 7/30/59
 Approved 9/14/59


8-31-59
 8-31-59
 8-31-59

8-7-39 To change
 in tank layout
 3rd tank ...
 demolished.
 8/13/59 - Sold to
 Orant that he
 can use 12-inch
 hollow tile
 under smoke pipe
 on wooden floor
 covering sufficient
 area so that all
 woodwork of floor
 within 18 inches
 of pipe will be
 protected - to be
 sure that these
 spaces will be
 continuous
 and open to the
 cellar so that
 if fire takes place
 in the smoke pipe
 itself, the heat
 in travelling
 downwards will
 pass through open
 spaces in the
 tile then
 into the open
 cellar harmlessly

inspect air burner
 8-31-59
 make paper structure
 + chimney supported by
 hollow tile

8-24-59 Slab supports
 outside fuel tank
 will not go in to

RECEIVED
JUN 22 1959
DEPT. OF PUBLIC WORKS
CITY OF OAKLAND



28-D.22

SURVEY AND INVESTIGATION OF TENEMENT AND LODGING HOUSES
QUESTIONABLE AS TO LEGAL AND SAFE USE

- 1. Location INDIA-98 Date Investigation Commenced _____
- 2. References: Complaints _____ Appl. BP _____ Inq. _____
- 3. Present Owner and Address _____
- 4. Present Lessee and Address _____
- 5. Building Permit Record: _____

Assessors' Record

- 6. Survey 1924; Owner Dudley C. Steen, Detroit No. tenants: 1
No. rooms 12; Class of Use Lodging
- 7. Assessors' change record since 1924: 1951 CHAS. C. KRASCHWIND, 1955 CHELSEY B. BURT


9. City Directory Record

1926	
1927	1939
1928	1940
1929	✓ 1941 <u>Cristiana Asamblea</u> Mrs. MAH E. S. FORTWORTH
1930	1942 <u>Cristiana Asamblea</u>
1931	1943 <u>Cristiana Asamblea</u>
1932	1944 <u>G. Assemblies</u> James P. Ray - 96 INDIA - Robert Samuels
1933	1945 <u>Asamblea Cristiana</u>
1934	1946 <u>Vacant</u>
1935	1947 <u>Asamblea Cristiana</u>
1936	1948 <u>Vacant</u>
1937	1949 <u>Vacant</u>
1938	1950 <u>Vacant</u>
	1951 <u>Vacant</u>

CONCLUSIONS

- 1952 - Angelo A. Giacullo
- 1953 - Angelo A. Giacullo
- 1954 - Vacant
- 1955 - Vacant
- 1956 - Vacant
- 1957 - Charles Percut
- 1958 - Charles Percut

Street Line of India Street
Showing Encroachments of Steps



L.B. 555/66
Profile

Comp. by W.S.B. 6/30/59
Checked by



APPLICATION FOR PERMIT

Class of Building or Type of Structure
Portland, Maine

Second Class

June 22, 1959

To the INSPECTOR OF BUILDINGS, PORTLAND, MAINE

The undersigned hereby applies for a permit to erect alter repair demolish install the following building structure equipment in accordance with the Laws of the State of Maine, the Building Code and Zoning Ordinance of the City of Portland, plans and specifications, if any, submitted herewith and the following specifications.

Location 98 India Street Within Fire Limits? _____ Dist. No. _____
 Owner's name and address Lorraine G. Orcutt, 98 India St. Telephone _____
 Lessee's name and address _____ Telephone _____
 Contractor's name and address owner Telephone _____
 Architect _____ Specifications _____ Plans yes No. of sheets _____
 Proposed use of building Detached Apartment No. families 2-3
 Last use _____ " " _____ No. families 2-3
 Material brick-frames No. stories 3 Heat _____ Style of roof _____ Roofing _____
 Other buildings on same lot _____ Fee \$.50
 Estimated cost \$ 160.

General Description of New Work

To change out existing wooden front steps to concrete and to erect new set of concrete steps front of building and change window to door front of building.
New steps are to lead down to basement apartment.

1/1/61 - Work not done - [Signature]

It is understood that this permit does not include installation of heating apparatus which is to be taken out separately by and in the name of the heating contractor. **PERMIT TO BE ISSUED TO** owner

Details of New Work

Is any plumbing involved in this work? _____ Is any electrical work involved in this work? _____
 Is connection to be made to public sewer? _____ If not, what is proposed for sewage? _____
 Has septic tank notice been sent? _____ Form notice sent? _____
 Height average grade to top of plate _____ Height average grade to highest point of roof _____
 Size, front _____ depth _____ at least 4' below grade _____ void or filled land? _____ earth or rock? _____
 Material of foundation concrete Thickness, top .8" bottom 2" cellar _____
 Material of underpinning _____ Height _____ Thickness _____
 Kind of roof _____ Rise per foot _____ Roof covering _____
 No. of chimneys _____ Material of chimneys _____ of lining _____ Kind of heat _____ fuel _____
 Framing Lumber—Kind _____ Dressed or full size? _____ Corner posts _____ Sills _____
 Size Girders _____ Columns under girders _____ Size _____ Max. on centers _____
 Kind and thickness of outside sheathing of exterior walls? _____
 Studs (outside walls and carrying partitions) 2x4-16" O. C. Bridging in every floor and flat roof span over 8 feet.
 Joists and rafters: 1st floor _____, 2nd _____, 3rd _____, roof _____
 On centers: 1st floor _____, 2nd _____, 3rd _____, roof _____
 Maximum span: 1st floor _____, 2nd _____, 3rd _____, height? _____
 If one story building with masonry walls, thickness of walls? _____

If a Garage

No. cars now accommodated on same lot _____, to be accommodated _____ number commercial cars to be accommodated _____
 Will automobile repairing be done other than minor repairs to cars habitually stored in the proposed building? _____

Miscellaneous

Will work require disturbing of any tree on a public street? no
 Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? yes

APPROVED:

Signature of owner

Lorraine G. Orcutt

Unit No. 59 / 1
Location 98 Durbie St
Owner D. Simpson & Co. (P) Ltd
Date of permit 1/19
Notif. closing-in
Inspr. closing-in
Final Notif.
Final Inspr.
Cert. of Occupancy issued
Staking Out Notice
Form Check Notice

NOTES

[Empty lined area for notes]

[Empty lined area for notes]

May 27, 1955

Mr. Chesley A. Croutt
229 Cumberland Avenue
Portland, Maine

Dear Mr. Croutt:

Re: 98 India Street

We recently received a complaint and an inspection was made of the property owned by you at 98 India Street, Portland, Maine. We found evidence that the property is now or has been recently occupied. This is contrary to our orders dated December 27, 1952, to a former owner and apply equally as well to you. You will notice our signs on the front and rear doors prohibiting the occupancy of the property.

We have reason to believe that persons congregate in the premises evenings causing disturbances, creating a nuisance and a detriment to the neighboring properties.

In addition, we found trash, litter, filth and debris within the property causing a health hazard to nearby property owners.

Therefore, you are hereby ordered to remove and properly dispose of all trash, litter, filth and debris within the structure and in the rear yard.

You are also hereby ordered to properly close, lock and secure the building against trespassers, and thereby reduce the present fire hazard.

The above mentioned conditions are in violation of the City Ordinances "Authority to Vacate Buildings" and "Garbage and Rubbish Containers", and must be corrected on or before June 2, 1955.

Very truly yours,

Edward W. Colby, M.D.
Health Director

cc: Chief of Police
Fire Chief
Bldg. Inspector

By: Gordon E. Martin
Housing Supervisor

CEM/s

RECEIVED

MAY 27 1955

DEPT. OF BLD'G. INSP.
CITY OF PORTLAND

COPY



(A) APARTMENT HOUSE ZONE
 CITY OF PORTLAND, MAINE
 DEPARTMENT OF BUILDING INSPECTION
COMPLAINT

gob

Location:
 98 India St.

INSPECTION COPY

COMPLAINT NO. 54/88

Date Received 11/8/54

Location 95 India St. Use of Building _____

Owner's name and address Christian G. Kruglund, 365 Danforth St. Telephone _____

Tenant's name and address _____ Telephone _____

Complainant's name and address Mr. Ventelino Gerino, 100 India St. Telephone _____

Description: Dilapidated and dangerous center section of this 3-section brick block.

NOTES: 11/9/54 - Better - LMS

[The following section contains multiple horizontal lines for notes, which are mostly blank or crossed out with a large 'X' over the entire form area.]

LOCATION 98 India St.

DATE 11/9/54

PERMIT _____

INQUIRY _____

COMPLAINT

Mr. McDonald:

This building is in three sections. The dilapidated part is the center section. I was unable to get in this section.

However, I talked to Mr. Corino and he says that part of the roof is gone letting in the rain. He is probably right.

The gutters and conductor pipes are all gone or are of no use. Most of the water therefore goes right into the cellar. This water has seeped in the foundation wall. About 5 feet of this wall is nothing but powder and stone. This also lets the water into the other cellars on each side.

In time this back wall sitting on this foundation will give away. — Allen



Original Permit No. _____

Amendment No. 1

AMENDMENT TO APPLICATION FOR PERMIT

Portland, Maine, March 31, 1919

To the INSPECTOR OF BUILDINGS, PORTLAND, ME.

The undersigned hereby applies for an amendment to Permit No. _____ pertaining to the building or structure comprised in the original application in accordance with the Law of the State of Maine, the Building Code of the City of Portland, plans and specifications, if any, submitted herewith, and the following specifications:

Location: 19 India Street Within Fire Limits? Yes Dist. No. _____

Owner's name and address: R. J. Callahan, 187 Blandis St.

Contractor's name and address: Venturino Corino, 17 Chatham St.

Plans filed as part of this Amendment: _____ No. of Sheets _____

Is an, plumbing work involved in this work? _____ Is any electrical work involved in this work? _____

Increased cost of work: _____ Additional fee: 2%

Framing Lumber: Kind? _____ Dressed or Full Size? _____

Description of Proposed Work

To Change Use of building from two rooms, first story, from dwelling to Minor Assembly Hall

Approved. _____

Signature of Owner P. G. Clapp

Chief of Fire Department.

Approved: _____

Commissioner of Public Works.


Inspector of Buildings.

INSPECTION COPY

3713
E.P.

The design of New Wood Girder shown on the accompanying plan, covering alterations to building at 98 India Street, Portland, Maine, has been made by the undersigned according to the latest rules of engineering practice and to comply with the allowable working stresses, floor loads, etc., required by the Building Code of the City of Portland.

T. C. Hutchins
T. C. Hutchins.



RECEIVED
MAR 22 1943
DEPT. OF BLD'G. INSP.
CITY OF PORTLAND

4x8 Post
8x12 Beam

15'

15'

FRONT ROOM

BACK ROOM

FRONT HALL

30'
3 1/2"
9' 6"
9'
New 8x12 Girder
New 4x8 Post Attachment

15'

15'

18

P.P. Kelly Contractors
98 Indica St.
193 Division
34507

15' 3"



APPLICATION FOR PERMIT

Class of Building or Type of Structure Second Class

Permit No. _____

Portland, Maine, March 22, 1943

To the INSPECTOR OF BUILDINGS, PORTLAND, ME.

The undersigned hereby applies for a permit to erect alter install the following building structure equipment in accordance with the Laws of the State of Maine, the Building Code of the City of Portland, plans and specifications, if any, submitted herewith and the following specifications:

Location 98 India Street Within Fire Limits? yes Dist. No. 1

Owner's or Lessee's name and address R. J. Callahan, 107 Middle St. Telephone _____

Contractor's name and address Ventolino Carino, 17 Chatham St. Telephone 3-0955

Architect _____ Plans filed yes No. of sheets 1

Proposed use of building Assembly hall and dwelling 2nd fl. vacant No. families 1

Other buildings on same lot _____

Estimated cost \$ 25. Fee \$ 25

Description of Present Building to be Altered

Material brick No. stories 2 Heat stove Style of roof pitch Roofing _____

Last use Assembly hall and dwelling No. families 1

General Description of New Work

To remove 13' bearing partition, first floor, to make one large room out of two rooms. Ex12 girder for support

It is understood that this permit does not include installation of heating apparatus which is to be taken out separately by and in the name of the heating contractor.

Details of New Work

Is any plumbing work involved in this work? no

Is any electrical work involved in this work? no Height average grade to top of plate _____

Size, front _____ depth _____ No. stories _____ Height average grade to highest point of roof _____

To be erected on solid or filled land? _____ earth or rock? _____

Material of foundation _____ Thickness, top _____ bottom _____ cellar _____

Material of underpinning _____ Height _____ Thickness _____

Kind of roof _____ Rise per foot _____ Roof covering _____

No. of chimneys _____ Material of chimneys _____ of lining _____

Kind of heat _____ Type of fuel _____ Is gas fitting involved? _____

Framing lumber—Kind _____ Dressed or full size? _____

Corner posts _____ Sills _____ Girt or ledger board? _____ Size _____

Material columns under girders _____ Size _____ Max. on centers _____

Studs (outside walls and carrying partitions) 2x4-16" O. C. Girders 6x8 or larger. Bridging in every floor and flat roof span over 8 feet. Sills and corner posts all one piece in cross section.

Joists and rafters: 1st floor _____, 2nd _____, 3rd _____, roof _____

On centers: 1st floor _____, 2nd _____, 3rd _____, roof _____

Maximum span: 1st floor _____, 2nd _____, 3rd _____, roof _____

If one story building with masonry walls, thickness of walls? _____ height? _____

If a Garage

No. cars now accommodated on same lot _____ to be accommodated _____

Total number commercial cars to be accommodated _____

Will automobile repairing be done other than minor repairs to cars habitually stored in the proposed building? _____

Miscellaneous

Will above work require removal or disturbing of any shade tree on a public street? no

Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? yes

Signature of owner By: P. G. Clepp

INSPECTION COPY

243 52

Permit No 43/
Location 95 Duane Street
Owner P. J. Callahan - V. Cruise
Date of permit 3/ 1943
Notif. closing-in
Inspn. closing-in
Final Notif.
Final Inspn.
Cert. of Occupancy issued

NOTES

3/23/43 - This use of these two rooms in the first story as an Italian Mission was evidently started about 1936 as it first appears in the 1937 Directory, without permit. There is only one exit from rooms as plan shows, altho it would be possible to replace rear window with door and steps leading to back yard. Upper floors are apparently vacant except for one man who is living in top story. This was originally a

bed room in the Mission section is used by the mother is heated by an oil burning space heater. Opening to the main should be provided with proper trim 4 + 12" x 12" collar.

There are finished rooms in basement and a partitioned directly beneath one to be removed. Mr. Clapp is to dig into partition to find out what foundation is where foot supports new beam will land. This is the center section of a 3 story block, each section being one at one time for a 10 room house. All sections have only one means of egress from upper stories. We have recently had a complaint exempt exits from 100 ft from State Inspector, which has been reported to Chief Sanborn. The first floor of this latter

section is used by the Irish Temperance Mission in the same manner as that at #98 has been used. The partitions have not been removed, but has a large opening as is common plan for work at #98. This use was established five years ago by lady who lives in house and whose husband runs mission for me. The two rooms are set up with a piano and other. There is only one exit as in other section - A.D.