

21-23 BRATTLE STREET



Full cut # 920R • Half cut # 9202R • Tail cut # 9203R • Full cut # 9205R



B2 BUSINESS ZONE

APPLICATION FOR PERMIT

Class of Building or Type of Structure Third Class
Portland, Maine August 5, 1960

PERMIT ISSUED

AUG 12 1960

CITY OF PORTLAND

To the INSPECTOR OF BUILDINGS, PORTLAND, MAINE

The undersigned hereby applies for a permit to erect ~~alter, repair, demolish~~ install the following building structure equipment in accordance with the Laws of the State of Maine, the Building Code and Zoning Ordinance of the City of Portland, plans and specifications, if any, submitted herewith and the following specifications:

Location 23 Brattle St. Within Fire Limits? _____ Dist. No. _____
 Owner's name and address Benjamin Baillargeon, 304 Cumberland St. Telephone UL-48382
Westbrook Me. Telephone _____
 Lessee's name and address _____ Telephone _____
 Contractor's name and address Joseph LeBel, Fort Hill Rd, Gorham Maine Telephone _____
 Architect _____ Specifications _____ Plans no No. of sheets _____
 Proposed use of building Apartment House No. families 3
 Last use _____ " " _____ No. families _____
 Material frame No. stories 3 Heat _____ Style of roof _____ Roofing _____
 Other buildings on same lot _____
 Estimated cost \$ 150.00 Fee \$ 2.00

General Description of New Work

To provide (2) tapered 8"x8" base and 6" x 6" tapered reinforced concrete piers under existing 3-story frame porch on side of building. (piers will be located 10' o.c.)

It is understood that this permit does not include installation of heating apparatus which is to be taken out separately by and in the name of the heating contractor. **PERMIT TO BE ISSUED TO** owner

Details of New Work

Is any plumbing involved in this work? _____ Is any electrical work involved in this work? _____
 Is connection to be made to public sewer? _____ If not, what is proposed for sewage? _____
 Has septic tank notice been sent? _____ Form notice sent? yes
 Height average grade to top of plate _____ Height average grade to highest point of roof _____
 Size, front _____ depth _____ No. stories _____ solid or filled land? _____ earth or rock? _____
 Material of foundation concrete piers at least 4' below grade Thickness, top _____ bottom _____ cellar _____
 Kind of roof _____ Rise per foot _____ Roof covering _____
 No. of chimneys _____ Material of chimneys _____ of lining _____ Kind of heat _____ fuel _____
 Framing Lumber—Kind _____ Dressed or full size? _____ Corner posts _____ Sills _____
 Size Girder _____ Columns under girders _____ Size _____ Max. on centers _____
 Studs (outside walls and carrying partitions) 2x4-16" O. C. Bridging in every floor and flat roof span over 8 feet.
 Joists and rafters: 1st floor _____, 2nd _____, 3rd _____, roof _____
 On centers: 1st floor _____, 2nd _____, 3rd _____, roof _____
 Maximum span: 1st floor _____, 2nd _____, 3rd _____, roof _____
 If one story building with masonry walls, thickness of walls? _____ height? _____

If a Garage

No. cars now accommodated on same lot _____, to be accommodated _____ number commercial cars to be accommodated _____
Will automobile repairing be done other than minor repairs to cars habitually stored in the proposed building? _____

APPROVED:

H. E. G. 8/11/60

Miscellaneous

Will work require disturbing of any tree on a public street? no
Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? yes
Benjamin Baillargeon

CF 207

INSPECTION COPY

Signature of owner

Benjamin Baillargeon



APPLICATION FOR PERMIT

PERMIT ISSUED
AUG 4 1960
01036
CITY of PORTLAND

Class of Building or Type of Structure Third Class

To the INSPECTOR OF BUILDINGS, Portland, Me.

PORTLAND, MAINE, August 4, 1960

The undersigned hereby applies for a permit to repair or renew roof covering of the following described building in accordance with the laws of Maine, the Building Code of the City of Portland, and the following specifications:

Location 25 Brattle St.

Owner's name and address Benjamin Baillargeon, 304 Cumberland St., Westbrook Me. Telephone _____

Contractor's name and address Harry Kimball, Westbrook Me. Telephone _____

Use of building—Present Apartment House Proposed Apartment House

No. of Stories 3 Style of roof hip Type of present roof covering Asphalt

Type and Grade of roofing to be used Asphalt Class C Und. Lab. No. plies _____

GENERAL DESCRIPTION OF NEW WORK

To cover portion of roof.

Fee \$.50
INSPECTION COPY

Signature of Owner by: Benjamin Baillargeon

To Building Department
REPORT OF FIRE

Date Oct. 24, 1955
Location ²³25 Brattle St.
Construction Wood
Height (Stories) 2-1/2
Owner Fred Sylvester *h.l.l. Conger*
Occupant Tenants
Floor of origin _____
Cause Defective chimney
Appx. Damage None
Remarks : Poor draft in chimney.

RECEIVED
OCT 31 1955
DEPT. OF BLD'G. INSP.
CITY OF PORTLAND

Fire Dept. H. W. Mann
By R.

INQUIRY BLANK

ZONE _____

FIRE DIST. _____

CITY OF PORTLAND, MAINE
DEPARTMENT OF BUILDING INSPECTION

Letter
Verbal
By Telephone

Date 8/4/60

LOCATION 23 Brattle St OWNER Benjamin Baillargeon

MADE BY C. L. ... TEL. UL 483 82

ADDRESS _____

PRESENT USE OF BUILDING apartments NO. STORIES 3

LAST USE OF BUILDING _____ CLASS OF CONSTRUCTION _____

REMARKS _____

INQUIRY Replacing porch members and possibly foundations 3 floors. would less than 30 high. could 6x6 to 4x4 tapered concrete piers be used.

ANSWER No. 8x8 or 9" dia. round unless the precast piers are reimpred + design cert presented + footing used.

DATE OF REPLY 8/4/60 REPLY BY J. E. ...



gdo

**UNLIMITED BUSINESS ZONE
CITY OF PORTLAND, MAINE
DEPARTMENT OF BUILDING INSPECTION
COMPLAINT**

INSPECTION COPY

COMPLAINT NO. 55/136

Date Received 10/31/55

Location 23 Brattle St.

Owner's name and address Fred Sylvester, 610 Congress St.

Tenant's name and address _____

Complainant's name and address _____

Description: Poor draft in chimney.

Use of Building _____

Telephone _____

Telephone _____

Telephone _____

Location: 23 Brattle St.

NOTES:

*Change off at least 2 times
to follow further at this
late date*

*and
8/1/57*



APPLICATION FOR PERMIT TO REPAIR BUILDING

PERMIT ISSUED
Permit No. 112
OCT 24 1931

Third Class Building

To the INSPECTOR OF BUILDINGS, PORTLAND, ME. Portland, Maine, October 24, 1931
The undersigned hereby applies for a permit to repair the following described building in accordance with the Laws of Maine, the Building Code of the City of Portland, and the following specifications:

Location 23 Brattle Street Ward 5 Within fire limits? yes Dist. No. 1
Owner's name and address Exchange Real Estate Co. 84 Exchange St. Telephone F 9882
Contractor's name and address H. A. Brenner, 62 Munjoy St. Telephone _____
Use of building apartment house 3 families
No. stories _____ Height _____ ft., Gross area _____ sq. ft., Style of roof _____
Type of present roof covering _____

General Description of New Work

To Repair after Fire to former condition

CERTIFICATE OF OCCUPANCY
REQUIREMENT IS WAIVED.
Around chimney on 52 floor.
Faulty const.

If Roof-Covering is to be Repaired or Renewed

When last repaired? _____, Area then repaired _____ sq. ft.
Are repairs or renewal due to damage by fire? yes If so, what area damaged? _____ sq. ft.
Area of roof to be repaired now? _____ sq. ft.
Type of roofing to be used _____ sq. ft.
Trade name and grade of roof covering to be used _____ No. plies _____
Estimated cost \$ 15.

INSPECTION COPY

Signature of owner by Fred H. Small Exchange Real Estate Co. Fee \$.25

6306A

Ward 5 Permit No. 31/2172
 Location 23 Pratt St
 Owner Exchange Real Est Co
 Date of permit 10/24/31
 Notif. closing-in
 Inspn. (closing-in)
 Final Notif.
 Final Inspn. 12/30/31
 Cert. of Occupancy issued None

NOTES
 10/26/31 - No work started
 A. J. [unclear]
 12/2/31 - Unable to get in
 A. J. [unclear]
 12/7/31 - Same A. J. [unclear]

~~PERMIT TO REPAIR BUILDINGS~~

DESCRIPTION OF WORK
 Estimated cost \$ [unclear]
 Nature of work and description of building to be repaired or altered
 Name of contractor
 Name of architect

Contract to be secured or procured

FILL IN COMPLETELY AND SIGN WITH INK

PERMIT ISSUED
Permit No. _____



APPLICATION FOR PERMIT FOR HEATING, COOKING OR POWER EQUIPMENT

Portland, Maine, October 12, 1940

To the INSPECTOR OF BUILDINGS, PORTLAND, ME.

The undersigned hereby applies for a permit to install the following heating, cooking or power equipment in accordance with the Laws of Maine, the Building Code of the City of Portland, and the following specifications:

Location 23 Prattle Street Use of Building tehnacht awaiting house No. Stories 2 New Building Existing

Name and address of owner of appliance Fred Sylvester,

Installer's name and address C. O. Morton, West Cumberland

Telephone 26-12

General Description of Work

To install water air furnace in place of stove heat for first floor

IF HEATER, POWER BOILER OR COOKING DEVICE

Is appliance or source of heat to be in cellar? YES If not, which story _____ Kind of Fuel coal

Material of supports of appliance (concrete floor or what kind) concrete shield to be provided 12"

Minimum distance to wood or combustible material, from top of appliance or casing top of furnace, 15" from front of appliance 6" from sides or back of appliance 6"

Size of chimney flue 8x12 Other connections to same flue none

IF OIL BURNER

Name and type of burner _____ Labeled and approved by Underwriters' Laboratories? _____

Will operator be always in attendance? _____ Type of oil feed (gravity or pressure) _____

Location oil storage _____ No. and capacity of tanks _____

Will all tanks be more than seven feet from any flame? _____ How many tanks fireproofed? _____

Amount of fee enclosed? 1.00 (\$1.00 for one heater, etc., 50 cents additional for each additional heater, etc., in same building at same time.)

Signature of Installer C. O. Morton

INSPECTION COPY

INSPECTION OF COMPLETED WORK
CERTIFICATE OF UNDERWRITERS' REQUIREMENT IS WAIVED

4079C

Permit No. 40/1574

Location 23 Brattle St.

Owner Fred Silver

Date of Permit 10/7/40

Post Card sent

Notif. for insp.

Approval Tag issued

Oil Buffer Check List (date)

1. Kind of heater
2. Label
3. Anti-siphon
4. Oil storage
5. Tank distance
6. Vent Pipe
7. Fill Pipe
8. Gauge
9. Rigidity
10. Feed safety
11. Pipe sizes and material
12. Control valve
13. Ash pit vent
14. Temp. or pressure safety
15. Instruction card
16. Other

General Description of Work

NOTES

10/14/40

1 1/2" to 1 3/4" below

floor in kitchen with no vent

The chimney to which this is connected is only 1 1/2" in diameter and has a kitchen range connected to it on each of three floors above. As well as these there is an oil burn- ing room heater on 2nd floor which is not to be heated by range. It is to be heated by range. It is to be disconnected. I was unable to get into the 2nd story so can't tell whether there is anything except kitchen drain in this apartment. Third floor has only kitchen range connected to it. Chimney needs cleaning out. I doubt if chimney has ever used in cells before.

AGS



APPLICATION FOR PERMIT

Class of Building or Type of Structure All Metal
Portland, Maine, January 21, 1953

PERMIT ISSUED
00085
JAN 21 1953
CITY OF PORTLAND, MAINE

To the INSPECTOR OF BUILDINGS, PORTLAND, MAINE

The undersigned hereby applies for a permit to erect alter repair demolish install the following building structure equipment in accordance with the Laws of the State of Maine, the Building Code and Zoning Ordinance of the City of Portland, plans and specifications, if any, submitted herewith and the following specifications:

Location 21-23 Brattle St. Within Fire Limits? yes Dist. No. _____
Owner's name and address Fred Sylvester, 211 High St. Telephone _____
Lessee's name and address _____ Telephone _____
Contractor's name and address Eli Pelkey, RFD 1, Yarmouth Telephone _____
Architect _____ Specifications _____ Plans no No. of sheets _____
Proposed use of building _____ No. families _____
Last use 1 car garage (metal) No. families _____
Material _____ No. stories _____ Heat _____ Style of roof _____ Roofing _____
Other buildings on same lot _____
Estimated cost \$ _____ Fee \$ 50

General Description of New Work

To demolish existing 1 car metal garage

It is understood that this permit does not include installation of heating apparatus which is to be taken out separately by and in the name of the heating contractor. **PERMIT TO BE ISSUED TO**

Details of New Work

Is any plumbing involved in this work? _____ Is any electrical work involved in this work? _____
Is connection to be made to public sewer? _____ If not, what is proposed for sewage? _____
Height average grade to top of plate _____ Height average grade to highest point of roof _____
Size, front _____ depth _____ No. stories _____ solid or filled land? _____ earth or rock? _____
Material of foundation _____ Thickness, top _____ bottom _____ cellar _____
Material of underpinning _____ Height _____ Thickness _____
Kind of roof _____ Rise per foot _____ Roof covering _____
No. of chimneys _____ Material of chimneys _____ of lining _____ Kind of heat _____ fuel _____
Framing lumber—Kind _____ Dressed or full size? _____
Corner posts _____ Sills _____ Girt or ledger board? _____ Size _____
Girders _____ Size _____ Columns under girders _____ Size _____ Max. on centers _____
Studs (outside walls and carrying partitions) 2x4-16" O. C. Bridging in every floor and flat roof span over 8 feet.
Joists and rafters: 1st floor _____, 2nd _____, 3rd _____, roof _____
On centers: 1st floor _____, 2nd _____, 3rd _____, roof _____
Maximum span: 1st floor _____, 2nd _____, 3rd _____, roof _____
If one story building with masonry walls, thickness of walls? _____ height? _____

If a Garage

No. cars now accommodated on same lot _____, to be accommodated _____ number commercial cars to be accommodated _____
Will automobile repairing be done other than minor repairs to cars habitually stored in the proposed building? _____

APPROVED:

Miscellaneous

Will work require disturbing of any tree on a public street? no
Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? yes
Fred Sylvester

INSPECTION COPY

Signature of owner By: Eli Pelkey

RMS



FILL IN AND SIGN WITH INK

APPLICATION FOR PERMIT FOR HEATING, COOKING OR POWER EQUIPMENT

Portland, Maine, 16 January 1953

PERMIT ISSUED
00073
JAN 16 1953
CITY OF PORTLAND

To the INSPECTOR OF BUILDINGS, PORTLAND, MAINE

The undersigned hereby applies for a permit to install the following heating, cooking or power equipment in accordance with the Laws of Maine, the Building Code of the City of Portland, and the following specifications:

Location 23-25 Brattle St. Use of Building Dwelling No. Stories 3 New Building
Name and address of owner of appliance Fred Sylvester 610 Congress St., City Existing "
Installer's name and address Easternoil & Equipment Co. 27 Portland St., Portland, Maine Telephone 3-6495

To install Model A Easternoil Burner in connection with existing One Pipe Hot Air Furnace -(Replacement)

IF HEATER, OR POWER BOILER

Location of appliance _____ Any burnable material in floor surface or beneath? _____
If so, how protected? _____ Kind of fuel? _____
Minimum distance to burnable material, from top of appliance or casing top of furnace _____
From top of smoke pipe _____ From front of appliance _____ From sides or back of appliance _____
Size of chimney flue _____ Other connections to same flue _____
If gas fired, how vented? _____ Rated maximum demand per hour _____
Will sufficient fresh air be supplied to the appliance to insure proper and safe combustion? _____

IF OIL BURNER

Name and type of burner Model A Easternoil Labeled by underwriter's laboratories? Yes
Will operator be always in attendance? _____ Does oil supply line feed from top or bottom of tank? Bottom
Type of floor beneath burner Concrete
Location of oil storage Cellar Number and capacity of tanks 1 - 275
If two 275-gallon tanks, will three-way valve be provided? _____
Will all tanks be more than five feet from any flame? _____ How many tanks fire proofed? _____
Total capacity of any existing storage tanks for furnace burners None

IF COOKING APPLIANCE

Location of appliance _____ Any burnable material in floor surface or beneath? _____
If so, how protected? _____ Kind of fuel? _____
Minimum distance to wood or combustible material from top of appliance _____
From front of appliance _____ From sides and back _____ From top of smokepipe _____
Size of chimney flue _____ Other connections to same flue _____
Is hood to be provided? _____ If so, how vented? _____ Forced or gravity? _____
If gas fired, how vented? _____ Rated maximum demand per hour _____

MISCELLANEOUS EQUIPMENT OR SPECIAL INFORMATION

Amount of fee enclosed? 2.00 (\$1.00 for one heater, etc., 50 cents additional for each additional heater, etc., in same building at same time)

APPROVED:

OK 1-16-53 [Signature]

Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? Yes

Signature of Installer

[Signature]

INSPECTION COPY



FILL IN AND SIGN WITH INK

APPLICATION FOR PERMIT FOR HEATING, COOKING OR POWER EQUIPMENT

Portland, Maine, July 2, 1947

01567
JUL 2 1947

To the INSPECTOR OF BUILDINGS, PORTLAND, MAINE

The undersigned hereby applies for a permit to install the following heating, cooking or power equipment in accordance with the Laws of Maine, the Building Code of the City of Portland, and the following specifications:

Location 23 Brattle St. Use of Building Dwelling No. Stories 2 1/2 Building Existing " " Name and address of owner of appliance Mr. Fred Ennes, 23 Brattle Street Installer's name and address Pallotta Oil Co., 112 Exchange St. Telephone 4-2671

General Description of Work

To install oil burner in connection with existing warm air furnace

IF HEATER, OR POWER BOILER

Location of appliance or source of heat Type of floor beneath appliance If wood, how protected? Kind of fuel Minimum distance to wood or combustible material, from top of appliance or casing top of furnace From top of smoke pipe From front of appliance From sides or back of appliance Size of chimney flue Other connections to same flue If gas fired, how vented? Rated maximum demand per hour

IF OIL BURNER

Name and type of burner Fluid Heat Labelled by underwriter's laboratories? Yes Will operator be always in attendance? Does oil supply line feed from top or bottom of tank? bottom Type of floor beneath burner concrete Number and capacity of tanks 1 - 275 gal. Location of oil storage basement If two 275-gallon tanks, will three-way valve be provided? Will all tanks be more than five feet from any flame? yes How many tanks fire proofed? none Total capacity of any existing storage tanks for furnace burners none

IF COOKING APPLIANCE

Location of appliance Kind of fuel Type of floor beneath appliance If wood, how protected? Minimum distance to wood or combustible material from top of appliance From front of appliance From sides and back From top of smokepipe Size of chimney flue Other connections to same flue Is hood to be provided? If so, how vented? If gas fired, how vented? Rated maximum demand per hour

MISCELLANEOUS EQUIPMENT OR SPECIAL INFORMATION

Amount of fee enclosed? \$1.00.. (\$1.00 for one heater, etc., 50 cents additional for each additional heater, etc., in same building at same time.)

APPROVED:

OK. 7-2-47. V. Paul

Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? yes

INSPECTION COPY

Signature of Installer

Pallotta Oil Company BY: Joe Pallotta



Location, Ownership and detail must be correct, complete and legible.
 Separate application required for every building.
 Plans must be filed with this application.

Application for Permit for Alterations, etc.

To the

Portland, August 31, 1923 102

INSPECTOR OF BUILDINGS:

The undersigned applies for a permit to alter the following described building:—

Description of Present Bldg.

Location 23 Brattle Street Ward 5 in fire limits? no
 Name of Owner or Lessee JAMES M. SWAN Address 150 Forest Ave
 " Contractor not let
 " Architect
 Material of Building is wood Style of Roof ditch Material of Roofing asphalt
 Size of Building is 30ft feet long; 20ft feet wide. No. of Stories 2 1/2
 Cellar Wall is constructed of stone is inches wide on bottom and batters to inches on top.
 Underpinning is brick is inches thick; is feet in height.
 Height of Building 28ft Wall, if Brick; 1st 2d 3d 4th 5th
 What was Building last used for? tenement No. of families? 3
 What will Building now be used for? tenement (3 families)

PERMIT MUST BE OBTAINED BEFORE BEGINNING WORK

Detail of Proposed Work

Raise roof so as to make three stories high, put in partitions
 take down rear portion of building and close in end of house
 all to comply with the building ordinance

Estimated Cost \$ 5,000.

If Extended On Any Side

Size of Extension, No. of feet long?; No. of feet wide?; No. of feet high above sidewalk?
 No. of Stories high?; Style of Roof?; Material of Roofing?
 Of what material will the Extension be built? Foundation?
 If of Brick, what will be the thickness of External Walls? inches; and Party Walls? inches.
 How will the extension be occupied? How connected with Main Building?

When Moved, Raised or Built Upon

No. of Stories in height when Moved, Raised, or Built upon? Proposed Foundations?
 No. of feet high from level of ground to highest part of Roof to be?
 How many feet will the External Walls be increased in height? Party Walls?

If Any Portion of the External or Party Walls Are Removed

Will an opening be made in the Party or External Walls? in? Story.
 Size of the opening? How protected?
 How will the remaining portion of the wall be supported?

Signature of Owner or
 Authorized Representative

J. M. Swan

1.25

21-23 BRATTLE STREET

--	--	--	--	--	--	--	--	--	--	--

--	--



APPLICATION FOR PERMIT
DEPARTMENT OF BUILDING INSPECTIONS SERVICES
ELECTRICAL INSTALLATIONS

Date Aug. 4, 1982
 Receipt and Permit number A78726

To the CHIEF ELECTRICAL INSPECTOR, Portland, Maine:

The undersigned hereby applies for a permit to make electrical installations in accordance with the laws of Maine the Portland Electrical Ordinance, the National Electric Code and the following specifications:

LOCATION OF WORK: 23 Brattle St.
 OWNER'S NAME: Tom Esten ADDRESS: same

	FEES
OUTLETS:	
Receptacles _____ Switches _____ Plugmold _____ ft. TOTAL <u>1-30</u>	<u>3.00</u>
FIXTURES. (number of)	
Incandescent <u>x</u> Fluorescent _____ (not strip) TOTAL <u>1-10</u>	<u>3.00</u>
Strip Fluorescent <u>48</u> ft.	<u>3.00</u>
SERVICES:	
Overhead _____ Underground _____ Temporary _____ TOTAL amperes _____ ..	
METERS: (number of) _____	
MOTORS: (number of)	
Fractional _____	
1 HP or over _____	
RESIDENTIAL HEATING:	
Oil or Gas (number of units) _____	
Electric (number of rooms) _____	
COMMERCIAL OR INDUSTRIAL HEATING:	
Oil or Gas (by a main boiler) _____	
Oil or Gas (by separate units) _____	
Electric Under 20 kws <u>x</u> Over 20 kws _____	<u>5.00</u>
APPLIANCES: (number of)	
Ranges _____	
Cook Tops _____	
Wall Ovens _____	
Dryers _____	
Fans _____ <u>3</u> _____	
Water Heaters _____ <u>1</u> _____	
Disposals _____	
Dishwashers _____ <u>1</u> _____	
Compactors _____	
Others (denote) _____	
TOTAL	<u>7.50</u>
MISCELLANEOUS: (number of)	
Branch Panels _____	
Transformers _____	
Air Conditioners Central Unit _____	
Separate Units (windows) _____	
Signs 20 sq. ft. and under _____	
Over 20 sq. ft. _____	
Swimming Pools Above Ground _____	
In Ground _____	
Fire/Burglar Alarms Residential _____	
Commercial _____	
Heavy Duty Outlets, 220 Volt (such as we _____	
Circus, Fairs, etc. _____	
Alterations to wires _____	
Repairs after fire _____	<u>2.00</u>
Emergency Lights, battery <u>2</u> _____	
Emergency Generators _____	
INSTALLATION FEE DUE: _____	
FOR ADDITIONAL WORK NOT ON ORIGINAL PERMIT DOUBLE FEE DUE: _____	
FOR REMOVAL OF A "STOP ORDER" (304-16.b)	
TOTAL AMOUNT DUE: _____	<u>23.50</u>
	<u>11.50</u> Credit
	<u>12.00</u> Bal.

INSPECTION:

Will be ready on _____, 19__; or Will Call x

CONTRACTOR'S NAME: John Perry
 ADDRESS: 381 Danforth St., City
 TEL.: 773-5824
 MASTER LICENSE NO.: 3695 SIGNATURE OF CONTRACTOR: _____
 LIMITED LICENSE NO.: _____

INSPECTOR'S COPY — WHITE
 OFFICE COPY — CANARY
 CONTRACTOR'S COPY — GREEN

23 Brattle Street

33-A-3



SWAMP WALKER

MADE IN U.S.A.

CITY OF PORTLAND - HEALTH DEPARTMENT
LEAD POISONING and LEAD BASE PAINT DETECTION PROGRAM

Address: 23 Brattle Street - 33-A-3 Date: 9-8-75
 D.U. Location: First Floor, left Owner: Earl Brand
 Occupant: Mrs. Dorothy Damico Owner's Address: 234 Middle Street
 Children: 4 Ages: 4, 3, 2 and 3 mos. Project Area: General
 Referred By: Nursing Patient's Name: Frances Damico
 Building Type: Detached Building Condition: FR No. D.U.: 6

DIGITAL ANALYZER (LEAD DETECTOR) READINGS Mg/cm²

INTERIOR ROOMS:	Kitchen	Bath	Living	Dining	Bd#1	Bd#2	Bd#3	Bd#4	Fire Place	
									Other	Liv. Rm.
W. Sills			22.8		6.7		4.9			
Doors		4.6	27.5		12.7	19.5	9.3			
Walls										
M. Board			20.9			10.6				
Cabinets										
Furniture										
Door Frame										
Other	6.7				24.8	13.6				32.4
COMMON AREAS:	Hall	Stair	F.Porch	R.Porch	Entry	Other	Other	Other	Other	
Steps										
Rails										
Doors										
Walls										
Other										

THE AREAS ABOVE CONTAIN A HIGH CONCENTRATION OF LEAD BASED PAINT (OVER 2.0 mg/cm²). THESE AREAS MUST BE DETOXIFIED, ON OR BEFORE October 10, 1975.

Comments: Condition of paint: tight.

IF YOU HAVE ANY QUESTIONS REGARDING THIS MATTER, PLEASE DO NOT HESITATE TO CALL THIS OFFICE.

Housing Inspector: RPT Berg Health Dept. - Housing Division - 775-5451
 R. Berg Ext. 448

PORTLAND HEALTH DEPARTMENT - NURSING DIVISION - HOUSING INSPECTIONS DIVISION - LABORATORY

PS Form 3811, Nov. 1973

SENDER: Complete items 1 and 2. Add your address in the "RETURN TO" space on reverse.

1. The following service is requested (check one).
- Show to whom and date delivered..... 15¢
 - Show to whom, date, & address of delivery.. 35¢
 - DELIVER ONLY TO ADDRESSEE and show to whom and date delivered..... 65¢
 - DELIVER ONLY TO ADDRESSEE and show to whom, date, and address of delivery 85¢

2. ARTICLE ADDRESSED TO:

3. ARTICLE DESCRIPTION:

REGISTERED NO.	CERTIFIED NO.	INSURED NO.
	487442	

(Always obtain signature of addressee or agent)

I have received the article described above.

SIGNATURE
Caro Brand

DATE OF DELIVERY
9/11/75

5. ADDRESS (Complete only if requested)

6. UNABLE TO DELIVER BECAUSE:



RETURN RECEIPT, REGISTERED, INSURED AND CERTIFIED MAIL

23
R
H