25 Brattle Street



CLOC

Date June 1, 1983

FOR YOUR INFORMATION AS A NEW OWNER

The following excerpts are from Chapter 307 of the City of Portland Municipal Codes regulating "Minimum Standards for Housing" commonly referred to as the City of Portland Housing Code.

SECTION 1 - MINIMUM STANDARDS FOR DWELLINGS ESTABLISHED: There are hereby established minimum standards for buildings used for dwelling purposes in the City of Portland. All such buildings not now conforming to these standards will be required to meet such minimum standards, and buildings newly constructed or converted for such purposes shall meet such minimum standards. The standards set forth herein are intended to be minimum only and shall not be construed otherwise, nor shall they apply wherever a greater standard is required by any other ordinance or law.

SECTION 19 - RESTRICTION ON CONVEYANCE OF PROPERTY: It shall be a violation of this ordinance for any person to sell, transfer, or otherwise dispose of any property against which an order has been issued by the Health Officer under the provisions of this ordinance unless he shall first furnish to the grantee a true copy of any such order and shall at the same time notify the Health Officer in writing of the intent to so transfer either by delivering said notice to the Health Officer and receiving a receipt therefore or by registered mail, return receipt requested, giving the name and address of the person to whom the transfer is proposed. In the event of a violation of this section of this ordinance, such person shall be subject to a fine of not less than \$50.00 nor more than \$100.00, in addition to any fine which may be imposed for failure to comply with any order of the Health Officer as provided herein.

TANDERS SEEDERS SEEDERS SEEDERS SEEDERS

SECTION 20 - RESPONSIBILITY HEREUNDER MAY NOT BE TRANSFERRED: No cortract or agreement between owner and/or operator and occupant relating to compliance with the terms of this ordinance shall be effective in relieving any person of responsibility for compliance with the provision of this ordinance as set forth herein.

SECTION 24 - PENALTY: Any person violating any of the provisions of this ordinance or failing or neglecting or refusing to obey any order or notice of the Health Officer issued hereunder shall be subject to a fine or not less than \$50.00 nor more than \$1,000.00 and each day's violation shall be considered to be a separate offense.

RE: 25 Brattle St. 33-A-3 Gen. - Owner: Harrison Sawyer, P.O. Box 7225, Portland 04112

AS THE NEW OWNER of the above, we must inform you that SECTION 19 - RESTRICTION ON CONVEYANCE OF PROPERTY, does apply to this property as the Housing Inspection Division, Health & Social Services has an open file in this case.

If you have any questions regarding this matter, please call the Housing Inspection Div. at 775-5451, Ext. 318 or 319.

· C L

And the second

NOTICE OF HOUSING CONDITIONS

			MARTIT
OTTV	VE	PORTLAND,	MATHE
CILL	Or.	I OH I HILL	

Department of Planning & Urban Development Inspections Services Division Tel. 775-5451 - Ext. 311 - 318 - 319

Mr. Harrison Sawyer P. O. Box 7225 Portland, Maine 04112 DU 3

Ch. 33 Blk. A Lot 3 Location: 25 Brattle St.

Project: Gen. Issued: June 1, 1983 Expires: Sept. 1, 1983

Dear Mr. Sawyer:

You are hereby notified, as owner or agent, that an inspection was made of the premises at 25 Brattle Street, Portland, Maine by Code Enforcement Officer

Michael Nucent Violations of Chapter 307 of the Municipal Codes (Minimum Standards for Housing) were found as described in detail on the attached "Housing Inspection Report".

In accordance with the provisions of the above mentioned Code, you are hereby ordered to correct those defects on or before Sept. 1, 1983. If you are unable to make such repairs within the specified time, you may contact this office to arrange a satisfactory repair schedule. If we do not hear from you within ten (10) days from this date, we will assume the repairs to be in progress and, on re-inspection within the time set forth above, will anticipate that the premises have been brought into compliance with Code Standards.

Please contact this office if you have any questions regarding this Notice.

Your cooperation will aid this Department in it's goal to maintain decent, safe, and sanitary housing for all of Portland's residents.

Very truly yours, Joseph E. Gray, Jr., Director of Planning & Urban Development

Lyle D. Noyes,

Inspection Services Division

Cone Enforcement Officer - Michael Nugent (10)

Attachments:

imr

•

HOUSING INSPECTION REPORT

OWNER:	Harrison	Sawver
CMMPRC	Harrison	Dawyer

CODE ENFORCEMENT OFFICER - Michael Nugent (10)

25 E attle Street, Portland, Maine 33-A-3 Gen. Notice of Housing Conditions DATED: June 1, 1983 EXPIRES: Sept. 1, 1983

ITEMS LISTED BELOW ARE IN VIOLATION OF "CHAPTER 307 OF THE MUNICIPAL CODES - MINIMUM STANDARDS FOR HOUSING" AND MUST BE CORRECTED.

S'ANDARDS FOR HOUSERG . LIS 1999	SEC. (S)
 REAR EXTERIOR - porch - cracked cement. REAR EXTERIOR - wall - broken siding. REAR EXTERIOR - window - rotted trim. FIRST FLOOR FRONT & THIRD FLOOR REAR HALL - stairways - inoperative lights. OVERALL - cellar - dampness. 	3-a 3-a 3-a 8 3-a
SECOND FLOOR OVERALL 6. KITCHEN - wall - peeling wall paper. 7. KITCHEN - window - worn sash, needs glazing. 8. KITCHEN - floor - worn floor. 9. KITCHEN - sink - inoperative hot water. 10. LIVING ROOM - window - worn sash. 11. BATHROOM - window - worn sash. 12. BATHROOM - floor - worn floor. 13. BATHROOM - toilet - leaking. 14. BATHROOM - floor - mildew. 15. BEDROOM - wall - loose and cracked plaster. 16. BEDROOM - window - worn sash.	3-b 3-c 3-c 3-c 3-c 3-b 3-b 3-c
THIRD FLOOR OVERALL 17. KITCHEN - ceiling - buckled tiles. 18. KITCHEN - floor - missing tiles. 19. LIVING ROOM - window - broken counterbalance cord. 20. FRONT BEDROOM - ceiling and wall - loose paint. 21. REAR BEDROOM - ceiling - broken plaster. 22. REAR BEDROOM - wall - peeling wall paper. 23. FRONT HALL - ceiling and wall - peeling paint and plaster.	3-b 3-c 3-b 3-b 3-b 3-b

*WHEN MAKING YOUR REPAIRS, FIRST PRIORITY IS TO BE GIVEN TO ITEMS WITH ASTERISKS, AS THEY CONSTITUTE EXTREME HAZARDS TO THE HEALTH OR SAFETY OF THE OCCUPANTS OF THIS STRUCTURE.

NOTICE OF HOUSING CONDITIONS

		TODAL AND	MAINE
CITY	OF	PORTLAND,	

Department of Planning & Urban Development Inspections Services Division Tel. 775-5451 - Ext. 311 - 318 - 319

Mr. Harrison Sawyer P. O. Box 7225 Portland, Maine 04112

Ch. 33 Blk. A Lot 3 Location: 25 Brattle St.

San Jaco Caralle Market Control

Project: Gen. Issued: June 1, 1983 Expires: Sept. 1, 1983

Dear Mr. Sawyer:

Michael Nucent. Violations of Chapter 307 of the Municipal Codes (Minimum Standards for Housing) were found as described in detail on the attached "Housing"

In accordance with the provisions of the above mentioned Code, you are hereby ordered to correct those defects on or before Sept. 1, 1983

to make such repairs within the specified time, you may contact this office to arrange a satisfactory repair schedule. If we do not hear from you within ten (10) days from this date, we will assume the repairs to be in progress and, on re-inspection within the time set forth above, will anticipate that the premises have been brought into compliance with Code Standards. with Code Standards.

Please contact this office if you have any questions regarding this Notice.

Your cooperation will aid this Department in it's goal to maintain decent, safe, and sanitary housing for all of Portland's residents.

Very truly yours, Joseph E. Gray, Jr., Director of Planning & Urban Development

By
Lyle D. Noyes,
Inspection Services Division

Code Enforcement Officer - Michael Nugent (10)

Attachments:

imr

HOUSING INSPECTION REPORT

		CODE ENFORCEME	OFFICE	R - Mìcha	el Nuge	nt (10)
		CODE ENFORCEME	MAI OLITO	-		
OWNER: Harrison S	awyer	- a Con	Notice	of Housing	, Condit	ions.
25 Brattle Street,	POLCIGIO,	Sept. le	1983			
DATED: June 1, 19)83 EAS	and House Sor	OF THE M	MUNICIPAL (CODES -	NINIMUM
DATED: June 1, 19	W ARE IN VIOLATION	OF "CHAPTER 30"				

STANDARDS FOR HOUSING" AND MUST BE CORRECTED.

ITEMS LISTED BELOW ARE IN STANDARDS FOR HOUSING" AND MUST BE CORRECTED.	SEC.(S)
1. REAR EXTERIOR - porch - cracked cement.	3-a 3-a
 REAR EXTERIOR - porch - broken siding. REAR EXTERIOR - wall - broken siding. REAR EXTERIOR - window - rotted trim. REAR EXTERIOR - window - rotted trim. FIRST FLOOR FRONT & THIRD FLOOR REAR HALL - stairways - inoperative lights. OVERALL - cellar - dampness. 	8 3 - a
5. OVERALL - Cellal	3-b
TOOR CUEDALL	3-c
SECOND FICOR OVERALL - peeling wall paper. 6. KTICHEN - wall - peeling wall paper. worn sash, needs glazing.	3 - b
6. KITCHEN - wall - peeling wall parts 7. KITCHEN - window - worn sash, needs glazing.	6-a
7. KITCHEN - WILLOW floor. 8. KITCHEN - floor - worn floor.	3-c
	3-c
	3-b
	6 - d
	3-b
13 BATHROOM - COILEC - ICC.	3-b 3-c
14. BATHROOM - Floor and cracked plaster.	3-0
15. BEDROOM - Wall worn sash. 16. BEDROOM - window - worn sash.	` .
- -	3-b 3-b
THIRD FLOOR OVERALL buckled tiles.	3-c
	3-b
10 VINCHEN = 11001 MILLS COUNTERPALATICE COLOR	3-b
19. LIVING ROOM - WIRE and Wall - loose Paint.	3-b
20. FRONT BEDROOM - Ceiling broken plaster.	3-b
21. REAR BEDROOM - ceiling bloken place. 22. REAR BEDROOM - wall - peeling wall paper. 23. FRONT HALL - ceiling and wall - peeling paint and plaster.	3.2
23. FRONT HALL " CEITING TO SEE THE SECOND TO	AS THEY

*WHEN MAKING YOUR REPAIRS, FIRST PRIORITY IS TO BE GIVEN TO ITEMS WITH ASTERISKS, AS THEY CONSTITUTE EXTREME HAZARDS TO THE HEALTH OR SAFETY OF THE OCCUPANTS OF THIS STRUCTURE.



CITY OF PORTLAND

JOSEPH E. SRAY, JR. DIRECTOR OF PLANNING AND URBAN DEVELOPMENT

June 1, 1983

Mr. Harrison Sawyer
P. O. Box 7225
Portland, Maine 04112

Re: 25 Brattle St.

During a recent inspection by Code Enforcement Officer Michael Nugent of the property owned by you at 25 Brattle Street, it was not that smoke detectors were missing in the following areas: Dear Sirs:

"PER THE MAINE STATE STATUTES, "SEC. 1.25 MRSA 2464", WITHIN TEN (10) DAYS OF THE DATE OF THIS NOTICE, A SMOKE ALARM MUST BE INSTALLED IN EACH AREA OF THIS STRUCTURE, AS LISTED BELOW:

First, Second & Third Floor

THE FIRE PREVENTION BUREAU HAS BEEN NOTIFIED OF THE ABOVE CONDITION(S).

PLEASE CALL THE FIRE PPEVENTION BUREAU AT 775-5451, EXT. 354, IF YOU HAVE ANY QUESTIONS REGARDING THE INSTALLATION OF THE REQUIRED SMOKE ALARMS."

Sincerely yours, Joseph E. Gray, Jr., Director of Planning & Urban Development

Inspection Services Division

• PORTLAND, MAINE 04101 • TELEPHONE (207) 775-5451

C Les did Ch. 33 Blk. A Lot 3 Location: 25 Brattle St. Project: Gen.
Issued: February 3, 1983
Expires: Fecil 3, 1983 Very truly yours, Joseph E. Gray, Jr., Director of Planning & Urban Development Lyle D. Noyes, Inspection Services Division

NOTICE OF HOUSING CONDITIONS

CITY OF PORTLAND, MAINE

Department of Planning & Urban Development Inspections Services Division Tel. 775-5451 - Ext. 311 - 318 - 319

P. O. Box 3646
Portland, Maine 04101

Camara & Esten Inc.

You are hereby notified, as owner or agent; that an inspection was made of the premises Dear Sir: . Violations of Chapter 307 of the Municipal Codes (Minimum at 25 Brattle St., Portland, Me. Standards for Housing) were found as described in detail on the attached "Housing Inspection Percent"

In accordance with the provisions of the above mentioned Code, you are hereby ordered to correct those defects on or before April 3, 1983

to make such repairs within the specified time, you may contact this office to arrange to make such repairs within the specified time, you within ten (10) days from a satisfactory repair schedule. If we do not hear from you within ten (10) this date, we will assume the repairs to be in progress and, on re-inspection within the this date, we will assume the repairs to be in progress and, on re-inspection within the time set forth above, will anticipate that the premises have been brought into compliance with Code Standards. Inspection Report".

Please contact this office if you have any questions regarding this Notice.

Your cooperation will aid this Department in it's goal to maintain decent, safe, and sanitary housing for all of Portland's residents.

Attachments:

jmr

HOUSING INSPECTION REPORT

HOUSING INSTRU	120)
OFFICER - M. Nugent	(10)
OWNER: Camara & Esten Inc.	
DALLO OD "CHAPTER JO"	Sec.(S)
STANDAGO	3 - a
1. REAR EXTE	3-a nts. 8 4-b 3-a
FIRST FLOOR No smoke detectors.	3-b 3-c
SECOND FLOOR OVERALL 7. KITCHEN - wall - peeling wall paper. 8. KITCHEN - window - worn sash, needs glazing. 8. KITCHEN - window - worn floor. 9. WITCHEN - floor - worn floor.	3-b 6-a 3-c
8. KITCHEN - window - World Stoor. 9. KITCHEN - floor - worn floor. 10. KITCHEN - sink - inoperative hot water. 11. KITCHEN - sink - worn sash. 12. KITCHEN - window - worn sash.	3-c
	3-b 6-d
10. KITCHIS ROOM - WINDOW - WOTH SASH. 11. LIVING ROOM - WINDOW - WOTH SASH. 12. BATHROOM - WINDOW - WOTH Floor. 13. DATHROOM - Floor - WOTH Floor.	3-b
	3-b
12 BALLINGS LE LEGALLIST	3-c
14. BATHROOM - tollet - mildew. 15. BATHROOM - floor - mildew. 16. BEDROOM - wall - loose and cracked plaster. 16. BEDROOM - wall - loose and cracked plaster.	
16. BEDROOM - wall - loose and window - worn sash. 17. BEDROOM window - worn sash. No smoke detectors.	3 - b
NO Provide a	3-b
TH'RD FLOOR OVERALL 18. KITCHEN - ceiling - buckled tiles. 18. KITCHEN - floor - missing tiles. **TITCHEN - floor - missing tiles.**	3-c
TH'RD FILOR 18. KITCHEN - ceiling - buckled tries. 19. KITCHEN - floor - missing tiles. 19. KITCHEN - grown - broken counterbalance cord. 20. LIVING ROOM - window - broken paint. 21. TRONT BEDROOM - ceiling and wall - loose paint.	3-p
KITCHEN - floor - missing broken counterparante	3-b
20. LIVING ROOM — William and Wall — 1005e Punt	3 - b 3 - b
19. KITCHEN - floor - Missing Counterbalance Counte	3-2
77 REAL DATE 17311 - Deciting 1 11mg blaster out 1	,
- 23. Right - cailing and war	CTERISKS, AS THEY
23. REAR BEDROOM - Wall - Peeling Plant 24. FRONT HALL - Ceiling and wall - Peeling Plant 24. FRONT HALL - Ceiling and wall - Peeling Plant 32. FRONT HALL - Ceiling and wall - Peeling All - Ceiling All	THIS STRUCTURE.
*WHEN MAKING YOUR REPAIRS TO THE HEALTH OR SALETT	
THE EXTREME MACHINE	

CONSTITUTE EXTREME HAZARDS TO



CITY OF PORTLAND

JOSEPH E. GRAY, JR. DIRECTOR OF PLANNING AND URBAN DEVELOPMENT

February 3, 1983

Camara & Esten Inc. P. O. Box 3646 Portland, Maine 04101

33-A-3 Re: 25 Brattle St.

During a recent inspection by Code Enforcement Officer Michael Nugent of the property owned by you at 25 Brattle Street, it was I that smoke detectors were missing in the following areas:

"PER THE MAINE STATE STATUTES, "SEC. 1.25 MRSA 2464", WITHIN TEN (10) DAYS OF THE DATE OF THIS NOTICE, A SMOKE ALARM MUST BE INSTALLED IN EACH AREA OF THIS STRUCTURE, AS LISTED BELOW:

First Floor & Second Floor 4 THIRD FLOOR

THE FIRE PREVENTION BUREAU HAS BEEN NOTIFIED OF THE ABOVE CONDITION(S).

PLEASE CALL THE FIRE PREVENTION BUREAU AT 775-5451, EXT. 354, IF YOU
HAVE ANY QUESTIONS REGARDING THE INSTALLATION OF THE REQUIRED SMOKE ALARMS."

Sincerely yours, Joseph E. Gray, Jr., Director of Planning & Urban Development

Lyle D. Noyes

Inspection Services Division

389 CONGRESS STREET • PORTLAND, MAINE 04101 • TELEPHONE (207) 775-5451

icer Nucent (10)

NOTICE OF HOUSING CONDITIONS

CITY	OF	PORTLAND,	MAINE
------	----	-----------	-------

Department of Planning & Urban Development Inspections Services Division Tel. 775-5451 - Ext. 311 - 318 - 319

Camara & Esten Inc. P. O. Box 3646 Portland, Maine 04101

Ch. 33 Blk. A Lot 3 Location: 25 Brattle St.

Project: Gen. Issued: February 3, 1983 Expires: April 3, 1983

You are hereby notified, as owner or agent, that an inspection was rade of the premises Dear Sir:

- Violations of Chapter 307 of the Municipal C les (Minimum Standards for Housing) were found as described in detail on the attach. "Housing

In accordance with the provisions of the above mentioned Code, you are hereby ordered to correct those defects on or before In accordance with the provisions of the above mentioned code, you are hereby ordered.

If you are unable to correct those defects on or before April 3, 1983

to make such repairs within the specified time, you may contact this office to arrange or make such repairs within the specified time, you may contact this office to arrange or the specified time, you may contact this office to arrange or the specified time, you may contact this office to arrange or the specified time, you may contact this office to arrange or the specified time, you may contact this office to arrange or the specified time, you may contact this office to arrange or the specified time, you may contact this office to arrange or the specified time, you may contact this office to arrange or the specified time, you may contact this office to arrange or the specified time, you may contact this office to arrange or the specified time, you may contact this office to arrange or the specified time, you may contact this office to arrange or the specified time, you may contact this office to arrange or the specified time, you may contact this office to arrange or the specified time, you may contact this office to arrange or the specified time, you may contact this office to arrange or the specified time, you may contact this office to arrange or the specified time, you may contact this office to arrange or the specified time. Inspection Report". to make such repairs within the specified time, you may contact this office to arrange a satisfactory repair scheduld. If we do not hear from you within ten (10) days from this date, we will assume the repaire to be in progress and an assignment of the in progress and an assignment of the progress and assignment of the progress and an assignment of the progress and an assignment of the progress and assignment of the pro a satisfactory repair schedule. If we do not hear from you within ten (10) days from this date, we will assume the repairs to be in progress and, on re-inspection within the time set forth above, will anticipate that the premises have been brought into compliance with fode Standards

Please contact this office if you have any questions regarding this Notice. with Code Standards.

Your cooperation will aid this Department in it's goal to maintain decent, safe, and sanitary housing for all of Portland's residents.

Very truly yours, Joseph E. Gray, Jr., Director of Planning & Urban Development

Attachments:

jmr

Lyre Di Moyes, Inspection Services Division

HOUSING INSPECTION REPORT

HOUSING INSPECTION TO THE CONTROL OF	1	i
OFFICER - M. Nugent ([0]	le le
MNER: Camara & Esten Inc. 25 Brattle Street, Portland, Maine 33-A-3 GEN. Notice of Housing Conduction EXPIRES: April 3, 1983 DATED: February 3, 1983 ITEMS LISTED BELOW ARE IN VIOLATION OF "CHAPTER 307 OF THE MUNICIPAL CODES MININ STANDARDS FOR HOUSING" AND MUST BE CORRECTED.	SBC • (S) 3-a 3-a	The second secon
1. REAR EXTERIOR - porch - cracked cement. 2. REAR EXTERIOR - wall - broken siding. 3. REAR EXTERIOR - window - rotted trim. 4. FIRST FLOOR FRONT & THIPD FLOOR REAR HALL - stairways - inoperative lights 5. OVERALL - cellar - debris. 6. OVERALL - cellar - dampness.	;. 8 4b 3a	
SECOND FICOR OVERALL 7. KITCHEN - wall - peeling wall paper. 8. KITCHEN - window - worn sash, needs glazing. 9. KITCHEN - floor - worn floor. 10. KITCHEN - sink - inoperative hot water. 11. LIVING ROOM - window - worn sash. 12. BATHROOM - window - worn sash. 13. BATHROOM - floor - worn floor. 14. RATHROOM - toilet - leaking. 15. BATHROOM - wall - loose and cracked plaster. 16. BEDROOM - window - worn sash. No smoke detectors.	3-b 3-c 3-b 6-a 3-c 3-b 5-d 3-b 3-b 3-c	
THIRD FLOOR OVERALL. 18. KITCHEN - Ceiling - buckled tiles. 19. KITCHEN - floor - missing tiles. 19. LIVING ROOM - window - broken counterbalance cord. 20. LIVING ROOM - window - broken plaster. 21. FRONT BEDROOM - Ceiling - broken plaster. 22. REAR BEDROOM - wall - peeling wall paper. 23. REAR BEDROOM - wall - peeling plaster and paint. 24. FRONT HALL - Ceiling and wall - peeling plaster and paint. *WHEN MAKING YOUR REPAIRS, FIRST PRIORITY IS TO BE GIVEN TO ITEMS WITH AS CONSTITUTE EXTREME HAZARDS TO THE HEALTH OR SAFETY OF THE OCCUPANTS OF THE CONSTITUTE EXTREME HAZARDS TO THE HEALTH OR SAFETY OF THE OCCUPANTS OF THE CONSTITUTE EXTREME HAZARDS TO THE HEALTH OR SAFETY OF THE OCCUPANTS OF THE CONSTITUTE EXTREME HAZARDS TO THE HEALTH OR SAFETY OF THE OCCUPANTS OF THE CONSTITUTE EXTREME HAZARDS TO THE HEALTH OR SAFETY OF THE OCCUPANTS OF THE CONSTITUTE EXTREME HAZARDS TO THE HEALTH OR SAFETY OF THE OCCUPANTS OF THE CONSTITUTE EXTREME HAZARDS TO THE HEALTH OR SAFETY OF THE OCCUPANTS OF THE CONSTITUTE EXTREME HAZARDS TO THE HEALTH OR SAFETY OF THE OCCUPANTS	3-b 3-c 3-b 3-b 3-b TERISKS, AS TH	ŒY

Charles of the second second



CITY OF PORTLAND

JOSEPH E. GRAY, JR.
DIRECTOR OF PLANNING
AND URBAN DEVELOPMENT

February 3, 1983

Camara & Esten Inc. P. O. Box 3646 Portland, Maine 04101

Re: 25 Brattle St. 33-A-3 Gen

Dear Sirs:

During a recent inspection by Code Enforcement Officer Michael Nugent of the property owned by you at 25 Brattle Street, it was noted that smoke detectors were missing in the following areas:

"PER THE MAINE STATE STATUTES, "SEC. 1.25 MRSA 2464", WITHIN TEN (19) DAYS OF THE DATE OF THIS NOTICE, A SMOKE ALARM MUST BE INSTAL' V EACH AREA OF THIS STRUCTURE, AS LISTED BELOW:

First Floor & Second Floor 4 THIKD FLOOR

THE FIRE PREVENTION BUREAU HAS BEEN NOTIFIED OF THE ABOVE CONDITION(S). PLEASE CALL THE FIRE PREVENTION BUREAU AT 775-5451, EXT. 354, IF YOU HAVE ANY QUESTIONS REGARDING THE INSTALLATION OF THE REQUIRED SMOKE ALARMS."

Sincerely yours, Joseph E. Gray, Jr., Director of Planding & Urban Development

Inspection Services Division

Code Enforcement Officer - Nugent (10)

imr

389 CONGRESS STREET • PORTLAND, MAINE 04101 • TELEPHONE (207) 775-5451

Housing Inspection Division

of Portland

1) Insp. Name M. NUGENT

Maty of Portland	STRUCTURE INSPECTION SCHED	ULE		nsp.	Form No. 7	
	STRUCTURE INSPECTION SCHED Proj.Code 5)Assr's: Chart 6)Bl. 7)Lot 8)C 4)Suft. 15)Direct 16)Street Name ARA 4 ESTEN INC. 3646	ensus: 11445	17) 19)St	St.Design.	2	
18)Owner or Agent: (47/4) 21)Address: PO BCX	136452 MANUE MAINE	OM I OF	dg. Type (30) Si	Zip Code: Const.	Mat. 32)0.Bs	がんかられた。
33)C.H. 34)Photo 35)Zones Viol. No. Remedy Cond. Vio	Rm. Units 126) Occ R U s 273 Oct Program (Program of State of Stat	NC RIFE	ype EXED	2 3A 2 3A	Rem. Date	
3 20	SIDING TRIM LIGHTS	RE 13 SE OA		2 3 A 2 8 2 4B	ł.	A CONTRACTOR OF THE PROPERTY O
*4	DEBRIS DAMPNESS	OA	CE	2 3A		
	- UNDENT	And the second s	TORENIN	or in property of the control of the	The same of the sa	Andrew Andrews September 1

city of Portland

Housing Inspection Division

STRUCTURE INSPECTION SCHEDULE

1) Insp. Name M, NUGENT

1 (Va) 1 7) Total 5	8)Census: Tract 9)Blk. 10)lnsp. 11)Form No.
2) Insp. Date 3) Insp. Type 4) Proj. Code 5) Assr's: Chart 6) Bl. 7) Lot 8	8)Census: 11act 17)St.Design.
2) insp. Bate 37 CO (10) Suft 15) Direct 16) Street Name	17/31/1003-g-V
12)House No. 13)Sec. H. No. 14)Out 2.	19)Status 20)Bldg's Rat.
12) House Inc. 12) House or Agent: CAMARA & ESTEN INC.	480
10)04110-	
21) Address: PO BOX 3646	Zip Code: 04/0/
22) City and State: DORTE AND MAINE 23) D. Units 24) Occ. D. U. s 25) Rm. Units 26) Occ. R U s 27) No. Occupants 28)	No. 13 11 129 Bldg. Type 30) Stories 31) Const. Mat 32) 0.8s
22/03/2 Under 12(4) Occ. D. U. S. 25) Rm. Units 26) Occ. R. U. S. 27) No. Occupants 28	Bin. Fac 39) Disp 40) Closing Da.
- 126 And 131 Land USE 77 D.D.	Bth Fac 39) Disp 40) Closing Bin.
33)C.H. 34) Photo 35) Zoned Fc1 36) Art 321 Land 55	Room Arez Resp. Code Sect. Viol. Rem. Date
YES NO	No. L Type Type Party Viol. Rem. Date
No Remedy Cond. Violation nestrape	RE EMO 2 3A
1 CR CEMENT	6W 0 2 A
- S. X /1/C	RETURN
2 BR SIDING	RE W 2 3A
3 RO TRIM	1/3 5% HA SEW 2 8
4 IN LIGHTS	13 RE 1917 DE 2 48
*7	THE ELECTION OF THE PROPERTY O
45 DERRIS	DACE 2 3A
* DAMPNESS	- OA SS
6	
5	
\$.	

NO VIOCATIONS EXCREPT NO SMOKE I Housing Inspection Division DWELLING UNIT SCHEDULE City of Portland FLR.# LOCATION ANTS NAME رىر RAMDA Ck'ng. Furn Hot Rent Rent + Lead Survey Child Results CODE <u>Un.10</u> BATHROOM 3(b) Plaster - L, C, M - Ceiling/Walls CODE Plaster - L, C, M - Ceiling/Walls
Window - loose, broken glass, glaze
Sash/Frames - broken, missing, worn
Floor - loose, worn, dam., buckled
Door - knob/lk - missing - Panels/Frames dam.
Toile - k - brkn, loose, leaks, Seat, lise crkd.
Lavatory - ipped, crkd, leaks, trap leaks
Bathtub/Shower - leaks cross connection
Wentilation Yes No KITCHEN Plaster - L, C, M, - Ceiling/Walls Windows - loose, broken glass, glaze 3(b) 3(c) Sash/Frames - broken, missing, worn
Floor - loose, worn, dam., buckled
Doors - Knob/lk - missing - Panels/Frames dam. 3(b) Doors - Knob/lk - missing - Panels/Frames da Counter/Stor. Space Yes No Sink - chipped, cracked, leaks Range - improper stack, flue, vent Refrigerator Space Yes No Plumbing (a) 6(a) Water Supply Hot Cold Electrical (a) Sanitation (a) 3 (b) 6(d) 6(4) 6 (d) 3(e) 6(c) 6(c) () Sanitation (b) CODE () Sanitation (a) 3(b) 3(c) CODE Plaster - L, C, M - Ceiling/Wails 3(b) windows - toose, broken, glaze
Sash/Frames - broken, missing, worn
Floor - loose, worn, damaged
Doors - Knobs/lk - missing, Panels/Frames dam.
Electrical (d) Windows - loose, broken, glaze Plaster - L, C, M, - Ceiling/Walls 3(c) Windows - loose, broken, glaze Sash/Frames - broken, missing, worn
Floor - loose, worn, damaged
Door - knob/lk - missing - Panels/Frames dam. 3(b) 3(c) 3(b) 3(b) Sanitation (d) Electrical (c) Code Sanitation (c) Bedrooms and/or other rooms 3(b) Plaster - L, C, M - Ceiling/Walls Windows - Loose, broken, glaze Sash/Frames - broken, missing, Floors - loose, worn, damaged

Door - knobs/lk - missing - Panels/Frames dam. Electrical (e) Sanitation (e) Clothes Closet Yes Sanitation - Vermin O Plumbing

REMARKS:

Housing Inspection Division NO SMOKE DEFECTORS

DWELLING UNIT SCHEDULE City of Portland 2) INSP. 9) #Peo 10) #A11'd 11)Slp.Rms. 1) INSP. Date 10 124 5)Flr.# 6)Location 7)Rmg.Tp. 8)#Rms. 21) Ck'ng DU OA 19)Hot Water 20)Dual Egress 12)Child Under 10 Code Room Type Code Sect. Violated Area Type Rem. - Date Party 30 WA KI DE WI 2 WD 8 3B PL 9 WO IN 10 WI WO WI WO 12 3B WO 13 LE 312 A WA WI WO

The in meaning property the second man

r. eferan edd

NO SMOKE DETECTOR Housing Inspection Division
DWELLING UNIT SCHEDULE City of Portland 1) INSP. Date 19)Hot Water 20)Dual 16)Rent Egress V&S Code Resp. Party Area Violated Type Type 2 3-6 01 Cond. BU FL 4927333 -3-C MI OUNTER BACANCE FR 60 RE PRASTER BR RE PE

The state of the s

The state of the s

CBB . 05L

Date: December 28, 1981

CITY OF PORTLAND

Department of Urban Development Housing Inspections Division Telephone: 775-5451 - Extension 311 - 312

Thomas Esten Barton Camara Box 3643 Portland, Maine .

Re: Premises located at 25 Brattle St

Dear Mr. Esten:

A re-inspection of the premises noted above was made on <u>December 28, 1981</u> by Housing Inspect r <u>Gayton Bartlett.</u>

This is to certify that you have complied with our request to correct the violation of the Municipal Codes relating to housing conditions as described in our "Notice of Housing Conditions" dated November 15, 1978 .

Thank you for your cooperation and your efforts to help us maintain decent, safe and sanitary housing for all Portland residents.

In order to aid in the preservation of Portland's existing housing inventory, it shall be the policy of this department to inspect each residential building at least once every five years. Although a property is subject to re-inspection at any time during the said five-year period, the next regular inspection of this property is scheduled for December 1986 •

Sincerely yours,

Joseph E. Gray, Jr., Director of Planning and Urban Development

Lyle D. Noyes
Inspection Services Division

Bartlett (6) Code Enforce

Mary Control

· Carlotti

14.337.38E

The state of the s

ADMINISTRATIVE HEARING DECISION

City of Portland Department of Neighborhood Conservation Housing Inspections Division Telephone: 775-5451 - Ext. 448 358	Date
Thomas Esten Barton Camara Box 3643 Portland, Maine	
Re: Premises located at 25 Brattle Street, Portland	i, Haine Gan. 33-A-2
Dear Sira:	
You are hereby notified that <u>a reinspection and your</u>	request for additional time
on	order to complete the work in
Please notify this office if all violations are correct dates, so that a "Certificate of Compliance" may	nentioned
In Attendance: Mr. Barton Camara M. Wing	ay, Jr., Director i Conservation
W	Lyle D. Noyes, Chief of Housing Inspections

ن جوزمونق

25 Brattle Street, Portland, Maine Gen. 33-A-2 Remaining Housing Code Violations to be corrected within time extension granted on attached "Administrative Hearing Decision" NORC - Nov. 15, 1978

9-2(2-FRONT-EXTERIORreplace-rotted-gutter-(entry-way canopy). 2	18 & or 3a
The state of the s	34-
1-30 3. FIRST FLOOR RIGHT EXTERIOR STAIRS Secure local treat.	3a
	3 a-
	3e-
5. OVERALL EXTERIOR ROOF TEPAL WINDOW replace broken of op-	3b
	3c
8 - SECOND FLOOR REAR HALL WINDOW TOPIECE WORN Cash.	
9-b-overing 1 more	
AND THE CORP.	3c
SECOND FLOOR SWEITCHEN WINDOW - replace broken glass.	35
9-2118 EITCHEN & NATHROCK-FLOORS - Keplose worn floors:	
9.241. MINDON - Noplace worn each	30.
9-26 12. LIVING-ROOM HINDON - replace broken and worn each .	30
9-26 12 LIVING ROOM HINDOW - Topiace or occur and a cash.	
4.14 12 TEVT PRONT PEDBOOM PERSON	
	25
THIRD FLOOR	30)
14 APPT DEAD REDECCH CELLERY	
Suggestion: You may wish to install single station smoke detectors in front and re	eat
Suggestion: You may wish to install single Station Smoke	
hell of first, second a time and the	
CUT COOD OF THE HAT US	

LOCATION 2 - Practile REINSPECTION RECOMMENDATIONS PROJECT _ OWNER THOMAS ESTEEN INSPECTOR MROWKI FINAL NOTICE HEARING NOTICE NOTICE OF HOUSING CONDITIONS Expired <u>Issued</u> Issued Expired * <u>Issued</u> 11/15/178 A reinspection was made of the above premises and I recommend the following action: ALL VIOLATIONS HAVE BEEN CORRECTED Send "CERTIFICATE OF COMPLIANCE" POSTING RELEASE_ DATE SATISFACTORY Rehabilitation in Progress 6-19-19 MW Time Extended To: WTX UNSATISFACTORY Progress 4 6 8 9 MW Time Extended To 127/87 MUL "FINAL NOTICE" 'NOTICE TO VACATE" POST Entire POST Dwelling Units UNSATISFACTORY Progress
"LEGAL ACTION" To Be Taken INSPECTOR'S REMARKS: Que CT 11 Viola Conested appears New owner app 11:5/79 2/15/79 GN MAU 9/24/19 MW Layo 10-30.79 Trew 4VM 1/30/80 9nW INSTRUCTIONS TO INSPECTOR to 1-2.3-81 12-23-80 MW

REINSPECTION RECOMMENDATIONS		COMMENDATIONS	/ T7	LOCATION 25 BRATTLE ST				
		FOOTHENDAT TONG	OK	PROJECT	GEVERAL			
B		100=15=		OWNER	T ESTEN & B. CAMARA			
INSPECTOR BARTLETT		TOTEL COLL	DATE 19 28 81					
NOTICE OF HOUSING CONDITIONS		ING CONDITIONS	HEARING NOTION	CE	FINAL NOTICE Tagged Expired	į.		
Issued		Expired	Issued Er	<u>spired</u>	Issued Expired			
11/15/7	18	1/15/79	<u> </u>			a		
A reinspe	ctio	was made of th	e above premises and	I recommend	the following action.			
DATE	GB	'LL VIOLATIONS Send "CERTIFICA	HAVE BEEN CORRECTED _ TE OF COMPLIANCE" _		"POSTING for Seak"			
15/38/31	(12)	SATISFACTORY Re	habilitation in Progr	ess		CP-party		
		Time Extended T	<u> </u>		THE PERSON OF TH]		
		Time Extended	lo:			-		
		Time Extended	ro:					
		UNSATISFACTORY Send "HEARING	Progress NOTICE"		"FINA , NOT ICE"			
		NOTICE TO VACA						
		POST Entire POST Dwelling						
		UNSATISFACTORY	Progress					
		"LEGAL ACTION"	To Be Taken					
5 23 8 12 98 5		INSPECTOR'S REM	to get the cleared	up. Lay	s laile lave et dans in			
ı			سنيدت پوندېون د يې پېښتان کاند تا د د د د د د د د د د د د د د د د د د					
		INSTRUCTIONS T	O INSPECTOR:					
					هم اور استهاري او در موادي هو او			
				, .,	در د			
				· · · · · · · · · · · · · · · · · · ·				
ł					Mark			
i i								
1								
:								

. . .

}.

took .

January 31, 1980

Mr. Thomas Esten & Mr. Berton Camara Box 3643 Portland, Maine

Re: 25 Brattle Street Portland, Maine

Dear Mr. Esten & Mr. Camara:

We recently received a complaint and an inspection was made by Housing Inspector Wing of the property owned by you at 25 Brattle Street, Portland, Maine. As a result of the inspection, you are hereby ordered to correct the following substandard housing conditions:

ion-oord-from-tho-coiling-light-in-the-SECOND PLOOR FRONT HALL.

The above mantioned condition is in violation of Chapter 307 of the Municipal Code of the City of Portland, Maine, and must be corrected on or before March 1, 1980.

Failure to comply with this order may result in a completat being filed for prosecution in District Court.

Sincerely yours, Joseph E. Gray, Jr., Director Noighborhood Conservation & Inspection Services

Lyle D. Noyes, Housing Code Administrator

Inspector M. Wing

dld

REINSPECTION RECOMMENDATIONS			LOCATION					
				PROJECT	NCP-B	e Gener	AL	<u></u> \$_
INSPECTOR		M. Wing		(MINF.R	Thomas	Ester	Borton	Came
	2	and rainty			•			
NOTICE &	none	ING CONDITIONS	HEARING 1	NOTICE	FINAL	NOTICE		T
Issued		Expired	Issued	Exr red	Issued	Ex	pired	
1-31-80	,	3-1-80	į			}		
			above premises	and I recommend	the followi	ng actio	n:	
	T-	was made or the	AVE BEEN CORRECT	FD				
DATE	į	send "CERTIFICAT	E OF COMPLIANCE"		"POST	TING RELE	ASE"	
1		SATISFACTORY Rel	abilitation in P	rogress				
		Time Extended To	<u>.</u>	<u>.</u>				
	1	Time Extended To	:					
		Time Extended To	:	i				
		UNSATTSFACTORY	rogress		1111 252.7	N/OT TAKE!		
		Send "HEARING N		ng ng gayan ay ay na na na ng na na Mgayanan na na na na na ng nangangan	"FENAL	NOT LOF!'	-1 <u>-</u>	
	1	NOTICE TO VACAT			m g i r			
		POST Entire POST Dwelling U	nits					
		UNSATISFACTORY	Progress		م آبالهٔ جسست باهد بدند.			
ļ		"LEGAL ACTION"	To Be Taken	والمام المسلم المعراقي المام ع	.2545			
	l			- 4.5.0 · · · · · · · · · · · · · · · · · · ·				
2.20	mul	INSPECTOR'S RENA	called +	request	il no	me-	time	
227		12 weeks	colled +					
2 2	mw	Flori	Thinks	Marined	wis	P		
かみり と	אומין		GO COLLEGE	elf see sin		M, ,		
	ŀ							
						 -		
	1							
								•
		INSTRUCTIONS TO	INSPECTOR:					
							,	
								· » — — — · · ·
								,
								,
					 			

PO7 0487056

RECEIPT FOR CERTIFIED MAIL

NO INSURANCE COVERAGE PROVIDED—
NOT FOR INTERNATIONAL MAIL

(See Reverse)

SENLID

SE

PS Form	SENDER: Camplete items 1, 2, and 3, Add your address in the "RETURN TO" space on reverse.	
Form 3811 AUG: 1978	1. The following service is requested (check one). Show to whom and date delivered	Control of the Contro
RETURN RE	2. ARTICLE ADDRESS 20, TO: Ji: Chomes Cita & The Barton Coman Bur 36 V 3 Port Land Rame	i de
RECEIPT, RE	3. ARTICLE DESCRIPTION: REGISTERED NO. CERTIFIED NO. INSURED NO.	25.
SIS	(Always obtain signature of addressee or agent)	10
"REGISTERED, INSURED	I have received the article described above. SIGNATURE \ Add.essee \ Authorized agent	ittle.
URED AND	DATE OF DELIVERY 2 - 4	de
CERTIFI	G. UNABLE TO DELIVER BECAUSE: CLERKS	Ņ
EU, MAIC	NITIALS	

January 31, 1980

Mr. Thomas Esten & Mr. Barton Camara Box 3643 Portland, Maine

> Re: 25 Brattle Street Portland, Maine

Dear Mr. Esten & Mr. Camara:

We recently received a complaint and an inspection was made by Housing Inspector Wing of the property owned by you at 25 Brattle Street, Portland, Maine. As a result of the inspection, you are hereby ordered to correct the following substandard housing conditions:

1. Remove illegal extension cord from the ceiling light in the SECOND FLOOR FRONT HALL.

The above mentioned condition is in violation of Chapter 307 of the Municipal Code of the City of Portland, Maine, and must be corrected on or before March 1, 1980.

Failure to comply with this order may result in a complaint being filed for prosecution in District Court.

Sincerely yours, Joseph E. Gray, Jr., Director Neighborhood Conservation & Inspection Services

Lyle D. Noyes,

Housing Code Administrator

Inspector Manland Wing

ADMINISTRATIVE HEARING DECISION

City of Portland Department of Neighborhood Conservation Housing Inspections Division Telephone: 775-5451 - Ext. 448-- 358 Date June 22, 1979 Thomas Esten Barton Camara Box 3643 Portland, Maine Re: Premises located at 25 Brattle Street, Portland, Maine Gen. 3-A-2 Dear Sira: You are hereby notified that a reinspection and your request for additional time referred premises resulted in the decision noted below. XX Expiration time extended to August 22, 1979 in order to complete the work in progress to correct the remaining fourteen (14) Housing Code violations as shown on the attached list. Notice modified as follows Please notify this office if all violations are corrected before the above mentioned dates, so that a "Certificate of Compliance" may be issued. Very truly yours, Joseph E. Gray, Jr., Director Neighborhood Conservation In Attendance: Mr. Berton Camara M. Wing

Chief of Housing Inspections

Maria Will mestication.


25 Brattle Street, Portland, Maine Gen. June 22, 1979

Remaining Housing Code Violations to be corrected within time extension granted on attached "Administrative Hearing Decision" NOHC - Nov. 15, 1978

1.	FRONT EXTERIOR - replace rotted gutter (entry way canopy). OVERALL EXTERIOR - WALLS & TRIM - remove peeling paint and make the exterior walls & trim of the structure weathertight and watertight by painting or	28
	some other suitable means.	3a
,	FIRST FLOOR RIGHT EXTERIOR STAIRS - secure loose tread.	3d
1.	DEAD DUTED TOD WALL - SECURE 1008E SISPDOSTUS.	3a 3a
T.	OMERATE EVERDION BOOK - replace Worn and 10086 surestee.	3c
-	THE THOUSE THE WALL WITHOUT THE PROJECT OF THE PROPERTY OF THE	3b
~	PIRCY & SECOND FLOOR - REAR HALL WALLS - IP repair of oren planter	3c
8.	SECOND FLOOR - REAR HALL WINDOW - replace worn sash.	-
SEC	OND FLOOR	3с
0	VITCHEN WINDOW - replace broken glass.	3b
10	KITCHEN & BATHROOM FLOORS - replace worn floors.	3c
11	patupoom winnow - replace worn sasn.	3c
12.	LIVING ROOM WINDOW - replace broken and worn sash.	3с
13.	LEFT FRONT BEDROOM WINDOW - replace worn sash.	
TH:	IRD FLOOR LEFT REAR BEDROOM CEILING - repair broken plaster.	3b
	·	

Suggestion: You may wish to install single station smoke detectors in front and rear hall of first, second & third floor apartments.

REQUEST FOR SEL	-	Par 2011 A * 100 2/2016 1 .		PC	ORTLAND	HEALTH	DEPAR	TMENT
DATE RECEIVED	4.	2/-8/ By		BUU	DISTRICT	(5)		10/0
REQUEST	NAME	Howa	Nd	Low	oura-	no	eno	ne.
BY	ADDRESS		2'	Brat	te. S	<u> </u>		
OWNER	NAME	CAMA	1RX	+ ESTE	-N		•	
OWNER	ADDRESS	RR#1	, Bo	X 15, HO	4415, 1	1A INE	·/	
CONDITIONS	ADDRESS		25	15)Zat	tle.	2110		
. 0				1				
JAAL	window	f, mo	h	eat.	//	1	• !	
		· · · · · · · · · · · · · · · · · · ·			_(/_	NIV		
				1		1		
COMMENTS TO	nant Da	11 some	onl	alway	us as	nom	el_) . A
	100	360 Callo			Rim 6	Suntel	May	115 th
		•					- (/	
SPECIAL INSTRUCTIO	NS							
				/				
DIVISION	SANITAT	ION		HOUSING		NURSING	,	
	ROUTINE			SPECIAL			ВҮ	
PRIORITY	LIPGENT			REPORT TO			DATE	



- J.

CERTIFICATE OF INSPECTION

DATE January 4, 1984

DU: 3

City of Portland Housing Inspections Division Department of Urban Development Tel: 775-5451 Ext. 311 - 312

Ed Brown 25 Brattle Street - Apt. #2 Portland, Maine 04101

Re: Premises located at: 25 Brattle St. 33-A-3 Gen.

Pear Mr. Brown:

An inspection of the above referred premises was recently completed by Code Enforcement Officer Michael Nugent

Although the structure does not meet the minimum standards as described in the Housing Code, it has been determined that no <u>major</u> code deficiencies exist at this time.

Iters included on the enclosed list should be corrected as part of your Iters included on the enclosed list should be corrected as part of your normal maintenance procedures in order to avoid extensive repairs in the future and to prolong the useful life of the building.

Thank you for your cooperation and your efforts to help us maintain decent, safe, and sanitary housing for all Portland residents.

Please do not nesitate to call this office if you have any questions regarding this notice.

Sincerely yours, Joseph E. Gray, Jr., Director of Planning Urban Development

Inspection Services Division

Code Enforcement Officer - M. Nugent (10

Enclosure

jmr

HOUSING INSPECTION REPORT

OWNER: Ed Brown

CODE ENFORCEMENT OFFICER: Michael Nugent (10)

25 Brattle Street, Portland, Maine 33-A-3 Gen. NOHC - 6-1-83 Certificate of Inspection dated January 4, 1984 Continued:

REAR EXTERIOR - wall - slightly broken.

THIRD FLOOR - LIVING ROOM - window - broken counterbalance cord..

NOTICE OF HOUSING CONDITIONS

CITY	0F	PORT	LAND,	MAINE

Department of Planning & Urban Development Inspections Services Division Tel. 775-5451 - Ext. 311 - 318 - 319

Mr. Hampton Sarlyer) EDBROWN
P. DEST 1275
PORTLAND, Maine 04112 DAME APT. 3

DU 3

Ch. 33 Blk. A Lot 3 Location: 25 Brabile St.

Project: Gen. Issued: June 1, 1983 Expires: Sept. 1, 1983

Dear Mr. Sawyer:

You are hereby notified, as owner or agent, that an inspection was made of the premises at 25 Brattle Street, Portland, Maine by Code Enforcement Officer Michael Nugent Violations of Chapter 307 of the Municipal Codes (Minimum Standards for Housing) were found as described in detail on the attached "Housing Inspection Report".

In accordance with the provisions of the above mentioned Code, you are hereby ordered to correct those defects on or before Sept. 1, 1983

Tf you are unable to make such repairs within the specified time, you may contact this office to arrange a satisfactory repair schedule. If we do not hear from you within ten (10) days from this date, we will assume the repairs to be in progress and, on re-inspection within the time set forth above, will anticipate that the premises have been brought into compliance with Code Standards.

Please contact this office if you have any questions regarding this Notice.

Your cooperation will aid this Department in it's goal to maintain decent, safe, and sanitary housing for all of Portland's residents.

Very truly yours, Joseph E. Gray, Jr., Director of Planning & Urban Development

Inspection Services Division

e Enforcement Officer - Wished Nurent (10)

Attachments:

imr

.

SEND STAND ADD BUT

HOUSING INSPECTION REPORT

TO ED BROWN - NEW OWNER #5

Harricon Sawyer, SAME CODE ENFORCEMENT OFFICER - Michael Nusgent ne 33-A-3 Gen. Notice of Housing Conditions EXPIRES: Sept. 1, 1983 25 Brattle Street, Portland, Maine DATED: June 1, 1983 ITEMS LISTED BELOW ARE IN VIOLATION OF "CHAPTER 307" THE MUNICIPAL CODES - MINIMUM STANDARDS FOR HOUSING" AND MUST BE CORRECTED. cracked cement. FEAR EXTERIOR 3-a -broken siding. REAR EXTERIOR - wall 3-a REAR EXTERIOR - window - rotted trim. FIRST FLOOR FRONT & THIRD FLOOR REAR HALL - stainways - inoperative lights. -dampness. OVERALL - cellar SECOND FLOOR OVERALL KITCHEN - floor - worn floor 1/3/83 - inoperative hot water: KITCHEN - sink LIVING ROOM - window - worn sash.fx BATHROOM - window - worn sash. BATTIPOOM - floor - worn floor, BATHROOM toilet - leaking of BATHROOM - floor - mildew BEDROOM - Wall - loose and cracked plaster: K THIRD FLOOR OVERALL KITCHEN - Celling - buckled tiles.

KITCHEN - Floor - missing tiles.

LIVING ROOM - window - broken counterbalance 19. FROMT BEDROOM - ceiling and wall - loose 20. REAR BEDROW - wall - peeling wall paper 21. FRONT HALL - ceiling and wall - peeling paint and plaster

*WHEN MAKING YOUR REPAIRS, FIRST PRIORITY IS TO BE GIVEN TO ITEMS WITH ASTERISKS, AS THEY CONSTITUTE EXTREME HAZARD" TO THE HEALTH OR SAFETY OF THE OCCUPANTS OF THIS STRUCTURE.