

Inspection Services
P. Samuel Hoffas
Chief



Planning and Urban Development
Joseph E. Gray Jr.
Director

CITY OF PORTLAND

BACK BAY TOWER ASSOCIATES
401 CUMBERLAND AVE
PORTLAND ME 04101

Re: 389 CUMBERLAND AVE
CBI: 036--1-037-001-01
DU: 99

Dear Sir:

The Housing Inspections Division of the Department of Planning and Urban Development has recently completed an overall inspection of the above-referred property.

Congratulations are extended to you for the general condition of your property which was found to meet the standards established by the City's Housing Code. We did, however, note the following items that could cause future problems:


1. EXT - GARAGE - 111.40
CEILING HAS LEAKING DRAIN PIPES

Good maintenance is the best way to protect the value of your property and neighborhood.

Please feel free to call on us if we can be of assistance to you.

Sincerely,


David Jordan
Code Enforcement Officer


Tammy Munson
Code Enfc. Off./ Field Supv.

Inspection Services
P. Samuel Hoffses
Chief



Planning and Urban Development
Joseph E. Gray Jr.
Director

CITY OF PORTLAND

BACK BAY TOWER ASSOCIATES
401 CUMBERLAND AVE
PORTLAND ME 04101

Re: 389 CUMBERLAND AVE
CBL: 036 - - I-037-001-01
DU: 99

Dear Sir:

The Housing Inspections Division of the Department of Planning and Urban Development has recently completed an overall inspection of the above-referred property.

Congratulations are extended to you for the general condition of your property which was found to meet the standards established by the City's Housing Code. We did, however, note the following items that could cause future problems:


1. EXT - GARAGE - 111.40
CEILING HAS LEAKING DRAIN PIPES

Good maintenance is the best way to protect the value of your property and neighborhood.

Please feel free to call on us if we can be of assistance to you.

Sincerely,


David Jordan
Code Enforcement Officer


Tammy Munson
Code Enfc.Offc./ Field Supv.