

37 BROWN STREET

SHAW-WALKER

Full cut # 9205H - Half cut # 9202R - Third cut # 9205R - Fifth cut # 9205R



GENERAL BUSINESS ZONE PERMIT ISSUED

APPLICATION FOR PERMIT TO REPAIR BUILDING

Third Class Building

To the INSPECTOR OF BUILDINGS, PORTLAND, ME. Portland, Maine, September 11, 1942
 The undersigned hereby applies for a permit to repair the following described building in accordance with the
 Laws of Maine, the Building Code of the City of Portland, and the following specifications:
 Location 37-39 Brown Street Within fire limits? yes Dist. No. 1
 Owner's name and address P. H. & J. M. Brown, 115 Congress Street Telephone _____
 Contractor's name and address Furnham-McLellan, 191 Congress St. Telephone 2-4957
 Use of building mercantile
 No. stories 1 Style of roof pitch Type of present roof covering asphalt roofing

General Description of New Work

To Repair after Fire to former condition. No alterations.

RECEIVED
 DEPARTMENT OF
 CITY ENGINEER
 PORTLAND, ME.
 SEP 11 1942
 CERTIFICATE OF OCCUPANCY
 REQUIREMENTS WAIVED

If Roof Covering is to be Repaired or Renewed

Is any plumbing work involved in this work? no Is any electrical work involved in this work? no
 Are repairs or renewal due to damage by fire? yes If so, what area damaged? _____ sq. ft.
 Area of roof to be repaired now? entire _____ sq. ft.
 Type of roofing to be used asphalt roofing No. plies _____
 Trade name and grade of roof covering to be used Class C No. 1, Lab.
 Estimated cost \$ 50 Fee \$ 50

INSPECTION COPY

Signature of owner _____
 P. H. & J. M. Brown
 Furnham-McLellan
 By: Paul B. McCallan

22-00179



APPLICATION FOR PERMIT

Permit No. 02340

Class of Building or Type of Structure Third Class MAR 20 1935

Portland, Maine, March 26, 1935

To the INSPECTOR OF BUILDINGS, PORTLAND, ME.

The undersigned hereby applies, or a permit to erect alter install the following building structure equipment in accordance with the Laws of the State of Maine, the Building Code of the City of Portland, plans and specifications, if any, submitted herewith and the following specifications:

Location Rear 17 Crown St. Ward 4 Within Fire Limits? Yes Dist. No. 1
 Owner's or lessor's name and address F. H. & J. E. Brown & Co., 37 Exchange St. Telephone _____
 Contractor's name and address Oxford Bracking Co., 37 Froble St. Telephone 4-3752
 Architect's name and address _____
 Proposed use of building _____ No. families _____
 Other buildings on same lot _____
 Plans filed as part of this application? No No. of sheets _____
 Estimated cost \$ _____ Fee \$.50

Description of Present Building to be Altered

Material not No. stories 1 Heat _____ Style of roof _____ Roofing _____
 Past use Candy kitchen No. families _____

General Description of New Work

To demolish 9' x 8' from building

It is understood that this permit does not include installation of heating apparatus which is to be taken out separately by and in the name of the heating contractor.

Details of New Work

Size, front _____ depth _____ No. stories _____ Height average grade to top of plate _____
 Height average grade to highest point of roof _____
 To be erected on solid or filled land? _____ earth or rock? _____
 Material of foundation _____ Thickness, top _____ bottom _____
 Material of underpinning _____ Height _____ Thickness _____
 Kind of Roof _____ Rise per foot _____ Roof covering _____
 No. of chimneys _____ Material of chimneys _____ of lining _____
 Kind of heat _____ Type of fuel _____ Is gas fitting involved? _____
 Corner posts _____ Sills _____ Girt or ledger board? _____ Size _____
 Material columns under girders _____ Size _____ Max. on centers _____
 Studs (outside walls and carrying partitions) 2x4-16" O. C. Girders 6x8 or larger. Bridging in every floor and flat roof span over 8 feet. Sills and corner posts all one piece in cross section.
 Joists and rafters: 1st floor _____, 2nd _____, 3rd _____, roof _____
 On centers: 1st floor _____, 2nd _____, 3rd _____, roof _____
 Maximum span: 1st floor _____, 2nd _____, 3rd _____, roof _____
 If one story building with masonry walls, thickness of walls? _____ height? _____

If a Garage

No. cars now accommodated on same lot _____, to be accommodated _____
 Total number commercial cars to be accommodated _____
 Mobile repairing be done other than minor repairs to cars habitually stored in the proposed building? _____

Miscellaneous

Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? yes
 Signature of owner By: W. B. Stebbins
 F. H. & J. E. Brown & Co.
 Oxford Bracking Co.

INSPECTION COPY