



APPLICATION FOR PERMIT

Class of Building or Type of Structure 2nd class
Portland, Maine, Sept. 10, 1958

PERMIT ISSUED

SEP 10 1958 01251

CITY of PORTLAND

To the INSPECTOR OF BUILDINGS, PORTLAND, MAINE

The undersigned hereby applies for a permit to erect alter repair demolish install the following building structure equipment in accordance with the Laws of the State of Maine, the Building Code and Zoning Ordinance of the City of Portland, plans and specifications, if any, submitted herewith and the following specifications:

Location 483 Congress St. Within Fire Limits? yes Dist. No. _____
Owner's name and address Portland Savings Bank, 483 Congress St. Telephone _____
Lessee's name and address _____ Telephone _____
Contractor's name and address F.W. Cunningham & Son 181 State St. Telephone 3-0246
Architect _____ Specifications _____ Plans yes No. of sheets 2
Proposed use of building Bank & Offices No. families _____
Last use _____ No. families _____
Material brick No. stories 4 Heat _____ Style of roof _____ Roofing _____
Other buildings on same lot _____
Estimated cost \$ 10,000 Fee \$ 10.00

General Description of New Work

To provide new and additional entrance in arcade for Portland Savings Bank, as per plans.

It is understood that this permit does not include installation of heating apparatus which is to be taken out separately by and in the name of the heating contractor. PERMIT TO BE ISSUED TO contractor

Details of New Work

Is any plumbing involved in this work? _____ Is any electrical work involved in this work? _____
Is connection to be made to public sewer? _____ If not, what is proposed for sewage? _____
Has septic tank notice been sent? _____ Form notice sent? _____
Height average grade to top of plate _____ Height average grade to highest point of roof _____
Size, front _____ depth _____ No. stories _____ solid or filled land? _____ earth or rock? _____
Material of foundation _____ Thickness, top _____ bottom _____ cellar _____
Material of underpinning _____ Height _____ Thickness _____
Kind of roof _____ Rise per foot _____ Roof covering _____
No. of chimneys _____ Material of chimneys _____ of lining _____ Kind of heat _____ fuel _____
Framing Lumber—Kind _____ Dressed or full size? _____ Corner posts _____ Sills _____
Size Girder _____ Columns under girders _____ Size _____ Max. on centers _____
Kind and thickness of outside sheathing of exterior walls? _____
Studs (outside walls and carrying partitions) 2x4-16" O. C. Bridging in every floor and flat roof span over 8 feet.
Joists and rafters: 1st floor _____, 2nd _____, 3rd _____, roof _____
On centers: 1st floor _____, 2nd _____, 3rd _____, roof _____
Maximum span: 1st floor _____, 2nd _____, 3rd _____, roof _____
If one story building with masonry walls, thickness of walls? _____ height? _____

If a Garage

No. cars now accommodated on same lot _____, to be accommodated _____ number commercial cars to be accommodated _____
Will automobile repairing be done other than minor repairs to cars habitually stored in the proposed building? _____

Miscellaneous

Will work require disturbing of any tree on a public street? no
Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? yes
Portland Savings Bank
F.W. Cunningham & Son

APPROVED:

C.N. 9/16/58 - agd

agd

INSPECTION COPY


Signature of owner by:

Thomas G. Peter

FM

NOTES

~~Dem. - V/L -~~
 10/6/58 *Work not done. The lead*
Allen
 10/20/58 *Same. - Allen*
 11/17/58 *Work started*
Allen
 12/1/58 *Work prog. as usual*
Allen
 12/29/58 *Work done except*
for doors & hardware -
Allen
 1/12/59 *- Same. Allen*
 1/28/59 *- 1/2 on doors etc.*
- Allen



Permit No. 58/1251

Location 483 Congress St
 Owner *Arthur J. King*
 Date of permit 9/16/58
 Notif. closing-in
 Inspn. closing-in
 Final Notif.
 Final Inspn.
 Cert. of Occupancy issued
 Staking Out Notice
 Form Check Notice

61 483 Congress Street
(Portland Savings Bank)

May 8, 1950

Mr. Carroll H. Wentworth, President
Prable, Inc.
477 Congress Street—Room 1206
Portland, Maine

Dear Mr. Wentworth:

Having occasion to be in the Portland Savings Bank and looking up at the ceiling, I noticed that the plaster covering of what is probably a steel beam supporting the upper stories of the building was bulging downward and crumbling.

Immediately there came to mind the very serious troubles they have been having in Boston with buildings of skeleton steel construction due to moisture from the outside penetrating through the masonry and attacking the steel framework. I was told that the first indication that they had of this trouble in quite a number of buildings was the fact that the masonry appeared to bulge in various parts of the exterior wall. Upon examination it was found out that this had been caused by corrosion of the steel and the corrosion or rust had a tendency to expand and push the masonry out.

It became necessary of course to renew or reinforce the structural members, and on one building only 20 years old, I was told that more than one hundred thousand dollars was spent to repair the steel work in the spots where the difficulty appeared. They have no idea how much farther the trouble will extend through the years. Needless to say when this steel work was repaired it was coated with a heavy, rubber-like substance instead of the formerly used paint with the hope that the steel thus treated will be good for the life of the building.

I am not trying to be an alarmist, but it looks very much as though water had penetrated this particular steel beam under the second floor of your building and had corroded the steel perhaps to important damage. Of course the moisture would tend to spoil the plaster work, but the trouble may be considerably deeper than this and affect the supports of the building itself.

I talked with Mr. Leighton of Portland Savings Bank, and he thought that this condition had existed for a long time.

Perhaps no important damage has been done to the steel beam, but it certainly seems prudent to find out and if any damage has occurred to repair it if needed, try to find a way to stop the water from reaching the steel, and coat the steel with a better preservative than is usually used on inside steel work.

I feel sure you will understand that this letter is intended to be of service to you and the owners of the building, and I will be interested to know what is found out about the matter.

Very truly yours,

Warren McDonald
Inspector of Buildings

W McD/G

April 9, 1956

AP - 477-481
AP - 477 Congress Street

Copies to Fred I. Merrill
22 Somerset Street
South Portland, Me.
Philip P. Snow
477 Congress Street

Preble, Inc.
477 Congress Street

Gentlemen:-

Building permit for alterations in fourth story of annex at the above location is issued herewith based on plan filed with application for permit, but subject to the following conditions:-

1. Unless certain bearing partition running at right angles to Congress Street in area where floor is to be shored up is to be left in place, in accordance with plan showing method of support for roof in place of partition is to be filed and issued before this part of work is done.
2. Notification for inspection is to be given this department before any work is applied to walls, partitions or ceilings.
3. Adjustment of sprinkler heads to accommodate new partition layout is to be made if necessary.

Very truly yours,

Albert J. Sears
Deputy Inspector of Buildings

AJS/G



(G) GENERAL BUSINESS ZONE

APPLICATION FOR PERMIT

Class of Building or Type of Structure

Portland, Maine, April 5, 1956

PERMIT ISSUED

00406

APR 9 1956

CITY OF PORTLAND

To the INSPECTOR OF BUILDINGS, PORTLAND, MAINE

The undersigned hereby applies for a permit to erect alter repair or reconstruct the following building...

Form with fields for Location, Owner's name and address, Lessee's name and address, Contractor's name and address, Architect, Proposed use of building, Last use, Material masonry, No. stories, Heat, Style of roof, Roofing, Other building on same lot, Estimated cost \$ 5,000., Fee \$ 5.00.

General Description of New Work

To-level floor and construct partitions and provide new exit, fourth floor annex, as per plans.

Permit Issued with Letter

It is understood that this permit does not include installation of heating apparatus which is to be taken out separately by and in the name of the heating contractor. PERMIT TO BE ISSUED TO Preble, Inc.

Details of New Work

Form with fields for plumbing, electrical work, connection to public sewer, septic tank, height average grade, foundation, underpinning, roof, chimneys, framing lumber, corner posts, girders, studs, joists and rafters, on centers, maximum span.

If a Garage

No. cars now accommodated on same lot, to be accommodated number commercial cars to be accommodated. Will automobile repairing be done other than minor repairs to cars habitually stored in the proposed building?

APPROVED:

with letter by [Signature]

Miscellaneous

Will work require disturbing of any tree on a public place? Will there be in charge of the above work a person who will see that the State and City requirements pertaining thereto are observed? YES

Preble, Inc.

Signature of owner by:

[Signature]

INSPECTION COPY

C16-254

NOTES

5/1/56 - Work on east end
 all done. Walls (a couple
 of feet for bottom) placed
 walling in position. Also
 5/18/56 - partition removed
 with a cover placed - Work
 on wood on all side - Allen
 5/18/56 - Call Mr. [unclear] about
 cover placed for carrying
 partition removed. Working
 all with full load of the
 with a [unclear] of work -
 Allen

6/13/56 - Work on [unclear]
 not finished - Allen

7/23/56 - Work on [unclear]
 Allen

7/26/56 - Called Joe [unclear]
 about amendment - Allen

10/2/56 - Called [unclear] home
 on this - Allen

10/9/56 - Amendment not
 needed to the [unclear] of
 [unclear] for [unclear] - Allen

11/23/56 - [unclear] about [unclear]
 spoke to Joe [unclear] about this
 Allen

1/8/57 - same - Allen

2/18/57 - same - Allen

INSPECTION NOT COMPLETED

Miscellaneous

Permit No. 561436
 Location 1717 Congress St.
 Owner [unclear]
 Date of permit 4/9/56
 Type of closing-in
 Inspn. closing-in
 Final Permit
 Final Inspn.
 Certificate of Occupancy issued
 Stopping Out Notice
 Form Check Notice

7

APPLICATION FOR AMENDMENT TO PERMIT



Amendment No. 1

Portland, Maine, Sept. 15, 1955

PERMIT ISSUED

SEP 29 1955

CITY of PORTLAND

To the INSPECTOR OF BUILDINGS, PORTLAND, ME.

The undersigned hereby applies for an amendment to Permit No. 55/1117 pertaining to the building or structure comprised in the original application in accordance with the Laws of the State of Maine, the Building Code and Zoning Ordinance of the City of Portland, plans and specifications, if any, submitted herewith, and the following specifications:

Location 477 Congress St. Within Fire Limits? yes Dist. No. 1
 Owner's name and address Preble, Inc., 477 Congress St. Telephone 2-8671
 Lessee's name and address _____ Telephone _____
 Contractor's name and address Googins & Clark, 16 Portland St. Telephone _____
 Architect _____ Plans filed yes No. of sheets 6
 Proposed use of building offices stores etc. No. families _____
 Increased cost of work 15,000. Additional fee 14.00

Description of Proposed Work

To construct 2-story masonry addition as per plans.

Permit Issued with Letter

Amendment to be issued to Preble Inc.

Details of New Work

Is any plumbing work involved in this work? _____ Is any electrical work involved in this work? _____
 Height average grade to top of plate _____ Height average grade to highest point of roof _____
 Size, front _____ depth _____ No. _____ filled land? _____ earth or rock? _____
 Material of foundation _____ bottom _____ cellar _____
 Material of underpinning _____ Thickness _____
 Kind of roof _____ Rise per foot _____ Roof covering _____
 No. of chimneys _____ Material of chimneys _____ of lining _____
 Framing, lumber—Kind _____ Dressed or full size? _____
 Corner posts _____ Sills _____ Girt or ledger board? _____ Size _____
 Girders _____ Size _____ Columns under girders _____ Size _____ Max. on centers _____
 Studs (outside walls and carrying partitions) 2x4-16" O. C. Bridging in every floor and flat roof span over 8 feet.
 Joists and rafters: 1st floor _____, 2nd _____, 3rd _____, roof _____
 On centers: 1st floor _____, 2nd _____, 3rd _____, roof _____
 Maximum span: 1st floor _____, 2nd _____, 3rd _____, roof _____

Approved: with letter by AGJ

Signature of Owner BY: Joseph A. Preble

Approved: [Signature]
 Inspector of Buildings.

INSPECTION COPY

August 30, 1955

AP - 477 Congress Street

Owner—^oPreble, Inc. Contractor—^cGeogins & Clark Engineer—^cPhilip P. Snow
477 Congress St. 46 Portland St. 477 Congress St.

Building permit for cutting in new exit door from second story of annex to roof at the above location is issued herewith based on plan filed with application for permit, but subject to the following conditions:-

- if steps leading up to new door are to be more than 40 inches wide, hand-rails are to be provided on each side of them.
- a platform extending at least nine inches beyond each side of the new door opening and extending at least three feet in front of it is to be provided on the roof outside the door.
- since the doorway will likely be called upon to serve as a means of egress for more than 20 people, a vestibule latchset is to be provided on the new door.

Very truly yours,

Warren McDonald
Inspector of Buildings

*O.K. 10/25/55
Allen*

AJS/S

Location 477 Congress St.

Complaint No. _____

Permit No. 55/1447

6/18/57 - Self-closing
 device needed on exit door -
 - Exit sign over exit door
 - Railing on roof to be
 made rigid.
 - Allan

7/11/57 - Self-closing device
 needed on exit door -
 - Railing on roof to be
 made rigid - Allan


8/13/57 - Same - Allan

9/17/57 - Same - Allan

9/24/57 - Made to mm

Standard about the above - Allan

9/27/57 - Work done - Allan





APPLICATION FOR PERMIT

Class of Building or Type of Structure

Portland, Maine, Aug. 29, 1955

PERMIT ISSUED

01447

AUG 30 1955

CITY OF PORTLAND

To the INSPECTOR OF BUILDINGS, PORTLAND, MAINE

The undersigned hereby applies for a permit to alter ~~the~~ ~~existing~~ ~~building~~ ~~structure~~ ~~and~~ ~~use~~ ~~of~~ ~~the~~ ~~same~~ ~~in~~ ~~accordance~~ ~~with~~ ~~the~~ ~~Laws~~ ~~of~~ ~~the~~ ~~State~~ ~~of~~ ~~Maine~~, ~~the~~ ~~Building~~ ~~Code~~ ~~and~~ ~~Zoning~~ ~~Ordinance~~ ~~of~~ ~~the~~ ~~City~~ ~~of~~ ~~Port-~~ ~~land~~, ~~plans~~ ~~and~~ ~~specifications~~, ~~if~~ ~~any~~, ~~submitted~~ ~~herewith~~ ~~and~~ ~~the~~ ~~following~~ ~~specifications~~:

Location **477-481 477 Congress St.** Within Fire Limits? **yes** Dist. No. **1**
 Owner's name and address **Preble, Inc., 477 Congress St.** Telephone **2-8671**
 Lessee's name and address _____ Telephone _____
 Contractor's name and address **Googins & Clark, 46 Portland St.** Telephone _____
 Architect _____ Specifications _____ Plans **yes** No of sheets **1**
 Proposed use of building **offices stores etc.** No. families _____
 Last use _____ No. families _____
 Material masonry No. stories **4** Heat _____ Style of roof _____ Roofing _____
 Other building on same lot _____
 Estimated cost \$ **500.** Fee \$ **2.00**

General Description of New Work

To provide new doorway to roof in the annex as per plan.

Permit Issued with Letter

It is understood that this permit does not include installation of heating apparatus which is to be taken out separately by and in the name of the heating contractor. **PERMIT TO BE ISSUED TO Preble, Inc.**

Details of New Work

Is any plumbing involved in this work? _____ Is any electrical work involved in this work? _____
 Is connection to be made to public sewer? _____ If not, what is proposed for sewage? _____
 Has septic tank notice been sent? _____ Form notice sent? _____
 Height average grade to top of plate _____ Height average grade to highest point of roof _____
 Size, front _____ depth _____ No. stories _____ solid or filled land? _____ earth or rock? _____
 Material of foundation _____ Thickness, top _____ bottom _____ cellar _____
 Material of underpinning _____ Height _____ Thickness _____
 Kind of roof _____ Rise per foot _____ Roof covering _____
 No. of chimneys _____ Material of chimneys _____ of lining _____ Kind of heat _____ fuel _____
 Framing lumber—Kind _____ Dressed or full size? _____
 Corner posts _____ Sills _____ Girt or ledger board? _____ Size _____
 Girders _____ Size _____ Columns under girders _____ Size _____ Max. on centers _____
 Studs (outside walls and carrying partitions) **2x4-16" O. C.** Bridging in every floor and flat roof span over 8 feet.
 Joists and rafters: 1st floor _____, 2nd _____, 3rd _____, roof _____
 On centers: 1st floor _____, 2nd _____, 3rd _____, roof _____
 Maximum span: 1st floor _____, 2nd _____, 3rd _____, roof _____
 If one story building with masonry walls, thickness of walls? _____ height? _____

If a Garage

No. cars now accommodated on same lot _____, to be accommodated _____ number commercial cars to be accommodated _____
 Will automobile repairing be done other than _____ repairs to cars habitually stored in the proposed building? _____

APPROVED:

with letter by A.J.S.

Miscellaneous

Will work require disturbing of any tree on a public street? **no**
 Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? **yes**

Preble, Inc.

INSPECTION COPY

Signature of owner by:

Joseph A. Landon
City of Portland

NOTES

9/14/55 - work started on 3rd floor
Allan
9/14/55 - work progressing
Allan
10/15/55 - Handled issue at 11th
month - Allan
10/16/55 - discussed on the 11th
with the owner on the job
Allan
10/25/55 - Done opening up
landlord's roof as bright
Done work to spread of the
at 11th floor in the
11/1/55 - Work started on addition
Allan
11/22/55 - Roof on structure to
be done inside - Allan
12/1/55 - Work progressing the
worked on 11th floor
the addition on 11th - Allan
12/27/55 - Work progressing
on 11th - Allan
1/30/56 - Work on 11th floor
done on 4th floor - Margaret
started 6) - Allan
2/7/56 - Work on 11th floor
Allan
3/27/56 - Margaret's bathroom
done on 4th floor
Allan
3/27/56 - Final floor on
addition in different than
our plans. Called the
owner. Called to the
shop of machine
plans and told him
would be better if
made up and brought in
Allan
4/11/56 - Work on 11th floor
Allan
4/24/56 - Done up 4th floor
to outside not done - Allan

Permit No. 551,447	5/14/56	Allen
Order	5/14/56	Allen
Date of permit	5/30/55	Allen
Notif. closing-in		
Insp. closing-in		
Final Notif.		
Final Insp.		
Cert. of Occupancy issued		
Stoppage Out Notice		
Form Check Notice		

5/24/56 - Call on 4th floor
done - Allan
7/22/56 - Work started on
4th floor - Allan
White light outside of window
to the roof -
11/6 in paper door made
in mosaic hall -
Railings on roof to be added -
9/5/57 - Work progressing - Allan
9/27/57 - White light outside
of window - Railings on roof to be
added - Allan
10/2/57 - Called Phil
on the - Allan
10/30/57 - White light outside
of window - Railings on roof to be
added - Allan
11/27/57 - Same as above - Allan
11/27/57 - Same as above - Allan
1/15/57 - Same as above - Allan
2/18/57 - Same as above - Allan
4/18/57 - Chick had
on Saturday - Allan
4/22/57 - Margaret's bathroom
done - Koetter
by Allan
5/25/57 - Phil called 4
said he would see what he
could do to clean this up
- Allan

INSPECTION COPY

May 21, 1957

Preble, Inc.
477 Congress St.
Mr. Philip Snow
477 Congress St.

Location - 477 Congress St.

Owner - Preble, Inc.

Job - Alterations

Gentlemen:-

Upon inspection of the above job on May 17, 1957, the following conditions or defects were found:

White light needed outside of exit door from stairway tower to roof on the fourth floor.

Two handrails are needed on stairway from the fifth floor to the fourth and this exit.

Self-closing device needed on exit door.

Exit sign needed over exit door.

Existing railing at edge of roof onto which new exit door opens is to be made rigid.

It is important that correction of these conditions be made before June 11, 1957 and notification be given this office of readiness for another inspection.

Very truly yours,

A. James Soule
Field Inspector

AAS/G

BP - 477 Congress Street

September 29, 1955

Owner-Prehle, Inc.
477 Congress St.

Engineer-Philip Snow
477 Congress St.

Contractor-Googins & Clark
46 Portland St.

Amendment #1 to Permit 55/1447 covering construction of two story addition approximately 20 feet by 34 feet above section of Arcade roof of building at the above location is issued herewith based on plans filed with application for permit, but subject to the following conditions:

1. Permit is issued on the understanding that all existing steel columns which will be called upon to support the additional loads from new construction are already fireproofed.
2. Where new steel beams are indicated to be encased in concrete, a minimum thickness of 2 inches is required at all points.
3. All new steps or stairs are to be of incombustible material instead of wood as indicated in at least one case.
4. If new doors leading to existing stairways are ever to serve as a means of egress for more than 20 people, they are required to be equipped with vestibule latch sets.
5. Glass block panel in new wall of addition is required to be constructed only of blocks approved by Underwriters' Laboratories, Inc. and ventilating sash are required to be of metal glazed with wire glass. Length of any panel of glass blocks is limited to 12 feet and area to 120 square feet. Permit is issued on the basis of compliance with this requirement.
6. Before steel joists in new floor and roof construction are erected it is necessary that there be on file at this office certification in writing from the fabricator of the joists that all welding in connection therewith has been designed and all shop welding performed according to the procedure and by properly qualified welders as set forth in the Code and qualification procedure established by the American Welding Society.
7. Metal lath and plaster ceiling required to provide two-hour fire resistance for floor and roof construction if of sanded gypsum plaster must have a thickness of not less than three-quarters of an inch beneath steel joists and of not less than one inch around supporting steel beams.

Very truly yours,

Inspector of Buildings

AJS/11



BUSINESS ZONE

APPLICATION FOR PERMIT

Class of Building or Type of Structure First Class

Portland, Maine, April 5, 1955

PERMIT ISSUED

00414
APR 5 1955

CITY OF PORTLAND

To the INSPECTOR OF BUILDINGS, PORTLAND, MAINE

The undersigned hereby applies for a permit to erect alter repair demolish install the following building structure equipment in accordance with the Laws of the State of Maine, the Building Code and Zoning Ordinance of the City of Portland, plans and specifications, if any, submitted herewith and the following specifications:

Location 477 Congress Street Within Fire Limits? yes Dist. No. 1
 Owner's name and address Preble, Inc., 477 Congress Street Telephone _____
 Lessee's name and address _____ Telephone _____
 Contractor's name and address Googins & Clark, 46 Portland St. Telephone _____
 Architect _____ Specifications _____ Plans yes No. of sheets 1
 Proposed use of building Stores and offices No. families _____
 Last use _____ " _____ No. families _____
 Material MASONRY No. stories _____ Heat _____ Style of roof _____ Roofing _____
 Other buildings on same lot _____
 Estimated cost \$ 200. Fee \$ 2.00

General Description of New Work

To partition off toilet rooms third floor rear annex as per plan.
2x4 studs, 16" O.C., sheetrock both sides.

It is understood that this permit does not include installation of heating apparatus which is to be taken out separately by and in the name of the heating contractor. **PERMIT TO BE ISSUED TO** Preble, Inc.

Details of New Work

Is any plumbing involved in this work? yes Is any electrical work involved in this work? _____
 Is connection to be made to public sewer? _____ If not, what is proposed for sewage? _____
 Has septic tank notice been sent? _____ Form notice sent? _____
 Height average grade to top of plate _____ Height average grade to highest point of roof _____
 Size, front _____ depth _____ No. stories _____ solid or filled land? _____ earth or rock? _____
 Material of foundation _____ Thickness, top _____ bottom _____ cellar _____
 Material of underpinning _____ Height _____ Thickness _____
 Kind of roof _____ Rise per foot _____ Roof covering _____
 No. of chimneys _____ Material of chimneys _____ of lining _____ Kind of heat _____ fuel _____
 Framing lumber—Kind _____ Dressed or full size? _____
 Corner posts _____ Sills _____ Girt or ledger board? _____ Size _____
 Girders _____ Size _____ Columns under girders _____ Size _____ Max. on centers _____
 Studs (outside walls and carrying partitions) 2x4-16" O. C. Bridging in every floor and flat roof span over 8 feet.
 Joists and rafters: 1st floor _____, 2nd _____, 3rd _____, roof _____
 On centers: 1st floor _____, 2nd _____, 3rd _____, roof _____
 Maximum span: 1st floor _____, 2nd _____, 3rd _____, roof _____
 If one story building with masonry walls, thickness of walls? _____ height? _____

If a Garage

No. cars now accommodated on same lot _____, to be accommodated _____ number commercial cars to be accommodated _____
 Will automobile repairing be done other than minor repairs to cars habitually stored in the proposed building? _____

APPROVED:
O.R. - 4/5/55 - ajs

Miscellaneous

Will work require disturbing of any tree on a public street? no
 Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? yes

Preble, Inc.

INSPECTION COPY

Signature of owner

By: Joseph A. Landon

NOTES

4/13/55 - Entire wall framed
4/17/55 - Jd done - all

Permit No. 55/414

Location 477 Cambridge St.

Owner Charles J. Sweeney

Date of permit 4/5/55

Notif. closing-in

Inspn. closing-in

Final Notif.

Final Inspn.

Cert. of Occupancy issued

Staking Out Notice

Form Check Notice

Large grid area for notes, mostly blank with a large 'X' drawn across it.



(G) GENERAL BUSINESS ZONE
APPLICATION FOR PERMIT

Class of Building or Type of Structure Second Class

Portland, Maine, Sept. 25, 1952

PERMIT ISSUED

SEP 30 1952

CITY of PORTLAND

To the INSPECTOR OF BUILDINGS, PORTLAND, MAINE

The undersigned hereby applies for a permit to ~~erect~~ alter ~~and~~ ~~rebuild~~ the following building ~~structure~~ ~~equipment~~ in accordance with the Laws of the State of Maine, the Building Code and Zoning Ordinance of the City of Portland, plans and specifications, if any, submitted herewith and the following specifications:

Location 477 Congress Street Within Fire Limits? yes Dist. No. 1
Owner's name and address Preble, Inc., 477 Congress Street Telephone _____
Lessee's name and address _____ Telephone _____
Contractor's name and address Googins & Clark, 46 Portland Street Telephone _____
Architect _____ Specifications _____ Plans yes No. of sheets 1
Proposed use of building offices, stores etc. No. families _____
Last use _____ " " _____ No. families _____
Material masonry No. stories 4 Heat _____ Style of roof _____ Roofing _____
Other buildings on same lot _____
Estimated cost \$ 900. Fee \$ 4.00

General Description of New Work

To rearrange partitions and doors on fourth floor of annex as per plan.

Revised letter sent 11/2/52.

CERTIFICATE OF OCCUPANCY REQUIREMENT IS WAIVED

It is understood that this permit does not include installation of heating apparatus which is to be taken out separately by and in the name of the heating contractor. PERMIT TO BE ISSUED TO Preble, Inc.

Details of New Work

Is any plumbing involved in this work? _____ Is any electrical work involved in this work? _____
Is connection to be made to public sewer? _____ If not, what is proposed for sewage? _____
Height average grade to top of plate _____ Height average grade to highest point of roof _____
Size, front _____ depth _____ No. stories _____ solid or filled land? _____ earth or rock? _____
Material of foundation _____ Thickness, top _____ bottom _____ cellar _____
Material of underpinning _____ Height _____ Thickness _____
Kind of roof _____ Rise per foot _____ Roof covering _____
No. of chimneys _____ Material of chimneys _____ of lining _____ Kind of heat _____ fuel _____
Framing lumber—Kind _____ Dressed or full size? _____
Corner posts _____ Sills _____ Girt or ledger board? _____ Size _____
Girders _____ Size _____ Columns under girders _____ Size _____ Max. on centers _____
Studs (outside walls and carrying partitions) 2x4-16" O. C. Bridging in every floor and flat roof span over 8 feet.
Joists and rafters: 1st floor _____, 2nd _____, 3rd _____, roof _____
On centers: 1st floor _____, 2nd _____, 3rd _____, roof _____
Maximum span: 1st floor _____, 2nd _____, 3rd _____, roof _____
If one story building with masonry walls, thickness of walls? _____ height? _____

If a Garage

No. cars now accommodated on same lot _____, to be accommodated _____ number commercial cars to be accommodated _____
Will automobile repairing be done other than minor repairs to cars habitually stored in the proposed building? _____

APPROVED:

O.K. - 9/30/52 - ags.

Miscellaneous

Will work require disturbing of any tree on a public street? no
Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? yes

Preble, Inc.

Joseph A. Choulin

Signature of owner by

INSPECTION COPY

NOTES

10-21-52. Not started yet

11-18-52. Same as above

12-6-52. Same as above

[Signature]

1/2/52 - Reopening letter

Permit No. 52/1652

Location 427 Congress St

Owner *[Signature]*

Date of permit 9/30/52

Notif. closing-in

Inspn. closing-in

Final Notif.

Final Inspn.

Cert. of Occupancy issued

Large empty lined area for additional notes or details.



(9) GENERAL BUSINESS ZONE

APPLICATION FOR PERMIT

Class of Building or Type of Structure Installation

Portland, Maine, February 23, 1949

PERMIT ISSUED

FEB 24 1949

CITY of PORTLAND

To the INSPECTOR OF BUILDINGS, PORTLAND, MAINE

The undersigned hereby applies for a permit to ~~install~~ install the following ~~equipment~~ equipment in accordance with the Laws of the State of Maine, the Building Code and Zoning Ordinance of the City of Portland, plans and specifications, if any, submitted herewith and the following specifications:

Location 177 Congress Street 479-461 Within Fire Limits? yes Dist. No. 1
 Owner's name and address Preble, Inc., 177 Congress Street Telephone _____
 Lessee's name and address _____ Telephone _____
 Contractor's name and address Grinnell Co., 275 W. Exchange St., Providence Telephone _____
 Architect _____ Specifications _____ Plans yes No. of sheets 3
 Proposed use of building Stores & Offices No. families _____
 Last use _____ " " _____ No. families _____
 Material masonry No. stories _____ Heat _____ Style of roof _____ Roofing _____
 Other buildings on same lot _____
 Estimated cost \$ _____ Fee \$1.00

General Description of New Work

To install wet (automat. :) sprinkler system on second, third and fourth floors of annex as per plans.

It is understood that this permit does not include installation of heating apparatus which is to be taken out separately by and in the name of the heating contractor. **PERMIT TO BE ISSUED TO** Everett ~~Sweetser~~ Sweetser, 38 Green St. Gorham, Maine

Details of New Work

Is any plumbing involved in this work? _____ Is any electrical work involved in this work? _____
 Height average grade to top of plate _____ Height average grade to highest point of roof _____
 Size, front _____ depth _____ No. stories _____ solid or filled land? _____ earth or rock? _____
 Material of foundation _____ Thickness, top _____ bottom _____ cellar _____
 Material of underpinning _____ Height _____ Thickness _____
 Kind of roof _____ Rise per foot _____ Roof covering _____
 No. of chimneys _____ Material of chimneys _____ of lining _____ Kind of heat _____ fuel _____
 Framing lumber—Kind _____ Dressed or full size? _____
 Corner posts _____ Sills _____ Girt or ledger board? _____ Size _____
 Girders _____ Size _____ Columns under girders _____ Size _____ Max. on centers _____
 Studs (outside walls and carrying partitions) 2x4-16" O. C. Bridging in every floor and flat roof span over 8 feet.
 Joists and rafters: 1st floor _____, 2nd _____, 3rd _____, roof _____
 On centers: 1st floor _____, 2nd _____, 3rd _____, roof _____
 Maximum span: 1st floor _____, 2nd _____, 3rd _____, roof _____
 If one story building with masonry walls, thickness of walls? _____ height? _____

If a Garage

No. cars now accommodated on same lot _____, to be accommodated _____ number commercial cars to be accommodated _____
 Will automobile repairing be done other than minor repairs to cars habitually stored in the proposed building? _____

APPROVED:

OK-2/24/49-ags

Miscellaneous

Will work require disturbing of any tree on a public street? no
 Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? yes

Preble Inc.
Grinnell Co.

Signature of owner by: E. Sweetser

INSPECTION COPY

AP 433 Congress Street-1

April 1, 1948

Portland Savings Bank
433 Congress Street
P. W. Cunningham & Sons
181 State Street

Subject: Building permit for alterations in first
story banking quarters at 433 Congress Street

Gentlemen:

Building permit for the above work is issued to the contractors on the assumption that the bottom of the reinforcement bars in the new floor will be no less than $3/4$ of an inch above the bottom of the slab, and that, if any part of the reinforced floor slab indicated on the plan is to have $1/2$ -inch diameter bars $4 1/2$ " on centers and with reinforcement at right angles to 20-inch I-beam, is to be new concrete, that the reinforcement bars will be bent up and carried along beneath the top of the slab over the 20-inch I-beam to care for negative tension.

Examination of the plan showing no emergency means of egress from the bank unless the existing windows near the bulkhead to be removed could be used to reach the open land next door owned by others, I phoned Mr. Hobbs of the Bank who said that the windows have never been usable as an emergency means of egress and that the doorway in rear wall of the banking quarters, now to be bricked up, is already closed and would lead to the quarters of other tenants anyway and thus could not serve as an emergency means of egress.

While the Building Code does not bear upon this existing situation, except that it does set forth what is considered to be minimum standards for safety, it seems my duty to call your attention to the situation while these changes are being made that those in charge of the bank may have opportunity, while the other work is going on, to correct this defect which perhaps has not been realized before.

I respectfully recommend that consideration be given to at least making one of these windows available for emergency exit or cutting in a doorway and providing fire door operative from the inside only as far to the rear of the banking quarters as possible to give access in case of emergency to the open air of the land next door, in either case the means of egress to be suitably marked with exit signs, directional or otherwise so that employees and patrons alike would know unerringly at time of emergency where to go to get out—thus to avoid a situation whereby some emergency developing in the front of first story or in the basement might trap persons between the rear wall of the banking quarters and the basement stairs. Even though the basement stairs are enclosed and may have fire door at bottom or top, the record of fire doors being maintained in such condition as to safeguard such a situation is not a good one.

If additional alterations should be decided upon to meet this condition, contractor should file application for amendment to the permit now issued with details of the change.

Very truly yours,

Inspector of Buildings

Wlad/S



(G) GENERAL BUSINESS ZONE
APPLICATION FOR PERMIT

Class of Building or Type of Structure Second Class
Portland, Maine, March 31, 1948

PERMIT ISSUED
00394
APR 1 1948
CITY of PORTLAND

To the INSPECTOR OF BUILDINGS, PORTLAND, MAINE

The undersigned hereby applies for a permit to ~~erect~~ alter ~~existing~~ ~~work~~ ~~on~~ ~~the~~ ~~following~~ building structure ~~erect~~ ~~in~~ ~~accordance~~ ~~with~~ ~~the~~ ~~Laws~~ ~~of~~ ~~the~~ ~~State~~ ~~of~~ ~~Maine~~, the Building Code and Zoning Ordinance of the City of Portland, plans and specifications, if any, submitted herewith and the following specifications:

Location 483 Congress Street
Owner's name and address Portland Savings Bank, 483 Congress Street Within Fire Limits? yes Dist. No. no
Lessee's name and address _____ Telephone _____
Contractor's name and address F.W. Cunningham & Sons, 181 State St. Telephone _____
Architect _____ Telephone _____
Proposed use of building Bank & Offices Specifications _____ Plans yes No of sheets 1
Last use _____ No. families _____
Material brick No. stories 4 Heat _____ Style of roof _____ No. families _____
Other buildings on same lot _____ Roofing _____
Estimated cost \$ 7000 Fee \$ 6.00

General Description of New Work

To make alterations in first story as per plans.

Permit Issued with Letter

CERTIFICATE OF OCCUPANCY
REQUIREMENT IS WAIVED

It is understood that this permit does not include installation of heating apparatus which is to be taken out separately by and in the name of the heating contractor. Permit to be issued to F. W. Cunningham & Sons

Details of New Work

Is any plumbing involved in this work? _____ Is any electrical work involved in this work? _____
Height average grade to top of plate _____ Height average grade to highest point of roof _____
Size, front _____ depth _____ No. stories _____ solid or filled land? _____ earth or rock? _____
Material of foundation _____ Thickness, top _____ bottom _____ cellar _____
Material of underpinning _____ Height _____ Thickness _____
Kind of roof _____ Rise per foot _____ Roof covering _____ Kind of heat _____ fuel _____
No. of chimneys _____ Material of chimneys _____ of lining _____ Dressed or full size? _____
Framing lumber—Kind _____ Sills _____ Girt or ledger board? _____
Corner posts _____ Size _____ Columns under girders _____ Size _____ Max. on centers _____
Joists and rafters: _____ 2x4-16" O. C. Bridging in every floor and flat roof span over 8 feet.
On centers: 1st floor _____, 2nd _____, 3rd _____, roof _____
Maximum span: 1st floor _____, 2nd _____, 3rd _____, roof _____
If one story building with masonry walls, thickness of walls? _____ height? _____

If a Garage

No. cars now accommodated on same lot _____, to be accommodated _____ number commercial cars to be accommodated _____
Will automobile repairing be done other than minor repairs to cars habitually stored in the proposed building? _____

Miscellaneous

Will work require disturbing of any tree on a public street? no
Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? yes

APPROVED:

INSPECTION COPY

Signature of owner by:

Portland Savings Bank
F. W. Cunningham & Sons

Frederic L. L...

B

Permit No. 48/394
Location 483 Congress St
Owner Portland Cement Co
Date of permit 4/1/48
Notif. closing-in _____
Inspn. closing-in _____
Final Notif. _____
Final Inspn. 11/18/48
Cert. of Occupancy issued none

NOTES

11/18/48 - Work done,
second means of egress
not provided. C.R.

Vertical text on the right side of the page, likely bleed-through from the reverse side of the document. The text is mostly illegible but appears to contain administrative or inspection-related information.



APPLICATION FOR PERMIT

PERMIT ISSUED
01818
SEP 20 1946

Class of Building or Type of Structure Second Class

Portland, Maine, Sept. 10, 1946

To the INSPECTOR OF BUILDINGS, PORTLAND, ME. Plan rec'd 9/10/46

The undersigned hereby applies for a permit to ~~erect, alter, repair, reconstruct, or demolish~~ install the following building, structure, equipment in accordance with the Laws of the State of Maine, the Building Code and Zoning Ordinance of the City of Portland, plans and specifications, if any, submitted herewith and the following specifications:

Location 483 Congress Street Within Fire Limits? _____ Dist. No. _____
 Owner's name and address Portland Savings Bank, 483 Congress Street Telephone _____
 Lessee's name and address _____ Telephone _____
 Contractor's name and address Ballard Oil & Equip. Co., 135 Marginal Way Telephone 2-1991
 Architect _____ Specifications _____ Plans yes No. of sheets 1
 Proposed use of building Bank & Offices No. families _____
 Last use Bank & Offices No. families _____
 Material _____ No. stories 4 Heat _____ Style of roof _____ Roofing _____

Memorandum from Department of Building Inspection, Portland, Maine
 483 Congress Street--Installation of air-conditioning for Portland Savings Bank
 by Ballard Oil & Equipment Company, installers--9/20/46

To Owner & Installer:

Please note that the standards for construction and installation of such a system, set up under the Building Code by the Board of Municipal Officers, are contained in pamphlet No. 21, standards of the National Board of Fire Underwriters for the Installation of Air-Conditioning, Warm Air Heating, Air Cooling and Ventilating systems, and copy of this pamphlet may be examined here if the installers do not have a copy.

WMD/S

CC: Portland Savings Bank
 483 Congress Street

(Signed) Warren McDonald
 Inspector of Buildings

It is understood that this permit does not include installation of heating apparatus which is to be taken out separately by and in the name of the heating contractor.

Details of New Work

Is any plumbing work involved in this work? _____ Is any electrical work involved in this work? _____
 Height average grade to top of plate _____ Height average grade to highest point of roof _____
 Size, front _____ depth _____ No. stories _____ solid or filled land? _____ earth or rock? _____
 Material of foundation _____ Thickness, top _____ bottom _____ cellar _____
 Material of underpinning _____ Height _____ Thickness _____
 Kind of roof _____ Rise per foot _____ Roof covering _____
 No. of chimneys _____ Material of chimneys _____ of lining _____ Kind of heat _____ fuel _____
 Framing lumber--Kind _____ Dressed or full size? _____
 Corner posts _____ Sills _____ Girt or ledger board? _____ Size _____
 Girders _____ Size _____ Columns under girders _____ Size _____ Max. on centers _____
 Studs (outside walls and carrying partitions) 2x4-16" O. C. Bridging in every floor and flat roof span over 8 feet.
 Joists and rafters: 1st floor _____, 2nd _____, 3rd _____, roof _____
 On centers: 1st floor _____, 2nd _____, 3rd _____, roof _____
 Maximum span: 1st floor _____, 2nd _____, 3rd _____, roof _____
 If one story building with masonry walls, thickness of walls? _____ height? _____

If a Garage

No. cars now accommodated on same lot _____, to be accommodated _____ number commercial cars to be accommodated _____
 Will automobile repairing be done other than minor repairs to cars habitually stored in the proposed building? _____

APPROVED:

Miscellaneous

Will work require disturbing of any tree on a public street? no
 Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? yes

Portland Savings Bank
 Ballard Oil & Equipment Co.

Signature of owner By: Raymond P. Pina

INSPECTION COPY

Permit No. 441818
Location 483 Congress St
Owner Portland Savings Bldg
Date of permit 9/20/46
Notif. closing-in _____
Inspn. closing-in _____
Final Notif. _____
Final Inspn. 9-25-47 PM
Cert. of Occupancy issued _____

NOTES

9-21-46 Work printed
10-25-46 740
Change Inc



(G) GENERAL BUSINESS ZONE
APPLICATION FOR PERMIT

PERMIT 100000

00429

Class of Building or Type of Structure First Class

Portland, Maine, March 25, 1946

To the INSPECTOR OF BUILDINGS, PORTLAND, ME.

The undersigned hereby applies for a permit to ~~erect~~ alter ~~or~~ ~~rebuild~~ ~~or~~ ~~reconstruct~~ all the following building structure equipment in accordance with the Laws of the State of Maine, the Building Code and Zoning Ordinance of the City of Portland, plans and specifications, if any, submitted herewith and the following specifications:

Location 477 Congress Street 472-481 Within Fire Limits? yes Dist. No. 1
Owner's name and address Preble, Inc., 477 Congress Street Telephone _____
Lessee's name and address _____ Telephone _____
Contractor's name and address J. H. Kennedy, 105 Preble Street Telephone _____
Architect _____ Specifications _____ Plans yes No. of sheets 1
Proposed use of building stores, offices and bank No. families _____
Last use _____ " " " " No. families _____
Material con. No. stories 4-12 Heat _____ Style of roof _____ Roofing _____
Other buildings on same lot _____
Estimated cost \$ 250. Fee \$ 1.00

General Description of New Work

To construct non-bearing partitions third floor annex to provide new toilet room as per plan. Studs 2x3, 16" O.C. metal lath and plaster. To provide vent up thru roof for ventilation.

INSPECTION NOT COMPLETED
CERTIFICATE OF OCCUPANCY
REQUIREMENT IS WAIVED

It is understood that this permit does not include installation of bearing apparatus which is to be taken out separately by and in the name of the heating contractor.

Details of New Work

Is any plumbing work involved in this work? yes Is any electrical work involved in this work? yes
Height average grade to top of plate _____ Height average grade to highest point of roof _____
Size, front _____ depth _____ No. stories _____ solid or filled land? _____ earth or rock? _____
Material of foundation _____ Thickness, top _____ bottom _____ cellar _____
Material of underpinning _____ Height _____ Thickness _____
Kind of roof _____ Rise per foot _____ Roof covering _____
No. of chimneys _____ Material of chimneys _____ of lining _____ Kind of heat _____ fuel _____
Framing lumber—Kind _____ Dressed or full size? _____
Corner posts _____ Sills _____ Girt or ledger board? _____ Size _____
Girders _____ Size _____ Columns under girders _____ Size _____ Max. on centers _____
Studs (outside walls and carrying partitions) 2x4-16" O. C. Bridging in every floor and flat roof span over 8 feet.
Joists and rafters: 1st floor _____, 2nd _____, 3rd _____, roof _____
On centers: 1st floor _____, 2nd _____, 3rd _____, roof _____
Maximum span: 1st floor _____, 2nd _____, 3rd _____, roof _____
If one story building with masonry walls, thickness of walls? _____ height? _____

If a Garage

No. cars now accommodated on same lot _____, to be accommodated _____ number commercial cars to be accommodated _____
Will automobile repairing be done other than minor repairs to cars habitually stored in the proposed building? _____

APPROVED:

Blank lines for signature and date.

Miscellaneous

Will work require disturbing of any tree on a public street? no
Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? yes

Preble, Inc.

J. B. Bradley

Signature of owner By: _____

INSPECTION COPY

Permit No 46/429

Location 477 Congress St

Owner P. B. Dine

Date of permit 3/26/46

Notif. closing-in

Inspn. closing-in

Final Notif

Final Inspn

Cert. of Occupancy issued

NOTES

INSPECTION NOT COMPLETED

REVISION FOR PERMIT

PLANS

11333

Large grid area for notes and details, mostly blank.



(G) GENERAL BUSINESS ZONE
APPLICATION FOR PERMIT

PERMIT ISSUED

00354
MAR 15 1946

Class of Building or Type of Structure Second Class

Portland, Maine, March 14, 1946

To the INSPECTOR OF BUILDINGS, PORTLAND, ME.

The undersigned hereby applies for a permit to ~~erect~~ alter ~~reconstruct~~ ~~demolish~~ all the following building-structure-equipment-in-accordance with the Laws of the State of Maine, the Building Code and Zoning Ordinance of the City of Portland, plans and specifications, if any, submitted herewith and the following specifications:

Location 477 Congress Street 479-481 Within Fire Limits? Yes Dist. No. 1
Owner's name and address Preble, Inc., 477 Congress St. Telephone _____
Lessee's name and address _____ Telephone _____
Contractor's name and address J. H. Kennedy, 105 Preble Street Telephone _____
Architect _____ Specifications _____ Plans yes No. of sheets 1
Proposed use of building Stores and offices No. families _____
Last use _____ " " _____ No. families _____
Material non- _____ No stories 12-1 Heat _____ Style of roof _____ Roofing _____

Memorandum from Department of Building Inspection, Portland, Maine

477 Congress St.-- Alterations in rear of second floor of annex for Preble, Inc. by J. H. Kennedy, Contractor---3/14/46

To Owner and Builder:

It is assumed that each separate tenancy in this area has an operative window adequate in size of opening and so located that persons could use the window to reach the roof and thence to the fire escape. If not, such arrangements should be made.

cc J. H. Kennedy,
105 Preble St.

(Signed) Warren McDonald
Inspector of Buildings

It is understood that this permit does not include installation of heating apparatus which is to be taken out separately by and in the name of the heating contractor.

Details of New Work

Is any plumbing work involved in this work? no Is any electrical work involved in this work? no
Height average grade to top of plate _____ Height average grade to highest point of roof _____
Size, front _____ depth _____ No. stories _____ solid or filled land? _____ earth or rock? _____
Material of foundation _____ Thickness, top _____ bottom _____ cellar _____
Material of underpinning _____ Height _____ Thickness _____
Kind of roof _____ Rise per foot _____ Roof covering _____
No. of chimneys _____ Material of chimneys _____ of lining _____ Kind of heat _____ fuel _____
Framing lumber--Kind _____ Dressed or full size? _____
Corner posts _____ Sills _____ Girt or ledger board? _____ Size _____
Girders _____ Size _____ Columns under girders _____ Size _____ Max. on centers _____
Studs (outside walls and carrying partitions) 2x4-16" O. C. Bridging in every floor and flat roof span over 8 feet.
Joists and rafters: 1st floor _____, 2nd _____, 3rd _____, roof _____
On centers: 1st floor _____, 2nd _____, 3rd _____, roof _____
Maximum span: 1st floor _____, 2nd _____, 3rd _____, roof _____
If one story building with masonry walls, thickness of walls? _____ height? _____

If a Garage

No. cars now accommodated or same lot _____, to be accommodated _____ number commercial cars to be accommodated _____
Will automobile repairing be done other than minor repairs to cars habitually stored in the proposed building? _____

APPROVED:

Miscellaneous

Will work require disturbing of any tree on a public street? no
Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? yes

Preble, Inc.

Signature of owner By: J. E. Bradbury

INSPECTION COPY

Permit No 46/354

Location 477 Congress St.

Owner Public Inc

Date of permit 3/15/46

Notif. closing-in _____

Inspn. closing-in _____

Final Notif _____

Final Inspn 10/23/46

Cert. of Occupancy issued None

NOTES

~~NOT FOR PERMIT~~



(G) GENERAL BUSINESS ZONE
APPLICATION FOR PERMIT

Class of Building or Type of Structure Second

PERMIT ISSUED
1824

DEC 22 1945

To the INSPECTOR OF BUILDINGS, PORTLAND, ME.
Portland, Maine, December 18, 1945

The undersigned hereby applies for a permit to ~~construct~~ alter ~~the~~ following building ~~structure~~ in accordance with the Laws of the State of Maine, the Building Code and Zoning Ordinance of the City of Portland, plans and specifications, if any, submitted herewith and the following specifications:

Location 179-181 Congress Street (rear)
Entrance 177 Within Fire Limits? yes Dist. No. 1
Owner's name and address Proble, Inc., 177 Congress Telephone _____
Lessee's name and address _____ Telephone _____
Contractor's name and address J. H. Kennedy, 105 Preble Street Telephone _____
Architect _____ Telephone _____
Proposed use of building Mercantile Specifications _____ Plans yes No. of sheets 1
Last use _____ No. families _____
Material brick No. stories 4 Heat _____ Style of roof _____ Roofing _____
Other buildings on same lot none
Estimated cost \$ 1200 Fee \$ 3.75

General Description of New Work

To re-arrange area on second floor formerly used by Postal Telegraph. Removing partitions and erecting partitions as per plan submitted. To accommodate ~~five~~ ^{four} separate 2x3 partitions, 16 inches on centers Upsom Board and 2x4 partitions, 16 inches on centers, plastered both sides.

INSPECTION NOT COMPLETED

CERTIFICATE OF OCCUPANCY
REQUIREMENT IS WAIVED

It is understood that this permit does not include installation of heating apparatus which is to be taken out separately by and in the name of the heating contractor.

Details of New Work

Is any plumbing work involved in this work? _____ Is any electrical work involved in this work? _____
Height average grade to top of plate _____ Height average grade to highest point of roof _____
Size, front _____ depth _____ No. stories _____ solid or filled land? _____ earth or rock? _____
Material of foundation _____ Thickness, top _____ bottom _____ cellar _____
Material of underpinning _____ Height _____ Thickness _____
Kind of roof _____ Rise per foot _____ Roof covering _____
No. of chimneys _____ Material of chimneys _____ of lining _____ Kind of heat _____ fuel _____
Framing lumber—Kind EmLac Dressed or full size? dressed
Corner posts _____ Sills _____ Girt or ledger board? _____ Size _____
Girders _____ Size _____ Columns under girders _____ Size _____ Max. on centers _____
Studs (outside walls and carrying partitions) 2x4-16" O. C. Bridging in every floor and flat roof span over 8 feet.
Joists and rafters: 1st floor _____ 2nd _____ 3rd _____ roof _____
On centers: 1st floor _____ 2nd _____ 3rd _____ roof _____
Maximum span: 1st floor _____ 2nd _____ 3rd _____ roof _____
If one story building with masonry walls, thickness of walls? _____ height? _____

If a Garage

No. cars now accommodated on same lot _____, to be accommodated _____ number commercial cars to be accommodated _____
Will automobile repairing be done other than minor repairs to cars habitually stored in the proposed building? _____

Miscellaneous

Will work require disturbing of any tree on a public street? no
Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? yes

APPROVED:

Empty box for approval signature

INSPECTION COPY

Signature of owner by:

J. S. Bradley
Proble, Inc.

Permit No 45/1824

Location 479-481 Congress St

Owner Puller, Inc

Date of permit 12/22/45

Notif. closing-in

Inspn. closing-in

Final Notif.

Final Inspection NOT COMPLETE!

Cert. of Occupancy issued

NOTES

1/10/46 Partitions shown
erected in Partitions
dated out on C-76

1/23/46 Windows east
wall to room #1 and
double hung windows
removed 2-4 lead to
roof in fireplace noted
on plan C-76

1/23/46 Partitions as
far back as possible
(to be removed) from
west side of C-76

3/19/46 Work necessary
erected on attached
plan under this date

RM

NO.	DATE	DESCRIPTION	BY
1			
2			
3			
4			
5			
6			
7			
8			
9			
10			
11			
12			
13			
14			
15			
16			
17			
18			
19			
20			
21			
22			
23			
24			
25			
26			
27			
28			
29			
30			
31			
32			
33			
34			
35			
36			
37			
38			
39			
40			
41			
42			
43			
44			
45			
46			
47			
48			
49			
50			
51			
52			
53			
54			
55			
56			
57			
58			
59			
60			
61			
62			
63			
64			
65			
66			
67			
68			
69			
70			
71			
72			
73			
74			
75			
76			
77			
78			
79			
80			
81			
82			
83			
84			
85			
86			
87			
88			
89			
90			
91			
92			
93			
94			
95			
96			
97			
98			
99			
100			



GENERAL BUSINESS ZONE
APPLICATION FOR PERMIT

PERMIT ISSUED
00133

FEB 15 1949

CITY OF PORTLAND

Class of Building or Type of Structure 1st Class
Portland, Maine, FEBRUARY 11, 1949

To the INSPECTOR OF BUILDINGS, PORTLAND, MAINE

The undersigned hereby applies for a permit to erect alter ~~rebuild~~ ^{install} the following building structure equipment in accordance with the Laws of the State of Maine, the Building Code and Zoning Ordinance of the City of Portland, plans and specifications, if any, submitted herewith and the following specifications:

Location 477 Congress Street Within Fire Limits? yes Dist. No. 1
Owner's name and address Preble, Inc., 477 Congress Street Telephone _____
Lessee's name and address _____ Telephone _____
Contractor's name and address Brown Construction Co., 562 Congress St. Telephone _____
Architect _____ Specifications _____ Plans yes No. of sheets 1
Proposed use of building Offices No. families _____
Actual use _____ " _____ No. families _____
Material masonry No. stories 12-4 Heat _____ Style of roof _____ Roofing _____
Buildings on same lot _____
Estimated cost \$ 2500. **INSPECTION NOT COMPLETE:** Fee \$ 5.00

General Description of New Work

To remove several partitions, 3rd floor annex, as per plan to provide office for New England Fire Rating Assoc., ~~xxx~~ to provide steel beams for support
To make minor alterations to non-bearing partitions in Room 312 of Annex.

Permit Issued with Letter

CERTIFICATE OF OCCUPANCY
REQUIREMENT IS WANTED

It is understood that this permit does not include installation of heating apparatus which is to be taken out separately by and in the name of the heating contractor. **PERMIT TO BE ISSUED TO** Preble, Inc.

Details of New Work

Is any plumbing involved in this work? _____ Is any electrical work involved in this work? _____
Height average grade to top of plate _____ Height average grade to highest point of roof _____
Size, front _____ depth _____ No. stories _____ solid or filled land? _____ earth or rock? _____
Material of foundation _____ Thickness, top _____ bottom _____ cellar _____
Material of underpinning _____ Height _____ Thickness _____
Kind of roof _____ Rise per foot _____ Roof covering _____
No. of chimneys _____ Material of chimneys _____ of lining _____ Kind of heat _____ fuel _____
Framing lumber—Kind _____ Dressed or full size? _____
Corner posts _____ Sills _____ Girt or ledger board? _____ Size _____
Girders _____ Size _____ Columns under girders _____ Size _____ Max. on centers _____
Studs (outside walls and carrying partitions) 2x4-16" O. C. Bridging in every floor and flat roof span over 8 feet.
Joists and rafters: 1st floor _____, 2nd _____, 3rd _____, roof _____
On centers: 1st floor _____, 2nd _____, 3rd _____, roof _____
Maximum span: 1st floor _____, 2nd _____, 3rd _____, roof _____
If one story building with masonry walls, thickness of walls? _____ height? _____

If a Garage

No. cars now accommodated on same lot _____, to be accommodated _____ number commercial cars to be accommodated _____
Will automobile repairing be done other than minor repairs to cars habitually stored in the proposed building? _____

Miscellaneous

Will work require disturbing of any tree on a public street? no
Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? yes

Preble, Inc.

APPROVED:
O.K. - 2/15/49 - OJS
with letter.

INSPECTION COPY

Signature of owner By: _____

Joseph C. Chandler

Permit No. 49-188

Location 477 Congress St.

Owner (P) Kelly, Inc.

Date of permit 2/15/49

Notif. closing-in

Inspn. closing-in

Final Notif.

Final Inspn.

Cert of Occupancy issued

INSPECTION NOT COMPLETE

NOTES

LOCATION 477 Congress St

DATE 2/15/49

PERMIT

INQUIRY

COMPLAINT

W.C. No. -

These alterations will open up the area on third story so that it will be possible to travel through offices to rear of building where access may be had through windows to roof of two story porch from which a sort of steel ship ladder arrangement leads to roof of arcade below from which access may be had across roof to fire escape leading to ground in alley to North Theater from
Bl-67 Public Street - C-48



APPLICATION FOR AMENDMENT TO PERMIT

Amendment No. 1

Portland, Maine, March 15, 1949

PERMIT ISSUED

MAR 17 1949

CITY of PORTLAND

To the INSPECTOR OF BUILDINGS, PORTLAND, MAINE

The undersigned hereby applies for amendment to Permit No. 49-188 pertaining to the building or structure comprised in the original application in accordance with the Laws of the State of Maine, the Building Code and Zoning Ordinance of the City of Portland, plans and specifications, if any, submitted herewith, and the following specifications:

Location 477 Congress St. 477-AB1 Within Fire Limits? yes Dist. No. 1

Owner's name and address Preble, Inc., 477 Congress Street Telephone _____

Lessee's name and address _____ Telephone _____

Contractor's name and address Brown Construction Co., 562 Congress St. Telephone _____

Architect _____ Plans filed yes. No. of sheets 1

Proposed use of building Offices No. families _____

Last use _____ No. families _____

Increased cost of work _____ Additional fee 25

Description of Proposed Work

To make alteration on third floor annex as per plan.

Details of New Work

Is any plumbing involved in this work? _____ Is any electrical work involved in this work? _____

Height average grade to top of plate _____ Height average grade to highest point of roof _____

Size, front _____ depth _____ No. stories _____ solid or filled land? _____ earth or rock? _____

Material of foundation _____ Thickness, top _____ bottom _____ cellar _____

Material of underpinning _____ Height _____ Thickness _____

Kind of roof _____ Rise per foot _____ Roof covering _____

No. of chimneys _____ Material of chimneys _____ of lining _____

Framing lumber—Kind _____ Dressed or full size? _____

Corner posts _____ Sills _____ Girt or ledger _____ Size _____

Girders _____ Size _____ Columns under girders _____ Size _____ Max. on centers _____

Studs (outside walls and carrying partitions) 2x4-16" O. C. Bridging in every floor and flat roof span over 8 feet.

Joists and rafters: 1st floor _____, 2nd _____, 3rd _____, roof _____

On centers: 1st floor _____, 2nd _____, 3rd _____, roof _____

Maximum span: 1st floor _____, 2nd _____, 3rd _____, roof _____

Approved: _____ Preble, Inc.



Signature of Owner by: Joseph A. Hardie

Approved: _____ Inspector of Buildings

INSPECTION COPY

1740 # x 12				360			
2880 # roof				2880		11.2 x 2 x 130	65
4200 #						195	155
10v12 Wood	10" WF 33			3120	1155 #		
Strip				5	6		
				15			24
							1150
							2680
							3120
Total R = 8 x 720 + 2880 + 17				15 R ₁ = 3120 x 5 + 1155 x 9			3120
= 7980 #				= 15600 + 10395			15600
(Weld less than assumed 10660 #)				= 25995			1650
				15			10395
							125
							3560
							25800
							7780
Max end is on the Cll beam 10660 #							
4: 3/4 bolts = 4 x 302 x 10000 # = 12000 # allowable							
M = 10660 x 36 = 38400 # ÷ 20000 = 19.2 assumed S							
35 = actual S							

RECEIVED
MAY 17 1955



RECEIVED
 MAR 17 1949
 DEPT. OF CIVIL ENGR.
 CITY OF PORTLAND

AP 477 Congress Street-I

February 15, 1949

Proble, Inc.
477 Congress Street
James C. Saunders & Associates
477 Congress Street

Subject: Permit for alterations to
offices in rear of third story of
Annex at 477 Congress Street

Gentlemen:

The permit for the above work is issued herewith based on plan filed with application and subject to the following:

1. We presume that investigation has been made to make sure of the adequacy of the column in the second story and its supports to take care of the added load to be put upon it from the new 4" lally column with the end of the new 10" wide flanged 33# beam and that if not, it will be made before erection of steel is started.
2. In the absence of any detail of the fireproofing of the new 18" wide flanged 50# beam we wish to call attention to Building Code requirements for a minimum thickness at all points of 2" of poured concrete with wire mesh or similar reinforcement embedded not less than three fourths of an inch from its outer edge.

Very truly yours,

Inspector of Buildings

MS/O

CC) Town Construction Company
302 Congress Street



(G) GENERAL BUSINESS ZONE
APPLICATION FOR PERMIT

Class of Building or Type of Structure second

Portland, Maine, June 22, 1945

To the INSPECTOR OF BUILDINGS, PORTLAND, ME.

The undersigned hereby applies for a permit to erect alter repair demolish install the following building structure equipment in accordance with the Laws of the State of Maine, the Building Code and Zoning Ordinance of the City of Portland, plans and specifications, if any, submitted herewith and the following specifications:

Location 481 (rear) Congress St. Within Fire Limits? Yes Dist. No. 1
Entrance through 477
Owner's name and address Proble Inc. 477 Congress St. Telephone _____
Lessee's name and address _____ Telephone _____
Contractor's name and address Brown Const. Co. 562 Congress St. Telephone 2-3893
Architect _____ Specifications _____ Plans _____ No. of sheets _____
Proposed use of building Mercantile No. families _____
Last use mercantile No. families _____
Material brick No. stories 2 Heat steam Style of roof flat Roofing _____
Other buildings on same lot _____
Estimated cost \$ 100 Fee \$ 50

General Description of New Work

Remove short run of steep stairs ^(wood) leading from mezzanine to second floor of Chapman Annex and replace with easier run by moving door at ~~###~~ foot of present run back about 12' (Former Postal Tel. office)
Cut in new door in corridor (formed by above work) to office.
No structural changes.

CERTIFICATE OF OCCUPANCY
REQUIREMENT IS WAIVED

It is understood that this permit does not include installation of heating apparatus which is to be taken out separately by and in the name of the heating contractor.

Details of New Work

Is any plumbing work involved in this work? no Is any electrical work involved in this work? _____
Height average grade to top of plate no Height average grade to highest point of roof _____
Size, front _____ depth _____ No. stories _____ solid or filled land? _____ earth or rock? _____
Material of foundation _____ Thickness, top _____ bottom _____ cellar _____
Material of underpinning _____ Height _____ Thickness _____
Kind of roof _____ Rise per foot _____ Roof covering _____
No. of chimneys _____ Material of chimneys _____ of lining _____ Kind of heat _____ fuel _____
Framing lumber—Kind _____ Dressed or full size? _____
Corner posts _____ Sills _____ Girt or ledger board? _____ Size _____
Girders _____ Size _____ Columns under girders _____ Size _____ Max. on centers _____
Stud (outside walls and carrying partitions) 2x4-16" O. C. Bridging in every floor and flat roof span over 8 feet.
Joists and rafters: 1st floor _____, 2nd _____, 3rd _____, roof _____
On centers: 1st floor _____, 2nd _____, 3rd _____, roof _____
Maximum span: 1st floor _____, 2nd _____, 3rd _____, roof _____
If one story building with masonry walls, thickness of walls? _____ height? _____

If a Garage

No. cars now accommodated on same lot _____ to be accommodated _____ number commercial cars to be accommodated _____
Will automobile repairing be done other than minor repairs to cars habitually stored in the proposed building? _____

APPROVED:

Miscellaneous

Will work require disturbing of any tree on a public street? no
Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? yes

INSPECTION COPY

Signature of owner Proble Inc. by H.C. Emery 63910

Permit No 45/620

Location 481 Congress St

Owner Preble, Inc

Date of permit 6/23/45

Notif. closing-in _____

Inspn. closing-in _____


Final Notif _____

Final Inspn 7/28/45

Cert. of Occupancy issued None

NOTES

7/5/45 - Work done except
for rebuilding of stairs
aged



January 25, 1945

Having checked this proposal roughly against Building Code requirements for Club and Lodge buildings and having looked the situation over at the building (the proposed quarters are really on the second story of that part of the building being directly over Portland Savings Bank quarters as far as I could see, instead of in third story as Mr. Grandall told me), I went up to see Mr. Grandall and we went down and look the rooms over together.

The large room would have a capacity of about 200 for seating arrangement and about 90 for dancing. The emergency means of egress situation is very bad, and even if they were able to put a door in the rear part of the large room leading out onto the roof, occupants of these quarters would have to walk along an obstructed roof and climb narrow steps onto a higher level roof, cross that roof for about 15 feet then climb down similar narrow steps (practically a ladder) to a lower level roof, cross that lower level, then climb up onto still another roof and cross that roof to reach the firescape which leads from that level down into an alley by the side of Potter's Furniture Store.

I told Mr. Grandall that it looked to me as though this matter of emergency means of egress presents ~~the~~ impossible difficulties; that some other features probably the matter of fire resistance between the Portland Savings Bank below and to these quarters could only be satisfied by allowances from the Municipal Officers and that if it came to that I should certainly have to recommend against asking any allowances on the means of egress.

I should judge from his reaction to that, that there will be no further effort to use the quarters for this purpose.

Warren McDonald

CC: A. Edwin Smith
City Clerk

*was not there
a c. from Smith
if so I might
to be removed
here - show
file with copy*

INQUIRY BLANK

ZONE G.

FIRE DIST. 1

CITY OF PORTLAND, MAINE
DEPARTMENT OF BUILDING INSPECTION

Verbal
By Telephone

DATE 1/19/45

LOCATION 119-481 over Portland Savings Bank
477 Congress OWNER Presle, Inc.
MADE BY H.C. Scandall, Post Gen. Exp. of United Seamen's Service. TEL. 3-1293
ADDRESS 477 Congress - Room 305

PRESENT USE OF BUILDING Bldg

CLASS OF CONSTRUCTION 2nd class NO. OF STORIES

REMARKS:

INQUIRY: What is required to convert rooms
at rear of this Bldg (4 rooms - 12 sq ft each
probably same as those used by Postal Tel.
formerly) to Union Assn. Hall
for United Seamen's Service - large room
to be used for games, dancing, perhaps more
etc - 2 rooms for offices, 1 for writing & one for
small kitchen (kitchen to be removed & replaced
by other rooms - 1 for kitchen & 1 for
other volunteer types

ANSWER: See memo dated 1/25/45
See notes - occupational use


DATE OF REPLY 1/25/45 REPLY BY WMM

479-481

RECEIVED
AUG 21 1941
DEPT. OF BLD'G. INSP.
CITY OF PORTLAND

Business
Office

Orndorff





Original Permit No. 11717 INSUR

Amendment No. 1

AUG 23 1941

AMENDMENT TO APPLICATION FOR PERMIT

To the INSPECTOR OF BUILDINGS, PORTLAND, ME.

Portland, Maine, August 21, 1941

The undersigned hereby applies for an amendment to Permit No. 11/1099 pertaining to the building or structure comprised in the original application in accordance with the Laws of the State of Maine, the Building Code of the City of Portland, plans and specifications, if any, submitted herewith, and the following specifications:

Location 177-181 Congress Street Within Fire Limits? Yes Dist. No. 1
 Owner's or Lessee's name and address Proble, Inc.
10336 Portland Savings Bank, 181 Congress Street
 Contractor's name and address Georgine G. Clark, 46 Portland St. No. of Sheets 2-168
 Plans filed as part of this Amendment? yes
 Is any plumbing work involved in this work? _____ Is any electrical work involved in this work? _____
 Increased cost of work 1.00 Additional fee .25
 Framing Lumber: Kind? _____ Dressed or Full Size? _____

Description of Proposed Work

To put in new partitions, 2x3 studs, 16" OC sheet rock both sides, to provide private office in room as shown on plan submitted, first floor of building.

Approved: _____
 Chief of Fire Department.

 Commissioner of Public Works.

Proble, Inc.
 By Portland Savings Bank
 By Georgine G. Clark
 Signature of Owner Georgine G. Clark
 Approved: 8/22/41
W. J. McDonald
 Inspector of Buildings

INSPECTION COPY

Rept. 33712-1

July 29, 1941

Geogins & Clark,
46 Portland Street,
Portland, Maine

Gentlemen:

Referring to your application for a building permit to cover certain changes in the building occupied by the Portland Savings Bank at 485 Congress Street, the fire door in the proposed new opening between the bank and the lobby of the Chapman Building is required to be of a type identified as Class B and is required to bear the Underwriters' Label establishing it as of that class. The Kelocain covered frame indicated on the plan does not satisfy the requirements for a Class B fire separation opening, but a structural metal frame will be necessary.

Will you be kind enough to have the plan (Miller & Deal, Inc. are receiving a copy of this letter) revised to indicate these required details clearly. Use labeled Class B door and the structural metal frame, so that our record may be complete enough to issue the permit?

In connection with the removal of the stairs to the collar under the Portland Savings Bank quarters, I have talked with Mr. Leighton of the bank and it is the understanding of both the Fire Chief and myself that this collar space is not used for any purpose other than storage such as vaults, etc., and that no one is habitually employed in this collar. These are the only circumstances under which to call for the removal of the stairs.

Very truly yours,

Inspector of Buildings

WSD/11


CC: Miller & Deal, Inc.

Please attach your statement of design to the revised plan.

Warren McDonald

CC: Portland Savings Bank
485 Congress Street,

Preble, Inc.
477 Congress Street





Class of Building or Type of Structure Second Class

PERMIT ISSUED
Permit No. 1479

AUG 1 1911

Portland, Maine, July 23, 1911

To the INSPECTOR OF BUILDINGS, PORTLAND, ME.

The undersigned hereby applies for a permit to erect alter, ~~amend~~ the following building structure ~~equipment~~ in accordance with the Laws of the State of Maine, the Building Code of the City of Portland, plans and specifications, if any, submitted herewith and the following specifications:

Location 483 Congress Street Within Fire Limits? yes Dist. No. 1
 Owner's or Lessee's name and address Prable, Inc. Portland Savings Bank Telephone _____
 Contractor's name and address Googins & Clark, 16 Portland Street Telephone 2-3168
 Architect _____ Plans filed yes No. of sheets 1
 Proposed use of building Banks, Offices and stores No. families _____
 Other buildings on same lot _____
 Estimated cost \$ 400 Fee \$ 1.00

Description of Present Building to be Altered

Material brick No. stories 11-1 Heat _____ Style of roof _____ Roofing _____
 Last use Banks, offices and stores No. families _____

General Description of New Work

enclosed
 To provide new entrance from bank to lobby of Chapman Building as per plan submitted
 To floor over existing basement stairs (easterly side) from Savings Bank, there is another
 stairway to this basement which is not used by the Public - 2x6 joists 16" OC, 4' span

It is understood that this permit does not include installation of heating apparatus which is to be taken out separately by and in the name of the heating contractor.

Details of New Work

Is any plumbing work involved in this work? _____
 Is any electrical work involved in this work? _____ Height average grade to top of plate _____
 Size, front _____ depth _____ No. stories _____ Height average grade to highest point of roof _____
 To be erected on solid or filled land? _____ earth or rock? _____
 Material of foundation _____ Thickness, top _____ bottom _____ cellar _____
 Material of underpinning _____ Height _____ Thickness _____
 Kind of roof _____ Rise per foot _____ Roof covering _____
 No. of chimneys _____ Material of chimneys _____ of lining _____
 Kind of heat _____ Type of fuel _____ Is gas fitting involved? _____
 Framing lumber—Kind _____ Dressed or full size? _____
 Corner posts _____ Sills _____ Girt or ledger board? _____ Size _____
 Material columns under girders _____ Size _____ Max. on centers _____
 Studs (outside walls and carrying partitions) 2x4-16" O. C. Girders 6x8 or larger. Bridging in every floor and flat roof span over 8 feet. Sills and corner posts all one piece in cross section.
 Joists and rafters: 1st floor _____, 2nd _____, 3rd _____, roof _____
 On centers: 1st floor _____, 2nd _____, 3rd _____, roof _____
 Maximum span: 1st floor _____, 2nd _____, 3rd _____, roof _____
 If one story building with masonry walls, thickness of walls? _____ height? _____

If a Garage

No. cars now accommodated on same lot _____ to be accommodated _____
 Total number commercial cars to be accommodated _____
 Will automobile repairing be done other than minor repairs to cars habitually stored in the proposed building? _____

Miscellaneous

Will above work require removal or disturbing of any shade tree on a public street? no
 Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? yes

INSPECTION COPY
 Signature of owner By Prable, Inc.
Portland Savings Bank, Lessee
 By Googins & Clark
 By A. H. Clark

Permit No. 41/1099
Location 485 Congress
List of Owners: [illegible]
Date of permit 8/1/41

Notif. closing-in
Inspn. closing-in

Final Notif.

Final Inspn. 10/31/41

Cert. of Occupancy issued

NOTES

8/13/41 - [illegible]
[illegible]
9/19/41 - [illegible]
[illegible] - [illegible]

~~[Large handwritten mark]~~

Table with multiple columns containing various data points, including dates, initials, and possibly inspection results.



(G) GENERAL BUSINESS ZONE
APPLICATION FOR PERMIT **PERMIT ISSUED**

Class of Building or Type of Structure First OCT 19 1934

Portland, Maine, Oct. 13, 1934

To the INSPECTOR OF BUILDINGS, PORTLAND, ME.

The undersigned hereby applies for a permit to erect alter ~~install~~ the following building ~~to include~~ equipment in accordance with the Laws of the State of Maine, the Building Code of the City of Portland, plans and specifications, if any, submitted herewith and the following specifications:

Location 477 Congress St. 479-481 Ward 4 Within Fire Limits Yes Dist. No. 1
 Owner's or Lessee's name and address Portland Savings Bank 477 Congress St. Telephone _____
 Contractor's name and address Coogins & Clark 46 Portland St. Telephone 2-5168
 Architect's name and address _____
 Proposed use of building Bank & offices No. families _____
 Other buildings on same lot no
 Plans filed as part of this application? no No. of sheets _____
 Estimated cost \$ 1000. Fee \$ 1.00

Description of Present Building to be Altered

Material Brick No. stories 14 Heat _____ Style of roof Flat Roofing _____
 Last use Bank & Offices No. families _____

General Description of New Work

Remove 2 non-bearing partitions making space now occupied by toilet and waiting room part of main floor space, work on first floor.

CERTIFICATE OF OCCUPANCY
 REQUIREMENT IS WAIVED

It is understood that this permit does not include installation of heating apparatus which is to be taken out separately by and in the name of the heating contractor.

Details of New Work

Size, front _____ depth _____ No. stories _____ Height average grade to top of plate _____
 Height average grade to highest point of roof _____
 To be erected on solid or filled land? _____ earth or rock? _____
 Material of foundation _____ Thickness, top _____ bottom _____
 Material of underpinning _____ Height _____ Thickness _____
 Kind of Roof _____ Rise per foot _____ Roof covering _____
 No. of chimneys _____ Material of chimneys _____ of lining _____
 Kind of heat _____ Type of fuel _____ Is gas fitting involved? _____
 Corner posts _____ Sills _____ Girt or ledger board? _____ Size _____
 Material columns under girders _____ Size _____ Max. on centers _____
 Studs (outside walls and carrying partitions) 2x4-16" O. C. Girders 6x8 or larger. Bridging in every floor and flat roof span over 8 feet. Sills and corner posts all one piece in cross section.
 Joists and rafters: 1st floor _____, 2nd _____, 3rd _____, roof _____
 On centers: 1st floor _____, 2nd _____, 3rd _____, roof _____
 Maximum span: 1st floor _____, 2nd _____, 3rd _____, roof _____
 If one story building with masonry walls, thickness of walls? _____ height? _____

If a Garage

No. cars now accommodated on same lot _____, to be accommodated _____
 Total number commercial cars to be accommodated _____
 Will automobile repairing be done other than minor repairs to cars habitually stored in the proposed building? _____

Miscellaneous

Will above work require removal or disturbing of any shade tree on a public street? no
 Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? Yes


Signature of owner Portland Savings Bank

INSPECTION COPY

C. H. Clark

30065 H

Ward 4 Permit No 3111628
Location 477 Bayview St
Owner William Dawson Bush
Date of permit 10/13/34
Notif. closing-in _____
Inspn. closing-in _____
Final Notif. _____
Final Inspn. 10/19/34 None
Cets. of Occupancy issued _____
10/19/34 done NOTES
Work being
done J.S.





APPLICATION FOR PERMIT

Class of Building or Type of Structure Second

Portland, Maine, April 26, 1930

PERMIT No. 11175
MAY 7 1930
0812

To the INSPECTOR OF BUILDINGS, PORTLAND, ME.

The undersigned hereby applies for a permit to erect alter ~~insert~~ the following building structure equipment in accordance with the Laws of the State of Maine, the Building Code of the City of Portland, plans and specifications, if any, submitted herewith and the following specifications:

Location 477 Congress Street (79-48) Ward 4 Within Fire Limits? Yes Dist. No. 1
Owner's or Lessee's name and address Postal Telegraph Co., Telephone _____
Contractor's name and address F. A. Rummy Co., 553 Forest Ave. Telephone F 4342
Architect's name and address _____
Proposed use of building Offices No. families _____
Other buildings on same lot _____

Description of Present Building to be Altered

Material brick No. stories 4 Heat _____ Style of roof _____ Roofing _____
Last use Offices No. families _____

General Description of New Work

To remove one bearing partition and support with steel beam as shown on plan
To enlarge ~~and~~ existing windows
To put in new partitions as shown on plan to provide suite of offices on second floor, west wing
To put 3" concrete floor over section of floor

Details of New Work

Size, front _____ depth _____ No. stories _____ Height average grade to highest point of roof _____
To be erected on solid or filled land? _____ earth or rock? _____
Material of foundation _____ Thickness, top _____ bottom _____
Material of underpinning _____ Height _____ Thickness _____
Kind of roof _____ Roof covering _____
No. of chimneys _____ Material of chimneys _____ of lining _____
Kind of heat _____ Type of fuel _____ Distance, heater to chimney _____
If oil burner, name and model _____
Capacity and location of oil tanks _____
Is gas fitting involved? _____ Size of service _____
Corner posts _____ Sills _____ Girt or ledger board? _____ Size _____
Material columns under girders _____ Size _____ Max. on centers _____
Studs (outside walls and carrying partitions) 2x4-16" O.C. Girders 6x8 or larger. Bridging in every floor and flat roof span over 8 feet. Sills and corner posts all one piece in cross section.
Joists and rafters: 1st floor _____, 2nd _____, 3rd _____, roof _____
On centers: 1st floor _____, 2nd _____, 3rd _____, roof _____
Maximum span: 1st floor _____, 2nd _____, 3rd _____, roof _____
If one story building with masonry walls, thickness of walls? _____ height? _____

If a Garage

No. cars now accommodated on same lot _____, to be accommodated _____
Total number commercial cars to be accommodated _____
Will automobile repairing be done other than minor repairs to cars habitually stored in the proposed building? _____

Miscellaneous

Will above work require removal or disturbing of any shade tree on a public street? no
Plans filed as part of this application? Yes No. sheets 2
Estimated cost \$ 1200. Fee \$ 3.75
Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? Yes

INSPECTION COPY

Signature of owner F. A. Rummy Co.
Postal Telegraph Co.

A J Bird

1626A

P
4. Permit No. 30/12

477 Congress St.

Postal Telegraph Co.

Date of permit 4/7/30

Notif. closing-in 5/26/30 - 3:15 P.M.

no. closing-in 5/27/30 - 8:15 A.M.

Final Notif.

Final Inspn.


Cert. of Occupancy issued

NOTES

- 5/10/30 - Clearing out
begin - A. G. J.
- 5/23/30 - Part of steel in place
- 5/27/30 - Permission given
to close in steel on 2nd
+ 3rd floors. Went over
inspecting of steel
beams with Messrs. G. J.
- 6/13/30 - Clearing
in windows G. J.
- 6/14/30 - Clear for Hayden
Clare office OK. without
door which is being
blocked. How about
closing in under stairs
- 7/12/30 - Work done G. J.



Auto Reg. Co. Amendment #1 Permit #250/812
 15 @ 42.9" I on 22' span. S/W/30



$$11 \times (130 + 60) \times 130 = 27,170$$

$$R_1 = 27,000 \times \frac{3}{22} + \frac{650 \times 22}{2} = 3681 + 7150 = 10,831$$

$$(10,500 \times 19 - 650 \times 19 \times 9.5) / 12 =$$

$$(20,5250 - 117,325) / 12 =$$

$$87,875 \times 12 =$$

Please figure
 in even 4'
 center and
 floor load
 twice.
 deduct

$$M = \frac{5T}{C}$$

$$\frac{T}{C} = \frac{87,875 \times 12}{78,000} = 58.87$$

11 x 65 x 134
 add 10 x 20 x 22
 = net deduct

5 of 15" @ 42.9" I = 58.91 of 48.95.

$$R_2 = 23,400 + 7150 = 30,550$$

$$30,550 + 23,180 = 53,730$$

4 1/2" 1 x W. Gully on 10' height good for 48,800

$$11 \times 125 \times 13 + 10 \times 20 \times 22 \times \frac{3}{22} + 7150 = 5057$$

$$22,225 - 5057 + 7150 = 19,238 + 7150 = 26,388 = R_2$$

$$24,388 + 23,100 = 49,596$$

Teague's - 2nd floor west wing of
Chapman Bldg. 5/3/50.

OK 2x8 spruce joists 12" O.C on 11' span good for 1422
 $110 \times 11 = 1210$
 $8 \times 10 \times 11 \times 110 = 12,100$
 $10.5 \times 11 \times 110 = 12,705$
 OK 10" x 35" L on 13' span good for 26,900
 $2 \times 12,705 = 25,400$

Front -


15" @ 41.9 I at 3rd floor level on 21' span good for 34,000*

$10.25 \times 22 \times (150 + 60) = 54,100$

$10 \times 21 \times (130 + 60) = 39,900 - 10,500 = 29,400*$

X $18 \times 21 \times 20 = 7560$

46450
 23200
 60
 $= 46360$



R₁ = 58,850

$20 \times 120 + 180 \times 5 = 3325$ or 3300

$R_1 = \frac{16 \times 23,400}{21} + \frac{6 \times 23,400}{21} + \frac{3300 \times 21}{21} =$

$= 24,200 + 34,650 = 58,850$

$M_1 = 58,850 \times 5 - 5 \times 3300 \times 2.5 =$

$= 294,250 - 41,250 = 253,000 \text{ ft-lb.}$

$M_2 = 58,850 \times 15.0 - (23,400 \times 10 + 3300 \times 7.5 \times 7.5) = 279,250 \text{ ft-lb.}$

$88,270$
 $603,250$
 $279,250 \times 12 = 3,354,000 \text{ in-lb.}$

$I_u = \frac{S I}{C}; \quad \frac{I}{C} = \frac{3,354,000}{18,000} = 187$

X S of 15" @ 54.7 I = 88.39; 2 x 88.39 = 176.78

OK S of 20" @ 65.4 = 116.95; 2 x 116.95 = 233.90

ESTIMATOR FURNISHED FOR ALL CLASSES OF BUILDINGS

F. A. RUMERY CO.
GENERAL CONTRACTORS

Office, 533 Forest Avenue

Portland, Maine

May 6, 1930.

SUBJECT: Proposed Alterations Second Floor Chapman Building.

Mr. Warren McDonald,
Inspector of Buildings,
Portland, Maine.

Dear Sir:

Upon further investigation of the loads coming upon the new third floor beams in the above building we find that the new beams originally called for on these plans are not of the proper size. Will you therefore kindly change the beam sizes shown on the blueprint now in your possession as follows:

Change 15"/42.9# to 15"/60.8#
and 18"/54.7# to 20"/65.4#.

Thanking you for your cooperation in this
matter, we are

Yours very truly,

F. A. RUMERY CO.

By



Designing Engineer.

SHB:S

Copies Sent To

Original Permit No. 20/812

Amendment 1
PERMIT ISSUED

AMENDMENT TO APPLICATION FOR PERMIT

Portland, Maine, May 19, 1930

To the INSPECTOR OF BUILDINGS, PORTLAND, ME.

The undersigned hereby applies for an amendment to Permit No. 20/812 pertaining to the building or structure comprised in the original application in accordance with the Laws of the State of Maine, the Building Code of the City of Portland, plans and specifications, if any, submitted herewith, and the following specifications:

Location 477 Congress Street Ward 4 With the Fire Limits? yes Dist. No. 1

Owner's or Lessee's name and address Postal Telegraph Co.

Contractor's name and address F. A. Dunbar Co. 555 Forest Ave. D.P. 4743

Plans filed as part of this Amendment yes No. of sheets 1

Description of Proposed Work

Replace wooden beams and column with steel beams and column as per plan submitted

Signature of Owner *Paul C. ...*

Approved:

Chief of Fire Department

Approved: *W. A. ...*

Commissioner of Public Works

W. A. ...
Inspector of Buildings

INSPECTION COPY

.25 fee

1895'D

Inspector of Buildings.

RM/HC
Enc.

#1626-I

2 8/2'

May 7, 1930

F. A. Rumery Company
535 Forest Avenue
Portland, Maine

Gentlemen:

Enclosed is the building permit covering alterations for the Postal Telegraph Company, lessees in the second story of the west wing of the Chapman Building; at 477 Congress Street.

In connection with the pair of 20" I beams intended to support the brick wall removed, please note that these I beams are to be fully fireproofed with poured concrete or the like; that care should be taken to provide sufficient bearing area upon the brick wall at both ends of this pair of beams at the rate of 135 pounds per square inch; and also please note and follow what Section 278 of the Building Code has to say with regard to separators in such a case.

Very truly yours,

Inspector of Buildings.

WM/HG
Enc.

R-5/16/30

#1552A-I

May 7, 1930

The Proble Corporation
477 Congress Street
Portland, Maine

Gentlemen:

Please refer to my letter of April 30th, 1930 concerning the strengthening of the roof of the west wing of the Chapman Building at 477 Congress Street.

When this letter was written, it was with the impression that this was a three story building. It is, of course, a four story building, and we find that it is not only necessary to strengthen the supports of the roof, but also the supports of the third floor as well as those of the second floor which the F. A. Rumery Company is already undertaking.

Please be governed accordingly.

Very truly yours,

Inspector of Buildings.

WM/HGO

1552-A
4-5/16/30

April 30, 1930

The Fréble Corporation
477 Congress Street
Portland, Maine

Gentlemen:

I have today issued the building permit to F. A. Rumery Company covering alterations in the third floor of the west wing of your building at 477 Congress Street, the contractors having furnished information to show that the third floor supports would be adequately strengthened.

As noted in my letter of April 22nd to the F. A. Rumery Company, copy to you, the roof of this section of the building is in about the same condition as the third floor, the timbers being very much overloaded.

It will be necessary for you to take immediate steps to have this roof structure reinforced in a manner similar to that which you plan to do in the case of the third floor.

Please have this matter attended to on or before May 15, 1930.

Very truly yours,

Inspector of Buildings.

m/n

CC-F. A. Rumery Co., -53. Forest Avenue

#1552-A

April 22, 1920

F. A. Ramory Company
535 Forest Ave. No
Portland, Maine

Gentlemen:

Referring to your application in the name of the Preble Corporation for a building permit to make alterations in the rear of the third floor at 477 Congress Street, I find upon examination that the crane girders are very much overloaded. They figure out scarcely strong enough to take the dead load alone as is clearly evident by the considerable sag in each one of them. I believe that it will be necessary to take definite steps to strengthen this floor before it is put to any use whatever.

Will you be kind enough to take this matter up with the owners who are receiving a copy of this letter, and submit a plan for strengthening the floor so that the building permit for the changes may be issued promptly? I would suggest at the same time that similar strengthening measures be taken under the roof of this part of the building, as that too is obviously overloaded.

Very truly yours,

Inspector of Buildings.

RM/HO

CC-Preble Corporation-477 Congress St.



APPLICATION FOR PERMIT

Permit No. _____

PERMIT
MAY 2 1930

Class of Building or Type of Structure Second

Portland, Maine, April 18, 1930

To the INSPECTOR OF BUILDINGS, PORTLAND, ME.

The undersigned hereby applies for a permit to ~~erect~~ alter ~~install~~ the following building structure equipment in accordance with the Laws of the State of Maine, the Building Code of the City of Portland, plans and specifications, if any, submitted herewith and the following specifications:

Location 477 Congress Street 479-481 Ward 4 Within Fire Limits? Yes Dist. No. 1

Owner's or Lessee's name and address Proble Corporation, 477 Congress St. Telephone _____

Contractor's name and address W. H. Harey Co., 523 Forest Ave. Telephone 7-4343

Architect's name and address _____ Telephone _____

Proposed use of building Offices

Other buildings on same lot _____ No. families _____

Description of Present Building to be Altered

Material brick No. stories 4 Heat _____ Style of roof _____ Roofing _____

Last use Offices No. families _____

General Description of New Work

To put in sheet rock and glass partitions to ~~divide~~ divide large room into three offices.
To ~~rearrange~~ rearrange stairway and partition as shown on plan submitted.

To remove two temporary ~~partitions~~ partitions.
These changes to be on third floor, west wing.

Details of New Work

Size, front _____ depth _____ No. stories _____ Height average grade to highest point of roof _____

To be erected on solid or filled land? _____ earth or rock? _____

Material of foundation _____ Thickness, top _____ bottom _____

Material of underpinning _____ Height _____ Thickness _____

Kind of roof _____ Roof covering _____

No. of chimneys _____ Material of chimneys _____ of lining _____

Kind of heat _____ Type of fuel _____ Distance heater to chimney _____

If oil burner, name and model _____

Capacity and location of oil tanks _____

Is gas fitting involved? _____ Size of service _____

Corner posts _____ Sills _____ Girt or ledger board? _____ Size _____

Material columns under girders _____ Size _____ Max. on centers _____

Studs (outside walls and carrying partitions) 2x4-16" O.C. Girders 8x8 or larger. Bridging in every floor and flat roof span over 8 feet. Sills and corner posts all one piece in cross section:

Joists and rafters: 1st floor _____ 2nd _____ 3rd _____ roof _____

On centers: 1st floor _____ 2nd _____ 3rd _____ roof _____

Maximum span: 1st floor _____ 2nd _____ 3rd _____ roof _____

If one story building with masonry walls, thickness of walls? _____ height? _____

If a Garage

No. cars now accommodated on same lot _____, to be accommodated _____

Total number commercial cars to be accommodated _____

Will automobile repairing be done other than minor repairs to cars habitually stored in the proposed building? _____

Miscellaneous

Will above work require removal or disturbing of any shade tree on a public street? no

Plans filed as part of this application? yes No. sheets 1

Estimated cost \$ 400. Fee \$ 70.

Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? Yes

Signature of owner Proble Corporation
W. H. Harey Co.

INSPECTION COPY

W. H. Harey