

61 CENTER STREET

SHAVE-WALKER

Full cut # 9203H • Full cut # 9203H • Full cut # 9203H • Full cut # 9203H



APPLICATION FOR PERMIT

Permit No. **0088**
PERMIT ISSUED

Class of Building or Type of Structure Third Class

JAN 16 1935

Portland, Maine, January 16, 1935

To the INSPECTOR OF BUILDINGS, PORTLAND, ME.

The undersigned hereby applies for a permit to erect alter install the following building structure equipment in accordance with the Laws of the State of Maine, the Building Code of the City of Portland, plans and specifications, if any, submitted herewith and the following specifications:

Location 51 Center Street Ward 4 Within Fire Limits? yes Dist. No. 1
 Owner's or Lessor's name and address Della Flaherty, 55 Center St. Telephone _____
 Contractor's name and address Antonio Leo, 117 Oxford St. Telephone no
 Architect's name and address _____
 Proposed use of building _____
 Other buildings on same lot _____ No. families _____
 Plans filed as part of this application? no No. of sheets _____
 Estimated cost \$ _____ Fee \$ 1.00

Description of Present Building to be Altered

Material wood No. stories 8 Heat _____ Style of roof _____ Roofing _____
 Last use tenant No. families 8

General Description of New Work

To demolish building

It is understood that this permit does not include installation of heating apparatus which is to be taken out separately by and in the name of the heating contractor.

Details of New Work

Size, front _____ depth _____ No. stories _____ Height average grade to top of plate _____
 Height average grade to highest point of roof _____
 To be erected on solid or filled land? _____ earth or rock? _____
 Material of foundation _____ Thickness, top _____ bottom _____
 Material of underpinning _____ Height _____ Thickness _____
 Kind of Roof _____ Rise per foot _____ Roof covering _____
 No. of chimneys _____ Material of chimneys _____ of lining _____
 Kind of heat _____ Type of fuel _____ Is gas fitting involved? _____
 Corner posts _____ Sills _____ Girt or ledger board? _____ Size _____
 Material columns under girders _____ Size _____ Max. on centers _____
 Studs (outside walls and carrying partitions) 2x4-16" O. C. Girders 6x8 or larger. Bridging in every floor and flat roof span over 8 feet. Sills and corner posts all one piece in cross section.
 Joists and rafters: 1st floor _____, 2nd _____, 3rd _____, roof _____
 On centers: 1st floor _____, 2nd _____, 3rd _____, roof _____
 Maximum span: 1st floor _____, 2nd _____, 3rd _____, roof _____
 If one story building with masonry walls, thickness of walls? _____ height? _____

If a Garage

No. cars now accommodated on same lot _____, to be accommodated _____
 Total number commercial cars to be accommodated _____
 Will automobile repairing be done other than minor repairs to cars habitually stored in the proposed building? _____

Miscellaneous

Will above work require removal or disturbing of any shade tree on a public street? no
 Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? yes

INSPECTION COPY

Signature of owner Della Flaherty
Antonio Leo

3427

Ward 4 permit No 35/88

Location 61 Center St.

Owner Dalia Flaherty

Date of perm 11/6/35

Notif closing-in

Inspr closing-in

Final Notif

Final Inspr 2/27/35 cdb

Cert. of Occupancy issued 1/23/36

NOTES

Complaint C 34/1465

1/27/35 work finished.

Fr. ins at street line to

protect cellar operation

cdb