

78-84 CENTER STREET



SHAM-WALKER

Full cut # 920H - Half cut # 920H - Third cut # 920H - Full cut # 920H

**CITY OF PORTLAND, MAINE**  
**Application for Permit to Install Wires**

*0314*

Permit No. *2775*  
 Issued

Portland, Maine *April 3*, 19*25*

To the City Electrician, Portland, Maine:

The undersigned hereby applies for a permit to install wires for the purpose of conducting electric current, in accordance with the laws of Maine, the Electrical Ordinance of the City of Portland, and the following specifications:

*(This form must be completely filled out - Minimum Fee, \$1.00)*

Owner's Name and Address *City of Portland High School* Tel. \_\_\_\_\_  
 Contractor's Name and Address *Melchior Bros* Tel. *797-8375*  
 Location *8th Street Lot* Use of Building *Office*  
 Number of Families \_\_\_\_\_ Apartments \_\_\_\_\_ Stores \_\_\_\_\_ Number of Stories \_\_\_\_\_  
 Description of Wiring: New Work \_\_\_\_\_ Additions \_\_\_\_\_ Alterations \_\_\_\_\_  
*Temp Service*

Pipe	Cable	Metal Molding	BX Cable	Plug Molding (No. of feet)	
No. Light Outlets		Plugs	Light Circuits	Plug Circuits	
FIXTURES: No.			Fluor. or Strip Lighting (No. feet)		
SERVICE: Pipe	Cable	Underground	No. of Wires	Size	
METERS: Relocated		Added	Total No. Meters		
MOTORS: Number	Phase	H. P.	Amps	Volts	Starter
HEATING UNITS: Domestic (Oil)		No. Motors		Phase	H.P.
	Commercial (Oil)	No. Motors		Phase	H.P.
		Electric Heat (No. of Rooms)			

APPLIANCES: No. Ranges \_\_\_\_\_ Watts \_\_\_\_\_ Brand Feeds (Size and No.) \_\_\_\_\_  
 Elec. Heaters \_\_\_\_\_ Watts \_\_\_\_\_  
 Miscellaneous \_\_\_\_\_ Watts \_\_\_\_\_ Extra Cabinets or Panels \_\_\_\_\_  
 Transformers \_\_\_\_\_ Air Conditioners (No. Units) \_\_\_\_\_ Signs (No. Units) \_\_\_\_\_

Will commence *19* Ready to cover in *will call* Inspection \_\_\_\_\_  
 Amount of Fee \$ *1.00*

Signed *Melchior Bros*  
*John A. Reedy*

DO NOT WRITE BELOW THIS LINE

SERVICE	<i>Temp</i>	METER	GROUND
VISITS: 1	<i>5-5-25</i>	2	3
		4	5
		6	7
		8	9
		10	11
		12	13

REMARKS:  
*Service called in*

INSPECTED BY \_\_\_\_\_ (OVER)



# APPLICATION FOR PERMIT

Class of Building or Type of Structure Second Class

Portland, Maine, September 23, 1970

To the INSPECTOR OF BUILDINGS, PORTLAND, MAINE

The undersigned hereby applies for a permit to erect alter repair demolish install the following building structure equipment in accordance with the Laws of the State of Maine, the Building Code and Zoning Ordinance of the City of Portland, plans and specifications, if any, submitted herewith and the following specifications:

Location 84 Center st. Within Fire Limits? \_\_\_\_\_ Dist. No. \_\_\_\_\_  
 Owner's name and address Eser Davidson, 43 Walton St. Telephone \_\_\_\_\_  
 Lessee's name and address Nicolina Ciccomancini, 16 Walton St. Telephone \_\_\_\_\_  
 Contractor's name and address \_\_\_\_\_ Telephone \_\_\_\_\_  
 Architect \_\_\_\_\_ Specifications \_\_\_\_\_ Plans yes No. of sheets 1  
 Proposed use of building Takeout No. families \_\_\_\_\_  
 Last use Church No. families \_\_\_\_\_  
 Material brick No. stories 3 Heat \_\_\_\_\_ Style of roof \_\_\_\_\_ Roofing \_\_\_\_\_  
 Other buildings on same lot \_\_\_\_\_  
 Estimated cost \$ \_\_\_\_\_ Fee \$ 5.00

### General Description of New Work

TO CHANGE USE OF FIRST FLOOR OF BUILDING FROM CHURCH TO "TAKEOUT" SERVICE, NO ALTERATIONS.

*10/22/70 = Refunded. work not being done.*  
 It is understood that this permit does not include installation of heating apparatus which is to be taken out separately by and in the name of the heating contractor. **PERMIT TO BE ISSUED TO Nicolina Ciccomancini**

### Details of New Work

Is any plumbing involved in this work? \_\_\_\_\_ Is any electrical work involved in this work? \_\_\_\_\_  
 Is connection to be made to public sewer? \_\_\_\_\_ If not, what is proposed for sewage? \_\_\_\_\_  
 Has septic tank notice been sent? \_\_\_\_\_ Form notice sent? \_\_\_\_\_  
 Height average grade to top of plate \_\_\_\_\_ Height average grade to highest point of roof \_\_\_\_\_  
 Size, front \_\_\_\_\_ depth \_\_\_\_\_ No. stories \_\_\_\_\_ solid or filled land? \_\_\_\_\_ earth or rock? \_\_\_\_\_  
 Material of foundation \_\_\_\_\_ Thickness, top \_\_\_\_\_ bottom \_\_\_\_\_ cellar \_\_\_\_\_  
 Kind of roof \_\_\_\_\_ Rise per foot \_\_\_\_\_ Roof covering \_\_\_\_\_  
 No. of chimneys \_\_\_\_\_ Material of chimneys \_\_\_\_\_ of lining \_\_\_\_\_ Kind of heat \_\_\_\_\_ fuel \_\_\_\_\_  
 Framing Lumber—Kind \_\_\_\_\_ Dressed or full size? \_\_\_\_\_ Corner posts \_\_\_\_\_ Sills \_\_\_\_\_  
 Size Girder \_\_\_\_\_ Columns under girders \_\_\_\_\_ Size \_\_\_\_\_ Max. on centers \_\_\_\_\_  
 Studs (outside walls and carrying partitions) 2x4-16" O. C. Bridging in every floor and flat roof span over 8 feet.  
 Joists and rafters: 1st floor \_\_\_\_\_, 2nd \_\_\_\_\_, 3rd \_\_\_\_\_, roof \_\_\_\_\_  
 On centers: 1st floor \_\_\_\_\_, 2nd \_\_\_\_\_, 3rd \_\_\_\_\_, roof \_\_\_\_\_  
 Maximum span: 1st floor \_\_\_\_\_, 2nd \_\_\_\_\_, 3rd \_\_\_\_\_, roof \_\_\_\_\_  
 If one story building with masonry walls, thickness of walls? \_\_\_\_\_ height? \_\_\_\_\_

### If a Garage

No. cars now accommodated on same lot \_\_\_\_\_, to be accommodated \_\_\_\_\_ number commercial cars to be accommodated \_\_\_\_\_  
 Will automobile repairing be done other than minor repairs to cars habitually stored in the proposed building? \_\_\_\_\_

APPROVED:

\_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

### Miscellaneous

Will work require disturbing of any tree on a public street? no  
 Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? yes

Nicolina Ciccomancini

CS 301

INSPECTION COPY

Signature of owner

*Nicolina Ciccomancini*  
 \_\_\_\_\_

Permit No. 701  
Location 84 Center St  
Owner Nicholas P. Corrao  
Date of permit 9/1/70  
Notif. closing-in \_\_\_\_\_  
Inspn. closing-in \_\_\_\_\_  
Final Notif. \_\_\_\_\_  
Final Inspn. \_\_\_\_\_  
Cert. of Occupancy issued \_\_\_\_\_  
Staking Out Notice \_\_\_\_\_  
Form Check Notice \_\_\_\_\_

NOTES

84 Center Street

Sept. 29, 1970

Nicholine Ciccomancini  
16 Wilson Street

cc to: Esler Davidson, 43 Walton St.

Dear Mr. Ciccomancini:

In checking your application to change the use of the first floor of the building from a church to a "take-out" service and the second permit to install hood for "pizza oven" at the above named location we find we are unable to continue processing both permits until further information is provided as follows:

1. An inspection of this property on Sept. 25th, shows that the floor joists are questionable, sagging badly in a number of places. We will have to know how this floor is to be strengthened before we can issue the permit for the change of use.
2. It was found that where the hood would be located that the ceiling and walls are combustible material, therefore the hood should not be closer than 18" to combustible material unless protection as listed in the Building Code is to be provided. If this is so we will need to know what the protection will be.
3. This hood shall completely cover all the cooking equipment plus an overhang of at least 6" on all sides of the equipment.
4. The distance from the floor to lower edge of the canopy hood will not exceed 7'.
5. The ductwork for this hood shall extend to 40" above the roof surface and 10' away from all buildings and lot lines.

Very truly yours,

A. Allan Soule  
Assistant Director of Building Inspection  
Department

AAS:m



1-2 INDUSTRIAL ZONE

# APPLICATION FOR PERMIT

Class of Building or Type of Structure Installation  
Portland, Maine, Sept. 24, 1970

To the INSPECTOR OF BUILDINGS, PORTLAND, MAINE

The undersigned hereby applies for a permit to erect alter repair demolish install the following building structure equipment in accordance with the Laws of the State of Maine, the Building Code and Zoning Ordinance of the City of Portland, plans and specifications, if any, submitted herewith and the following specifications:

Location 84 Center St. Within Fire Limits? \_\_\_\_\_ Dist. No. \_\_\_\_\_  
 Owner's name and address Eser Davidson, 47 Walton St. Telephone \_\_\_\_\_  
 Lessee's name and address Nicholino Ciccomancini, 16 Wilson St. Telephone \_\_\_\_\_  
 Contractor's name and address " " " " Telephone 774-7411  
 Architect \_\_\_\_\_ Specifications \_\_\_\_\_ Plans yes No. of sheets 1  
 Proposed use of building \_\_\_\_\_ Takeout \_\_\_\_\_ No. families \_\_\_\_\_  
 Last use \_\_\_\_\_ Church \_\_\_\_\_ No. families \_\_\_\_\_  
 Material brick No. stories 3 Heat \_\_\_\_\_ Style of roof \_\_\_\_\_ Roofing \_\_\_\_\_  
 Other buildings on same lot \_\_\_\_\_ Fee \$ 10.00  
 Estimated cost \$ \_\_\_\_\_

### General Description of New Work

To install hood for "pizza oven" as per plan.  
(first floor)

*10/22/70 - Refunded work not being done.*

It is understood that this permit does not include installation of heating apparatus which is to be taken out separately by and in the name of the heating contractor. **PERMIT TO BE ISSUED TO owner**

### Details of New Work

Is any plumbing involved in this work? \_\_\_\_\_ Is any electrical work involved in this work? \_\_\_\_\_  
 Is connection to be made to public sewer? \_\_\_\_\_ If not, what is proposed for sewage? \_\_\_\_\_  
 Has septic tank notice been sent? \_\_\_\_\_ Form notice sent? \_\_\_\_\_  
 Height average grade to top of plate \_\_\_\_\_ Height average grade to highest point of roof \_\_\_\_\_  
 Size, front \_\_\_\_\_ depth \_\_\_\_\_ No. stories \_\_\_\_\_ solid or filled land? \_\_\_\_\_ earth or rock? \_\_\_\_\_  
 Material of foundation \_\_\_\_\_ Thickness, top \_\_\_\_\_ bottom \_\_\_\_\_ cellar \_\_\_\_\_  
 Kind of roof \_\_\_\_\_ Rise per foot \_\_\_\_\_ Roof covering \_\_\_\_\_  
 No. of chimneys \_\_\_\_\_ Material of chimneys \_\_\_\_\_ of lining \_\_\_\_\_ Kind of heat \_\_\_\_\_ fuel \_\_\_\_\_  
 Framing Lumber—Kind \_\_\_\_\_ Dressed or full size? \_\_\_\_\_ Corner posts \_\_\_\_\_ Sills \_\_\_\_\_  
 Size Girder \_\_\_\_\_ Columns under girders \_\_\_\_\_ Size \_\_\_\_\_ Max. on centers \_\_\_\_\_  
 Studs (outside walls and carrying partitions) 2x4-16" O. C. Bridging in every floor and flat roof span over 8 feet.  
 Joists and rafters: 1st floor \_\_\_\_\_ 2nd \_\_\_\_\_ 3rd \_\_\_\_\_, roof \_\_\_\_\_  
 On centers: 1st floor \_\_\_\_\_ 2nd \_\_\_\_\_ 3rd \_\_\_\_\_, roof \_\_\_\_\_  
 Maximum span: 1st floor \_\_\_\_\_ 2nd \_\_\_\_\_ 3rd \_\_\_\_\_, roof \_\_\_\_\_  
 If one story building with masonry walls, thickness of walls? \_\_\_\_\_ height? \_\_\_\_\_

### If a Garage

No. cars now accommodated on same lot \_\_\_\_\_, to be accommodated \_\_\_\_\_ number commercial cars to be accommodated \_\_\_\_\_  
 Will automobile repairing be done other than minor repairs to cars habitually stored in the proposed building? \_\_\_\_\_

APPROVED:

\_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

### Miscellaneous

Will work require disturbing of any tree or a public street? no  
 Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? yes

Nicholino Ciccomancini

CS 301

INSPECTION COPY

Signature of owner by:

*Nicholino Ciccomancini*



C 78-84 Center St.,  
corner of Spring St.

August 6, 1953

Dr. Edward W. Colby, Director of Health

Warren McDonald, Inspector of Buildings

Poultry at 78-84 Center St.

We have a complaint from Dorothy Short, 33 Spring St., that a number of roosters are being kept on the property owned by Honorah Agnes Connolly, who lives at 16 Tyng St., and that they are objectionable to the neighborhood.

The property is in a General Business Zone where the Zoning Ordinance does not pronounce the keeping of poultry a non-conforming use.

In line with your recent memo concerning the control the Health Department has over keeping of poultry, <sup>perhaps</sup> you will have the situation investigated to see if the situation should be corrected from the health standpoint.

WMcD/B

Inspector of Buildings



INTER-OFFICE CORRESPONDENCE

CITY OF PORTLAND, MAINE  
HEALTH DEPARTMENT


*Pl file with complaint & check 9/9/53*

**TO:** Warren McDonald, Inspector of Buildings **DATE:** September 8, 1953  
**FROM:** Dr. Edward W. Colby, Health Director  
**SUBJECT:** Foultry at 78-84 Center Street.

Complaint forwarded from your office, your File #C 78-84 Center Street, corner of Spring Street.

As of August 24, 1953, a recheck inspection at the above premises indicates that the poultry have been eliminated.

Very truly yours,



Edward W. Colby, M. D.  
Health Director

EWC:beb

RECEIVED  
SEP 9 1953  
DEPT. OF BLD'G. INSP.  
CITY OF PORTLAND

(G) GENERAL BUSINESS ZONE

APPLICATION FOR PERMIT

Class of Building or Type of Structure Second Class

Portland, Maine, October 2<sup>nd</sup> 1951



To the INSPECTOR OF BUILDINGS PORTLAND, MAINE

The undersigned hereby applies for a permit to ~~erect~~ alter ~~erect~~ ~~erect~~ the following building ~~structure~~ ~~work~~ in accordance with the Laws of the State of Maine, the Building Code and Zoning Ordinance of the City of Portland, plans and specifications, if any, submitted herewith are the following specifications:

Location 84 Center Street Within Fire Limits? yes Dist. No. 1  
Owner's name and address Ellen Connolly, 16 Tyng Street Telephone 3-4986  
Lessee's name and address Merle G. Chadbourne, Harmony, Maine Telephone \_\_\_\_\_  
Contractor's name and address " " " Telephone \_\_\_\_\_  
Architect \_\_\_\_\_ Specifications \_\_\_\_\_ Plans no No. of sheets \_\_\_\_\_  
Proposed use of building Manufacture of moccasins and apartment house No. families 2  
Last use business and " " " No. families "  
Material brick No. stories 3 Heat 2 stories Style of roof \_\_\_\_\_ Roofing \_\_\_\_\_  
Other buildings on same lot \_\_\_\_\_ Fee \$ 2.00  
Estimated cost \$ 200.

General Description of New Work

To use entire first story of this building for the manufacture of moccasins. To erect two non-bearing partitions, one 20' long and one 2' long, 2x3 studs, 16" on centers, covered on front side with sheetrock. These partitions are to be erected so that it will be more convenient to heat. It is intended to have 3 sewing machines, two of them weighing approximately 125 pounds each and one weighing 400 pounds.

It is understood that this permit does not include installation of heating apparatus which is to be taken out separately by and in the name of the heating contractor. PERMIT TO BE ISSUED TO Merle G. Chadbourne

Details of New Work

Is any plumbing involved in this work? \_\_\_\_\_ Is any electrical work involved in this work? \_\_\_\_\_  
Height average grade to top of plate \_\_\_\_\_ Height average grade to highest point of roof \_\_\_\_\_  
Size, front \_\_\_\_\_ depth \_\_\_\_\_ No. stories \_\_\_\_\_ solid or filled land? \_\_\_\_\_ earth or rock? \_\_\_\_\_  
Material of foundation \_\_\_\_\_ Thickness, top \_\_\_\_\_ bottom \_\_\_\_\_ cellar \_\_\_\_\_  
Material of underpinning \_\_\_\_\_ Height \_\_\_\_\_ Thickness \_\_\_\_\_  
Kind of roof \_\_\_\_\_ Rise per foot \_\_\_\_\_ Roof covering \_\_\_\_\_  
No. of chimneys \_\_\_\_\_ Material of chimneys \_\_\_\_\_ of lining \_\_\_\_\_ Kind of heat \_\_\_\_\_ fuel \_\_\_\_\_  
Framing lumber—Kind \_\_\_\_\_ Dressed or full size? \_\_\_\_\_  
Corner posts \_\_\_\_\_ Sills \_\_\_\_\_ Girt or ledger board? \_\_\_\_\_ Size \_\_\_\_\_  
Girders \_\_\_\_\_ Size \_\_\_\_\_ Columns under girders \_\_\_\_\_ Size \_\_\_\_\_ Max. on centers \_\_\_\_\_  
Studs (outside walls and carrying partitions) 2x4-16" O. C. Bridging in every floor and flat roof span over 8 feet.  
Joists and rafters: 1st floor \_\_\_\_\_, 2nd \_\_\_\_\_, 3rd \_\_\_\_\_, roof \_\_\_\_\_  
On centers: 1st floor \_\_\_\_\_, 2nd \_\_\_\_\_, 3rd \_\_\_\_\_, roof \_\_\_\_\_  
Maximum span: 1st floor \_\_\_\_\_, 2nd \_\_\_\_\_, 3rd \_\_\_\_\_, roof \_\_\_\_\_  
If one story building with masonry walls, thickness of walls? \_\_\_\_\_ height? \_\_\_\_\_

If a Garage

No. cars now accommodated on same lot \_\_\_\_\_, to be accommodated \_\_\_\_\_ number commercial cars to be accommodated \_\_\_\_\_  
Will automobile repairing be done other than minor repairs to cars habitually stored in the proposed building? \_\_\_\_\_

Miscellaneous

Will work require disturbing of any tree on a public street? no  
Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? yes

Ellen Connolly

Signature of owner by: Merle G. Chadbourne

APPROVED:

Permit No. 51

Location 84 Center St.

Owner Merle G. Chadbourne

Date of permit 1/51

Notif. closing-in \_\_\_\_\_

Inspn. closing-in \_\_\_\_\_

Final Notif. \_\_\_\_\_

Final Inspn. \_\_\_\_\_

Cert. of Occupancy issued \_\_\_\_\_

NOTES

*Not to work  
Referenced  
1/7/51*

*Vertical lines and faint text on the right side of the page, possibly bleed-through or a separate column.*

AP 84 Center Street-I

October 24, 1957

Mr. Merle G. Chadbourne  
Harmen,  
Maine

Dear Mr. Chadbourne:

A number of questions arise concerning your application for a building permit to make alterations in the first story of the building at 84 Center Street to equip space for manufacture of moccasins about which information is needed before a permit may be issued. These are as follows:

1. Will any inflammable rubber cement or cement of a similar nature be used in the manufacturing process? If so, are any provisions to be made for special protection of the handling and storage thereof?
2. How many people are there likely to be in the first story at any one time? If this number is to be more than twenty, a second means of egress is required from the building.

Very truly yours,

Warren McDonald  
Inspector of Buildings

AJS/G

10/24/51

- 1- 1st story always used for business.
  - 2- One apt. in each of 2nd + 3rd stories. Fourth vacant
  - 3- No. of employees
  - 4- Any rubber cement to be used or storage.
  - 5- First floor heavily framed.
- Hold for more information  
see letter 10/24/51  
RM 9

LOCATION 84 Center

DATE 10/23/57

PERMIT

INQUIRY \_\_\_\_\_

COMPLAINT \_\_\_\_\_

aggs.

Is check.

Besides the question of strength of floor slab that all exits based on number of persons accommodated in new plant, we ought to question about the use of rubber cement and storage on the basis of hazardous material.

It will be best also to check the use of doors above a 2 ft height in the light of 202 et seq.

WMD  
10/24/57. Bldg. 4 stories high, apts, above 1st?



# APPLICATION FOR PERMIT

Class of Building or Type of Structure Third Class  
Portland, Maine, February, 1949

PERMIT ISSUED  
00174  
FEB 10 1949  
CITY of PORTLAND

To the INSPECTOR OF BUILDINGS, PORTLAND, MAINE

The undersigned hereby applies for a permit to ~~erect~~ demolish ~~such~~ the following building ~~as follows~~ in accordance with the Laws of the State of Maine, the Building Code and Zoning Ordinance of the City of Portland, plans and specifications, if any, submitted herewith and the following specifications:

Location 80-82 Center Street Within Fire Limits? yes Dist. No. 1  
 Owner's name and address Agnes Connolly, 16 Tyng Street Telephone \_\_\_\_\_  
 Lessee's name and address \_\_\_\_\_ Telephone \_\_\_\_\_  
 Contractor's name and address Owner Specifications \_\_\_\_\_ Plans \_\_\_\_\_ No. of sheets \_\_\_\_\_  
 Architect \_\_\_\_\_ No. families \_\_\_\_\_  
 Proposed use of building \_\_\_\_\_ No. families 2  
 Last use Dwelling & shop Style of roof \_\_\_\_\_ Roofing \_\_\_\_\_  
 Material wood No. stories 2 1/2 Heat \_\_\_\_\_  
 Other buildings on same lot \_\_\_\_\_ Fee \$ 1.00  
 Estimated cost \$ \_\_\_\_\_

### General Description of New Work

To demolish 2 1/2-story frame dwelling  
Do you agree to tightly and permanently close all sewers or drains connecting with public or private sewers from this building or structure to be demolished, under the supervision and to the approval of the Department of Public Works of the City of Portland? yes

INSPECTION NOT COMPLETE  
6/7/49

It is understood that this permit does not include installation of heating apparatus which is to be taken out separately by and in the name of the heating contractor. PERMIT TO BE ISSUED TO

### Details of New Work

Is any plumbing involved in this work? \_\_\_\_\_ Is any electrical work involved in this work? \_\_\_\_\_  
 Height average grade to top of plate \_\_\_\_\_ Height average grade to highest point of roof \_\_\_\_\_  
 Size, front \_\_\_\_\_ depth \_\_\_\_\_ No. stories \_\_\_\_\_ solid or filled land? \_\_\_\_\_ earth or rock? \_\_\_\_\_  
 Material of foundation \_\_\_\_\_ Thickness, top \_\_\_\_\_ bottom \_\_\_\_\_ cellar \_\_\_\_\_  
 Material of underpinning \_\_\_\_\_ Height \_\_\_\_\_ Thickness \_\_\_\_\_  
 Kind of roof \_\_\_\_\_ Rise per foot \_\_\_\_\_ Roof covering \_\_\_\_\_  
 No. of chimneys \_\_\_\_\_ Material of chimneys \_\_\_\_\_ of lining \_\_\_\_\_ Kind of heat \_\_\_\_\_ fuel \_\_\_\_\_  
 Framing lumber—Kind \_\_\_\_\_ Dressed or full size? \_\_\_\_\_  
 Corner posts \_\_\_\_\_ Sills \_\_\_\_\_ Girt or ledger board? \_\_\_\_\_ Size \_\_\_\_\_  
 Girders \_\_\_\_\_ Size \_\_\_\_\_ Columns under girders \_\_\_\_\_ Size \_\_\_\_\_ Max. on centers \_\_\_\_\_  
 Studs (outside walls and carrying partitions) 2x4-16" O. C. Bridging in every floor and flat roof span over 8 feet.  
 Joists and rafters: 1st floor \_\_\_\_\_, 2nd \_\_\_\_\_, 3rd \_\_\_\_\_, roof \_\_\_\_\_  
 On centers: 1st floor \_\_\_\_\_, 2nd \_\_\_\_\_, 3rd \_\_\_\_\_, roof \_\_\_\_\_  
 Maximum span: 1st floor \_\_\_\_\_, 2nd \_\_\_\_\_, 3rd \_\_\_\_\_, roof \_\_\_\_\_  
 If one story building with masonry walls, thickness of walls? \_\_\_\_\_ height? \_\_\_\_\_

### If a Garage

No. cars now accommodated on same lot \_\_\_\_\_, to be accommodated \_\_\_\_\_ number commercial cars to be accommodated \_\_\_\_\_  
Will automobile repairing be done other than minor repairs to cars habitually stored in the proposed building? \_\_\_\_\_

### Miscellaneous

Will work require disturbing of any tree on a public street? no  
Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? yes

APPROVED:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Signature of owner

Ellen M. O'Neill

INSPECTION COPY

Permit No. 49/174  
 Location 90-92 Center St.  
 Owner Agnes Conolly  
 Date of permit 2/10/49  
 Notif. closing-in \_\_\_\_\_  
 Inspn. clo. \_\_\_\_\_  
 Final Notif. \_\_\_\_\_  
 Final Inspn. \_\_\_\_\_  
 Cert. of Occupancy issued none

INSPECTION NOT COMPLETED  
 6/17/49

NOTES

412749- ~~wholesale~~  
 617149- ~~wholesale~~ to make  
 from the ~~imp.~~ 28

*(This section contains a large diagonal line and faint, illegible text from the reverse side of the document.)*

I hereby certify that the above information is true and correct to the best of my knowledge and belief.  
 Date: \_\_\_\_\_  
 Signature: \_\_\_\_\_  
 Title: \_\_\_\_\_





# APPLICATION FOR PERMIT

## PERMIT ISSUED

Permit No. 1319

SEP 10 1941

Class of Building or Type of Structure Third ClassPortland, Maine, September 10, 1941

INSPECTOR OF BUILDINGS, PORTLAND, ME.

The undersigned hereby applies for a permit to ~~erect~~ alter in whole the following building structure ~~equipment~~ in accordance with the Laws of the State of Maine, the Building Code of the City of Portland, plans and specifications, if any, submitted herewith and the following specifications:

Location Spring Street Within Fire Limits? yes Dist. No. 1  
 Owner's or lessee's name and address Agnes M. Connolly, 3 Tyng St. Telephone \_\_\_\_\_  
 Contractor's name and address F. R. Wardwell, 20 Tyng St. Telephone \_\_\_\_\_  
 Architect \_\_\_\_\_ Plans filed \_\_\_\_\_ No. of sheets \_\_\_\_\_  
 Proposed use of building \_\_\_\_\_ No. families \_\_\_\_\_  
 Other buildings on same \_\_\_\_\_ Fee \$ \_\_\_\_\_  
 Estimated cost \$ \_\_\_\_\_

### Description of Present Building to be Altered

Material wood No. stories 2 Heat \_\_\_\_\_ Style of roof \_\_\_\_\_ Roofing \_\_\_\_\_  
 Last use dwelling house No. families 1

### General Description of New Work

To demolish building 24' x 46'

Do you agree to tightly and permanently close all sewers or drains connecting with public or private sewers from this building or structure to be demolished, under the supervision and to the approval of the Department of Public Works of the City of Portland? Yes

It is understood that this permit does not include installation of heating apparatus which is to be taken out separately by and in the name of the heating contractor.

### Details of New Work

Is any plumbing work involved in this work? \_\_\_\_\_  
 Is any electrical work involved in this work? \_\_\_\_\_ Height average grade to top of plate \_\_\_\_\_  
 Size, front \_\_\_\_\_ depth \_\_\_\_\_ No. stories \_\_\_\_\_ Height average grade to highest point of roof \_\_\_\_\_  
 To be erected on solid or filled land? \_\_\_\_\_ earth or rock? \_\_\_\_\_  
 Material of foundation \_\_\_\_\_ Thickness, top \_\_\_\_\_ bottom \_\_\_\_\_ cellar \_\_\_\_\_  
 Material of underpinning \_\_\_\_\_ Height \_\_\_\_\_ Thickness \_\_\_\_\_  
 Kind of roof \_\_\_\_\_ Rise per foot \_\_\_\_\_ Roof covering \_\_\_\_\_  
 No. of chimneys \_\_\_\_\_ Material of chimneys \_\_\_\_\_ of lining \_\_\_\_\_  
 Kind of heat \_\_\_\_\_ Type of fuel \_\_\_\_\_ Is gas fitting involved? \_\_\_\_\_  
 Framing lumber—Kind \_\_\_\_\_ Dressed or full size? \_\_\_\_\_  
 Corner posts \_\_\_\_\_ Sills \_\_\_\_\_ Girt or ledger board? \_\_\_\_\_ Size \_\_\_\_\_  
 Material columns under girders \_\_\_\_\_ Size \_\_\_\_\_ Max. on centers \_\_\_\_\_  
 Studs (outside walls and carrying partitions) 2x4-16" O. C. Girders 6x8 or larger. Bridging in every floor and flat roof span over 8 feet. Sills and corner posts all one piece in cross section.  
 Joists and rafters: 1st floor \_\_\_\_\_, 2nd \_\_\_\_\_, 3rd \_\_\_\_\_, roof \_\_\_\_\_  
 On centers: 1st floor \_\_\_\_\_, 2nd \_\_\_\_\_, 3rd \_\_\_\_\_, roof \_\_\_\_\_  
 Maximum span: 1st floor \_\_\_\_\_, 2nd \_\_\_\_\_, 3rd \_\_\_\_\_, roof \_\_\_\_\_  
 If one story building with masonry walls, thickness of walls? \_\_\_\_\_ height? \_\_\_\_\_

### If a Garage

No. cars now accommodated on same lot \_\_\_\_\_ to be accommodated \_\_\_\_\_  
 Total number commercial cars to be accommodated \_\_\_\_\_  
 Will automobile repairing be done other than minor repairs to cars habitually stored in the proposed building? \_\_\_\_\_

### Miscellaneous

Will above work require removal or disturbing of any shade tree on a public street? no  
 Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? yes  
 Signature of owner Agnes M. Connolly  
 By F. R. Wardwell

INSPECTION COPY

Permit No. 41/1319

Location 8 Squiring St

Owner James M. Connolly

Date of perm. 9/10/41

Notif. closing in \_\_\_\_\_

Inspn. closing-in \_\_\_\_\_

Final Notif. \_\_\_\_\_

Final Inspn. 9/22/41. c/c

Cert. of Occupancy issued None

NOTES

~~9/22/41. Permit. started L.~~

~~TIME FOR~~



# APPLICATION FOR PERMIT

PERMIT ISSUED

Permit No. 0362

MAR 31 1941

Class of Building or Type of Structure third

Portland, Maine, Mar. 31, 1941

To the INSPECTOR OF BUILDINGS, PORTLAND, ME.

The undersigned hereby applies for a permit to ~~erect~~ alter ~~the~~ following building ~~structure~~ equipment in accordance with the Laws of the State of Maine, the Building Code of the City of Portland, plans and specifications, if any, submitted herewith and the following specifications:

Location 6 Spring St. 78-84 Center St Within Fire Limits? Yes Dist. No. 1  
 Owner's or Lessee's name and address Agnes Connolly 16 Tyng St. Telephone \_\_\_\_\_  
 Contractor's name and address Not Let Telephone \_\_\_\_\_  
 Architect \_\_\_\_\_ Plans filed \_\_\_\_\_ No. of sheets \_\_\_\_\_  
 Proposed use of building \_\_\_\_\_ No. families \_\_\_\_\_  
 Other buildings on same lot \_\_\_\_\_  
 Estimated cost \$ \_\_\_\_\_ Fee \$ 1.00

### Description of Present Building to be Altered

Material frame No. stories 2 1/2 Heat \_\_\_\_\_ Style of roof \_\_\_\_\_ Roofing \_\_\_\_\_  
 Last use Dwelling house No. families 2

### General Description of New Work

To demolish 2 1/2 Story frame dwelling 20x30

Do you agree to tightly and permanently close all sewers or drains connecting with public or private sewers from this building or structure to be demolished, under the supervision and to the approval of the Department of Public Works of the City Portland? yes

It is understood that this permit does not include installation of heating apparatus which is to be taken out separately by and in the name of the heating contractor.

### Details of New Work

Is any plumbing work involved in this work? \_\_\_\_\_  
 Is any electrical work involved in this work? \_\_\_\_\_ Height average grade to top of plate \_\_\_\_\_  
 Size, front \_\_\_\_\_ depth \_\_\_\_\_ No. stories \_\_\_\_\_ Height average grade to highest point of roof \_\_\_\_\_  
 To be erected on solid or filled land? \_\_\_\_\_ earth or rock? \_\_\_\_\_  
 Material of foundation \_\_\_\_\_ Thickness, top \_\_\_\_\_ bottom \_\_\_\_\_ cellar \_\_\_\_\_  
 Material of underpinning \_\_\_\_\_ Height \_\_\_\_\_ Thickness \_\_\_\_\_  
 Kind of roof \_\_\_\_\_ Rise per foot \_\_\_\_\_ Roof covering \_\_\_\_\_  
 No. of chimneys \_\_\_\_\_ Material of chimneys \_\_\_\_\_ of lining \_\_\_\_\_  
 Kind of heat \_\_\_\_\_ Type of fuel \_\_\_\_\_ Is gas fitting involved? \_\_\_\_\_  
 Framing lumber—Kind \_\_\_\_\_ Dressed or full size? \_\_\_\_\_  
 Corner posts \_\_\_\_\_ Sills \_\_\_\_\_ Girt or ledger board? \_\_\_\_\_ Size \_\_\_\_\_  
 Material columns under girders \_\_\_\_\_ Size \_\_\_\_\_ Max. on centers \_\_\_\_\_  
 Studs (outside walls and carrying partitions) 2x4-16" O. C. Girders 6x8 or larger. Bridging in every floor and flat roof span over 8 feet. Sills and corner posts all one piece in cross section.  
 Joists and rafters: 1st floor \_\_\_\_\_, 2nd \_\_\_\_\_, 3rd \_\_\_\_\_, roof \_\_\_\_\_  
 On centers: 1st floor \_\_\_\_\_, 2nd \_\_\_\_\_, 3rd \_\_\_\_\_, roof \_\_\_\_\_  
 Maximum span: 1st floor \_\_\_\_\_, 2nd \_\_\_\_\_, 3rd \_\_\_\_\_, roof \_\_\_\_\_  
 If one story building with masonry walls, thickness of walls? \_\_\_\_\_ height? \_\_\_\_\_

### If a Garage

No. cars now accommodated on same lot \_\_\_\_\_ to be accommodated \_\_\_\_\_  
 Total number commercial cars to be accommodated \_\_\_\_\_  
 Will automobile repairing be done other than minor repairs to cars habitually stored in the proposed building? \_\_\_\_\_

### Miscellaneous

Will above work require removal or disturbing of any shade tree on a public street? no  
 Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? yes

Signature of owner Agnes Connolly

900

Permit No. 41/362

Location 6 Spring St. 78-84 Center St.

Owner Agnes Capronilly

Date of permit 3/31/41

Notif. closing-in

Inspn. closing-in


Final Notif

Final Inspn. 4/2/41 *alig.*

Cert. of Occupancy issued *1/19/46*

NOTES

*7/24/41. Sement started. (1)6*





17) GENERAL BUSINESS 20X22 Permit No. 1-192  
**APPLICATION FOR PERMIT PERMIT ISSUED**

Clas. of Building or Type of Structure Second Class

Portland, Maine, August 1, 1935

To the INSPECTOR OF BUILDINGS, PORTLAND, ME.

The undersigned hereby applies for a permit to erect alter install the following building structure equipment in accordance with the Laws of the State of Maine, the Building Code of the City of Portland, plans and specifications, if any, submitted herewith and the following specifications:

Location 84 Center Street Ward 4 Within Fire Limits? yes Dist. No. 114  
 Owner's or Lessee's name and address Mrs. Grace Palmer 84 Center St. Telephone 2-8855  
 Contractor's name and address Frank Dohette, 211 - 1st - Westbrook Telephone \_\_\_\_\_  
 Architect's name and address \_\_\_\_\_  
 Proposed use of building Restaurant and tenements No. families 2  
 Other buildings on same lot \_\_\_\_\_  
 Plans filed as part of this application? yes No. of sheets 1  
 Estimated cost \$ 50. Fee \$ .50

**Description of Present Building to be Altered**

Material brick No. stories 4 Heat \_\_\_\_\_ Style of roof \_\_\_\_\_ Roofing \_\_\_\_\_  
 Last use Restaurant and tenements No. families 2

**General Description of New Work**

To build ~~add~~ 2 new toilets on Center St. side. Partitions to be 2x3 studding covered both sides sheetrock. Vestibules to be at least 50' deep. Doors on toilets and vestibules to be made self-closing in such a way that there will be little chance of both doors being open the same time. Partitions to extend to ceiling. Present windows at least three squares feet in area for ventilation. Front doors will open outward and will be recessed so as not to swing over sidewalk.

*Approved by Restaurant Inspector*

It is understood that this permit does not include installation of heating apparatus which is to be taken out separately by and in the name of the heating contractor.

**Details of New Work**

Size, front \_\_\_\_\_ depth \_\_\_\_\_ No. stories \_\_\_\_\_ Height average grade to top of plate \_\_\_\_\_  
 To be erected on solid or filled land? \_\_\_\_\_ earth or rock? \_\_\_\_\_ Height average grade to highest point \_\_\_\_\_  
 Material of foundation \_\_\_\_\_ Thickness, top \_\_\_\_\_ bottom \_\_\_\_\_  
 Material of underpinning \_\_\_\_\_ Height \_\_\_\_\_ Thickness \_\_\_\_\_  
 Kind of Roof \_\_\_\_\_ Rise per foot \_\_\_\_\_ Roof covering \_\_\_\_\_  
 No. of chimneys \_\_\_\_\_ Material of chimneys \_\_\_\_\_ of lining \_\_\_\_\_  
 Kind of heat \_\_\_\_\_ Type of fuel \_\_\_\_\_ Is gas fitting involved? \_\_\_\_\_  
 Corner posts \_\_\_\_\_ Sills \_\_\_\_\_ Girt or ledger board? \_\_\_\_\_ Size \_\_\_\_\_  
 Material columns under girders \_\_\_\_\_ Size \_\_\_\_\_ Max. on centers \_\_\_\_\_  
 Studs (outside walls and carrying partitions) 2x4-16" O. C. Girders 6x8 or larger. Bridging in every floor and flat roof span over 8 feet. Sills and corner posts all one piece in cross section.  
 Joists and rafters: 1st floor \_\_\_\_\_, 2nd \_\_\_\_\_, 3rd \_\_\_\_\_, roof \_\_\_\_\_  
 On centers: 1st floor \_\_\_\_\_, 2nd \_\_\_\_\_, 3rd \_\_\_\_\_, roof \_\_\_\_\_  
 Maximum span: 1st floor \_\_\_\_\_, 2nd \_\_\_\_\_, 3rd \_\_\_\_\_, roof \_\_\_\_\_  
 If one story building with masonry walls, thickness of walls? \_\_\_\_\_ height? \_\_\_\_\_

CERTIFICATE OF OCCUPANCY REQUIREMENT IS WAIVED

**If a Garage**

No. cars now accommodated on same lot \_\_\_\_\_, to be accommodated \_\_\_\_\_  
 Total number commercial cars to be accommodated \_\_\_\_\_  
 Will automobile repairing be done other than minor repairs to cars habitually stored in the proposed building? \_\_\_\_\_

**Miscellaneous**

Will above work require removal or disturbing of any shade tree on a public street? no  
 Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? yes

Mrs Graco Palmer

Signature of owner by \_\_\_\_\_

*Edward J. Donahue*

INSPECTION COPY

Ward 4 Permit No 35/1192<sup>I</sup>  
Location 84 Center St.  
Owner Mrs. Grace Palmer  
Date it 8/6/35  
Notif. closing-in  
Inspn. closing-in  
al  
Final Inspn.  
INSPECTION NOT COMPLETE  
C. of Occupancy issued

smooth surfaces  
that will stand  
washing and  
remain sanitary  
and

3/14/89. This store  
is vacant and has been  
for some time. etc.

NOTES

8/6/35 - On this date  
these new partitions  
had been erected  
and gypsum  
wall board  
put on sides.  
Inside of one toilet  
had been papered.  
James Willett Sr.  
Portland is carpenter  
Told him that  
that paper must  
be removed and  
new work finished  
properly, cracks  
and holes filled  
and painting or other  
similar finish  
applied to give



Original Permit No. 34/171

Amendment No. 2

# AMENDMENT TO APPLICATION FOR PERMIT

Portland, Maine, January 16, 1955

To the INSPECTOR OF BUILDINGS, PORTLAND, ME.

The undersigned hereby applies for an amendment to Permit No. 34/171 pertaining to the building or structure comprised in the original application in accordance with the Laws of the State of Maine, the Building Code of the City of Portland, plans and specifications, if any, submitted herewith, and the following specifications:

Location 84 Center St. Ward 4 With the Fire Limits? yes Dist. No. 1

Owner's or Lessee's name and address Harrington's Grocery, Cranston, R.I.

Contractor's name and address J. H. Middlebrook, 12 Elm St.

Plans filed as part of this Amendment Y/B No. of Sheets 1

Increased cost of work \_\_\_\_\_ Additional fee 25

Description of Proposed Work  
To hang sign as per plan attached filed with amendment.

Contractor J. H. Middlebrook  
Signature of Contractor

Approved: Oliver T. Scuderi  
Chief of Fire Department

Approved: Warren J. Smith  
Inspector of Buildings

INSPECTION COPY  
Commissioner of Public Works

45B



Original Permit No. **PERMIT 15311**

Amendment No. 1

**JAN 15 1935**

# AMENDMENT TO APPLICATION FOR PERMIT

Portland, Maine January 14, 1935

To the INSPECTOR OF BUILDINGS, PORTLAND, ME.

The undersigned hereby applies for an amendment to Permit No. 34/172 pertaining to the building or structure comprised in the original application in accordance with the Laws of the State of Maine, the Building Code of the City of Portland, plans and specifications, if any, submitted herewith, and the following specifications:

Location B4 Center St. Ward 4 With the Fire Limits? yes Dist. No. 1

Owner's or Lessee's name and address Harringtonett Brewery, Cranston, R.I.

Contractor's name and address J.H. Middlebrook, 18 Elm St

Plans filed as part of this Amendment YES No. of Sheets 1

Increased cost of work \_\_\_\_\_ Additional fee \$25

Description of Proposed Work  
To hang sign as per plan attached filed with amendment.

Contractor J.H. Middlebrook  
Signature of Owner

Approved: Oliver T. Gaultier  
Chief of Fire Department.

Approved: 1/15/35  
Warren & Sorell  
Inspector of Buildings

INSPECTION COPY  
Commissioner of Public Works.





(3) GENERAL BUSINESS ZONE PERMIT ISSUED  
Permit No. 6771

APPLICATION FOR PERMIT TO ERECT SIGN  
OVER PUBLIC SIDEWALK OR STREET  
JUN 12 1934

Portland, Maine, June 5, 1934

To the INSPECTOR OF BUILDINGS, PORTLAND, ME.

The undersigned hereby applies for a permit to erect the following described sign extending over a public sidewalk or street in accordance with the Building Code of the City of Portland, and the following specifications:

Location 84 Centre St. Ward 4 Within Fire Limits? Yes Dist. No. \_\_\_\_\_

Owner of building to which sign is to be attached Connelly Heirs

Name and address of owner of sign Harraganatt Brewery, Cranston, R. I.

Contractor's name and address J. H. Middlebrook, 12 Elm St. Telephone 3-2312

When does contractor's bond expire? Jan. 1, 1935

Information Concerning Building

No. stories 3 Material of wall to which sign is to be attached Brick

CERTIFICATE OF OCCUPANCY  
REQUIREMENT IS WAIVED

Details of Sign and Connections

Electric? Gloss Face Vertical dimension after erection 31" Horizontal 4' - 7"

Weight 40 lbs., Will there be any hollow spaces? No Any rigid frame? Yes

Material of frame Gal. Iron No. advertising faces 2, material Glass

No. rigid connections 2 Are they fastened directly to frame of sign? Yes

No. through bolts \_\_\_\_\_, Size \_\_\_\_\_, Location, top or bottom \_\_\_\_\_

No. guys 2, material Stranded Cable, Size 3/16

Minimum clear height above sidewalk or street 15--0

Minimum projection into street 6--0

Signature of contractor J. H. Middlebrook Fee \$ \_\_\_\_\_  
*Oliver P. Saubon*

INSPECTION COPY

Ord 4 Permit No. 34/171  
 Loc 84 Center St.  
 Owner Murtagansett Brewery  
 Date of permit 6/12/34  
 Sign Contractor \_\_\_\_\_  
 Final Inspn. 1/16/35. Oda

NOTES

~~6/14/34 - Ready for dumping of sludge  
 to 124/34 location OK  
 Shop OK.~~

~~1/8/35 - sign erected  
 in different location  
 than shown on plan. One  
 guy across window  
 bibbit at middle of  
 window. etc.~~



~~1/10/35 - Mr. Middlebrooks  
 said that Chief does not  
 object to guy across  
 window if another  
 window in same room  
 not blocked OK.~~



(G) GENERAL BUSINESS PERMIT ISSUED  
Permit No. 1-2077

# APPLICATION FOR PERMIT TO ERECT SIGN OVER PUBLIC SIDEWALK OR STREET

SEP 18 1933

Portland, Maine, September 18, 1933

To the INSPECTOR OF BUILDINGS, PORTLAND, ME.

The undersigned hereby applies for a permit to erect the following described sign extending over a public sidewalk or street in accordance with the Building Code of the City of Portland, and the following specifications:

Location 74 Center Street Ward 4 Within Fire Limits? yes Dist. No. 1  
Owner of building to which sign is to be attached The Conley Estate  
Name and address of owner of sign Harold G. Lunch 84 Center St.  
Contractor's name and address Flynn, The Painter 243A Middle St. Telephone 4-4925  
When does contractor's bond expire? January 1934

### Information Concerning Building

No. stories 4 Material of wall to which sign is to be attached brick

CERTIFICATE OF OCCUPANCY REQUIREMENT IS WAIVED

NOTIFICATION BEFORE LATHING OR CLOSING IN IS NOT REQUIRED

### Details of Sign and Connections

Electric? no Vertical dimension after erection 32" Horizontal 41 1/2"  
Weight 55 lbs., Will there be any hollow spaces? no Any rigid frame? yes  
Material of frame wood No. advertising faces 2, material steel  
No. rigid connections 2 Are they fastened directly to frame of sign? yes  
No. through bolts no, Size ---, Location, top or bottom ---  
No. guys 4, material cable, Size 1/2"  
Minimum clear height above sidewalk or street 16'  
Maximum projection into street 41 1/2"

Fee \$ 1.00

Signature of contractor Flynn, The Painter  
By Edmund J. Rooney

INSPECTION COPY Oliver T. Sanborn


CITY OF PORTLAND, ME.

Ward 4 Permit No. 33/1347  
 Location 84 Center St  
 Owner Harold L. Lunsdale  
 Date of permit 9/15/33  
 Sign Contractor \_\_\_\_\_  
 Final Inspn. 10/13/33

NOTES

10/13/33 - *signature* - A. J. [illegible]

DIAL ELECTRIC COMPANY HAS DIRECT  
 PERMISSION FOR WORK TO BE DONE



DEPARTMENT OF STREET LIGHTS AND CANNONWORKS

VOUCHER NO. \_\_\_\_\_ DATE \_\_\_\_\_

AMOUNT PAID TO CONTRACTOR \_\_\_\_\_

CHECK NO. \_\_\_\_\_ DATE \_\_\_\_\_

RECEIVED BY \_\_\_\_\_



Permit No. \_\_\_\_\_

## APPLICATION FOR PERMIT TO REPAIR BUILDING

Third Class Building

FEB 4 1931

Portland, Maine, February 2, 1931

To the INSPECTOR OF BUILDINGS, PORTLAND, ME.

The undersigned hereby applies for a permit to repair the following described building in accordance with the Laws of Maine, the Building Code of the City of Portland, and the following specifications:

Location 8 Spring Street Ward 4 Within fire limits? yes Dist. No. 1  
 Owner's name and address Ellen Connolly, 21 Tyng St. Telephone \_\_\_\_\_  
 Contractor's name and address J. J. Maloney Co., 270 Middle St. Telephone 7785  
 Use of building dwelling house 1 family  
 No. stories \_\_\_\_\_ Height \_\_\_\_\_ ft, Gross area \_\_\_\_\_ sq. ft., Style of roof \_\_\_\_\_  
 Type of present roof covering \_\_\_\_\_

## General Description of New Work

To Repair after Fire to former condition. No alterations

Around chimney  
1st and 2d floors

## If Roof Covering is to be Repaired or Renewed

When last repaired? \_\_\_\_\_ Area then repaired \_\_\_\_\_ sq. ft.  
 Are repairs or renewal due to damage by fire? yes If so, what area damaged? \_\_\_\_\_ sq. ft.  
 Area of roof to be repaired now? \_\_\_\_\_ sq. ft.  
 Type of roofing to be used \_\_\_\_\_ No. plies \_\_\_\_\_  
 Trade name and grade of roof covering to be used \_\_\_\_\_  
 Estimated cost \$ 200. Fee \$ .75

INSPECTION COPY

Signature of owner Ellen ConnollyBy John J. Maloney

4075A

Ward 4 Permit No. 31/96

Location Spring St

Owner Elliott Connolly

Date of permit 2/4/31

Notif. closing-in \_\_\_\_\_

Inspn. closing-in \_\_\_\_\_

Final Notif. \_\_\_\_\_

Final Inspn. 2/13/31

Cert. of Occupancy issued None

NOTES

2/6/31 - Entirely new chimney being erected - A.J.

2/13/31 - Chimney has been closed in without notice for inspection being given. Carpenter on job says proper clearances were made from woodwork and from what I saw of way chimney was started at time of last inspection I should say that this is O.K. Firestop in at first floor and carpenter says that other floors were stopped O.K. (over)

safety collars used around flue openings on first and second floors. - A.J.

RECEIVED 1 5011 12 3 30 1931



FILL IN COMPLETELY AND SIGN WITH INK

PERMIT ISSUED  
Permit No. 3357

APPLICATION FOR PERMIT FOR HEATING, COOKING OR POWER EQUIPMENT

Oct. 11, 1930

Portland, Maine, \_\_\_\_\_

To the INSPECTOR OF BUILDINGS, PORTLAND, ME.

The undersigned hereby applies for a permit to install the following heating, cooking or power equipment in accordance with the Laws of Maine, the Building Code of the City of Portland, and the following specifications:  
8 Spring Street dwelling house

Location Patrick Donahue Use of Building 8 Spring St.

Name and address of owner Portland Stove Foundry Co. 39 Kennebec St. Ward 4  
6500

Contractor's name and address \_\_\_\_\_ Telephone \_\_\_\_\_

General Description of Work

Hot Air Heater

To install \_\_\_\_\_

IF HEATER, POWER BOILER OR COOKING DEVICE

Is heater or source of heat to be in cellar? \_\_\_\_\_ If not, which story \_\_\_\_\_ Kind of fuel coal

Material of supports of heater or equipment (concrete floor or what kind) concrete floor

Minimum distance to wood or combustible material, from top of boiler or casing, top of furnace, \_\_\_\_\_ over 4'

from top of smoke pipe \_\_\_\_\_, from front of heater \_\_\_\_\_, from sides or back of heater \_\_\_\_\_

IF OIL BURNER

Name and type of burner \_\_\_\_\_ Approved by Underwriters' Laboratories? \_\_\_\_\_

Location oil storage \_\_\_\_\_ No. and capacity of tanks \_\_\_\_\_

Will all tanks be more than seven feet from any flame? \_\_\_\_\_ How many tanks fireproofed? \_\_\_\_\_

Amount of fee enclosed? \$1.00 (\$1.00 for one heater, etc., 50 cents additional for each additional heater, etc., at same building at same time.)

Signature of contractor W. Larkin

INSPECTION COPY

78-84 Center

STICK BEFORE LATE  
OR LATE

3357-A

Ward / Permit No. 342315

Location Spring St.

Owner Patrick Donohue

Date of permit 10/13/30

Notif. closing-in \_\_\_\_\_

Inspn. closing-in \_\_\_\_\_

Final Notif. \_\_\_\_\_

Final Inspn. 2/5/31

Cert. of Occupancy issued None

NOTES

11/7/30 - One pipe  
noticed controls  
removed. Timber  
across front of chimney  
to be removed at least  
a 2x4x8 approx.

11/7/30 - Mr. Loshin  
said that he will  
look after controls  
in pipe. - A.J.S.

1/14/31 - Sawyer + damper  
taken out of fire  
hot air pipe. Hole  
knocked in chimney  
and cleanout door  
taken out. Should  
have cleanout door  
replaced + opening  
around it bricked  
up. Timber close to chimney

very not yet moved  
and in chimney. A.J.S.  
1/26/31 - Fire at kind chimney  
here last night. On  
inspection after fire found  
that cleanout door had  
been put in + woodwork  
moved away from chimney  
before fire. Fire  
started in outside wall  
at level of sill at point  
which could not be  
seen at time of inspection.

A.J.S.  
2/5/31 - Have above  
work taken care of  
under Permit # 31976  
A.J.S.

RECEIVED  
FEB 11 1931  
C. H. OR GOOD TIME





(G) GENET

SS ZONE

PERMIT ISSUED  
Permit No. 1032  
FEB 4 1929

# APPLICATION FOR PERMIT TO ERECT SIGN OVER PUBLIC SIDEWALK OR STREET

Portland, Maine, Jan. 31, 1929

To the INSPECTOR OF BUILDINGS, PORTLAND, ME.

The undersigned hereby applies for a permit to erect the following described sign extending over a public sidewalk or street in accordance with the Building Code of the City of Portland, and the following specifications:

Location 52 Spring St. (78-84 Center St.) Ward 4 Within Fire Limits? Yes Dist. No. \_\_\_\_\_

Owner, of building to which sign is to be attached E. T. BURROWER CO.

Name and address of owner of sign Same

Contractor's name and address J. H. Middlebrook 10 Elm St. Telephone 9-830

When does contractor's bond expire? May 4, 1929

### Information Concerning Building

No. stories Five Material of wall to which sign is to be attached Brick

### Details of Sign and Connections

Two Reflectors  
Electric? \_\_\_\_\_ Vertical dimension after erection 44 inch Horizontal 30 in.

Weight 30 lbs., Will there be any hollow spaces? No Any rigid frame? Yes

Material of frame Gal. strap Iron No. advertising faces Two, material Enamelled Iron

No. rigid connections Two Are they fastened directly to frame of sign? Yes

No. through bolts None, Size \_\_\_\_\_, Location, top or bottom \_\_\_\_\_

No. guys Two, material Iron Rod, Size 5/8 inch

Minimum clear height above sidewalk or street 11 ft.

Maximum projection into street 6 ft.

Fee \$ 1.00

Signature of contractor J. H. Middlebrook

INSPECTION COPY

Oliver P. Sawyer

Per. L.M.M.


8474

W. 4 Permit No. 29/92  
Location 28 Spring St. 78-84  
Owner G. T. Burkes Co.  
Date Permit 2/4/29  
Sign Contractor  
Final Inspn. 5/12/29 C. C. O.

DAER PUBLIC SIDEWALK OR SIDEWALK  
APPLICATION FOR PERMIT TO ERECT SIGN

NOTES  
See the Property Code of the City of New York and the provisions thereof relating to the erection of signs on sidewalks and streets.  
The applicant is to be held responsible for the erection of signs on sidewalks and streets.  
The applicant is to be held responsible for the erection of signs on sidewalks and streets.

Details of sign and construction  
The applicant is to be held responsible for the erection of signs on sidewalks and streets.  
The applicant is to be held responsible for the erection of signs on sidewalks and streets.  
The applicant is to be held responsible for the erection of signs on sidewalks and streets.





(G) ... 539 ZONE

PERMIT ISSUED  
Permit No. 0002

# APPLICATION FOR PERMIT TO ERECT SIGN OVER PUBLIC SIDEWALK OR STREET

JAN 2 1928

Portland, Maine, Dec. 29, 1928 19

To the INSPECTOR OF BUILDINGS, PORTLAND, ME.

The undersigned hereby applies for a permit to erect the following described sign extending over a public sidewalk or street in accordance with the Building Code of the City of Portland, and the following specifications:

Location 2 Spring St. (78 8th Center Street) Ward 4 Within Fire Limits? Yes Dist. No. \_\_\_\_\_

Owner of building to which sign is to be attached E. T. Burrows Co.

Name and address of owner of sign Standard Oil Co. of N. Y.

Contractor's name and address J. H. Middlebrook 10 Elm St. Telephone P 830

When does contractor's bond expire? May 4, 1929

## Information Concerning Building

No. stories Five Material of wall to which sign is to be attached Brick

## Details of Sign and Connections

Electric? No Vertical dimension after erection 24 inches Horizontal 38 inches

Weight 40 lbs. lbs., Will there be any hollow spaces? No Any rigid frame? Yes

Material of frame Wood No. advertising faces 2, material Gal. Iron

No. rigid connections Two Are they fastened directly to frame of sign? Yes

No. through bolts None, Size \_\_\_\_\_, Location, top or bottom \_\_\_\_\_

No. guys One, material Iron-Rod, Size 1/4 inch

Minimum clear height above sidewalk or street 15-0

PRO Maximum projection into street 6-0 Fee \$ \_\_\_\_\_

Signature of contractor J. H. Middlebrook


INSPECTION COPY

838 12

Ward 4 Permit No. 29/2  
 If Spring St. 78-84 Center St.  
 Owner Standard Oil Co. of N.Y.  
 Date of permit 7/2/29  
 Sub Contractor \_\_\_\_\_  
 Final Inspn. 7/30/29

NOTES

OWNERS MUST MAINTAIN OR STREET  
 SECTION FOR PERMIT TO ERECT SIGN



IN REPLY TO THE  
 CITY ENGINEER  
 THE FOLLOWING  
 INFORMATION IS  
 FURNISHED FOR  
 YOUR RECORD  
 THE SIGN TO BE  
 ERECTED IS  
 TO BE LOCATED  
 ON THE EAST  
 SIDE OF THE  
 STREET  
 BETWEEN  
 SPRING ST.  
 AND CENTER ST.  
 THE SIGN IS  
 TO BE ERECTED  
 ON THE SIDEWALK  
 AND SHALL NOT  
 OBSTRUCT THE  
 WALKWAY  
 THE SIGN SHALL  
 BE ERECTED  
 IN ACCORDANCE  
 WITH THE  
 ORDINANCES  
 OF THE CITY  
 OF NEW YORK  
 CONCERNING  
 THE ERECTION  
 OF SIGNS  
 IN THE CITY  
 OF NEW YORK

REGISTRATION COMMA

APPROVED FOR THE CITY ENGINEER  
 \_\_\_\_\_  
 CITY ENGINEER